

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0511</u>	MAKE <u>CAT</u>	HOURS _____	DAYS _____	BASIC MACHINE	HYDRAULIC ENGINE IMPLEMENTS
MODEL <u>303.5E2</u>	SERIAL # _____	REASON		POWER TRAIN	ELECTRIC DRIVE TRAIN UNEXPLAINED
HOUR METER <u>2K HRS</u>	MILES _____	PARTS	LABOR	COMPONENT LOCATION	
		OTHER _____		FRONT REAR	LEFT RIGHT UPPER LOWER
				OTHER _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE: _____	DATE COMPLETED <u>6-25-18</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC <u>ALI</u>	
SMOKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>bought used check over</u>					
REPAIRED: <u>serviced, replaced both arm rests</u> <u>replaced all teeth on 18" bucket</u>					
PARTS: <u>teeth pins & ret.</u>		<u>123.³⁹</u>		<u>Thompson</u>	
<u>Arm rests</u>		<u>77.⁹⁴</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>511</u> MAKE <u>CAT</u> MODEL <u>3035</u> SERIAL # _____ HOUR METER <u>2,628 HRS</u> MILES _____	HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: <u>3-6-19</u> DATE COMPLETED <u>3-20-19</u> MECHANIC <u>Chanks</u> JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____	
PROBLEM: <u>boom leaking down</u>		
REPAIRED: <u>replaced spool & seals in RT control valve</u> <u>packed boom cylinder</u>		
PARTS: <u>Pilot valve Parts 291.⁰⁰ Thompson</u> <u>+ boots</u> <u>boom Cyl. seal kit 390.¹⁷ Thompson</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES													
EQUIP. # <u>0511</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS													
MAKE <u>Cat</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED													
MODEL <u>303.5</u>	PARTS _____ LABOR _____	COMPONENT LOCATION													
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER													
HOUR METER <u>3K HRS</u>		OTHER _____													
MILES _____															
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>9-12-19</u> DATE COMPLETED <u>9-17-19</u>													
		MECHANIC <u>All</u>													
PROBLEM: <u>Service</u>		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER												
REPAIRED: <u>serviced replaced seat bottom replaced bearings pins & seals stick to bucket. to link to bucket</u>															
PARTS: <table border="0"><tr><td><u>All Filters</u></td><td><u>150.⁶³</u></td><td><u>Thompson</u></td></tr><tr><td><u>Seat bottom</u></td><td><u>370.⁴³</u></td><td><u>Thompson</u></td></tr><tr><td><u>bearings & seals</u></td><td><u>239.⁰⁴</u></td><td><u>Thompson</u></td></tr><tr><td><u>2-pins</u></td><td><u>247.⁹⁴</u></td><td><u>Thompson</u></td></tr></table>				<u>All Filters</u>	<u>150.⁶³</u>	<u>Thompson</u>	<u>Seat bottom</u>	<u>370.⁴³</u>	<u>Thompson</u>	<u>bearings & seals</u>	<u>239.⁰⁴</u>	<u>Thompson</u>	<u>2-pins</u>	<u>247.⁹⁴</u>	<u>Thompson</u>
<u>All Filters</u>	<u>150.⁶³</u>	<u>Thompson</u>													
<u>Seat bottom</u>	<u>370.⁴³</u>	<u>Thompson</u>													
<u>bearings & seals</u>	<u>239.⁰⁴</u>	<u>Thompson</u>													
<u>2-pins</u>	<u>247.⁹⁴</u>	<u>Thompson</u>													

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0511</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>303.5</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>3500 HRS</u>		OTHER _____	
MILES <u>3500 HRS</u>			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>3-6-2020</u> MECHANIC <u>Charles</u>	
JOB NAME/LOCATION		JOB NUMBER	
<u>Shop</u>			
PROBLEM: <u>New Thumb</u>			
REPAIRED: <u>Installed Thumb</u>			
PARTS: <u>Thumb</u>		<u>\$ 2,000.⁰⁰</u>	<u>Thompson</u>
<u>Fittings</u>		<u>\$ 66.15</u>	<u>IR&G</u>

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0511</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON _____	POWERTRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>303.5</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>3500 HRS</u>	OTHER _____	OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE <u>2-4-2020</u> DATE COMPLETED <u>3-6-2020</u> MECHANIC <u>Charles</u>	
		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>needs serviced & muffler insulator</u>			
REPAIRED: <u>serviced & insulator</u>			
PARTS: <u>All Filters</u> <u>152.44</u> <u>Thompson</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP.# <u>0511</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>303.5</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE: _____ DATE COMPLETED <u>4-9-2020</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____	JOB NAME/LOCATION <u>Jones Burnett</u> JOB NUMBER _____	
PROBLEM: <u>blown hose</u>		
REPAIRED: <u>replaced boom hose</u>		
PARTS: <u>Hose</u> <u>\$165.00</u> <u>IR&B</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0511</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>303.5</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>4K HRS</u>		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>10-14-20</u> DATE COMPLETED <u>10-29-20</u>	MECHANIC <u>Ben/Caleb</u>
		JOB NAME/LOCATION <u>J.B</u>	JOB NUMBER
PROBLEM: <u>Service & check starter</u>			
REPAIRED: <u>serviced, had starter rebuilt</u>			
PARTS: <u>Filters</u> <u>152.18</u> <u>Thompson</u>			
<u>Starter Rebuilt - CROOKS auto etc. 86.70 86.70</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0511</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Cat</u>	REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>303.5</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>9-28-19</u> MECHANIC <u>Charles</u> JOB NAME/LOCATION <u>Ashland Farms</u> JOB NUMBER _____
PROBLEM: <u>needs fan belt</u>		
REPAIRED: <u>replaced belt.</u>		
PARTS: <u>belt</u> <u>20.65</u> <u>Thompson</u> <u>472-3145</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0511</u> MAKE <u>CAT</u> MODEL <u>303.5</u> SERIAL # _____ HOUR METER _____ MILES _____	HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE <u>11-5-20</u> DATE COMPLETED <u>11-5-20</u> MECHANIC <u>James</u>	
PROBLEM: <u>bucket cylinder leaking</u>		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
REPAIRED: <u>sealed bucket cylinder</u> <u>replaced back up alarm</u>			
PARTS: <u>seal kit</u> <u>585-5979</u>		<u>199.91</u>	<u>Thompson</u>

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0571</u> MAKE <u>CAT</u> MODEL <u>303.5</u> SERIAL # _____ HOUR METER _____ MILES _____	HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>11-3-20</u> MECHANIC <u>James</u>	
JOB NAME/LOCATION		JOB NUMBER	
PROBLEM: <u>Bad battery</u>			
REPAIRED: <u>Replaced battery</u>			
PARTS: <u>MTP-24</u> <u>136^{of}</u> <u>Tide-stak battery</u> <u>30 mo. replacement</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0511</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>303.5</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>5-18-21</u> MECHANIC <u>Caleb</u> JOB NAME/LOCATION _____ JOB NUMBER _____
PROBLEM: <u>Boom cylinder guard broken</u>		
REPAIRED: <u>replaced guard</u>		
PARTS: <u>cylinder guard</u> <u>91.08</u> <u>Thompson</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0511</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>303.5</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE: _____ DATE COMPLETED <u>7-29-21</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____	JOB NAME/LOCATION <u>Northlake</u> JOB NUMBER _____	
PROBLEM: <u>blown Hyd hose</u>		
REPAIRED: <u>replaced hose</u>		
PARTS: <u>hose</u> <u>297.⁰⁰</u> <u>IR+L</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0511</u>	MAKE <u>CAT</u>	MODEL <u>303.5</u>	SERIAL # _____	HOURS _____ DAYS _____	REASON _____
_____	_____	_____	_____	PARTS _____ LABOR _____	OTHER _____
_____	_____	_____	_____	OTHER _____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	SMOKES SHORTED VIBRATE OTHER _____	DATE: <u>3-9-23</u>	DATE COMPLETED: <u>3-16-23</u>	MECHANIC: <u>ALL</u>
PROBLEM: <u>Ayd leak + very loose bucket</u>			JOB NAME/LOCATION: <u>Shops</u>	JOB NUMBER _____	
REPAIRED: <u>replaced A link, thumb + stick bushings and pins.</u>					
<u>Fixed leak on valve body.</u>					
PARTS: <u>pins bearings + seals 638.²⁵ Thompson</u>					
<u>links, pins + bearings 1275.⁵⁹ Thompson</u>					
<u>Pin 139.⁵⁶ Thompson</u>					
<u>spacers 144.⁶⁸ Thompson</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0511</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>303.5</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER <u>SK NRS</u>		OTHER _____
MILES _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: <u>5-18-23</u> DATE COMPLETED <u>5-22-23</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Anthony & BRIAN</u>
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Vintage Edge</u>
JOB NUMBER _____		JOB NUMBER _____
PROBLEM: <u>Service</u>		
REPAIRED: <u>Service</u>		
PARTS: <u>Filters</u>	<u>191.44</u>	<u>Thompson</u>

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0571</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>303.5</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER <u>5,800 HRS</u>		OTHER _____
MILES _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE: <u>12-15-23</u> DATE COMPLETED <u>2-19-24</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC <u>Anthony</u>	
SMOKES SHORTED VIBRATE OTHER _____	JOB NAME/LOCATION <u>West Trinity</u> JOB NUMBER <u>Steve Trace</u>	
PROBLEM: <u>Service</u>		
REPAIRED: <u>serviced</u>		
PARTS: <u>Filters</u>	<u>248.23</u>	<u>Thompson</u>

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0511</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>303.5</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: <u>6-18-24</u> DATE COMPLETED <u>6-20-24</u> MECHANIC <u>James</u>		
	JOB NAME/LOCATION <u>To Shop</u>	JOB NUMBER	
PROBLEM: <u>leak at foot controls</u> <u>belt squeak</u>			
REPAIRED: <u>replaced foot control plunger seal</u> <u>replaced alt. belt.</u>			
PARTS: <u>seals + belts</u>	<u>327.00</u>	<u>Thompson</u>	

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES			
EQUIP. # <u>0511</u>		HOURS _____	DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS			
MAKE <u>Cat</u>		REASON		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED			
MODEL <u>303.5</u>		PARTS _____	LABOR _____	COMPONENT LOCATION			
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER			
HOUR METER _____				OTHER _____			
MILES _____							

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE: <u>1-24-25</u>	DATE COMPLETED: <u>1-25-25</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____	JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____

PROBLEM: Thumb only moves one way.
boom cylinder leaking. speed sensor wiring.

REPAIRED: packed boom cylinder. Replaced RT Joy
stick. repaired wiring going to engine.

PARTS: <u>seal kit</u>	<u>357.96</u>	<u>Thompson</u>
<u>boot</u>	<u>81.36</u>	<u>Thompson</u>
<u>700.00</u>	<u>Joystick</u>	<u>Thompson</u>

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>0511</u> MAKE <u>CAT</u> MODEL <u>303.5</u> SERIAL # _____ HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
--	---	--

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: <u>1-8-25</u> DATE COMPLETED <u>1-14-25</u> MECHANIC <u>Ben</u>
	JOB NAME/LOCATION: <u>Ambreys To Shop</u> JOB NUMBER _____

PROBLEM: won't start

REPAIRED: pump fixed starting problem. wiring problem going to speed sensor. repaired wiring

PARTS: pump 106.13 Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0511</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS			
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED			
MODEL <u>303.5</u>	PARTS _____ LABOR _____	COMPONENT LOCATION			
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER			
HOUR METER <u>6K MRS</u>		OTHER _____			
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: <u>3-13-25</u>	DATE COMPLETED <u>3-19-25</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC _____			
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION	JOB NUMBER		
PROBLEM: <u>Service</u>					
REPAIRED: <u>serviced</u>					
PARTS: <u>filters</u> <u>125.18</u> <u>Thompson</u>					