




THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>110</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>	REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>CP563</u>	PARTS LABOR	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>5-26-12</u>	
		MECHANIC <u>James</u>	
		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>won't start old batteries</u>			
REPAIRED: <u>replaced both batteries</u>			
PARTS: <u>2 - Gup 27 batteries 207.55 Advance Auto Parts</u>			



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>110</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>CP563</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER <u>3,208</u>	OTHER _____	OTHER _____
MILES _____		
REASON FOR FAILURE: <u>BROKEN</u> <u>WORN</u> ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM <u>LEAKING</u> NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>11-8-12</u>
		MECHANIC <u>JAMES</u>
		JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____
PROBLEM: <u>Two mounts on RT side of drum broken. Vibrator motor leaks, check over.</u>		
REPAIRED: <u>replaced broken mount. Vibrator motor cracked covered crack with JB weld. replaced blown hydraulic hose</u>		
PARTS: <u>2-mounts 55.⁰⁰ EA</u> <u>White House Equipment</u> <u>seal 28.²¹</u> <u>Thompson Machinery</u> <u>Hyd. Hose 127.²³</u> <u>NAPA</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>110</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>CP563</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____	_____	OTHER _____	
MILES _____	_____	_____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____	DATE COMPLETED <u>10-7-13</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Cris</u>	
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>Throttle cable rusted out</u>			
REPAIRED: <u>replaced cable</u>			
PARTS: <u>cable assembly 169.⁸⁷ Thompson</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>110</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Cat</u>	REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>CP563</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER <u>3500 HRS</u>		OTHER _____
MILES _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: _____ DATE COMPLETED <u>6-5-15</u>	
	MECHANIC <u>James + Steven</u>	
PROBLEM: <u>needs seat cushions</u> <u>service</u>	JOB NAME/LOCATION <u>Reid Hill</u>	
	JOB NUMBER	
REPAIRED: <u>replaced seat cushions and serviced</u>		
PARTS: <u>seat cushions</u> <u>324.²⁹</u> <u>Thompson</u>		
<u>All filters</u> <u>167.⁷⁵</u> <u>Tenn. Filter sales</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>110</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>CP563</u>		PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____			OTHER _____
MILES _____			

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE: _____ DATE COMPLETED <u>5-19-16</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC <u>James & Steven</u>
SMOKE SHORTED VIBRATE OTHER _____	JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____

PROBLEM: Fix leaks

REPAIRED: replaced shaft seal in hyd pump replaced belts replaced vibrator motor, repair exhaust replaced one battery.

PARTS: <u>seals, clamps & belts</u>	<u>308.44</u>	<u>Thompson</u>
<u>seal</u>	<u>28.25</u>	<u>Thompson</u>
<u>belt set</u>	<u>64.24</u>	<u>Thompson</u>
<u>seals</u>	<u>25.73</u>	<u>Thompson</u>
<u>motor</u>	<u>2386.44</u>	<u>Thompson</u>
<u>seal kit</u>	<u>135.40</u>	<u>Thompson</u>
<u>Tube</u>	<u>403.46</u>	<u>Thompson</u>
<u>batteries</u>	<u>106.00</u>	<u>Advance Auto Parts</u>

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

<p>EQUIPMENT INFORMATION</p> <p>EQUIP. # <u>110</u></p> <p>MAKE <u>CAT</u></p> <p>MODEL <u>CP563</u></p> <p>SERIAL # _____</p> <p>HOUR METER _____</p> <p>MILES _____</p>	<p>EQUIPMENT DOWNTIME</p> <p>HOURS _____ DAYS _____</p> <p>REASON _____</p> <p>PARTS _____ LABOR _____</p> <p>OTHER _____</p>	<p>COMPONENT CODES</p> <p>BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS</p> <p>POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED</p> <p>COMPONENT LOCATION</p> <p>FRONT REAR LEFT RIGHT UPPER LOWER</p> <p>OTHER _____</p>
--	--	---

<p>REASON FOR FAILURE: <input type="checkbox"/> BROKEN <input type="checkbox"/> WORN <input type="checkbox"/> ABUSE <input type="checkbox"/> LOOSE <input type="checkbox"/> SEIZED</p> <p><input type="checkbox"/> OVERHEAT <input type="checkbox"/> PLANNED <input type="checkbox"/> CONTAM <input type="checkbox"/> LEAKING <input type="checkbox"/> NOISY <input type="checkbox"/> SCRATCH</p> <p><input type="checkbox"/> SMOKES <input type="checkbox"/> SHORTED <input type="checkbox"/> VIBRATE <input type="checkbox"/> OTHER _____</p>	<p>DATE: _____ DATE COMPLETED <u>8-6-16</u></p> <p>MECHANIC <u>Steve B</u></p>
---	--

JOB NAME/LOCATION <u>Mr. Tuley work</u>	JOB NUMBER _____
---	------------------

PROBLEM: seat rusted out

REPAIRED: replaced seat

seat 1,220.00 Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963


EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>110</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>CP563</u>	PARTS LABOR	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____		DATE: _____ DATE COMPLETED <u>11-29-16</u>	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		MECHANIC _____	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		JOB NAME/LOCATION	JOB NUMBER
SMOKES SHORTED VIBRATE OTHER _____		<u>Wilson Bank Lebanon</u>	
PROBLEM: <u>vibrator switch broken</u>			
REPAIRED: <u>replaced switch</u>			
PARTS: <u>Switch + Cat</u> <u>65.00</u> <u>Thompson</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0702</u>	HOURS _____ DAYS _____	BASIC MACHINE	HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>CAT</u>	REASON _____	POWER TRAIN	ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>CP563</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT	REAR LEFT RIGHT UPPER LOWER
HOUR METER <u>4K HRS</u>		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE <u>7-26-18</u>	DATE COMPLETED <u>8-15-18</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC <u>Tony</u>		
SMOKES SHORTED VIBRATE OTHER _____	JOB NAME/LOCATION	JOB NUMBER	
<u>Shop</u>			
PROBLEM: _____ _____ _____			
REPAIRED: <u>serviced</u> _____ _____ _____ _____ _____ _____			
PARTS: <u>All Filters</u> <u>180.23</u> <u>Tenn Filter</u> _____ _____ _____			



THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES			
EQUIP. # <u>G702</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS			
MAKE <u>CAT</u>		REASON		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED			
MODEL <u>CP563</u>		PARTS _____ LABOR _____		COMPONENT LOCATION			
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER			
HOUR METER _____				OTHER _____			
MILES _____							
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE <u>12-13-18</u> DATE COMPLETED <u>12-19-18</u>			
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC <u>James Bryan</u>			
SMOKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION <u>MCH</u>		JOB NUMBER	
PROBLEM: <u>blown hose from Pump to motor</u>							
REPAIRED: <u>replaced hose filled hydraulic Tank</u>							
PARTS: <u>Filter</u>		<u>76.²⁹</u>		<u>Thompson</u>			
<u>Hose</u>		<u>206.¹⁰</u>		<u>Thompson</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0702</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>CP563</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE <u>6-4-19</u>	DATE COMPLETED <u>7-31-19</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC <u>Charles</u>	
SMOKE SHORTED VIBRATE OTHER _____	JOB NAME/LOCATION <u>Ashland to shop</u>	JOB NUMBER _____

PROBLEM: Service & won't move
brought to shop spacers 106.57 Thompson
Hoses 1,028.46 Nashville Rubber & Gasket

REPAIRED: replaced bad fire holders
replaced clean cylinders 2 bearings 210.00 Thompson
replaced water pump tensioner pulley & belt.
Replaced hitch pins & bearings, replaced 6 old hoses & blade
Pins & Bushings 579.32 Thompson
seals 133.84 Thompson
bearings 195.53 Thompson

PARTS: All Filters 184.82 Teau Filter sales
belts cover & washers 198.35 Thompson
3 Drum Mounts 320.33 Thompson
Belt, pulley & Hardware 169.20 Thompson
3 clean cylinders 350.48 Thompson

Pins 447.99 Thompson
Bushings 172.35 Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>0702</u> MAKE <u>Cat</u> MODEL <u>CP563</u> SERIAL # _____ HOUR METER _____ MILES _____		EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>1-9-2020</u> MECHANIC <u>BUYAO</u>	JOB NAME/LOCATION <u>James Brummett</u>
PROBLEM: <u>won't start</u>		JOB NUMBER	
REPAIRED: <u>replaced bad batteries</u>			
PARTS: <u>2 - MT-27</u> <u>\$273.63</u> <u>Interstate Battery</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0702</u> MAKE <u>CAT</u> MODEL <u>CP563</u> SERIAL # _____ HOUR METER _____ MILES _____	HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: _____ DATE COMPLETED <u>12-16-21</u> MECHANIC <u>Ben</u> JOB NAME/LOCATION <u>West Trinity</u> JOB NUMBER _____	
PROBLEM: <u>blown tire</u>		
REPAIRED: <u>replaced tire</u>		
PARTS: <u>23.1-26 Primex 2459, 60 Gateway Tire</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0702</u> MAKE <u>CAT</u> MODEL <u>CP563</u> SERIAL # _____ HOUR METER _____ MILES _____	HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: _____ DATE COMPLETED <u>1-5-22</u> MECHANIC <u>Anthony</u> JOB NAME/LOCATION <u>West Trinity</u> JOB NUMBER _____	
PROBLEM: <u>blown hyd. hose</u>		
REPAIRED: <u>replaced hose</u>		
PARTS: <u>hose</u> <u>82 70</u> <u>Nashville Rubbe + Gasket</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0702</u>		HOURS _____ DAYS _____	BASIC MACHINE	HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>CAT</u>		REASON _____	POWER TRAIN	ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>CP563</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 3-26-22
MECHANIC All
JOB NAME/LOCATION Shop JOB NUMBER _____

PROBLEM: Pump down

REPAIRED: removed pump had rebuilt replaced old control & cable, removed block & di's armed valve. changed engine oil & filter, changed hydraulic oil. Replaced 4 scraper tips

PARTS: Pump repair	6,391. ¹³	Mid South hydraulics
2 pump hoses	154. ⁹²	Thompson
O-rings & seals	109. ³⁵	Thompson
Oil Filter & Hy. Filter	86. ²⁹	Thompson
Control & cable	1,066. ⁷⁰	Thompson
TIPS & locks	248. ²⁸	Thompson
sending unit	91. ⁶⁹	Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>0702</u> MAKE <u>CAT</u> MODEL <u>CP563</u> SERIAL # _____ HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: <u>4-4-22</u> DATE COMPLETED <u>4-5-22</u> MECHANIC <u>Ben</u>	JOB NAME/LOCATION: <u>Iron Mountain</u> JOB NUMBER _____
PROBLEM: <u>broken rubber mounts in drum</u>		
REPAIRED: <u>replaced mounts</u>		
PARTS: <u>Mounts & Hardware 688.71 Thompson</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0702</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>CP563</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>8-31-22</u>
PROBLEM: <u>leak + broken pad</u>		MECHANIC <u>Ben</u>
		JOB NAME/LOCATION <u>Steve Trace</u> JOB NUMBER _____
REPAIRED: <u>replaced blown hose and 1 right drum pad</u>		
PARTS: <u>hose</u> <u>577.38</u> <u>Thompson</u>		
<u>Mount</u> <u>157.56</u> <u>Thompson</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0702</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>CP563</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____				DATE <u>12-6-22</u> DATE COMPLETED <u>3-21-23</u>	
				MECHANIC <u>All</u>	
				JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____	
PROBLEM: <u>drum hammer quit working hole in radiator</u>					
REPAIRED: <u>new bearings & seals in drum had radiator recored. replaced park valve in rear pump.</u>					
PARTS: <u>bearings & seals 3433.⁶⁵ Thompson</u>					
<u>radiator re-core 2092.⁹² ECJ</u>					
<u>valve & Rad. cap 522.⁶³ Thompson</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0702</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>CP563</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE: _____ DATE COMPLETED <u>4-12-23</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC <u>Anthony</u>	
SMOKES SHORTED VIBRATE OTHER _____	JOB NAME/LOCATION: <u>Sparta Pk.</u> JOB NUMBER _____	
PROBLEM: <u>overheating</u>		
REPAIRED: <u>replaced water pump tensioner pulley.</u>		
PARTS: <u>pulley</u> <u>368.97</u> <u>Thompson</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0702

MAKE Cat

MODEL CP563

SERIAL # _____

HOUR METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON _____

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: 7-6-23 DATE COMPLETED 7-10-23

MECHANIC James

JOB NAME/LOCATION
To Shop

JOB NUMBER

PROBLEM: pump solenoid getting hot.

REPAIRED: replaced solenoid and update manifold

PARTS: Solenoid + Manifold 693.94

Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0702</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>CAT</u>	REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>CP563</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER <u>5K HRS</u>		OTHER _____
MILES _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE <u>8-31-23</u> DATE COMPLETED <u>9-12-23</u> MECHANIC <u>Anthony</u> JOB NAME/LOCATION <u>Limestone Trail</u> JOB NUMBER _____	
PROBLEM: <u>Service</u>		
REPAIRED: <u>Service</u>		
PARTS: <u>Filters</u>	<u>239.11</u>	<u>Tea Filter</u>

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0702</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>CP563</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____	OTHER _____	OTHER _____	
MILES _____	OTHER _____	OTHER _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE: _____ DATE COMPLETED <u>10-11-23</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC <u>James</u>		
SMOKES SHORTED VIBRATE OTHER _____	JOB NAME/LOCATION	JOB NUMBER	
PROBLEM: <u>Fuel leaking off</u>	<u>Shop</u>		
REPAIRED: <u>replaced main fuel filter & hand prime pump.</u>			
PARTS: <u>Filter + pump 160. Thompson</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0702</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>CPS63</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		DATE: _____ DATE COMPLETED <u>2-19-24</u> MECHANIC <u>Bev</u>	
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>A. Thun</u>	JOB NUMBER
PROBLEM: <u>won't start</u>			
REPAIRED: <u>replaced old batteries</u>			
PARTS: <u>2 MT-27</u> <u>291.82</u> <u>Interstate battery</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0702</u>	HOURS _____ DAYS _____	REASON	BASIC MACHINE	HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Cat</u>	PARTS _____ LABOR _____	OTHER _____	POWER TRAIN	ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>CP563</u>			COMPONENT LOCATION	
SERIAL # _____			FRONT REAR	LEFT RIGHT UPPER LOWER
HOUR METER _____			OTHER _____	
MILES _____				

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE: <u>3-13-25</u>	DATE COMPLETED: <u>4-15-25</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC: <u>Ben</u>	
SMOKE SHORTED VIBRATE OTHER _____	JOB NAME/LOCATION: <u>Shop</u>	JOB NUMBER _____

PROBLEM: Service, check over.
no back up alarm.

REPAIRED: Excess water in fuel tank. Flushed tank.
Serviced. Replaced batteries. Replaced broken
left door cylinder.

PARTS: <u>Filters</u>	<u>251. ²⁸</u>	<u>Tenn Filter</u>
<u>batteries</u>	<u>351. ⁶⁶</u>	<u>Advance</u>
<u>door cylinder</u>	<u>173. ²⁵</u>	<u>Thompson</u>