

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>207</u> MAKE <u>CAT</u> MODEL <u>2590</u> SERIAL # <u>FTL04814</u> HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
--	---	--

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: _____ DATE COMPLETED <u>7-26-16</u> MECHANIC <u>JAMES</u> JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____
---	--

PROBLEM: fuel leak at tank

REPAIRED: replaced grommet at fuel tank

Parts Grommets 23, 33 Thompson Machinery

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>207</u> MAKE <u>CAT</u> MODEL <u>259D</u> SERIAL # _____ HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
--	---	--

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 9-1-16
MECHANIC James
JOB NAME/LOCATION Smith Travel JOB NUMBER _____

PROBLEM: Bad battery

REPAIRED: replaced battery

Battery \$146.⁰⁰ Interstate

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>02017</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>259D</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>1,500 HRS</u>		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>6-26-17</u> MECHANIC <u>JAMES & Steven B</u>	
PROBLEM: <u>need serviced</u>		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
REPAIRED: <u>serviced</u>			
PARTS: <u>Filters</u> <u>172.⁰⁹</u> <u>Thompson</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>207</u>	HOURS _____ DAYS _____	BASIC MACHINE	HYDRAULIC
MAKE <u>Cat</u>	REASON	ENGINE	IMPLEMENTS
MODEL <u>259D</u>	PARTS	POWER TRAIN	ELECTRIC
SERIAL # _____	LABOR	DRIVE TRAIN	UNEXPLAINED
HOUR METER _____	OTHER _____	COMPONENT LOCATION	
MILES _____		FRONT	REAR
		LEFT	RIGHT
		UPPER	LOWER
		OTHER _____	
REASON FOR FAILURE: <input type="checkbox"/> BROKEN <input type="checkbox"/> WORN <input type="checkbox"/> ABUSE <input type="checkbox"/> LOOSE <input type="checkbox"/> SEIZED <input type="checkbox"/> OVERHEAT <input type="checkbox"/> PLANNED <input type="checkbox"/> CONTAM <input type="checkbox"/> LEAKING <input type="checkbox"/> NOISY <input type="checkbox"/> SCRATCH <input type="checkbox"/> SMOKES <input type="checkbox"/> SHORTED <input type="checkbox"/> VIBRATE <input type="checkbox"/> OTHER _____		DATE: _____ DATE COMPLETED <u>7-11-17</u>	
		MECHANIC <u>James</u>	
		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>Flip cutting edge</u>			
REPAIRED: <u>Flipped cutting edge</u>			
PARTS: <u>bolts & nuts 56^{1/4} Thompson</u>			

IEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
QUIP. # <u>0803</u>		HOURS _____	DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>259D</u>		PARTS _____	LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE: _____	DATE COMPLETED <u>7-15-25</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC <u>Bryan</u>	
SMOKES SHORTED VIBRATE OTHER _____	JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____

PROBLEM: Monitor malfunction

REPAIRED: replaced monitor

PARTS: Monitor 1268.24 Thompson

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
IP. # <u>0803</u>		HOURS _____	DAYS _____	BASIC MACHINE	HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>CAT</u>		REASON		POWER TRAIN	ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>259D</u>		PARTS	LABOR	COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT	REAR LEFT RIGHT UPPER LOWER
HOUR METER _____				OTHER _____	
NOTES _____					

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE: _____	DATE COMPLETED <u>7-9-25</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC <u>Bryan</u>	
SWITCHES SHORTED VIBRATE OTHER _____	JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____

PROBLEM: needs tracks

REPAIRED: replaced tracks

PARTS: 2-592-5827 Tracks 3598.⁹⁰ Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0803</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>259D</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		
REASON FOR FAILURE: <input type="checkbox"/> BROKEN <input type="checkbox"/> WORN <input type="checkbox"/> ABUSE <input type="checkbox"/> LOOSE <input type="checkbox"/> SEIZED <input type="checkbox"/> OVERHEAT <input type="checkbox"/> PLANNED <input type="checkbox"/> CONTAM <input type="checkbox"/> LEAKING <input type="checkbox"/> NOISY <input type="checkbox"/> SCRATCH <input type="checkbox"/> SMOKES <input type="checkbox"/> SHORTED <input type="checkbox"/> VIBRATE <input type="checkbox"/> OTHER _____		DATE <u>11-17-17</u> DATE COMPLETED <u>12-21-17</u> MECHANIC <u>Steven B.</u> JOB NAME/LOCATION <u>Wilson Bank</u> JOB NUMBER _____
PROBLEM: <u>brake lock switch broken</u>		
REPAIRED: <u>replaced switch</u>		
PARTS: <u>switch</u> <u>27.50</u> <u>Thompson</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0803</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>259D</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>1-22-18</u> MECHANIC <u>Steven B.</u>	
PROBLEM: <u>belt</u>		JOB NAME/LOCATION <u>Nissan Substation</u> JOB NUMBER _____	
REPAIRED: <u>replaced belt</u>			
PARTS: <u>belt</u> <u>17.50</u> <u>Thompson</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0803</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>259D</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>ZK HRS</u>		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>2-2-18</u>	MECHANIC <u>Charles</u>
PROBLEM: <u>Service</u>		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
REPAIRED: <u>serviced</u>			
PARTS: <u>All Filters</u> <u>213.06</u> <u>Thompson Machinery</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0803</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>259D</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>3-9-18</u>	MECHANIC <u>Charles</u>
JOB NAME/LOCATION <u>Shop</u>		JOB NUMBER _____	
PROBLEM: <u>blown hose</u>			
REPAIRED: <u>replaced blown hose</u>			
PARTS: <u>hose</u> <u>154.00</u> <u>NAPA</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0803</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>259D</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>4-20-18</u>	MECHANIC <u>James</u>
PROBLEM: <u>won't start</u>		JOB NAME/LOCATION <u>Wilson Bank</u>	JOB NUMBER _____
REPAIRED: <u>replaced bad battery</u>			
PARTS: <u>Grp 65</u> <u>141.99</u> <u>Crooks</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0803</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>259D</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>7-13-18</u>	
		MECHANIC <u>James</u>	
		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>right safety arm broken</u>			
REPAIRED: <u>replaced arm</u>			
PARTS: <u>Arm & Hardware</u> <u>140.⁰⁰</u> <u>Thompson</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>0803</u> MAKE <u>Cat</u> MODEL <u>259D</u> SERIAL # _____ HOUR METER <u>2,400 HRS</u> MILES _____		EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
REASON FOR FAILURE: <input type="checkbox"/> BROKEN <input type="checkbox"/> WORN <input type="checkbox"/> ABUSE <input type="checkbox"/> LOOSE <input type="checkbox"/> SEIZED <input type="checkbox"/> OVERHEAT <input type="checkbox"/> PLANNED <input type="checkbox"/> CONTAM <input type="checkbox"/> LEAKING <input type="checkbox"/> NOISY <input type="checkbox"/> SCRATCH <input type="checkbox"/> SMOKES <input type="checkbox"/> SHORTED <input type="checkbox"/> VIBRATE <input type="checkbox"/> OTHER _____		DATE: _____ DATE COMPLETED <u>P-6-18</u> MECHANIC <u>Charles</u>	JOB NAME/LOCATION <u>Southern Bank</u> JOB NUMBER _____
PROBLEM: <u>broken left track</u>			
REPAIRED: <u>replaced left track RT on stand by</u> <u>replaced RT Track next day</u>			
PARTS: <u>Rubber Tracks 2965.22 Thompson</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0803</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>259D</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>2500 HRS</u>		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>9-5-18</u> DATE COMPLETED <u>9-11-18</u> MECHANIC <u>Charles</u>	
PROBLEM: <u>Service</u>		JOB NAME/LOCATION <u>Legend's Dr</u>	JOB NUMBER
REPAIRED: <u>serviced</u>			
PARTS: <u>All Filters</u> <u>213.86</u> <u>Thompson</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>0803</u> MAKE <u>Cat</u> MODEL <u>259D</u> SERIAL # _____ HOUR METER _____ MILES _____		EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____		COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____				DATE: _____ DATE COMPLETED <u>9-20-18</u> MECHANIC <u>Charles</u>	
PROBLEM: <u>oil leak</u>				JOB NAME/LOCATION: <u>Legend Dr</u> JOB NUMBER _____	
REPAIRED: <u>replaced breaker fitting at travel motor</u>					
PARTS: <u>Fitting & seals</u> <u>29.41</u> <u>Thompson</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0803</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>259D</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE: _____ DATE COMPLETED <u>10-23-18</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC <u>Charles</u>
SMOKES SHORTED VIBRATE OTHER _____	JOB NAME/LOCATION <u>heads to shop</u> JOB NUMBER _____

PROBLEM: DPF Full capacity, needs cleaned

REPAIRED: Had DPF Filter cleaned, replaced bucket sensor, replaced intake throttle valve repaired wiring.

PARTS: <u>Clean DPF</u>	<u>\$299.⁰⁰</u>	<u>Cumberland International</u>
<u>Gaskets</u>	<u>88.⁷⁰</u>	<u>Thompson</u>
<u>Sensors</u>	<u>604.⁰⁰</u>	<u>Thompson</u>
<u>valve</u>	<u>466.⁰⁰</u>	<u>Thompson</u>
<u>sewer & Gaskets</u>	<u>335.⁰¹</u>	<u>Thompson</u>

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0803</u> MAKE <u>CAT</u> MODEL <u>259D</u> SERIAL # _____ HOUR METER _____ MILES _____	HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: _____ DATE COMPLETED <u>10-31-18</u> MECHANIC <u>Charles</u>	
JOB NAME/LOCATION <u>Cargill</u>		JOB NUMBER
PROBLEM: <u>cab mount missing</u>		
REPAIRED: <u>replaced cab mount</u>		
PARTS: <u>Mount & Hardware 14140 Thompson</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0803</u>		HOURS _____	DAYS _____	BASIC MACHINE	HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Cat</u>		REASON		POWER TRAIN	ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>259D</u>		PARTS _____	LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR	LEFT RIGHT UPPER LOWER
HOUR METER _____				OTHER _____	
MILES _____					
REASON FOR FAILURE: <input type="checkbox"/> BROKEN <input type="checkbox"/> WORN <input type="checkbox"/> ABUSE <input type="checkbox"/> LOOSE <input type="checkbox"/> SEIZED				DATE: _____ DATE COMPLETED <u>11-5-18</u>	
<input type="checkbox"/> OVERHEAT <input type="checkbox"/> PLANNED <input type="checkbox"/> CONTAM <input type="checkbox"/> LEAKING <input type="checkbox"/> NOISY <input type="checkbox"/> SCRATCH				MECHANIC <u>Charles</u>	
<input type="checkbox"/> SMOKES <input type="checkbox"/> SHORTED <input type="checkbox"/> VIBRATE <input type="checkbox"/> OTHER _____				JOB NAME/LOCATION <u>Cargill</u>	
PROBLEM: <u>blown hose</u>				JOB NUMBER _____	
REPAIRED: <u>replaced on travel motor hose</u>					
PARTS: <u>hose assembly 348 3E Thompson</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0803</u>	MAKE <u>CAT</u>	HOURS _____ DAYS _____	REASON _____	BASIC MACHINE	HYDRAULIC ENGINE IMPLEMENTS
MODEL <u>259D</u>	SERIAL # _____	PARTS _____ LABOR _____	OTHER _____	POWER TRAIN	ELECTRIC DRIVE TRAIN UNEXPLAINED
HOURLY METER _____	MILES _____			COMPONENT LOCATION	
				FRONT REAR LEFT RIGHT UPPER LOWER	
				OTHER: _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: _____	DATE COMPLETED <u>11-29-15</u>	
			MECHANIC <u>James (Charles)</u>		
			JOB NAME/LOCATION <u>Beckwith</u>	JOB NUMBER _____	
PROBLEM: <u>ran out of fuel, locked up fuel pump</u>					
REPAIRED: _____					
PARTS: <u>Pump</u> <u>197.75</u> <u>Thompson</u>					
<u>Filter</u> <u>24.04</u> <u>Thompson</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0803</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>259D</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: _____ DATE COMPLETED <u>2-1-19</u>		
	MECHANIC <u>Charles</u>		
PROBLEM: _____ _____ _____	JOB NAME/LOCATION <u>Maple Crossing</u>		
	JOB NUMBER		
REPAIRED: <u>replaced travel motor hose</u> _____ _____ _____ _____ _____ _____			
PARTS: <u>Hose</u> <u>271.93</u> <u>Thompson</u> _____ _____ _____ _____			

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>803</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>259D</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: <u>3-25-19</u> DATE COMPLETED <u>3-25-19</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Charles</u>	
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Pine wood</u>	
JOB NUMBER			
PROBLEM: <u>bad key switch</u>			
REPAIRED: <u>replaced key switch</u>			
PARTS: <u>key switch ? Thompson</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0803</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>259D</u>	PARTS LABOR	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>3K HRS</u>		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE <u>5-22-19</u> DATE COMPLETED <u>6-4-19</u>	
		MECHANIC <u>JAMES</u>	
JOB NAME/LOCATION		JOB NUMBER	
<u>Shop</u>			
PROBLEM: <u>needs service</u>			
REPAIRED: <u>serviced & washed</u>			
PARTS: <u>All Filters</u> <u>222.00</u> <u>Thompson Machinery</u> <u>Guard bolt & lock</u> <u>66.33</u> <u>Thompson Machinery</u> <u>seat bottom</u> <u>394.62</u> <u>Thompson Machinery</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0803</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>259D</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____	DATE COMPLETED <u>6-17-19</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Charles</u>	
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Cumberland</u>	JOB NUMBER
PROBLEM: <u>blown RT Travel motor hose</u>			
REPAIRED: <u>replaced hose and topped off hydraulic</u>			
PARTS: <u>hose</u> <u>312. ^{LL}</u> <u>Thompson</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0803</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>Z59D</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>6-28-19</u>	MECHANIC <u>Charles</u>
		JOB NAME/LOCATION <u>Carsill</u>	JOB NUMBER
PROBLEM: <u>blown Travel motor hose</u>			
REPAIRED: <u>replaced hose</u>			
PARTS: <u>hose assembly</u> <u>266.19</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0803</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Cat</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>259D</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE <u>2-4-2020</u> DATE COMPLETED <u>2-6-2020</u> MECHANIC <u>BEN & BRYAN</u>	
PROBLEM: <u>Service, check over</u>	JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
REPAIRED: <u>serviced, replaced fan belt, welded cross tubes</u>		
PARTS: <u>All Filters</u> <u>321.32</u> <u>Thompson Machinery</u> <u>belt</u> <u>6.25</u> <u>O'Reilly Auto Parts</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0803</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>Z59D</u>	PARTS LABOR	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>2-22-2020</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Charles</u>	
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION	JOB NUMBER
		<u>Cambridge behavior</u>	
PROBLEM: <u>blown hose</u>			
REPAIRED: <u>replaced hose at left boom cylinder</u>			
PARTS: <u>hose + cable ties 15-3.55 Incl. Rubber & Gasket</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>All Track Steers</u> MAKE _____ MODEL _____ SERIAL # _____ HOUR METER _____ MILES _____	HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>3-6-2020</u> MECHANIC <u>Ben</u> JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____	
PROBLEM: <u>new grapple</u>			
REPAIRED: <u>installed and check over.</u>			
PARTS: <u>4000 co Thompson</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>0803</u> MAKE <u>CAT</u> MODEL <u>259D</u> SERIAL # _____ HOUR METER <u>3548 HRS</u> MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: <u>4-1-2020</u> DATE COMPLETED <u>4-3-2020</u> MECHANIC <u>James</u>	JOB NAME/LOCATION: <u>Shop</u> JOB NUMBER _____
PROBLEM: <u>Alt. not charging</u>		
REPAIRED: <u>replaced Alternator</u>		
PARTS: <u>New Alternator 206.48</u> <u>Crook's Auto</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0803</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>259D</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>4-9-2020</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Charles</u>	
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Water Town Farm</u>	JOB NUMBER
PROBLEM: <u>blown hose at Final Drive</u>			
REPAIRED: <u>replaced hose</u>			
PARTS: <u>hose</u> <u>70.11</u> <u>Thompson</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0803</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>259D</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>8-6-20</u>	MECHANIC <u>Ben</u>
PROBLEM: <u>bad battery</u>		JOB NAME/LOCATION <u>Airport Logistics</u>	JOB NUMBER _____
REPAIRED: <u>replaced battery</u>			
PARTS: <u>MTP-65HD</u> <u>151.26</u> <u>Interstate battery</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>0803</u> MAKE <u>CAT</u> MODEL <u>259D</u> SERIAL # _____ HOUR METER <u>3385 HRS</u> MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: _____ DATE COMPLETED <u>7-20-20</u> MECHANIC <u>Ben</u> JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____	
PROBLEM: <u>coupler broken</u> <u>cutting edge needs replaced</u>		
REPAIRED: <u>replaced coupler plate. new cutting</u> <u>edge on bucket.</u>		
PARTS: <u>Coupler plate</u> <u>1,999.⁴³</u> <u>Thompson</u> <u>Edge and bolts</u> <u>297.²⁸</u> <u>Thompson</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0803</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>	REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>259D</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>4K HRS</u>		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>9-10-20</u> DATE COMPLETED <u>9-17-20</u>	MECHANIC <u>Bew</u>
		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>service, boom brace pin broken out of Arm</u>			
REPAIRED: <u>repaired both arms and assembled. serviced (Greased) washed</u>			
PARTS: <u>All Filters 161.⁰⁶</u> <u>Thompson</u> <u>link assembly 39.⁸⁸</u> <u>Thompson</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0803</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>259D</u>	PARTS LABOR	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>2-5-21</u>	
		MECHANIC <u>Ben</u>	
		JOB NAME/LOCATION	JOB NUMBER
		<u>View</u>	
PROBLEM: <u>blown hose</u>			
REPAIRED: <u>replaced hose going to grapple bucket</u>			
PARTS: <u>hose</u> <u>99.05</u> <u>IRYG</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0803</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>259D</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>3-9-21</u> DATE COMPLETED <u>3-16-21</u> MECHANIC <u>A11</u>	
		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>left armrest bolt rust out.</u> <u>seat bottom bad</u>			
REPAIRED: <u>replaced hardware + Arm rest</u> <u>replaced seat bottom</u>			
PARTS: <u>Armrest + Hardware 168.⁹⁵</u> <u>Thompson</u> <u>seat bottom in stock</u> <u>Thompson</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0803</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>259D</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # <u>Track steer</u>		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____				DATE: _____ DATE COMPLETED <u>6-5-21</u>	
				MECHANIC <u>All</u>	
				JOB NAME/LOCATION <u>shop</u>	JOB NUMBER
PROBLEM: <u>RT speed sensor damaged and harness worn out tracks</u>					
REPAIRED: <u>replaced speed sensor + harness replaced both tracks</u>					
PARTS: <u>sensor & wiring 335.12</u> <u>Thompson</u> <u>2-tracks</u> <u>in stock</u> <u>white House equipment</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0803</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS			
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED			
MODEL <u>259D</u>	PARTS _____ LABOR _____	COMPONENT LOCATION			
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER			
HOUR METER _____		OTHER _____			
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____		DATE COMPLETED <u>7-8-21</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Ben</u>			
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Eastgate</u>		JOB NUMBER _____	
PROBLEM: <u>Engine quit</u>					
REPAIRED: <u>replaced bad fuel pump & filter</u>					
PARTS: <u>Pump & Filter</u> <u>240.69</u> <u>Thompson</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0803</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>259D</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>7-22-21</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Mt. Juliet Sub Station</u>
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Ben</u>
PROBLEM: <u>blown hose</u>		
REPAIRED: <u>replaced travel hose</u>		
PARTS: <u>Hose</u>	<u>326.00</u>	<u>Thompson</u>

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0803</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>259D</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER <u>4500 HRS</u>		OTHER _____
MILES _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>9-29-21</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Ben</u>
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____
PROBLEM: <u>service</u>		
REPAIRED: <u>serviced</u>		
PARTS: <u>All Filters</u> <u>167.24</u> <u>Thompson</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0803</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MAKE <u>CAT</u>	REASON _____	COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER
MODEL <u>259D</u>	PARTS _____ LABOR _____	OTHER _____
SERIAL # _____	OTHER _____	
HOUR METER <u>4600 HRS</u>		
MILES _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE <u>10-26-21</u> DATE COMPLETED <u>10-28-21</u> MECHANIC <u>Ben + James</u>
JOB NAME/LOCATION <u>To Shop</u>		JOB NUMBER _____
PROBLEM: <u>RT link pin broken</u>		
REPAIRED: <u>replaced link assembly</u>		
PARTS: <u>link ass.</u>	<u>2258.50</u>	<u>Thompson</u>
<u>spacer</u>	<u>30.00</u>	<u>Thompson</u>

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0803</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>259D</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>1-27-21</u> DATE COMPLETED <u>1-31-22</u>
PROBLEM: <u>left rear idler leaking</u>		MECHANIC <u>James</u>
		JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____
REPAIRED: <u>replaced left idler</u>		
PARTS: <u>Idler</u> <u>1153.56</u> <u>Thompson</u>		
<u>536-3552</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP.# <u>0803</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>259D</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>5K HRS</u>		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: <u>9-7-21</u>	DATE COMPLETED <u>9-21-22</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>James & Anthony</u>	
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>Service</u>			
REPAIRED: <u>serviced & new tracks</u>			
PARTS: <u>filter</u> <u>220.38</u> <u>Thompson</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0803</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>Z59D</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>1-9-22</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION	JOB NUMBER
		<u>Caleb House</u>	
PROBLEM: <u>Electric fuel pump quit.</u>			
REPAIRED: <u>replaced pump and fuel filters</u>			
PARTS: <u>Pump + filter</u> <u>301.21</u> <u>Thompson</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0803</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>259D</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>1-13-22</u> DATE COMPLETED <u>1-13-23</u>	MECHANIC <u>Ben</u>
		JOB NAME/LOCATION <u>For stock</u>	JOB NUMBER
PROBLEM: <u>Arm bolts, spacers, rings and bearing. Keep coming apart</u>			
REPAIRED: _____ _____ _____ _____ _____ _____			
PARTS: <u>bearing & hardware</u> <u>455.⁴⁰</u> <u>Thompson</u> _____ _____ _____			

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0803</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>259D</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>5,500 HRS</u>		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE: <u>9-6-23</u> DATE COMPLETED <u>9-27-23</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC <u>Brian</u>		
SMOKES SHORTED VIBRATE OTHER _____	JOB NAME/LOCATION <u>To Shop</u>	JOB NUMBER	
PROBLEM: <u>Service</u>			
REPAIRED: <u>serviced</u>			
PARTS: <u>Filters</u>	<u>221.51</u>	<u>Thompson</u>	
<u>brackets, nut & bolts</u>	<u>244.79</u>	<u>Thompson</u>	

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0803</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>259D</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: <input type="checkbox"/> BROKEN <input type="checkbox"/> WORN <input type="checkbox"/> ABUSE <input type="checkbox"/> LOOSE <input type="checkbox"/> SEIZED		DATE <u>10-23-23</u> DATE COMPLETED <u>10-31-23</u>	
OVERHEAT <input type="checkbox"/> PLANNED <input type="checkbox"/> CONTAM <input type="checkbox"/> LEAKING <input type="checkbox"/> NOISY <input type="checkbox"/> SCRATCH		MECHANIC <u>Ben</u>	
SMOKES <input type="checkbox"/> SHORTED <input type="checkbox"/> VIBRATE <input type="checkbox"/> OTHER _____		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>boom cylinder bushings worn</u>			
REPAIRED: <u>replaced boom cylinder pins</u>			
PARTS: <u>2 bushings</u> <u>73.²²</u> <u>Thompson</u>			
<u>2 pins</u> <u>159.⁶⁴</u> <u>Thompson</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0803</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE <u>IMPLEMENTS</u>	POWER TRAIN <u>ELECTRIC</u> DRIVE TRAIN UNEXPLAINED
MAKE <u>CAT</u>	REASON	COMPONENT LOCATION	
MODEL <u>259 D</u>	<u>PARTS</u> LABOR	<u>FRONT</u> REAR LEFT <u>RIGHT</u> UPPER LOWER	
SERIAL # <u>L04814</u>	OTHER _____	OTHER _____	
HOUR METER _____			
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE: _____ DATE COMPLETED <u>11-8-23</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC <u>Ben</u>		
SMOKES SHORTED VIBRATE OTHER _____	JOB NAME/LOCATION _____ JOB NUMBER _____		
PROBLEM: <u>Sensor for boom lift & bucket level</u>			
REPAIRED: <u>New Harness</u>			
PARTS: <u>Harness \$399.05 Wrong Harness Returned</u>			
<u>New Harness #491-4814 \$451.22 problem fixed fixed</u>			
<u>machine is Ready to go.</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0803
MAKE CAT
MODEL 259D
SERIAL # _____
HOUR METER _____
MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
REASON _____
PARTS _____ LABOR _____
OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
COMPONENT LOCATION
FRONT REAR LEFT RIGHT UPPER LOWER
OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SMOKES SHORTED VIBRATE OTHER _____

DATE 10-2-24 DATE COMPLETED 10-3-24

MECHANIC Ben

JOB NAME/LOCATION

JOB NUMBER

Shop

PROBLEM: broken speed sensor

REPAIRED: replaced speed sensor

PARTS: Jenior 364.20 Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0F03</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Cat</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>259D</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE: _____ DATE COMPLETED <u>10-30-24</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC <u>A. Werry</u>
SMOKES SHORTED VIBRATE OTHER _____	JOB NAME/LOCATION <u>Shop</u>
	JOB NUMBER _____

PROBLEM: not charging

REPAIRED: replaced alternator
replaced angle sensor Bew

PARTS: <u>Alternator</u>	<u>272.97</u>	<u>ATB Truck</u>
<u>sensor</u>	<u>459.06</u>	<u>Thompson</u>

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>0F03</u> MAKE <u>CAT</u> MODEL <u>259D</u> SERIAL # _____ HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
---	---	--

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: <u>1-15-25</u> DATE COMPLETED <u>1-16-25</u> MECHANIC <u>Bill</u>	JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
---	--	----------------------------------	------------

PROBLEM: pin came out.

REPAIRED: installed RT arm brace pin, straightened sensor arm & bracket, New Redt plate

PARTS linkage bolts 109.66 Thompson