

EQUIPMENT  
REPAIRS

DATE 3-26-15

MILEAGE/HOURS 250 HRS

EQUIPMENT REPAIRED #308 CAT 303.5

REPAIRS MADE serviced

HOURS WORKED \_\_\_\_\_

PARTS USED Oil, Fuel & Hyd. Filters Thompson

EQUIPMENT  
REPAIRS

DATE 6-5-15

MILEAGE/HOURS 500 HRS

EQUIPMENT REPAIRED #308 CAT 303.5

REPAIRS MADE serviced

---

---

HOURS WORKED \_\_\_\_\_

PARTS USED

Filters

\$145.96

Thompson

EQUIPMENT  
REPAIRS

DATE 7-27-15

MILEAGE/HOURS 614 HRS

EQUIPMENT REPAIRED #308 CAT 303.5

REPAIRS MADE serviced

HOURS WORKED \_\_\_\_\_

PARTS USED

Filters                      152.<sup>26</sup>                      Thompson

EQUIPMENT  
REPAIRS

DATE 3-14-16

MILEAGE/HOURS 1K Hrs.

EQUIPMENT REPAIRED #308 303.5 Mini Exc.

REPAIRS MADE Serviced

HOURS WORKED \_\_\_\_\_

PARTS USED

All Filters Ex Fuel  
Fuel Filter

Thompson Machinery  
Tenn Filter

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

<p><b>EQUIPMENT INFORMATION</b></p> <p>EQUIP. # <u>308</u></p> <p>MAKE <u>CAT</u></p> <p>MODEL <u>303.5</u></p> <p>SERIAL # <u>Mini EX</u></p> <p>HOUR METER _____</p> <p>MILES _____</p>	<p><b>EQUIPMENT DOWNTIME</b></p> <p>HOURS _____ DAYS _____</p> <p>REASON _____</p> <p>PARTS _____ LABOR _____</p> <p>OTHER _____</p>	<p><b>COMPONENT CODES</b></p> <p>BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS</p> <p>POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED</p> <p><b>COMPONENT LOCATION</b></p> <p>FRONT REAR LEFT RIGHT UPPER LOWER</p> <p>OTHER _____</p>
---	--	---

<p>REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED</p> <p>OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH</p> <p>SMOKES SHORTED VIBRATE OTHER _____</p>	<p>DATE: _____ DATE COMPLETED <u>4-15-16</u></p> <p>MECHANIC <u>James</u></p>
<p>JOB NAME/LOCATION <u>Shops</u>      JOB NUMBER _____</p>	

PROBLEM: blown Hyd hose going to boom cylinder

---



---

REPAIRED: replaced hose

---



---



---



---



---

PARTS: hose      119.36      Napa

---



---

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>308</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MAKE <u>CAT</u>	REASON _____	COMPONENT LOCATION	
MODEL <u>303.5</u>	PARTS _____ LABOR _____	FRONT REAR LEFT RIGHT UPPER LOWER	
SERIAL # _____	OTHER _____	OTHER _____	
HOUR METER _____			
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>10-26-16</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Charles</u>	
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Smith Travel</u>	JOB NUMBER _____
PROBLEM: <u>muffler insulator bad</u>			
REPAIRED: <u>replaced insulator &amp; clamp</u>			
PARTS: <u>insulator</u>		<u>111.06</u>	<u>Thompson</u>

# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>308</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>303.5</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>1-25-17</u>	MECHANIC <u>Eric To Shop</u>
PROBLEM: <u>new 18" bucket</u>		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
REPAIRED:			
PARTS: <u>18" buck</u> <u>850.<sup>00</sup></u> <u>Thompson</u> <u>4 TAX</u>			

# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>308</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>CAT</u>	REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>303.5</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER <u>240 HRS</u>		OTHER _____
MILES _____		

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE: <u>3-27-17</u> DATE COMPLETED <u>4-3-17</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC <u>JAMES V STEEN B.</u>
SMOKES SHORTED VIBRATE OTHER _____	JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____

PROBLEM: Serviced

---

---

REPAIRED: Serviced and washed

---

---

---

---

---

---

PARTS: All Filters 157.97 Thompson

---

---

---

---

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>308</u> MAKE <u>CAT</u> MODEL <u>303.5</u> SERIAL # <u>Mini EX</u> HOUR METER _____ MILES _____	HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>6-2-17</u> MECHANIC <u>James</u>	
PROBLEM: <u>blown hose on stick</u>		JOB NAME/LOCATION <u>Pacific Dental</u>	JOB NUMBER
REPAIRED: <u>replaced hose</u>			
PARTS: <u>hose</u>		<u>59.49</u>	<u>NAPA</u>

# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

<b>EQUIPMENT INFORMATION</b> EQUIP. # <u>30A</u> MAKE <u>CAT</u> MODEL <u>303.5</u> SERIAL # _____ HOUR METER _____ MILES _____	<b>EQUIPMENT DOWNTIME</b> HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	<b>COMPONENT CODES</b> BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED <b>COMPONENT LOCATION</b> FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
---	---	--

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: _____ DATE COMPLETED <u>6-15-17</u> MECHANIC <u>JAMES + STEVEN B.</u>
	JOB NAME/LOCATION: <u>Shop</u> JOB NUMBER: _____

PROBLEM: bucket pins & bearings worn out

REPAIRED: replaced pins & bushings in stick on bucket end. replaced H-link pins & bushings

PARTS: <u>Shims</u>	<u>26.21</u>	<u>Thompson</u>
<u>pins &amp; bearings</u>	<u>671.53</u>	<u>Thompson</u>
<u>bearings</u>	<u>340.23</u>	<u>Thompson</u>

# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

<b>EQUIPMENT INFORMATION</b> EQUIP. # <u>0502</u> MAKE <u>CAT</u> MODEL <u>303.5E</u> SERIAL # _____ HOUR METER <u>3K HRS</u> MILES _____	<b>EQUIPMENT DOWNTIME</b> HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	<b>COMPONENT CODES</b> BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED <b>COMPONENT LOCATION</b> FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
---	---	--

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: _____ DATE COMPLETED <u>6-11-18</u> MECHANIC <u>All</u>
JOB NAME/LOCATION: <u>Shop</u>	
JOB NUMBER: _____	

PROBLEM: needs serviced

REPAIRED: serviced

PARTS: <u>Filters</u>	<u>84.79</u>	<u>Tenn Filter Sales</u>
<u>Hyd Filters</u>	<u>167.26</u>	<u>Thompson</u>

# TEC

## THORNE'S EXCAVATING COMPANY, LLC SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0502</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>303.5</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>8-23-18</u> MECHANIC <u>Tony</u> JOB NAME/LOCATION <u>Southern Bank</u> JOB NUMBER _____
PROBLEM: <u>Broken Hose</u>		
REPAIRED: <u>replaced hose</u>		
PARTS: <u>Hose Assembly</u> <u>86.25</u> <u>Nashville Rubbrs &amp; Gaskets</u>		

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

<b>EQUIPMENT INFORMATION</b> EQUIP. # <u>0502</u> MAKE <u>CAT</u> MODEL <u>303.5</u> SERIAL # _____ HOUR METER _____ MILES _____		<b>EQUIPMENT DOWNTIME</b> HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____		<b>COMPONENT CODES</b> BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____				DATE: <u>11-5-18</u> DATE COMPLETED <u>11-6-18</u> MECHANIC <u>Charles</u>	
				JOB NAME/LOCATION: <u>Shop</u> JOB NUMBER _____	
PROBLEM: <u>HR meter, service, muffler insulator</u>					
REPAIRED: <u>serviced, HR meter, insulator</u>					
PARTS: <u>Filters &amp; meter</u> <u>271.54</u> <u>Thompson</u>					
<u>Insulator</u> <u>165.18</u> <u>Thompson</u>					

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0502</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>303.5</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>3500 HRS</u>		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>6-5-19</u>	MECHANIC <u>JAMES</u>
PROBLEM: <u>Service</u>		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
REPAIRED: <u>serviced</u>			
PARTS: <u>Fitted 90, 93 Thompson Machinery</u>			

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0502</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>303.5</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>7-3-19</u>	MECHANIC <u>JAMES</u>
PROBLEM: <u>broken boot</u>		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
REPAIRED: <u>replaced boot</u>			
PARTS: <u>boot</u> <u>185.55</u> <u>Thompson</u>			

# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>CAT 411</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>MINI EXC</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>303.5</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: <u>9-13-19</u> DATE COMPLETED _____	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>All</u>	
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION	JOB NUMBER
		<u>Shop</u>	
PROBLEM: <u>2' Buckets</u>			
REPAIRED: _____			
PARTS: <u>675 EACH Plus Freight + Tax Thompson</u>			

# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0502</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>303.5</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # <u>Mini Ex.</u>	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>812 HRS</u>		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>11-12-19</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Bryan</u>	
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION _____ JOB NUMBER _____	
PROBLEM: <u>blade control worn out</u>			
REPAIRED: <u>replaced pilot blade control</u>			
PARTS: <u>pilot valve</u> <u>722.25</u> <u>Thompson</u> <u>438-8362</u>			

# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0502</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>303.5</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>782 WRS</u>		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>12-19-19</u>	
MECHANIC <u>Charles</u>		JOB NAME/LOCATION _____ JOB NUMBER _____	
PROBLEM: <u>won't start</u>		<u>Shop</u>	
REPAIRED: <u>replaced battery</u>			
PARTS: <u>battery</u> <u>106.40</u> <u>Interstate battery</u>			

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0502</u>	HOURS _____ DAYS _____	BASIC MACHINE	HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>CAT</u>	REASON _____	POWER TRAIN	ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>303.5</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT	REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: <u>1-8-2020</u>	DATE COMPLETED <u>1-14-2020</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>ALL</u>	
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION	JOB NUMBER
		<u>Shop</u>	
PROBLEM: <u>boom support, H-link need pins &amp; bushings</u>			
REPAIRED: <u>replaced boom support pins &amp; bushings replaced support to cab body pins &amp; bushings removed H-link, replaced bushings and replaced bushing in bucket cylinder rod.</u>			
PARTS <u>Pins bearings &amp; seals 2202.03</u>		<u>Thompson</u>	

# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0502</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>303.5</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>1K HRS</u>		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>3-10-2020</u>	MECHANIC <u>Bryan &amp; James</u>
		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>Service</u>			
REPAIRED: <u>serviced</u> <u>replaced muffler insulator</u>			
PARTS: <u>Filters + insulator 162.34</u> <u>Thompson</u>			

# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0502</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>303.5</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>1500 HRS</u>		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE <u>10-14-20</u> DATE COMPLETED <u>10-27-20</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Ben / Caleb</u>	
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>C.B.</u>	JOB NUMBER
PROBLEM: <u>Service</u>			
REPAIRED: <u>serviced</u>			
PARTS: <u>Filters</u> <u>170.65</u> <u>Thompson</u>			

# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0502</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MAKE <u>CAT</u>	REASON	COMPONENT LOCATION	
MODEL <u>303.5</u>	PARTS _____ LABOR _____	FRONT REAR LEFT RIGHT UPPER LOWER	
SERIAL # _____	OTHER _____	OTHER _____	
HOUR METER _____	_____	_____	
MILES _____	_____	_____	
_____	_____	_____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>11-30-20</u>	MECHANIC <u>All</u>
_____		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>bad stick bushings at bucket</u>			
_____			
REPAIRED: <u>replaced stick bushings &amp; seals &amp; pin.</u>			
_____			
_____			
_____			
_____			
_____			
PARTS: <u>pin bushings &amp; seals 341.<sup>04</sup> Thompson</u>			
_____			
_____			
_____			
_____			

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0502</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>303.5</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>24 HRS</u>		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>9-3-21</u> DATE COMPLETED _____ MECHANIC _____	JOB NAME/LOCATION <u>Eastgate</u> JOB NUMBER _____
PROBLEM: <u>Service</u>			
REPAIRED: <u>serviced</u>			
PARTS: <u>All Filters</u> <u>168.00</u> <u>Thompson</u>			

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0502</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>303.5</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER <u>2K HRS</u>		OTHER _____
MILES _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: _____ DATE COMPLETED <u>9-8-21</u>	
	MECHANIC <u>BEN</u>	
PROBLEM: <u>broken track &amp; top roller</u>	JOB NAME/LOCATION <u>EASTGATE</u>	JOB NUMBER
REPAIRED: <u>replaced top roller &amp; both tracks</u>		
PARTS: <u>Top roller &amp; freight 370<sup>cc</sup> Thompson</u> <u>new tracks in stock</u>		

# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0502</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>303.5</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: _____ DATE COMPLETED <u>11-16-21</u>	
	MECHANIC <u>James</u>	
	JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>left top roller bad</u>		
REPAIRED: <u>replaced roller</u>		
PARTS: <u>roller</u> <u>252.30</u> <u>Thompson</u>		

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

<b>EQUIPMENT INFORMATION</b>		<b>EQUIPMENT DOWNTIME</b>		<b>COMPONENT CODES</b>	
EQUIP. # <u>0511</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>303.5</u>		PARTS _____ LABOR _____		<b>COMPONENT LOCATION</b>	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>4500 HRS</u>				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____				DATE: <u>9-16-21</u> DATE COMPLETED <u>11-16-21</u>	
				MECHANIC <u>Ben</u>	
				JOB NAME/LOCATION _____	
				JOB NUMBER _____	
PROBLEM: <u>Service</u>					
REPAIRED: <u>serviced</u>					
PARTS: <u>All Filters</u> <u>155.4P</u> <u>Thompson</u>					
<u>Needs new oil pan plug - no other issues found.</u>					

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0502</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>303.5</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE <u>11-18-21</u> DATE COMPLETED <u>11-19-21</u>
		MECHANIC <u>Anthony</u>
		JOB NAME/LOCATION <u>GARY</u>
		JOB NUMBER
PROBLEM: <u>Muffler insulator fell apart</u>		
REPAIRED: <u>replaced insulator</u>		
PARTS: <u>Insulator</u> <u>120.3L</u> <u>Thompson</u>		

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

<b>EQUIPMENT INFORMATION</b> EQUIP. # <u>0502</u> MAKE <u>CAT</u> MODEL <u>303.5</u> SERIAL # _____ HOUR METER <u>5,500 HRS</u> MILES _____		<b>EQUIPMENT DOWNTIME</b> HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	<b>COMPONENT CODES</b> BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED <b>COMPONENT LOCATION</b> FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>3-2-22</u> MECHANIC <u>All</u>	JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____
PROBLEM: <u>Service, new HR meter</u>			
REPAIRED: <u>serviced, replaced HR meter + mutter insulator, changed final drive oil.</u>			
PARTS: <u>All Filters HR meter 299.15 Thompson</u>			

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

<b>EQUIPMENT INFORMATION</b>		<b>EQUIPMENT DOWNTIME</b>		<b>COMPONENT CODES</b>	
EQUIP. # <u>0502</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>303.5</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____				DATE: <u>7-28-22</u> DATE COMPLETED <u>7-29-22</u>	
PROBLEM: <u>needs starter</u>				MECHANIC <u>Anthony</u>	
				JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____	
REPAIRED: <u>had starter rebuilt</u>					
PARTS: <u>starter</u> <u>86.70</u> <u>Crooks'</u>					

# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>00702</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>303.5</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: <u>5-2-23</u> DATE COMPLETED _____
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>James</u>
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION
		JOB NUMBER
PROBLEM: <u>bad motor mounts</u>		
REPAIRED: <u>replaced motor mounts</u>		
PARTS: <u>mounts</u>	<u>266.<sup>38</sup></u>	<u>Thompson</u>
<u>breather</u>	<u>117.<sup>37</sup></u>	<u>Thompson</u>

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0502</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>303.5</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>800 HRS</u>	OTHER _____	OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: <u>8-29-23</u> DATE COMPLETED _____	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Ben, James &amp; Bryan</u>	
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>To Shop</u>	JOB NUMBER _____
PROBLEM: <u>won't run then no hydraulics ordered other two injectors</u>			
REPAIRED: <u>replaced no. 2 injector replaced other two injectors replaced pump drive coupling changed engine oil,</u>			
PARTS: <u>Injector 550.00 Thompson</u> <u>Fittes &amp; coupling 288.57 Thompson</u> <u>4 bolts 27.06 Thompson</u>			

# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0502</u>	HOURS _____ DAYS _____	BASIC MACHINE    HYDRAULIC    ENGINE    IMPLEMENTS	
MAKE <u>Cat</u>	REASON	POWER TRAIN    ELECTRIC    DRIVE TRAIN    UNEXPLAINED	
MODEL <u>303.5</u>	PARTS                  LABOR	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT    REAR    LEFT    RIGHT    UPPER    LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE:    BROKEN    WORN    ABUSE    LOOSE    SEIZED		DATE: _____    DATE COMPLETED <u>10-5-23</u>	
OVERHEAT    PLANNED    CONTAM    LEAKING    NOISY    SCRATCH		MECHANIC <u>James</u>	
SMOKES    SHORTED    VIBRATE    OTHER _____		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>Air in fuel Engine sputtering.</u>			
REPAIRED: <u>replaced fuel transfer pump</u>			
PARTS: <u>Pump</u> <u>134.<sup>20</sup></u> <u>Thompson</u>			

# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0502</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>303.5</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE: _____ DATE COMPLETED <u>11-14-23</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC <u>Ben &amp; Justin</u>	
SMOKES SHORTED VIBRATE OTHER _____	JOB NAME/LOCATION <u>Creeks Town Homes</u> JOB NUMBER _____	
PROBLEM: <u>Needs Tracks</u>		
REPAIRED: <u>replaced Tracks</u>		
PARTS: <u>Tracks (566-2975) 2647.00 Thompson</u>		

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0512</u> MAKE <u>313F CAT</u> MODEL <u>313F</u> SERIAL # <u>D10048</u> HOUR METER _____ MILES _____	HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC <input checked="" type="checkbox"/> ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>11-30-23</u> MECHANIC <u>Ben &amp; Anthony</u> JOB NAME/LOCATION _____ JOB NUMBER _____	
PROBLEM: <u>Water Separator <del>sensor</del> warning full</u> <u>Changed filter warning light still on.</u>			
REPAIRED: <u>replaced filter sensor</u>			
PARTS: <u>Separator element #311-3901-44.41</u> <u>sensor</u> <span style="float: right;"><u>Thompson</u></span>			

# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0502</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS			
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED			
MODEL <u>303.5</u>	PARTS _____ LABOR _____	COMPONENT LOCATION			
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER			
HOUR METER <u>1K HRS</u>		OTHER _____			
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: <u>1-10-24</u>	DATE COMPLETED <u>1-23-24</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Anthony</u>			
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION	JOB NUMBER		
		<u>Case Town Homes</u>			
PROBLEM: <u>Service</u>					
REPAIRED: <u>Service</u>					
PARTS: <u>filters</u> <u>21.30</u> <u>Thompson</u>					

# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0502</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>303.5</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE <u>5-15-24</u>	DATE COMPLETED <u>5-20-24</u>
		MECHANIC <u>All</u>	
		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>Oil leak &amp; seat</u>			
REPAIRED: <u>replaced seat</u> <u>removed pump removed main seal replaced</u> <u>seal. Assembled</u>			
PARTS: <u>seat</u> <u>1341.21</u> <u>Thompson</u> <u>hose &amp; clamps</u> <u>177.51</u> <u>Thompson</u> <u>seal</u> <u>37.65</u> <u>Thompson</u> <u>2 gaskets</u> <u>2338</u> <u>Thompson</u> <u>installer</u> <u>307.35</u> <u>Thompson</u>			



# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0502</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>303.5</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: <u>9-11-24</u>	DATE COMPLETED <u>9-13-24</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Anthony</u>	
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION	JOB NUMBER
PROBLEM: <u>Engine noise</u>		<u>Shop</u>	
REPAIRED: <u>replaced rear mounts.</u>			
PARTS: <u>4 mount rubbers 137.94 Thompson</u>			

# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0502</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Cat</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>303.5</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE: <u>11-19-24</u> DATE COMPLETED <u>11-25-24</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC <u>James + Roger</u>	
SMOKES SHORTED VIBRATE OTHER _____	JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>loose stick pin &amp; bushings</u>		
REPAIRED: <u>replaced pin &amp; bushings. Welded in</u>		
<u>bushings</u>		
PARTS: <u>pin &amp; 4 bushings</u> <u>445.04</u> <u>Thompson</u>		

IEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES			
QUIP. # <u>0502</u>		HOURS _____	DAYS _____	BASIC MACHINE	HYDRAULIC	ENGINE	IMPLEMENTS
MAKE <u>Cat</u>		REASON _____		POWER TRAIN	ELECTRIC	DRIVE TRAIN	UNEXPLAINED
MODEL <u>303.5</u>		PARTS _____	LABOR _____	COMPONENT LOCATION			
SERIAL # _____		OTHER _____		FRONT	REAR	LEFT	RIGHT
HOUR METER <u>2000 HRS</u>				UPPER	LOWER		
MILES _____				OTHER _____			

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE: <u>5-29-25</u>	DATE COMPLETED: <u>6-26-25</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____	JOB NAME/LOCATION: <u>Shop</u>	JOB NUMBER _____

PROBLEM: Service

---



---

REPAIRED: Service'd

---



---



---



---

PARTS: Filters in stock