

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

<b>EQUIPMENT INFORMATION</b> SERIAL # <u>304</u> MAKE <u>Volvo</u> MODEL <u>BL70B</u> SERIAL # _____ HOUR METER <u>1K HRS</u> MILES _____		<b>EQUIPMENT DOWNTIME</b> HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____		<b>COMPONENT CODES</b> BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED <b>COMPONENT LOCATION</b> FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____				DATE: _____ DATE COMPLETED _____ MECHANIC <u>JAMES + Steve</u>	
PROBLEM: <u>check over bought at auction</u>				JOB NAME/LOCATION <u>Shop</u> JOB NUMBER <u>6-23-16</u>	
REPAIRED: <u>Serviced, Touch up front packed bucket cylinders on hoe end replaced hood latch + straightened front support</u>					

Hardware	11.95	NAPA
Paint & Latch	114.14	Scott Equipment
All Filters	223.02	Scott Tenn Filter
Seal Kits	463.59	Scott Equipment

# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

<b>EQUIPMENT INFORMATION</b> EQUIP. # <u>304</u> MAKE <u>Volvo</u> MODEL <u>BL7013</u> SERIAL # _____ HOUR METER _____ MILES _____	<b>EQUIPMENT DOWNTIME</b> HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	<b>COMPONENT CODES</b> BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED <b>COMPONENT LOCATION</b> FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
--	---	--

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED  
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH  
SMOKES SHORTED VIBRATE OTHER \_\_\_\_\_

DATE: \_\_\_\_\_ DATE COMPLETED 7-19-16

MECHANIC Steve B

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: outtrigger cylinder leaking off fuel cap broken

REPAIRED: replaced fuel cap  
packed left outtrigger cylinder

PARTS: fuel cap & seal kit 290.<sup>12</sup> Scott Equipment





# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>304</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Volvo</u>	REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>BL70B</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>12-22-16</u> MECHANIC <u>Charles</u>	
PROBLEM: <u>master switch bad</u>		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
REPAIRED: <u>replaced master switch</u>			
PARTS: <u>master switches 154.32 Thompson</u>			

# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>#304</u>	HOURS _____ DAYS _____	BASIC MACHINE    HYDRAULIC    ENGINE    IMPLEMENTS	
MAKE <u>Volvo</u>	REASON	POWER TRAIN    ELECTRIC    DRIVE TRAIN    UNEXPLAINED	
MODEL <u>B170B</u>	PARTS                  LABOR	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT    REAR    LEFT    RIGHT    UPPER    LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE:    BROKEN    WORN    ABUSE    LOOSE    SEIZED		DATE: _____    DATE COMPLETED <u>2-16-17</u>	
OVERHEAT    PLANNED    CONTAM    LEAKING    NOISY    SCRATCH		MECHANIC <u>Pittman Eq.</u>	
SMOKES    SHORTED    VIBRATE    OTHER _____		JOB NAME/LOCATION <u>Pittman Eq.</u>	JOB NUMBER
PROBLEM: <u>new Hammer for back end.</u>			
REPAIRED: _____			
PARTS: <u>JB 452 Hammer 20,613.<sup>20</sup></u> <u>Pittman Equipment</u>			

# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>304</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Volvo</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>B170B</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE: _____ DATE COMPLETED <u>2-27-17</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC <u>JAMES &amp; STEVEN B</u>	
SMOKES SHORTED VIBRATE OTHER _____	JOB NAME/LOCATION <u>Lebanon School</u>	
PROBLEM: <u>blown hose</u>	JOB NUMBER _____	
REPAIRED: <u>replaced hose going to boom</u>		
PARTS: <u>Hose 154.00 Nashville Rubber Gasket</u>		

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>304</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Volvo</u>		REASON		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>BL70B</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: _____	DATE COMPLETED <u>3-9-17</u>
	MECHANIC <u>All</u>	
	JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____

PROBLEM: \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

REPAIRED: Flipped edge + new bolts

front forks

plate beam

packed front bucket tilt cylinders

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

<u>Cut Edge &amp; Bolts</u>	<u>526.59</u>	<u>White House Equipment</u>
<u>Forks</u>	<u>1,100.<sup>00</sup></u>	<u>White House Equipment</u>
<del>At \$22 Hammer</del>		<del>Pittman Equipment</del>

# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>304</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Volvo</u>	REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>BL70B</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>3-15-17</u> MECHANIC <u>James + Steven B</u>	
JOB NAME/LOCATION		JOB NUMBER	
<u>Cool Springs</u>			
PROBLEM: <u>Blows Hydraulic Hose</u>			
REPAIRED:			
PARTS: <u>Hose</u> <u>113.29</u> <u>Nashville Rubber Gasket</u>			

# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>304</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Volvo</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>BL70B</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>5-24-17</u>	MECHANIC <u>All</u>
		JOB NAME/LOCATION <u>CO-OP</u>	JOB NUMBER
PROBLEM: <u>needs rear tires</u>			
REPAIRED: <u>replaced rear tires</u>			
PARTS: <u>2-19.5-24 985 <del>45</del> Gateway Tire</u> <u>MAXAM 12PL</u> <u>Incl. RY TL</u>			

# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>304</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Volvo</u>	REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>BL70B</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: _____ DATE COMPLETED <u>6-29-17</u> MECHANIC <u>6-29-17 James J. Steen</u>	JOB NAME/LOCATION <u>Nissan Sub</u>
		JOB NUMBER
PROBLEM: <u>grease line broken off of hammer</u>		
REPAIRED: <u>grease lines to hammer</u>		
PARTS: <u>Hoses \$150.00 Nashville Rubber &amp; Gasket</u>		

# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>304</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Volvo</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>BL70B</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>4500 HRS</u>		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>3-17-18</u> MECHANIC <u>Charles</u>	
		JOB NAME/LOCATION <u>Shops</u>	JOB NUMBER
PROBLEM: <u>serviced</u>			
REPAIRED: <u>serviced, replaced pin lock on hammer</u>			
PARTS: <u>All Filters</u> <u>93.45</u> <u>TF5</u>			

# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0304</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Volvo</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>BL70B</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED _____ MECHANIC _____	
PROBLEM: <u>won't start</u>		JOB NAME/LOCATION	JOB NUMBER
REPAIRED: <u>replaced bad battery</u>			
PARTS: <u>Gap 31 MHD</u> <u>140.54</u> <u>IBJ</u>			

# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0304</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Volvo</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>BL70B</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER <u>1670. HRS</u>	MILES _____	OTHER _____
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>5-22-18</u> DATE COMPLETED <u>5-22-18</u>
		MECHANIC <u>James</u>
PROBLEM: <u>boom lock cylinder blown</u>		JOB NAME/LOCATION <u>Maple Crossing</u>
<u>Too much pressure</u>		JOB NUMBER _____
REPAIRED: <u>replaced cylinder</u>		
<u>servo pressure set to 510 psi</u>		
<u>replaced Trans. shift knob.</u>		
<u>replaced anti-lube micro.</u>		
<u>put boom lock cylinder back on.</u>		
PARTS: <u>cylinder</u>	<u>546.<sup>00</sup></u>	<u>Scott Equipment</u>
<u>Knob</u>	<u>126.<sup>60</sup></u>	<u>Scott Equipment</u>
<u>anti-lube</u>	<u>800.<sup>75</sup></u>	<u>Pittman Equipment</u>

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0304</u>		HOURS _____	DAYS _____	BASIC MACHINE	HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Volvo</u>		REASON		POWER TRAIN	ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>BL70B</u>		PARTS _____	LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR	LEFT RIGHT UPPER LOWER
HOUR METER _____				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____				DATE: _____	DATE COMPLETED _____
				MECHANIC _____	
				JOB NAME/LOCATION _____	JOB NUMBER _____
PROBLEM: <u>Stick cylinder fully retracted (stuck)</u>					
REPAIRED: <u>Trash in valve from cylinder, cylinder needs repaired</u> <u>replaced one bucket cylinder hose</u>					
PARTS: <u>Hose</u> <u>99.<sup>12</sup></u> <u>Crook's Auto</u>					
<u>Books</u> <u>519.<sup>27</sup></u> <u>Scott Equipment</u>					
<u>NT</u> <u>30.<sup>43</sup></u> <u>Scott Equipment</u>					

# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0304</u>	HOURS _____ DAYS _____	BASIC MACHINE	HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Volvo</u>	REASON	POWER TRAIN	ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>B470B</u>	PARTS LABOR	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR	LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____	DATE COMPLETED <u>9-26-18</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Charles</u>	
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION	JOB NUMBER
		<u>Beckwith</u>	
PROBLEM: <u>Seat adjuster broken</u>			
REPAIRED: <u>replaced seat adjuster</u>			
PARTS: <u>Adjuster kit</u>	<u>458.04</u>	<u>Scott Equipment</u>	

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

<b>EQUIPMENT INFORMATION</b> EQUIP. # <u>0304</u> MAKE <u>Volvo</u> MODEL <u>BL70B</u> SERIAL # _____ HOUR METER _____ MILES _____		<b>EQUIPMENT DOWNTIME</b> HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____		<b>COMPONENT CODES</b> BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____				DATE <u>12-17-18</u> DATE COMPLETED <u>1-11-19</u> MECHANIC <u>Charles</u>	
PROBLEM: <u>bucket cylinder leaking off</u>				JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____	
REPAIRED: <u>replaced cylinder packing</u>					
PARTS: <u>Seal Kit</u> <u>259.99</u> <u>Scott Equipment</u>					

# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0304</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Volvo</u>	REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>BL70B</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: _____ DATE COMPLETED <u>2-5-19</u> MECHANIC <u>Chanks</u>	
PROBLEM: <u>needs front tires</u>	JOB NAME/LOCATION <u>Providence Point</u> JOB NUMBER _____	
REPAIRED: <u>replaced front tires</u>		
PARTS <u>2-12.5/80-18</u> <u>472.73</u> <u>Gateway Tire</u> <u>D55017</u>		

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0304</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Volvo</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>BL70B</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>ZK HRS</u>		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>2-7-19</u> DATE COMPLETED <u>2-18-19</u> MECHANIC: <u>JAMES</u>	
PROBLEM: <u>Service</u>		JOB NAME/LOCATION <u>Slag</u>	JOB NUMBER
REPAIRED: <u>Service</u>			

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>304</u> MAKE <u>Volvo</u> MODEL <u>BL70B</u> SERIAL # _____ HOUR METER _____ MILES _____	HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: _____ DATE COMPLETED <u>2-27-19</u> MECHANIC <u>Charles</u>	
PROBLEM: <u>blown hose</u>	JOB NAME/LOCATION: <u>Towne Place</u> JOB NUMBER: _____	
REPAIRED: <u>replaced A bucket cylinder hose</u>		
PARTS: <u>hose</u> <u>90.84</u> <u>Nashville Rubber &amp; Gasket</u>		

# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0304</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Volvo</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>B670B</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>6-25-19</u>	MECHANIC <u>Charles</u>
		JOB NAME/LOCATION <u>Boone Place</u>	JOB NUMBER
PROBLEM: <u>blown hose</u>			
REPAIRED: <u>replaced outrigger hose.</u>			
PARTS: <u>Hose Assembly 62.717 IR+G</u>			

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0304</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Volvo</u>	REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>BL70B</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>7-15-19</u> DATE COMPLETED <u>7-15-19</u> MECHANIC <u>Charles</u> JOB NAME/LOCATION <u>Cargill</u> JOB NUMBER _____
PROBLEM: <u>blown hose on rear of machine</u>		
REPAIRED: _____ _____ _____ _____ _____ _____		
PARTS: <u>Hose</u> <u>119.64</u> <u>Nashville Rubber &amp; Gasket</u> _____ _____ _____		

# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0304</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Volvo</u>	REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>BL70B</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>7-18-19</u> MECHANIC <u>Charles</u>	
JOB NAME/LOCATION		JOB NUMBER	
<u>Cargill</u>			
PROBLEM: <u>broken pin</u>			
REPAIRED: <u>replaced broken pin at boom 1 stick cylinder connection</u>			
PARTS: <u>Pin</u> <u>419.57</u> <u>Scott Equipment</u>			

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0304</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Volvo</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>BL70B</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>2500 HRS</u>	OTHER _____	OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		DATE: <u>11-1-19</u>	DATE COMPLETED <u>11-28-19</u>
SMOKES SHORTED VIBRATE OTHER _____		MECHANIC <u>All</u>	
		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>Service</u>			
REPAIRED: <u>serviced</u> <u>repaired head latch</u> <u>broken park brake cable</u>			
PARTS: <u>All Filters</u> <u>177.46</u> <u>"Tenn Filter sales"</u> <u>Hyd Backordered Filter</u> <u>68.34</u> <u>brake cable</u> <u>294.56</u> <u>Scott Equipment</u>			

# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0304</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Volvo</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>BL70B</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE: _____ DATE COMPLETED <u>12-9-19</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC <u>Bryan</u>	
SMOKES SHORTED VIBRATE OTHER _____	JOB NAME/LOCATION <u>Family Behavior</u>	
PROBLEM: <u>blown hammer hose</u>	JOB NUMBER	
REPAIRED: <u>replaced hose</u>		
PARTS: <u>Hose Assembly</u> <u>138.00</u> <u>TRIG</u>		

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0304</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Volvo</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>BL70B</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____	_____	OTHER _____	
MILES _____	_____	_____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>4-27-2010</u>	MECHANIC <u>Ben</u>
_____		JOB NAME/LOCATION <u>Farm W Town</u>	JOB NUMBER _____
PROBLEM: <u>leaking hyd. quick connect</u>			
REPAIRED: <u>replaced bad connector</u> <u>bought extras</u>			
PARTS: <u>Male &amp; Female Couplers 854.20</u> <u>Incl. Rubber &amp; Gasket</u> <u>Fittings 53.42</u> <u>Incl. Rubber &amp; Gasket</u>			

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0304</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Volvo</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>BL70B</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE <u>5-14-20</u> DATE COMPLETED <u>5-15-20</u> MECHANIC <u>Charles</u>	
		JOB NAME/LOCATION <u>W. TOWN FARM</u>	JOB NUMBER
PROBLEM: <u>cut front tire</u>			
REPAIRED: <u>replaced with new tire</u>			
PARTS: <u>Deestone 12.5/80-18 299.<sup>72</sup> Gateway</u>			

# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0304</u> MAKE <u>Volvo</u> MODEL <u>BL70B</u> SERIAL # _____ HOUR METER _____ MILES _____	HOURS _____ DAYS _____  REASON  PARTS _____ LABOR _____  OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS  POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED  COMPONENT LOCATION  FRONT REAR LEFT RIGHT UPPER LOWER  OTHER _____ _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED  OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH  SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>8-11-20</u>  MECHANIC <u>Ben</u>	
PROBLEM: <u>blown hose at hammer</u>		JOB NAME/LOCATION <u>Jones Brummet</u>	JOB NUMBER
REPAIRED: <u>replaced hose</u>			
PARTS: <u>hose</u> <u>135.01</u> <u>Crook's</u>			

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0304</u> MAKE <u>Volvo</u> MODEL <u>BL70B</u> SERIAL # _____ HOUR METER _____ MILES _____	HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: _____ DATE COMPLETED <u>8-10-20</u> MECHANIC <u>Ben</u>		
JOB NAME/LOCATION		JOB NUMBER	
<u>Jewel Drummet</u>			
PROBLEM: <u>leaking hose at hammer, park brake sticking</u>			
REPAIRED: <u>replaced hose, lubed and adjuster park brake lever.</u>			
PARTS: <u>hose Assembly</u> <u>69.<sup>14</sup></u> <u>Cook's Auto Parts</u>			

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0304</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Volvo</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>BL70B</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>8-20-20</u> MECHANIC <u>Ben</u>
JOB NAME/LOCATION		JOB NUMBER
<u>James Brummett</u>		
PROBLEM: <u>hose blown going to hammer</u>		
REPAIRED: <u>replaced hose</u>		
PARTS: <u>hose</u> <u>69.14</u> <u>Crooks'</u>		

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0304</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Volvo</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>BL70B</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>9-16-20</u> MECHANIC <u>James</u>	
		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>park brake check switch broken</u>			
REPAIRED: <u>replaced park brake check switch</u>			
PARTS: <u>switch 100.57 Scott Equipment</u>			

# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP.# <u>0304</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Volvo</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>BL70B</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>11-11-20</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____			
JOB NAME/LOCATION <u>parta pk</u>		JOB NUMBER _____	
PROBLEM: <u>Rear Tire hole too big</u>			
REPAIRED: <u>replaced tire</u>			
PARTS: <u>1C.5/80-18</u> <u>248.24</u> <u>Gateway Tire</u>			

# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0304</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Volvo</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>BL70B</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>4-13-21</u> DATE COMPLETED <u>4-14-21</u>	MECHANIC <u>James</u>
PROBLEM: <u>bad hammer hoses</u>		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
REPAIRED: <u>replaced hoses with higher psi hoses + hose guard.</u>			
PARTS: <u>2-hoses</u> <u>924,45</u> <u>IR+G</u>			

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

<b>EQUIPMENT INFORMATION</b> EQUIP. # <u>0304</u> MAKE <u>Valvo</u> MODEL <u>BL70B</u> SERIAL # _____ HOUR METER _____ MILES _____	<b>EQUIPMENT DOWNTIME</b> HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	<b>COMPONENT CODES</b> BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: _____ DATE COMPLETED <u>6-10-21</u> MECHANIC <u>Bew</u>	JOB NAME/LOCATION <u>ME HARRIS</u> JOB NUMBER _____
PROBLEM: <u>blown hose</u>		
REPAIRED: <u>replaced hose &amp; picked up quick couplings</u>		
PARTS: <u>hose &amp; couplings 595.91 IR46</u>		

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0304</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Volvo</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>B670B</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>7-15-21</u> MECHANIC <u>Ben</u>
JOB NAME/LOCATION		JOB NUMBER
<u>Carver</u>		
PROBLEM: <u>blow hose to front bucket lift cylinder.</u>		
REPAIRED: <u>replaced hose</u>		
PARTS: <u>Hose</u> <u>99.19</u> <u>Cook Auto Parts</u>		

# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0401</u> MAKE <u>Atlas Copco</u> MODEL <u>452</u> SERIAL # _____ HOUR METER _____ MILES _____	HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE <u>10-21-21</u> DATE COMPLETED <u>1-19-22</u> MECHANIC <u>P. Homan</u>	
JOB NAME/LOCATION <u>Pittman</u>		JOB NUMBER
PROBLEM: <u>Hammer needs sealed, bushings and new bit.</u>		
REPAIRED: <u>sealed hammer 2-new bits</u>		
PARTS: <u>Hammer Kit &amp; bit 3577.95</u> <u>Seal Kit 320.61</u> <u>Hyd. &amp; Fuel Filters 195.67</u> <u>Tenn Filter sales</u>		

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0304</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Volvo</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>BL70B</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER <u>3K HRS</u>		OTHER _____
MILES _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>1-20-22</u> MECHANIC <u>James &amp; Caleb</u> JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____
PROBLEM: <u>Service</u>		
REPAIRED: <u>serviced</u>		
PARTS: <u>All Filters</u> <u>285.09</u> <u>Tenn Filter sales</u>		



# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0304</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Volvo</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>BL70B</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>3-15-22</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Bew</u>
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION
PROBLEM: <u>blow hose</u>		JOB NUMBER
REPAIRED: <u>replaced main pressure hose from pump to valve body</u>		
PARTS: <u>hose</u>	<u>161.87</u>	<u>Nashville rubber &amp; Gasket</u>

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0304</u> MAKE <u>Volvo</u> MODEL <u>BL70B</u> SERIAL # _____ HOUR METER _____ MILES _____	HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>11-1-22</u> DATE COMPLETED <u>11-7-22</u> MECHANIC <u>James + Brian</u>
JOB NAME/LOCATION: <u>Shop</u> JOB NUMBER _____		
PROBLEM: <u>hazel push button broken Damaged hose</u>		
REPAIRED: <u>replaced hazel latch + bucket tilt hose</u>		
PARTS: <u>Push button</u> <u>138.<sup>64</sup></u> <u>Scott Equipment</u>		
<u>Tumbler</u> <u>30.<sup>30</sup></u> <u>Scott Equipment</u>		
<u>hose</u> <u>104.<sup>98</sup></u> <u>Cook's</u>		

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

### EQUIPMENT INFORMATION

EQUIP. # 0304  
MAKE Volvo  
MODEL BL70B  
SERIAL # \_\_\_\_\_  
HOUR METER \_\_\_\_\_  
MILES \_\_\_\_\_

### EQUIPMENT DOWNTIME

HOURS \_\_\_\_\_ DAYS \_\_\_\_\_  
REASON \_\_\_\_\_  
PARTS \_\_\_\_\_ LABOR \_\_\_\_\_  
OTHER \_\_\_\_\_

### COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS  
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

### COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER  
OTHER \_\_\_\_\_

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED  
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH  
SMOKES SHORTED VIBRATE OTHER \_\_\_\_\_

DATE: \_\_\_\_\_ DATE COMPLETED 3-7-23

MECHANIC Ben

JOB NAME/LOCATION  
Job Station

JOB NUMBER

PROBLEM: won't start

REPAIRED: replaced alt. & battery system o.k.

PARTS: Alt. 415.<sup>00</sup> ATB Electric  
Battery 171.<sup>00</sup> Advance

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

<b>EQUIPMENT INFORMATION</b>		<b>EQUIPMENT DOWNTIME</b>		<b>COMPONENT CODES</b>	
EQUIP. # <u>0304</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Volvo</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>BL70B</u>		PARTS _____ LABOR _____		<b>COMPONENT LOCATION</b>	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____				DATE <u>6-6-23</u> DATE COMPLETED <u>6-8-23</u>	
				MECHANIC <u>James</u>	
PROBLEM: <u>broken left outrigger cylinder pin.</u>				JOB NAME/LOCATION <u>To shop</u>	
				JOB NUMBER _____	
REPAIRED: <u>replaced outrigger pin.</u>					
PARTS: <u>pin</u> <u>337.20</u> <u>Scott Equipment</u>					

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0304</u> MAKE <u>Volvo</u> MODEL <u>BL70B</u> SERIAL # _____ HOUR METER _____ MILES _____		HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____				DATE <u>8-10-23</u> DATE COMPLETED <u>9-11-23</u> MECHANIC <u>All</u>	
PROBLEM: <u>Service</u> <u>Two cylinders leaking, boom won't stay locked</u>				JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____	
REPAIRED: <u>serviced, packed RT outrigger cylinder &amp; stick cylinders</u>					

PARTS	<u>filters</u>	<u>\$317.02</u>	<u>Tenn Filte sales</u>
	<u>Seal kit</u>	<u>240<sup>00</sup></u>	<u>Scott Equipment</u>
	<u>Seal kit</u>	<u>299.07</u>	<u>Scott Equipment</u>
	<u>Nut</u>	<u>41.89</u>	<u>Scott Equipment</u>
	<u>base</u>	<u>140.80</u>	<u>Crook's Auto</u>
	<u>cylinder</u>	<u>130.75</u>	<u>Scott Equipment</u>

# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0304</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Volvo</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>BL70B</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>3700 HRS</u>		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>5-30-24</u> DATE COMPLETED <u>6-6-24</u> MECHANIC <u>Anthony</u>	
		JOB NAME/LOCATION <u>41st Ave</u>	JOB NUMBER
PROBLEM: <u>Service</u>			
REPAIRED: <u>Service</u>			
PARTS: <u>filters</u>		<u>324.96</u>	<u>Rear Filter</u>

# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES			
EQUIP. # <u>#0308</u>	HOURS _____ DAYS _____	BASIC MACHINE	HYDRAULIC	ENGINE	IMPLEMENTS		
MAKE <u>Volvo</u>	REASON _____	POWER TRAIN	ELECTRIC	DRIVE TRAIN	UNEXPLAINED		
MODEL <u>BL70B</u>	PARTS _____ LABOR _____	COMPONENT LOCATION					
SERIAL # _____	OTHER _____	FRONT	REAR	LEFT	RIGHT	UPPER	LOWER
HOUR METER _____		OTHER _____					
MILES _____							
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE <u>6-17-24</u>	DATE COMPLETED <u>6-24-24</u>				
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>All</u>					
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>shop</u>	JOB NUMBER _____				
PROBLEM: <u>starter not engaging</u>							
REPAIRED: <u>replaced starter, removed leaking hammer</u>							
PARTS: <u>starter</u>		<u>520.<sup>00</sup></u>	<u>Crooks</u>				
<u>Seals</u>		<u>400.<sup>00</sup></u>	<u>Pittman</u>				

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0304</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Volvo</u>	REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>B170B</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE: _____ DATE COMPLETED <u>4.29.25</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC <u>Ben</u>
SMOKES SHORTED VIBRATE OTHER _____	JOB NAME/LOCATION <u>Shop</u>
	JOB NUMBER _____

PROBLEM: Towers moving

REPAIRED: repaired rear control towers

PARTS: cabs, cylinder 921.96 Scott Equipment  
Jenior.

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES			
EQUIP. # <u>0304</u>	HOURS _____ DAYS _____	BASIC MACHINE	HYDRAULIC	ENGINE	IMPLEMENTS		
MAKE <u>Valve</u>	REASON _____	POWER TRAIN	ELECTRIC	DRIVE TRAIN	UNEXPLAINED		
MODEL <u>BL70B</u>	PARTS _____ LABOR _____	COMPONENT LOCATION					
SERIAL # _____	OTHER _____	FRONT	REAR	LEFT	RIGHT	UPPER	LOWER
HOUR METER _____		OTHER _____					
MILES _____							
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE <u>8-1-24</u>	DATE COMPLETED <u>8-23-24</u>				
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Ben</u>					
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Authem to shop</u>	JOB NUMBER _____				
PROBLEM: <u>dash broken hammer switch broken</u>							
REPAIRED: <u>replaced dash &amp; hammer switch</u> <u>replaced park brake pads &amp; switch</u>							
PARTS: <u>dash &amp; switch</u>		<u>352.41</u>	<u>Scott Equipment</u>				
<u>pads &amp; switch</u>		<u>768.88</u>	<u>Scott Equipment</u>				