

ANNUAL **INSPECTION REPORT**

Aspen Aerials, Inc. 4303 West 1st Street Duluth, Minnesota 55807-2759USA

Phone: 218-624-1111*Fax: 218-624-1714*Email address: service@aspenaerials.com

Prepared By	Andrew Skinner	Serial Number	10202 N	Nodel A-62	Customer un	it # CH-77336
Customer	Alabama Dept. of Tra	nsportation		Date	August 31, 2	2023
Contact	Tom Kirsopp		The state of the s	Phone	# (256) 571-7	214
Address	23445 Hwy 431 PO Box 550			Email Address	Krisoppt@dot.state./	Al.us
City	Guntersville		State/Province	Alabama	Zip Code	35976
Inservice Date	July 20, 2012		First I	Rebuild Complet	ed Date	
			☐ Secon	nd Rebuild Comp	pleted Date	and the second s
				Rebuild is d	ue on: Date	July 20, 2024
PTO HOURS	1,759		CHASSIS HOU	JRS 3,894	The control of the co	
AUX ENG. HOURS	213		CHASSIS MILE	46,501		

TEST AND REPORT LIMITATIONS

This report is provided to you with the understanding that ASPEN AERIALS, INC.'s responsibility is solely to conduct the inspection and assist you with the interpretation of the results. The decisions you make thereafter, concerning the equipment, are your responsibility. Aspen Aerials is not responsible for decisions you make or their consequences.

WARNING

This inspection determines the state of the equipment only at the time the inspection was performed! Any overloads, accidents or abuse of this equipment, after the test, could result in the inspection performed, no longer being valid. Structural damage may have occurred even though the equipment visually may appear intact and usable after said overloads accidents or abuse. Furthermore, materials experience a normal aging process whether abuse occurs or not. Therefore, the unit must be inspected before each use, to insure its structural integrity.

Description of codes used in this report	Defect Code
Immediate action is required - Take unit out of service	1 <u>C</u> RITICAL
Repair as soon as possible, it may become critical	2
Repair soon, next time the unit is in for maintenance	3
No repair needed. Area should be watched for further degradation	4
Review Notes prior to using unit	5
Item Inspected and no work is required	OK
Not Applicable	NA

WELDING NOTE

Aspen Aerials requires that all structural welding on this unit, be performed to AWS D1.1 steel and D1.2 aluminum standards. Contact the Service Department at Aspen Aerials for welding instructions, prior to any welding being performed.

MANUALS AND DECALS	
ANSI/SIA Manual of Responsibilities in the manual storage box	Defect Code OK
Operators & Service manual with truck	Notes: Keep a copy of the operators manual with the unit at all times.
Capacity decals in place, secure & legible, at all control stations	
X All safety & instructional decals installed, secure and legible.	Everything was compliant at time of inspection.
a instructional decais installed, secure and legible.	
TRUCK CAB AND UNIT POWER PANEL	
▼ Chassis instrument panel checked	Defect Code OK Notes:
✓ Unit power, switch panel checked and operational	Everything was compliant at time of inspection.
▼ Tag/Pusher Axle function ▼ Windshield ▼ Tag/Pusher Axle function ▼ Tag	
ELECTRICAL WIRES AND HYDRAULIC HOSES	
Wires Hoses	Defect Code #2 Notes:
▼ Secured , ties and clamps checked	Monitor the hoses and wires running through the booms and
Pivot points and access holes checked	turntables for proper slack, adjust as needed. Make sure all exposed hoses and wires are covered with hose wrap.
Checked for wear and rubbing	Turret 2 hoses and wires should be repositioned and wrapped
✓ Wrap and protective covering in place	in hose wrap to not allow damage.
∇ Din Connectors	Multiple hoses in boom 3 catrac are dry rotting and cracked.
ズ 12Volt	Recommend replacing.
⊠ 120Volt	
LIMIT SYSTEM	
▼ Test all switches for proper functioning	Defect Code #2
▼ Mounting	Boom 4 angle switch broken. Recommend replacing.
▼ T-2 plate, switch contact	Platform rotation switch adjusted at time of inspection.
🔀 Axle Lock Interlock	at time of inspection.
Type ids one sytem	
HYDRAULIC CYLINDERS	
∇ Check for leaks or damage	Defect Code #2
∇ Visually Inspect Welds	Notes:
	Keep all exposed cylinder rods lubricated when the truck is not in use.
▼ Holding Valves	Down 1 I'm I
▼ Pins	Boom 1 cylinder and turret 2 leveling cylinder have pitting. Recommend keeping cylinders lubricated at all times.
∇ Check for Rust/Corrosion	and times.
▼ Check that updates are installed	
Serial Number 10202	
7	Page 2 of 7

INTERCOM SYSTEM		
Test 🛛 Cab station		Defect Code OK Notes:
▼ T1 station	X Check headset at each station	Intercoms working at time of inspection.
Number of head		
Number of fleat	dset stations three	
∇ Wires		
▼ Fasteners		
CONTROL SYSTEM		
	n controls return to neutral when released	Defect Code #2
∇ Check condition of con-	trol enclosures and protective boots	DP600 has dark spots in the screen. Recommend replacing
▼ Check control enable s	ystem	before unreadable.
Foot Switch, if equippe	Fact Slow function	
∇ Cable Connections	Control Adjustment function	
Control Set Installation	▼ Platform Controller	
2 To See Histaliación		
Is unit equipped with a Plus	s-One system? Yes	
	,	
Was a program revision inst	talled during this inspection? No	Type of Controls NBB HyPro 8 with Cable
Program Rev. REV 219	Ground Cont	rol # 9600102773 Platform Control # 9600102838
CHASSIS, SUBFRAME, PEDES	TAL DECK BODY	
▼ Visually Inspect Welds		Defect Code #3
	∇ Engine Area ✓	Notes: Monitor air pressure in tires at all times.
▼ Frame Clips		
Mounting Bolts	□ Lights □ Lights	Rear ladder bent and won't come down. Recommend repairing/replacing.
■ Body boxes	☐ Tag/Pusher Axle Components	
VY body boxes	Check subframe condition	2/4 tag axle tires chewed up. Recommend replacing if they worsen.
▼ Tires		7000000
/ Tiles		Mud flaps on tag axle missing both sides. Recommend
		replacing.
AUXILIARY ENGINE, COMPRE	SSOR, GENERATOR	
■ Battery connections check	ked	Defect Code #3 Notes:
	▼ Engine Oil	Auxiliary engine motor oil a little dark. Recommend changing,
▼ GFI Outlets		
X AC Electrical System		
parties and the second		Air Filter Part #650971/652089
Generator output 120 V	AC @ 60Hz	Oil Filter Part #651965
Air compressor loads		
7.11 compressor loads		Fuel Filter Part #651967
Serial Number 10202		

Page 3 of 7

HYDRAULIC SYSTEM	
▼ Hydraulic fluid level	Defect Code #4
▼ Tank condition, gauges, filters, cap	Notes: Aspen Aerials recommends that all filters get replaced annually
∇ Check hydraulic pressures and ensure proper adjustness.	
	Deve and the second sec
X Port reliefs	tank. Recommend cleaning and monitoring to see where leak is
▼ Perform holding valve test	coming from.
Emergency Override System	Hydraulic oil reservoir low on hydraulic fluid. Recommend
	topping off.
Mounting of Components	
□ Dump Valve Blocks	
	Potential Potential
	Return Filter Part #095664
	Pressure Filter Part #096703
	Leveling Filter Part #096703
AXLE LOCK AND COUNTERWEIGHT SYSTEMS	
Front Rear	Defect Code OK Notes:
Locks Locks	Front axle lock spring bolts tightened to specification.
Operation, in/out, contact with switches	One bolt on driver side mounting plate loose. Tightened to specification at time of inspection.
✓ Wires and hoses routing checked	
Check clearances	Driver side rear axle lock side plate bolts loose. Taken out and refastened with red loctite at time of inspection.
	Rear axle locks disassembled, inspected, greased, assembled and adjusted at time of inspection.
	an non-net a time of inspection.
▼ Torque Mounting Bolts	
▼ Torque Spring Bolts	_
Rear Sliding counterweight installed? Yes	□ Diverter valve and springs checked
TURNTABLES #1 AND #2	Drive System Operation, in/out, contact with switches
N T	
∇ v:	T2 Defect Code #3 Notes:
57 0	runt table gears very dry. Recommend using open gear lube to
V C D M	T2 lubricate.
N C D 0	
2 11	IX T2
r Ecvening Anns, it equ	
r zevenig/anrin, ne	
	if equipped
V Guarus	
Are brakes installed? No Brake torque value T-1 N/A	ft/lbs
Brake torque value T-2 N/A	
Serial Number 10202	10/100
Property of the second	Page 4 of 7

BOOMS		
▼ Visually inspect welds		Defect Code #3
▼ Visually inspect all cylinder connections		Notes: Boom 3 stow pad broken. Recommend repairing/ replacing.
	81 ft/lbs	Platform half moon rest pad damaged. Recommend replacing.
Pins Are pin keepers installed?	Voc	_
X Bushings	120 ft/lbs	
▼ Lubrication	▼ Wearpads	
▼ Guards	trap 🛛 Boom Rest	
	d Measurements (A-52)	
N/A		
PLATFORM or WALKWAY		
∇ Check mounting installation	✓ Platform Rests	Defect Code OK
∇ Visually inspect welds and construction		Notes: Everything was compliant at time of inspection.
Access door latches working properly		ereally during was compliant at time of inspection.
Check for loose and missing parts		
Safety lanyard connections	▼ Tie off Connection	
y Country larry and confrections	Ladder (if installed)	
▼ Heater operation ▼ 12V I ▼ 12	ight receptacles	X 120v/220v Electrical Outlets
TILT ALARM / ENGINE KILL SYSTEMS		
Test engine kill system ズ T1 ズ Plat	form 🛛 Cab	Defect Code OK
Other Locations Rear of subframe on both s	ides.	Notes: Engine kill stops all operational at time of inspection.
▼Test stepping relays		St. 11 Management
a createspring relays		Tilt alarm operational at time of inspection.
▼Test tilt alarm horn operation		
Check mounting installation		
y cereek mounting installation		
OTHER	ı	
O MILL		Defect Code OK
Unauthorized Modifications or Additions	No	Notes: Everything was compliant at time of inspection.
R Paint and overall appearance		everything was compliant at time of inspection.
X Applicable safety bulletins completed X Greasing and lubricating		
X Decals	_	
Is hy-rail gear installed on this unit?	No Hy-rail or	
	I Hy-rail vi	sual inspection
Any changes in personnel or ownership? Cu	stomer Comments? Other n	otes.
Serial Number 10202		

Page 5 of 7