

EQUIPMENT
REPAIRS

DATE 7-11-03

MILEAGE/HOURS 1870

EQUIPMENT REPAIRED CP 563 # 110

REPAIRS MADE Complete service changed oil & filter, hyda oil & filter, changed differential oil. check weight shaft bearing oil and drum support bearing housing oil. changed air filters

HOURS WORKED _____

PARTS USED

Fuel filter
Fuel filter
oil filter
inner air filter
outer air filter } # - \$ 82.46
Hydro filter

adaptor
reducer } - \$ 14.55
3/4 nipple

2 new tires # 1147.13
23.1-26

Bestone Tires

EQUIPME
REPAIR:

2 ea @ 525⁰⁰ ea

TOTAL
W/TAX

1147.13

DATE 8-5-03

MILEAGE/HOURS 1890

EQUIPMENT REPAIRED #110 CP-563

REPAIRS MADE Rebuild rear end new bolts
in ring gear on axle new wheel ends
and rings One new bearing and cup.
Install Tires & Fluid

HOURS WORKED _____

PARTS USED

cone bearing \$14.94 ~~\$25.97~~

cup - \$8.72

2 retainers - \$34.52 each

2 seal rings \$4.91 each

2 seal - 9R6223 - \$9.83 each

2 locks \$11.84 each

8 Bolt - 3.23 each

\$162.48

Rear Tires - \$1148.00

Genet of oil - \$102.00

Wood Stud - Ball & nut - \$7.03

4 shocks for doors - \$271.58

EQUIPMENT
REPAIRS

DATE 8-20-03

MILEAGE/HOURS _____

EQUIPMENT REPAIRED CP 563 #110

REPAIRS MADE Replace two Rubber Mounts
on drive drums.

HOURS WORKED _____

PARTS USED

Mounts - \$ 155.38

EQUIPMENT
REPAIRS

DATE 3-24-04

MILEAGE/HOURS _____

EQUIPMENT REPAIRED #110

REPAIRS MADE install new battery and
one new rubber on drum.

HOURS WORKED _____

PARTS USED

battery # 51.29

EQUIPMENT
REPAIRS

DATE 4-6-04

MILEAGE/HOURS 2051

EQUIPMENT REPAIRED # 110 563

REPAIRS MADE replace two hydro hoses
on blade.

HOURS WORKED _____

PARTS USED

2- hoses \$197.18

EQUIPMENT
REPAIRS

DATE 10-7-04

MILEAGE/HOURS 2168

EQUIPMENT REPAIRED #110 CR 563

REPAIRS MADE Replace Exh. tube and
Exh. Man. Baskets,

HOURS WORKED _____

PARTS USED

Baskets
Exh. tube) \$294.72

EQUIPMENT
REPAIRS

DATE 10-7-04

MILEAGE/HOURS 2168

EQUIPMENT REPAIRED #110 CP-563

REPAIRS MADE install four bolts in front.
replace Exh. pipe, muffler, Exh. manifold
Gaskets and hydro elec. valves.

HOURS WORKED _____

PARTS USED

C Bolts \$ 20.28
C valve \$ 493.77
(Gasket
Exh. pipe) \$ 75.43

5 studs
gaskets
Clamp
bolts
locks
locknuts
Muffler
Gasket
pipe

\$ 307.48

Total \$ 896.96

EQUIPMENT
REPAIRS

DATE 5-3-05

MILEAGE/HOURS _____

EQUIPMENT REPAIRED # 110

REPAIRS MADE pin and washer in
central cables

HOURS WORKED _____

PARTS USED

*pin
washer*) \$ 5.97

EQUIPMENT
REPAIRS

DATE 6-20-05

MILEAGE/HOURS 2300

EQUIPMENT REPAIRED 110 563

REPAIRS MADE install new shaft, bearings
retainer and seals
change engine oil & filter, fuel
filter

HOURS WORKED _____

PARTS USED

shaft \$ 623.41

Bearing & seal \$ 74.22
\$ 17.19

EQUIPMENT
REPAIRS

DATE 10-28-05

MILEAGE/HOURS _____

EQUIPMENT REPAIRED #710 CP563

REPAIRS MADE replace fan & water pump
belt

HOURS WORKED _____

PARTS USED

belt @ 51.06

EQUIPMENT
REPAIRS

DATE 1-17-06

MILEAGE/HOURS _____

EQUIPMENT REPAIRED #110 CP 563

REPAIRS MADE service seals in front pump
smash plate, springs, bearing kit, seal kit
in rear pump for drum drive.

HOURS WORKED \$ 986.10 total

PARTS USED

CAT	\$40.36
seals	\$50.53
orings	\$15.48
piston	\$14.42
Rings	\$2.04
	\$66.48
	\$10.08
Caps	
Plus	\$9.85
<hr/>	
total	209.24

Nashville hydro.	
1 bearing kit	\$ 111.97
1 smash plate	\$ 389.52
2 springs	\$ 10.60
1 seal kit	\$ 165.00
air fits	\$ 34.00
<hr/>	
total	776.86

EQUIPMENT
REPAIRS

DATE 3-30-06

MILEAGE/HOURS _____

EQUIPMENT REPAIRED #110 CP563

REPAIRS MADE Right axle seal leaking

HOURS WORKED _____

PARTS USED

seal
retainer) \$ 60.34
orings

lock \$ 14.20

EQUIPMENT REPAIRS

DATE 1-16-07

MILEAGE HOURS 2500

EQUIPMENT REPAIRED 110

REPAIRS MADE complete service

oil, fuel, hydra, Blow air

HOURS WORKED _____

PARTS USED _____

EQUIPMENT
REPAIRS

DATE 7-25-07

MILEAGE/HOURS 2660

EQUIPMENT REPAIRED #110 CP563

REPAIRS MADE hydro hose to front
Drum from tank

HOURS WORKED _____

PARTS USED

Naps.

hose \$ 63.71

6-Tip

+
Locks \$197.95

EQUIPMENT
REPAIRS

DATE 8-9-07

MILEAGE/HOURS _____

EQUIPMENT REPAIRED #110 CP-563

REPAIRS MADE Hydro hose

HOURS WORKED _____

PARTS USED

Napa
Hose \$ 70.07

EQUIPMENT
REPAIRS

DATE 8-16-07

MILEAGE/HOURS _____

EQUIPMENT REPAIRED #110 CP563

REPAIRS MADE Hydro hose

HOURS WORKED _____

PARTS USED

H.11 top

hose @ 91.02

Fitting @ 15.10

7. Pins

6. Tips 205.60 Cot

EQUIPMENT
REPAIRS

DATE 8-22-07

MILEAGE/HOURS _____

EQUIPMENT REPAIRED #110 CP563

REPAIRS MADE replaced broken hyd. filter
service indicator

HOURS WORKED _____

PARTS USED

Indicator kit \$75.55 Thompson

EQUIPMENT
REPAIRS

DATE 8-27-07

MILEAGE/HOURS _____

EQUIPMENT REPAIRED CP563 #110

REPAIRS MADE _____

Replaced scraper tips

HOURS WORKED _____

PARTS USED

8 Tips & 7 pin \$205.60 Thompson

EQUIPMENT
REPAIRS

DATE 8-6-08

MILEAGE/HOURS _____

EQUIPMENT REPAIRED #110 CP-563

REPAIRS MADE vibratory seal and mount
O-rings for motor


HOURS WORKED _____

PARTS USED

seal
O-ring

\$18.48
#3.ES

Thompson Machiners



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963


EQUIPMENT INFORMATION EQUIP. # <u>110</u> MAKE <u>CAT</u> MODEL <u>CP563</u> SERIAL # _____ HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
---	--	--

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: _____ DATE COMPLETED <u>3-23-09</u> MECHANIC <u>JAMES</u> JOB NAME/LOCATION <u>MT. Juliet</u> JOB NUMBER _____
---	--

PROBLEM: Engine sputtering.

REPAIRED: replaced main fuel filter. cleaned out sfp. bowl.


PARTS: _____



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>110</u> MAKE <u>CAT</u> MODEL <u>563</u> SERIAL # _____ HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: _____ DATE COMPLETED _____ MECHANIC <u>JAMES</u> JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____	
PROBLEM: <u>drum vibrator locked up.</u>		
REPAIRED: <u>remove drum</u>		
<u>Counter shaft 548.¹⁷⁵ Thompson</u>		
PARTS: <u>HAMMER</u>		
seals <u>seals</u> \$199. ²² / \$4.49 Thompson		
<u>Bearings</u> \$1501. ¹⁶ Motions Industrial		
<u>Rubber Mounts</u> 301. ⁰⁶ Thompson		
<u>shaft</u> 939. ⁰¹ Thompson		

Bearings 56.⁸⁰ ~~Thompson~~ O'Keilly Auto Parts



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>110</u> MAKE <u>Cat</u> MODEL <u>CP563</u> SERIAL # _____ HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
---	--	--

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: _____ DATE COMPLETED <u>4-24-09</u> MECHANIC <u>JAMES</u> JOB NAME/LOCATION <u>MT Juliet</u> JOB NUMBER _____
---	---

PROBLEM: Hammer motor case leaking
5-28-09 still leaking.

REPAIRED: covered case with epoxy
7-2-09 covered case with JB weld

PARTS: Epoxy 6.00 NAPA

EQUIPMENT
REPAIRS

DATE 11-25-09

MILEAGE/HOURS 3000 HRS


EQUIPMENT REPAIRED #110 CP563 Cat

REPAIRS MADE serviced

HOURS WORKED _____

PARTS USED

Filters	83. ⁰⁰	Term Filter
Hyd filter	54. ⁰⁰	Thompson




THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>110</u> MAKE <u>CAT</u> MODEL <u>CP563</u> SERIAL # _____ HOUR METER _____ MILES _____	HOURS _____ DAYS _____ REASON PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED _____ MECHANIC <u>JAMES</u> JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____	
PROBLEM: <u>steering cylinders leaking</u> <u>blade control leaking</u>			
REPAIRED: <u>replaced seals in both steer cylinders</u> <u>replaced seals in blade control valve</u>			
PARTS: <u>seal kits</u> <u>53.45</u> <u>4 O-rings</u> <u>66.64</u> <u>Thompson</u> <u>2-seals</u> <u>32.62</u> <u>12.19</u> <u>Signal Industrial Supply</u>			



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>110</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>	REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>CP563</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>5-26-12</u>	
		MECHANIC <u>James</u>	
		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>won't start old batteries</u>			
REPAIRED: <u>replaced both batteries</u>			
PARTS: <u>2 - Gup 27 batteries 207.55 Advance Auto Parts</u>			



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>110</u> MAKE <u>CAT</u> MODEL <u>CP563</u> SERIAL # _____ HOUR METER <u>3208</u> MILES _____	HOURS _____ DAYS _____ REASON PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
REASON FOR FAILURE: <u>BROKEN</u> <u>WORN</u> ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM <u>LEAKING</u> NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>11-8-12</u> MECHANIC <u>JAMES</u> JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____
PROBLEM: <u>Two mounts on RT side of digger broken. Vibrator motor leaks, check over.</u>		
REPAIRED: <u>replaced broken mount, Vibrator motor cracked covered crack with JB weld, replaced blown hydraulic hose</u>		
PARTS: <u>2-Mounts 55.⁰⁰ EA</u> <u>White House Equipment</u> <u>seal 28.²¹</u> <u>Thompson Machinery</u> <u>Hyd. Hose 127.²³</u> <u>NAPA</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>110</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>CP563</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>10-7-13</u>	
		MECHANIC <u>Cris</u>	
PROBLEM: <u>Throttle cable rusted out</u>		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
REPAIRED: <u>replaced cable</u>			
PARTS: <u>cable assembly 169.⁸⁷ Thompson</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>110</u> MAKE <u>Cat</u> MODEL <u>CP563</u> SERIAL # _____ HOUR METER <u>3500 HRS</u> MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: _____ DATE COMPLETED <u>6-5-15</u> MECHANIC <u>James + Steven</u>	JOB NAME/LOCATION <u>Reid Hill</u> JOB NUMBER _____
PROBLEM: <u>needs seat cushions service</u>		
REPAIRED: <u>replaced seat cushions and serviced</u>		
PARTS: <u>seat cushions</u> <u>324.²⁵</u> <u>Thompson</u> <u>All Filters</u> <u>167.²⁵</u> <u>Terex Filter saks</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>110</u> MAKE <u>CAT</u> MODEL <u>CP-563</u> SERIAL # _____ HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
--	---	--

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SMOKES SHORTED VIBRATE OTHER _____

DATE 10-9-15 DATE COMPLETED _____

MECHANIC James

JOB NAME/LOCATION Smith Travel JOB NUMBER _____

PROBLEM: muffler rusted out

REPAIRED: replaced muffler

PARTS: muffler stack & clamps 47.51 Thompson
+275.23
322.77
switch 90.00 Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>110</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>CP563</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 5-19-16
MECHANIC James & Steven
JOB NAME/LOCATION Shop JOB NUMBER _____

PROBLEM: Fix leaks

REPAIRED: replaced shaft seal in hyd pump, replaced belts, replaced vibrator motor, repair exhaust, replaced one battery.

PARTS: <u>seals, clamps & belts</u>	<u>308.44</u>	<u>Thompson</u>
<u>seal</u>	<u>28.25</u>	<u>Thompson</u>
<u>belt set</u>	<u>64.24</u>	<u>Thompson</u>
<u>seals</u>	<u>25.73</u>	<u>Thompson</u>
<u>motor</u>	<u>2386.44</u>	<u>Thompson</u>
<u>seal kit</u>	<u>135.40</u>	<u>Thompson</u>
<u>Tube</u>	<u>403.46</u>	<u>Thompson</u>
<u>batteries</u>	<u>106.00</u>	<u>Advance Auto Parts</u>

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

<p>EQUIPMENT INFORMATION</p> <p>EQUIP. # <u>110</u></p> <p>MAKE <u>CAT</u></p> <p>MODEL <u>CP563</u></p> <p>SERIAL # _____</p> <p>HOUR METER _____</p> <p>MILES _____</p>	<p>EQUIPMENT DOWNTIME</p> <p>HOURS _____ DAYS _____</p> <p>REASON _____</p> <p>PARTS _____ LABOR _____</p> <p>OTHER _____</p>	<p>COMPONENT CODES</p> <p>BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS</p> <p>POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED</p> <p>COMPONENT LOCATION</p> <p>FRONT REAR LEFT RIGHT UPPER LOWER</p> <p>OTHER _____</p>
--	--	---

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 8-6-16

MECHANIC STEVEN B

JOB NAME/LOCATION MR. ZUBET MBE JOB NUMBER _____

PROBLEM: SEAT rusted out

REPAIRED: replaced seat

SEAT 1,220.00 Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>110</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MAKE <u>CAT</u>	REASON _____	COMPONENT LOCATION	
MODEL <u>CP563</u>	PARTS _____ LABOR _____	FRONT REAR LEFT RIGHT UPPER LOWER	
SERIAL # _____	OTHER _____	OTHER _____	
HOUR METER _____			
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>11-29-16</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC _____	
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Wilson Bank Lebanon</u>	JOB NUMBER _____
PROBLEM: <u>vibrator switch broken</u>			
REPAIRED: <u>replaced switch</u>			
PARTS: <u>Switch + Cat</u> <u>65.00</u> <u>Thompson</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0702</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>CP563</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>4K HRS</u>		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE <u>7-26-18</u>	DATE COMPLETED <u>8-15-18</u>
		MECHANIC <u>Tony</u>	
		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: _____ _____ _____			
REPAIRED: <u>serviced</u> _____ _____ _____ _____ _____ _____			
PARTS: <u>All Filters</u> <u>180.23</u> <u>Tenn Filter</u> _____ _____ _____ _____			

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>5702</u> MAKE <u>CAT</u> MODEL <u>CP563</u> SERIAL # _____ HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
--	---	--

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE <u>12-13-18</u> DATE COMPLETED <u>12-19-18</u> MECHANIC <u>James & Bryan</u> JOB NAME/LOCATION <u>MCM</u> JOB NUMBER _____
---	---

PROBLEM: blown hose from Pump to motor

REPAIRED: replaced hose filled hydraulic Tank

PARTS: Filter 76.29 Thompson
Hose 206.10 Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0702</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>CP563</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE <u>6-4-19</u>	DATE COMPLETED <u>7-31-19</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC <u>Charles</u>	
SMOKES SHORTED VIBRATE OTHER _____	JOB NAME/LOCATION <u>Ashland to shop</u>	JOB NUMBER _____

PROBLEM: Service & won't move
brought to shop spaces 106.5" Thompson
Hoses 1,028.46 Nashville Rubber & Gasket

REPAIRED: replaced bad tire holders
replaced clean cylinders 2 bearings 215.06 Thompson
replaced water pump tensioner pulley & belt.
Replaced hitch pins & bearings, replaced 6 old hoses & blade
Pins & Bushings 579.32 Thompson
Seals 133.84 Thompson
Bearings 195.53 Thompson

PARTS: All Filters 184.82 Tenn Filter Sales
belt's cover & washers 197.38 Thompson
3 Drums Mounts 320.33 Thompson
belt, pulley & hardware 169.20 Thompson
3 clean cylinders 350.48 Thompson

Pins 447.99 Thompson
Bushings 172.35 Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0702</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>CP563</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>1-9-2020</u>	MECHANIC <u>Bryan</u>
PROBLEM: <u>won't start</u>		JOB NAME/LOCATION <u>Jones Brummett</u>	JOB NUMBER
REPAIRED: <u>replaced bad batteries</u>			
PARTS: <u>2 - MT-27</u> <u>\$273.⁶³</u> <u>Interstate Battery</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0702</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>CAT</u>	REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>CP563</u>	PARTS LABOR	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>12-16-21</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Ben</u>
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>West Trinity</u>
PROBLEM: <u>blown tire</u>		JOB NUMBER
REPAIRED: <u>replaced tire</u>		
PARTS: <u>23.1-26 Primex 2459, 60 Gateway Tire</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>0702</u> MAKE <u>CAT</u> MODEL <u>CP563</u> SERIAL # _____ HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: _____ DATE COMPLETED <u>1-5-22</u> MECHANIC <u>Anthony</u> JOB NAME/LOCATION <u>West Trinity</u> JOB NUMBER _____	
PROBLEM: <u>blow hyd. hose</u>		
REPAIRED: <u>replaced hose</u>		
PARTS: <u>hose</u> <u>82.70</u> <u>Nashville Rubbe + Gasket</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0702</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>CP563</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____				DATE: _____ DATE COMPLETED <u>3-26-22</u>	
				MECHANIC <u>All</u>	
				JOB NAME/LOCATION <u>Shop</u>	
				JOB NUMBER _____	
PROBLEM: <u>Pump down</u>					
REPAIRED: <u>removed pump had rebuilt replaced old control & cable, removed block & di's armed valve. changed engine oil & filter, changed hydraulic oil. Replaced 4 scrape tips</u>					
PARTS: <u>Pump repair 6,391.¹³ Mid South Hydraulics</u>					
<u>2 pump bases 154.⁹² Thompson</u>					
<u>O-rings & seals 109.³⁰ Thompson</u>					
<u>Oil Filter Hyd Unit 86.⁸⁷ Thompson</u>					
<u>Control & cable 1066.¹⁰ Thompson</u>					
<u>Tips & locks 248.²⁴ Thompson</u>					
<u>sealing unit 91.⁶⁹ Thompson</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>0702</u> MAKE <u>CAT</u> MODEL <u>CP563</u> SERIAL # _____ HOUR METER _____ MILES _____		EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____		COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____				DATE: <u>4-4-22</u> DATE COMPLETED <u>4-5-22</u> MECHANIC <u>Ben</u>	
PROBLEM: <u>broken rubber mounts in drum</u>				JOB NAME/LOCATION: <u>Iron Mountain</u> JOB NUMBER _____	
REPAIRED: <u>replaced mounts</u>					
PARTS: <u>Mounts & Hardware 688.71 Thompson</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>0702</u> MAKE <u>CAT</u> MODEL <u>CP563</u> SERIAL # _____ HOUR METER _____ MILES _____		EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>8-31-22</u> MECHANIC <u>Ben</u>	JOB NAME/LOCATION <u>Steve Trace</u> JOB NUMBER _____
PROBLEM: <u>leak + broken pad</u>			
REPAIRED: <u>replaced blown hose and 1 right drum pad</u>			
PARTS: <u>hose</u>		<u>517.38</u>	<u>Thompson</u>
<u>Mount</u>		<u>157.56</u>	<u>Thompson</u>

TEC

THORNES EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	
EQUIP. #	0702	HOURS	DAYS
MAKE	CAT	REASON	
MODEL	CP563	PARTS	LABOR
SERIAL #		OTHER	
HOUR METER			
MILES			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			
SMOKES SHORTED VIBRATE OTHER			
PROBLEM: <i>drum hammer quit working hole in radiator</i>			
REPAIRED: <i>new bearings & seals in drum</i>		REPAIRED: <i>had radiator recored. replaced park valve in rear pump.</i>	
PARTS: <i>bearings & seals 3433.01</i>		PARTS: <i>radiators re-core 2092.92</i>	
DATE COMPLETED: <i>12-6-22</i>		DATE COMPLETED: <i>3-21-23</i>	
MECHANIC: <i>All</i>		MECHANIC: <i>All</i>	
JOB NAME/LOCATION: <i>Shop</i>		JOB NAME/LOCATION: <i>Shop</i>	
COMPONENT CODES		COMPONENT CODES	
BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
COMPONENT LOCATION		COMPONENT LOCATION	
FRONT REAR LEFT RIGHT UPPER LOWER		FRONT REAR LEFT RIGHT UPPER LOWER	
OTHER		OTHER	
JOB NUMBER		JOB NUMBER	

REPAIRED: <i>new bearings & seals in drum</i>		REPAIRED: <i>had radiator recored. replaced park valve in rear pump.</i>	
PARTS: <i>bearings & seals 3433.01</i>		PARTS: <i>radiators re-core 2092.92</i>	
DATE COMPLETED: <i>12-6-22</i>		DATE COMPLETED: <i>3-21-23</i>	
MECHANIC: <i>All</i>		MECHANIC: <i>All</i>	
JOB NAME/LOCATION: <i>Shop</i>		JOB NAME/LOCATION: <i>Shop</i>	
COMPONENT CODES		COMPONENT CODES	
BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
COMPONENT LOCATION		COMPONENT LOCATION	
FRONT REAR LEFT RIGHT UPPER LOWER		FRONT REAR LEFT RIGHT UPPER LOWER	
OTHER		OTHER	
JOB NUMBER		JOB NUMBER	

value & park cap
 522.63
 Thompson
 EC5
 Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0702

MAKE Cat

MODEL CP563

SERIAL # _____

HOUR METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON _____

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 4-12-23

MECHANIC A. Shany

JOB NAME/LOCATION Sparta Pk.

JOB NUMBER _____

PROBLEM: overheating

REPAIRED: replaced water pump tensioner pulley.

PARTS: pulley

368.97

Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0702</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>CP563</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____				DATE: <u>7-6-23</u> DATE COMPLETED <u>7-10-23</u>	
				MECHANIC <u>James</u>	
				JOB NAME/LOCATION <u>To Shop</u>	
				JOB NUMBER _____	
PROBLEM: <u> pump solenoid getting hot.</u>					
REPAIRED: <u>replaced solenoid and update manifold</u>					
PARTS: <u>Solenoid + Manifold 693.98</u> <u>Thompson</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0702</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>CP563</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>5K HRS</u>	OTHER _____	OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE <u>8-31-23</u> DATE COMPLETED <u>9-12-23</u>		
	MECHANIC <u>Anthony</u>		
	JOB NAME/LOCATION <u>Limestone Trail</u>	JOB NUMBER	
PROBLEM: <u>Service</u>			
REPAIRED: <u>Serviced</u>			
PARTS <u>Filters</u>	<u>239.¹¹</u>	<u>Tenn Filter</u>	

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0702</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>CP563</u>	PARTS LABOR	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>10-11-23</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>James</u>	
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION	JOB NUMBER
		<u>Shop</u>	
PROBLEM: <u>Fuel leaking off</u>			
REPAIRED: <u>replaced main fuel filter & hand prime pump.</u>			
PARTS: <u>Filter + pump 160.⁰⁰ Thompson</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0702</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>CAT</u>	REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>CPS63</u>	PARTS LABOR	COMPONENT LOCATION
SERIAL # _____	OTHER	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>2-19-24</u>
		MECHANIC <u>Ben</u>
		JOB NAME/LOCATION <u>Arthur</u>
		JOB NUMBER
PROBLEM: <u>won't start</u>		
REPAIRED: <u>replaced old batteries</u>		
PARTS: <u>2 MT-27</u> <u>291.82</u> <u>Interstate battery</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0702</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Cat</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>CP563</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE: <u>3-13-25</u>	DATE COMPLETED <u>4-15-25</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____	JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____

PROBLEM: Service, check over.
no back up alarm.

REPAIRED: Excess water in fuel tank. Flushed tank.
Serviced. Replaced batteries. Replaced broken
left door cylinder.

PARTS: <u>Filters</u>	<u>251.28</u>	<u>Tenn Filter</u>
<u>batteries</u>	<u>351.66</u>	<u>Advance</u>
<u>door cylinder</u>	<u>173.25</u>	<u>Thompson</u>