

COMPLETE

31-POINT INSPECTION

Date OCT 10/25

Year / Make / Model

2006 HYUNDAI TUCSON.

VIN KM8JM72D66U455417

Mileage 288054 kms

Stock 102.

OK Checked and OK

MR

May Require Further Attention

RA

Requires immediate Attention

Under Hood Inspection

- 1 Check Battery Voltage/Amperage/Charging
- 2 Check Starter
- 3 Check Coolant Levels
- 4 Check Oil levels
- 5 Check Power Steering
- 6 Check Master Brake Cylinder
- 7 Check Belts
- 8 Check Ignition System
- 9 Check Engine & Trans Supports

OK	MR	RA
☒	☐	☒
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐

Comments

BATTERY DEAD.

Interior Inspection

- 10 Check Seat Belts
- 11 Check Instrument Panel, Warning Lights
- 12 Check Front & Rear Defroster
- 13 Check Hazard Lights & Horn
- 14 Check Power Lock System
- 15 Check Hood Latch & Fuel Filler Door Cable
- 16 Check Air Bag System
- 17 Check inside Rear-view Mirror

OK	MR	RA
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐

Exterior Inspection

- 18 Check Windshield, Wiper arms and Blades
- 19 Check Outside Mirrors
- 20 Check All Exterior Lights
- 21 Check Wheels & Spare Tire

OK	MR	RA
☒	☐	☐
☒	☐	☐
☒	☐	☒
☒	☐	☐

L/S + R/S Low BEAM OUT.

Inspection Under Hood

- 22 Check Physical Damage
- 23 Check Upper & Lower Ball Joints
- 24 Check Brake Calipers/Wheel Cylinders/Tubes
- 25 Check Struts/Shocks
- 26 Check Tie Rod Ends/CV Boots
- 27 Check Upper & Lower Control Arms
- 28 Check Sway Bars Bushings
- 29 Check Emergency Brake Cables
- 30 Check Front / Rear Brakes
- 31 Check Tires

OK	MR	RA
☒	☐	☒
☒	☐	☐
☒	☐	☐
☒	☐	☒
☒	☐	☒
☒	☐	☒
☒	☐	☐
☒	☐	☐
☒	☐	☒
☒	☐	☐

REAR SUBFRAME RUSTED INTO
PIECES. FRAME BROKEN IN
4 SPOTS.

FRONT STRUTS WORN OUT
L/S FRONT CV AXLE FAILED.

Front Wear - 5%

Rear Wear - 60%

5/32

4/32

Notes

Tow.

NOT TO BE DRIVEN. NOT SAFE

VERY LOW POWER - BARELY DRIVES.

Curtis