Bowen Auto Repair
1703 A Bowen Road
Nanaimo, BC V9S 1G8
Tel: (250) 753-9300
Tel: (250) 753-9300
Tel: (250) 753-9300

Cuotoman	and by the mandacturer					
Customer Name.			Year/Model: 2018	Year/Model: 2018 ryunda Date: Nov. 2 /200		
RO/Tag:	Mileage: 162574				Sale. 1000 A 1 000	
CHECKED AND OKAY AT THIS		IRF FI	UTURE ATTENTION			
Recommended Schedu				. REQUIRES IMME	EDIATE ATTENTION	
☐ Accessory Drive Belt(s)	Oil Filter		Check Battery	Mind Hay Leven	The state of the s	
Cabin Air Filter	Seat Filter		State of He	alth	Good Bad	
Engine Air Filter					Battery Terminals	
☐ Engine Coolant	Spark Plugs Tire Rotation	1			(Clean if necessary) Declined Battery	
☐ Fuel Filter	☐ Tire Rotation ☐ Transmission Filter		0%	100%	Declined Battery	
Oil Change			Measur	Check Brakes e Front / Rear Brake	es Lininas	
Comments:	Transmission Fluid		LF/			
				60	RF	
Checked Fluid	evels and Fill					
OK FILL OK FILL	OK FILL					
Engine Oil Power Ste	Transmission (if equipped with dipsi	tick)				
Brake Reservoir Window W	sher Coolant Recovery Re	servoir				
Check Following Syste						
Operation of horn, interi		Declined				
turn signals, hazard and	brake lamps		LR			
Radiator, heater, and air	conditioning hoses for leaks	П			RR	
and damage		-	Over 5 mm or 7/3	32" (Disc) or Over 2 mi	m or 3/32" (Drum)	
Windshield for cracks, c	ips and pitting		3 to 5 mm or 4/32" to 7/32	" (Disc) or 1.01 to 2mm	(Drum) or 2/32" to 3/32"	
Windshield washer spray and wiper blades	, wiper operation	П			or 2/32" or Less (Drum)	
			The same of the sa	ents Not Taken This S	Service Visit	
Accessory drive belt(s.)			Comments:		_	
Brake system (including	nes, hoses, and parking end-play and bearing noise			Check Tires		
			LF	TREAD DEPTH	RF	
Clutch operation (if equi	ped)		7/32" or Greater		7/32" or Greater	
Constant velocity (CV) d	ve axle boots (if equipped)		4/32" to 6/32"	115-1	4/32" to 6/32"	
Drive shaft, transmission,	u-joint and shift linkage (if		3/32" or less		3/32" or less	
equipped) and lubricate (a	s needed)			345		
Engine Cooling system,	oses and clamps		7/32" or Greater	3611	7/32" or Greater	
Exhaust sustain (I I.			4/32" to 6/32"		4/32" to 6/32"	
Exhaust system (leaks, d	image, loose parts)	Ш	3/32" or less		3/32" or less	
Oil and / or fluid leaks			LR		RR Declined Tire	
Shocks/struts and other	uspension components		15		Declined Tire	
Tor leaks and/or damage		Ш	LF WE	EAR PATTERN / DAMAG	RF F	
State Inspection Due (IF APPLICAB	.E) / /		LR		RR	
	MO DAY YEAR		Tire Wear Indicates:			
Comments:	Alignment Check Needed Wheel Balance Needed					
			Comments:			
This Courtesy Inspection Complete	by Your Dealership Team!		Tire Pressure Set to Fac	tory Recommended PS	SI	
Service Advisor:			FRONT		REAR	
Technician: Casey Bart	off /					
			Customer Signature:			
Form AP-FD-QC-O Reorder From:	A Plus Dealer Supplies orders@aplusdirect.com	om • 1-	800-334-6329			