



Canadian Tire Associate Store 0350
J.L. HEERINGA ENTERPRISES LTD.
2801 CLIFFE AVENUE

Courtenay BC V9N 2L8
Phone: 250-338-6553 Fax:
e-mail:

PAGE:	1
DATE:	Oct 26 25
INVOICE	
20035000131143	

GST REG#: R122584824
PST REG#: 10025546

SOLD TO:
9122933.0350

1

Courtenay BC 1111

MOBILE :
BUSINESS:
EMAIL :
HOME:
FAX :

COLOUR	VEHICLE DESCRIPTION	PLATE	UNIT#	TAG	ODO IN
	2015 LAND ROVER RANGE ROVER EVOQUE 4-1999 2.0L DOHC	hp783n			157192
VIN	VEHICLE OPTIONS			ADV	ODO AUTH
SALVP2BG8FH076866				LC01	157192
TIME IN	PROMISED	TERMS	GST EXEMPT#	P.O.	ODO OUT
11:00	12:00	Cash		SEASONAL	157192
QTY	ITEM	DESCRIPTION	WARR	NET	EXT.PRICE
4	3022408	Bridgestone *P235/55R19 BLI DMV2 *P235/55R19 Bridgestome Blizzak DM-V2 (015913) 235/55R19 105T DOT Number(1): DOT Number(2): DOT Number(3): DOT Number(4): Effective until Oct 23 2025 New Tire Mount and Balance 19 Oct 18 25 Reminder: Seasonal Tire Changeover Apr 27 26 A reminder will be sent to you on the date above RECOMMEND ALIGNMENT CHECK WITH PURCHASE OF NEW TIRES. W/ WALL OR LETTERING - IN - OUT DISPOSE OF OLD TIRES - YES TOSS NO LOCKING WHEEL NUTS AFTER WHEEL REMOVAL WE RECOMMEND A RETORQUE AT 80 - 100 KLMS ALIGNMENT 06 Oct 18 25 IF A STEERING ANGLE RESET IS NEEDED THERE WILL BE AN EXTRA CHARGE OF \$ 29.00. TECH WILL HAVE TO ADVISE SERVICE WRITER IF THIS SERVICE IS NEEDED. English: Visit canadiantire.ca/en/automotive/tires-wheel/tire-registration.html to register your new tire's DOT codes French: Enregistrez les codes DOT sur www.canadiantire.ca/fr/automobile/pneus-et-jantes/tire-registration.html *TIRE REPLACEMENT ADVANTAGE* *PNEUS DE REMPLACEMENT AVANTAGE* Free spare tire change service for the first year after purchase when Tire Replacement Advantage purchased. (Service gratuit de emplacement d'un	T1	266.49	1065.96
4	NTMBA R SRTC			30.00	120.00
1	ssali			145.00	145.00

INVOICE TO:

I hereby authorize you and your employees to carry out the repairwork described above and to purchase on my account any parts and materials necessary to carry out the repairwork subject to the estimate described above. I hereby authorize you and your employees to operate the vehicle listed above in connection with the repairwork, including operation for the purposes of testing, inspection or delivery. I HEREBY RELEASE AND FOREVER DISCHARGE YOU AND EACH OF YOUR EMPLOYEES FROM ANY LOSSES I MAY SUFFER RELATING TO DAMAGE TO OR LOSS OF MY VEHICLE AND/OR ANY ITEMS CONTAINED THEREIN THAT ARE CAUSED BY CIRCUMSTANCES BEYOND YOUR CONTROL. I acknowledge that, upon the completion of the repairwork authorized hereby, you will have a lien pursuant to applicable repair and storage lien legislation and that you may register that lien and seize, at your discretion and at my sole cost and expense, the vehicle for non-payment of any invoice issued for such repairwork. By signing below I acknowledge and agree to the terms and conditions above and to those printed on the reverse side of this form.

Customer Signature: _____

PARTS:	
LABOUR:	
OTHER:	
SUB-TOTAL:	
GST/HST:	
PST:	
TOTAL:	Cont'd



Canadian Tire Associate Store 0350
J.L. HEERINGA ENTERPRISES LTD.
2801 CLIFFE AVENUE

Courtenay BC V9N 2L8
Phone: 250-338-6553 Fax:
e-mail:

PAGE: 2
DATE: Oct 26 25



INVOICE

20035000131143

GST REG#: R122584824
PST REG#: 10025546

SOLD TO:
9122933.0350

1

Courtenay BC 1111

MOBILE :
BUSINESS:
EMAIL :
HOME:
FAX :

COLOUR	VEHICLE DESCRIPTION	PLATE	UNIT#	TAG	ODO IN
	2015 LAND ROVER RANGE ROVER EVOQUE 4-1999 2.0L DOHC	hp783n			157192
VIN	VEHICLE OPTIONS	ADV	ODO AUTH		
SALVP2BG8FH076866		LC01	157192		
TIME IN	PROMISED	TERMS	GST EXEMPT#	P.O.	ODO OUT
11:00	12:00	Cash		SEASONAL	157192
QTY	ITEM	DESCRIPTION	WARR	NET	EXT.PRICE
4	2989327	pneu de secours pour la première année après l'achat lors d'une inscription au programme Valeur à neuf.)			
4	2990103	Call Roadside Assistance if you require assistance: (Appelez l'Assistance routière pour obtenir de l'aide): 1-800-444-4597			
		ADVANCE DISPOSAL FEE		6.50	26.00
		TIRE REPLACEMENT ADV		19.99	79.96
		Subtotals Tax out 1436.92 Tax in 1609.34			
2.2h	SSRRS	REAR TOE ECCENTRIC+LINK (NEED COST OF PARTS, DEALER CLOSED ON SUNDAY)			
		Remove & Replace Transverse Link Bushing Rear, Both 19 Oct 26 25		Declined	Declined
1	SSALI	DOES NOT Include Alignment ALIGNMENT 19 Oct 26 25			
		IF A STEERING ANGLE RESET IS NEEDED THERE WILL BE AN EXTRA CHARGE OF \$ 29.00. TECH WILL HAVE TO ADVISE SERVICE WRITER IF THIS SERVICE IS NEEDED.		Declined	Declined
		Subtotals Tax out 0.00 Tax in 0.00			
		(Declined: Tax out 464.00 Tax in 519.68)			
1	SS	Shop Supplies		18.55	18.55
		Authorized on: Oct 26 2025			
		Thank you for your business. ANY VEHICLE SERVICE THAT HAS HAD WHEELS REMOVED MUST RETURN IN 100 KM FOR A RE-TORQUE			
		*** Warranty Code Legend ***			
		TL: See Service Manager for details			
		*** Global Warranty Message ***			
		Installed parts warranties applicable only when product is installed at a Canadian Tire Automotive Service Centre, otherwise warranties may vary.			
		Warranty not available for commercial use. A minimum labour warranty of 100 days			

INVOICE TO:

I hereby authorize you and your employees to carry out the repairwork described above and to purchase on my account any parts and materials necessary to carry out the repairwork subject to the estimate described above. I hereby authorize you and your employees to operate the vehicle listed above in connection with the repairwork, including operation for the purposes of testing, inspection or delivery. I HEREBY RELEASE AND FOREVER DISCHARGE YOU AND EACH OF YOUR EMPLOYEES FROM ANY LOSSES I MAY SUFFER RELATING TO DAMAGE TO OR LOSS OF MY VEHICLE AND/OR ANY ITEMS CONTAINED THEREIN THAT ARE CAUSED BY CIRCUMSTANCES BEYOND YOUR CONTROL. I acknowledge that, upon the completion of the repairwork authorized hereby, you will have a lien pursuant to applicable repair and storage lien legislation and that you may register that lien and seize, at your discretion and at my sole cost and expense, the vehicle for non-payment of any invoice issued for such repairwork. By signing below I acknowledge and agree to the terms and conditions above and to those printed on the reverse side of this form.

Customer Signature: _____

PARTS:
LABOUR:
OTHER:
SUB-TOTAL:
GST/HST:
PST:
TOTAL: Cont'd



Canadian Tire Associate Store 0350
J.L. HEERINGA ENTERPRISES LTD.
2801 CLIFFE AVENUE

Courtenay BC V9N 2L8
Phone: 250-338-6553 Fax:
e-mail:

PAGE: 3
DATE: Oct 26 25



INVOICE

20035000131143

GST REG#: R122584824

PST REG#: 10025546

SOLD TO:
9122933.0350

1

Courtenay BC 1111

MOBILE :
BUSINESS:
EMAIL :

HOME:
FAX :

COLOUR	VEHICLE DESCRIPTION	PLATE	UNIT#	TAG	ODO IN
	2015 LAND ROVER RANGE ROVER EVOQUE 4-1999 2.0L DOHC	hp783n			157192
VIN	VEHICLE OPTIONS			ADV	ODO AUTH
SALVP2BG8FH076866				LC01	157192
TIME IN	PROMISED	TERMS	GST EXEMPT#	P.O.	ODO OUT
11:00	12:00	Cash		SEASONAL	157192

QTY	ITEM	DESCRIPTION	WARR	NET	EXT.PRICE
	/ 5500 km applies to installed parts unless otherwise stated above. Installed parts warranty starts on the completion date shown on the customer invoice. Please see auto parts staff for cash & carry parts warranties. ***Wheel Retorque*** Canadian Tire checks every tire after installation and retorques to the manufacturer's recommended values. It is recommended to have your wheels retorqued after driving for a short distance to account for any settling that can happen from continuous contact with the road. For added protection, kindly return to this location for a free wheel retorque after driving your vehicle between 50km and 100km. ***PRIVACY TERMS*** Canadian Tire Corporation, Limited, its affiliates, Associate Dealers, and service providers ("CTC" or "our") collect and use the personal information provided by you to fulfill this contract. CTC may also collect and use your information to administer the delivery of and market warranties, products, services, and loyalty programs to you, and to analyze your relationship with us. Please visit www.canadiantire.ca for details on CTC's privacy policy. If you do not wish for your information to be kept in our database, please contact CTC's Corporate Customer Relations at 1-866-846-5841 or via email at https://www.ctfs.com/ContactUs/. ***Tire Storage Terms*** Storage term: (applicable only to customers who have purchased tire storage) Tires will be stored up to a maximum of 8 months from Invoice date OR until customer requests to have Tires removed from the storage location for any reason, at which point the storage term will end. Canadian Tire is not responsible for unclaimed tires at expiration of storage term. Tires left beyond 30 days of term expiration date will be disposed of without any liability or obligation to customer. Payment for Tire Storage is deemed to be acceptance of these terms by customer.				

INVOICE TO:

I hereby authorize you and your employees to carry out the repairwork described above and to purchase on my account any parts and materials necessary to carry out the repairwork subject to the estimate described above. I hereby authorize you and your employees to operate the vehicle listed above in connection with the repairwork, including operation for the purposes of testing, inspection or delivery. I HEREBY RELEASE AND FOREVER DISCHARGE YOU AND EACH OF YOUR EMPLOYEES FROM ANY LOSSES I MAY SUFFER RELATING TO DAMAGE TO OR LOSS OF MY VEHICLE AND/OR ANY ITEMS CONTAINED THEREIN THAT ARE CAUSED BY CIRCUMSTANCES BEYOND YOUR CONTROL. I acknowledge that, upon the completion of the repairwork authorized hereby, you will have a lien pursuant to applicable repair and storage lien legislation and that you may register that lien and seize, at your discretion and at my sole cost and expense, the vehicle for non-payment of any invoice issued for such repairwork. By signing below I acknowledge and agree to the terms and conditions above and to those printed on the reverse side of this form.

Customer Signature: _____

PARTS:	1065.96
LABOUR:	265.00
OTHER:	124.51
SUB-TOTAL:	1455.47
GST/HST:	72.77
PST:	101.88
TOTAL:	1630.12

Tire Inspection Report

Date: Oct 26 2025

Page: 1/1

RepairOrder 20035000131143

2015 LAND ROVER RANGE ROVER EVOQUE 4-1999 2.0L DOHC

Odometer In: 157192

VIN: SALVP2BG8FH076866

Odometer Out: 157192

Plate: hp783n



VEHICLE WALK AROUND

Comments

Exterior Lights

☐ OK ☐ Suggested ☒ Required

☐ Headlights

☐ Brake Lights

☐ Turn Signals

passenger side brake light out

Required: Part no longer performs intended function

Wiper Blades

☒ OK ☐ Suggested ☐ Required

☐ Torn

☐ Streaks

☐ Rear

Horn

☒ OK ☐ Suggested ☐ Required

☐ No Sound

Dash Warning Lights

☐ OK ☒ Suggested ☐ Required

☒ Check Engine

☐ TRAC

☐ ABS

Suggest: Technician's recommendation based on substantial and informed experience

Oil Change Due?

☒ OK ☐ Suggested ☐ Required

☐ Yes

☐ No

☐ N/A

Fluid Leaks

☒ OK ☐ Suggested ☐ Required

☐ Engine Oil

☐ Power Steering

☐ Coolant

AROUND THE WHEELS - FRONT

Comments

Tire Pressure: Driver Side

☒ OK ☐ Suggested ☐ Required

☐ Under Inflated

☐ Over Inflated

☐ Filled Up

Tire Pressure: Passenger Side

☒ OK ☐ Suggested ☐ Required

☐ Under Inflated

☐ Over Inflated

☐ Filled Up

Tire Tread: Driver Side

☒ OK ☐ Suggested ☐ Required

☐ Sugg.(-5/32)

☐ Req.(-2/32)

☐ Puncture

Tire Tread: Passenger Side

☒ OK ☐ Suggested ☐ Required

☐ Sugg.(-5/32)

☐ Req.(-2/32)

☐ Puncture

Steering & Suspension

☒ OK ☐ Suggested ☐ Required

☐ Loose

☐ Leaking

☐ Mileage

Brakes

☒ OK ☐ Suggested ☐ Required

☐ Sugg.(-4mm)

☐ Req.(-3mm)

☐ N/A

AROUND THE WHEELS - REAR

Comments

Tire Pressure: Driver Side

☒ OK ☐ Suggested ☐ Required

☐ Under Inflated

☐ Over Inflated

☐ Filled Up

Tire Pressure: Passenger Side

☒ OK ☐ Suggested ☐ Required

☐ Under Inflated

☐ Over Inflated

☐ Filled Up

Tire Tread: Driver Side

☒ OK ☐ Suggested ☐ Required

☐ Sugg.(-5/32)

☐ Req.(-2/32)

☐ Puncture

Tire Tread: Passenger Side

☒ OK ☐ Suggested ☐ Required

☐ Sugg.(-5/32)

☐ Req.(-2/32)

☐ Puncture

Steering & Suspension

☒ OK ☐ Suggested ☐ Required

☐ Loose

☐ Leaking

☐ Mileage

Brakes

☒ OK ☐ Suggested ☐ Required

☐ Sugg.(-4mm)

☐ Req.(-3mm)

☐ N/A

ADDITIONAL FINDINGS

Comments

See Comments

☒ OK ☐ Suggested ☐ Required

☐ N/A

Reason Codes

Required:

A - Part no longer performs intended function

B - Part does not meet a design specification (regardless of performance)

C - Part is missing

Suggested:

1 - Part is close to end of useful life (just above discard specifications, or weak, failure likely to occur soon, etc.)

2 - Address a customer need, convenience, or request (to stiffen ride, enhance performance, eliminate noise, etc.)


3 - To comply with maintenance recommended by the vehicle Original Equipment Manufacturer

4 - Technician's recommendation based on substantial and informed experience



SALVP2BG8FH076866

Land Rover : Range Rover Evoque : 2015 : except Convertible ExpressAlign Total Alignment



• One or more values are not within specification. Tire wear, handling and safety problems may result.



Reset Required!

Electronic Stability Control (ESC) equipped vehicles require a reset of the system after wheel alignment.

CodeLink® or OEM scan tool is required to perform reset and to ensure correct functionality of the ESC system.

ESC has been mandated in the US and Canada from the 2012 model year on. The EU also mandated ESC from November 1st, 2014 on. See below for how to verify the vehicle is equipped with the system for earlier model years or in other countries.



To determine if a vehicle is equipped with Electronic Stability Control (ESC): Immediately after turning the ignition to the ON position and during the instrument cluster bulb check, look for the ESC indicator. This may be a symbol as shown or the actual name of the system (VSC, VDC, ESP, etc.)

The manufacturer does not specify a rear CAMBER adjustment.

The manufacturer does not specify front CAMBER and CASTER adjustments.







COURTENAY AUTOMOTIVE REPAIR CAR
2440-D Cliffe Avenue
Courtenay, BC. V9N 2L6
Phone: (250)-338-0131 | Fax: (250)-338-7823
<https://www.google.com> | CARCENTRE18@GMAIL.COM

Invoice # 027695
Original Est # 56709
GST#780081683
PST #11103197

Invoice

Balance Due: \$3,030.04

2015 Land Rover - Range Rover Evoque - Pure

2L, In-Line4 (122CI) VIN(G)

VIN: SALVP2BG8 FH076866

Odometer: In 145,690 Out 145,696

Color:

Work Complete: 02-25-2025

Service Advisor: ALEX WILCOX

Customer ID: 9466

Type	Description	Part #	Qty/Hr	Sale/Rate	Total
SHOCK &/OR STRUT ASSEMBLY - Remove & Install or Remove & Replace - Both					\$2,947.30
Labor	SHOCK &/OR STRUT ASSEMBLY - Remove & Install or Remove & Replace - Both NOTES: Need extra time to take the struts apart and transfer parts over to the new struts. - When the RF strut was removed the bearing plate is broken and coming apart. The bearing plates need to be replaced. - With the wheel were off i noticed the front brakes are super rusty and the inside face of the rotor is rust and its grinding the pads. The RR brake are hardly working, the outer face of the rotor is rusty and it doesn't look like the pads are garbing when applied. I recommend a 4 wheel brake job. Pads calipers and rotors. - assembled new struts - installed front struts		5.00 hr	\$135.00	\$675.00
Part	COILS	LR024490	2.00	\$175.21	\$350.42
Part	Bilstein Suspension Strut (Front Left)	LR4609L	1.00	\$495.71	\$495.71
Part	Bilstein Suspension Strut (Front Right)	LR4609R	1.00	\$488.32	\$488.32
Part	Altrom Group Suspension Strut Mount (Front)	VO4637	2.00	\$80.60	\$161.20
Part	Front strut bearing plate	18198	2.00	\$150.43	\$300.86
Part	FREIGHT CHARGE	FREIGHT	1.00	\$25.00	\$25.00
Labor	WHEEL ALIGNMENT completed alignment		1.00 hr		\$135.00
Parts: \$1,821.51 Labor: \$810.00 Tax: \$315.79 Total: \$2,947.30					
Order					\$82.75
Misc	Haz Mat.				\$24.30
Misc	Shop Supplies				\$49.58
Total: \$82.75 Tax: \$8.87					

Original Estimate: \$0.00 Revisions: \$2,478.19 Revised Estimate: \$2,478.19

Revision # 1 Previous Estimate Amount: \$0.00 | Additional Cost: \$2478.19 | Revised Estimate: \$2478.19 |

Parts: \$1495.65 Labor: \$648.00 Sublet: \$0.00 Taxes & Fees: \$334.54

Authorized by: on: 2025-02-18 2:27:29 PM , Initiated By - Shop Reason:

Thank you for your business.

I am the person who requested that the above work be done and material supplied, or I am the authorized agent for that person/company. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

Labor	\$810.00
Parts	\$1,821.51
HazMat	\$24.30
Supplies	\$49.58
Subtotal	\$2,705.39
Labor Tax	\$100.12
Parts Tax	\$224.53
Order Total:	\$3,030.04

PLEASE HAVE ALL YOUR WHEELS RETORQUED WITHIN 50-80 KM

Signature _____ Date _____ Time _____

Technician(s) :BUJOTZEK, KEENAN

Courtenay Automotive Repair Centre

Phone Number: 250-338-0131

Customer:

Company:

License No:

Odometer:

Date:

VIN

Technician:

Order No.:

2/25/2025 2:54 PM

SALVP2BG8FH076866

VEHICLE ALIGNMENT REPORT

LAND ROVER, 2015, RANGE ROVER EVOQUE (LV) All Models

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	3.8°	2.4°	3.9°	4.0°
		Right	3.8°	2.4°	3.9°	4.0°
	Camber	Left	-0.4°	-1.3°	0.2°	-0.4°
		Right	-0.9°	-1.3°	0.2°	-0.9°
	Toe	Left	-0.20°	0.00°	0.20°	0.10°
		Right	0.30°	0.00°	0.20°	0.10°
Total		0.10°	0.00°	0.40°	0.20°	
Rear	Camber	Left	-1.8°	-2.0°	-0.5°	-1.8°
		Right	-1.3°	-2.0°	-0.5°	-1.3°
	Toe	Left	0.00°	-0.05°	0.20°	0.00°
		Right	0.15°	-0.05°	0.20°	0.15°
		Total	0.15°	0.00°	0.40°	0.15°
	Thrust Angle		0.1°	-0.1°	0.1°	0.1°
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left		12.7°	----	----	12.7°
	Right		13.5°	----	----	13.5°
Included Angle	Left		12.3°	----	----	12.3°
	Right		12.6°	----	----	12.6°
Toe Out On Turns	Left		----	----	----	----
	Right		----	----	----	----
Maximum Turns	Left		----	----	----	----
	Right		----	----	----	----
Toe Curve Change	Left		----	----	----	----
	Right		----	----	----	----
Setback	Front		0.2"	----	----	0.1"
	Rear		-0.2"	----	----	-0.2"
Track Width Diff.			0.0"			0.0"
Wheel Base Diff.			0.3"			0.3"
Front Ride Height	Left		0.0"	17.1"	18.1"	0.0"
	Right		0.0"	17.1"	18.1"	0.0"
Rear Ride Height	Left		0.0"	17.8"	18.8"	0.0"
	Right		0.0"	17.8"	18.8"	0.0"
Frame Angle						----