

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>705</u> MAKE <u>I.R.</u> MODEL <u>5D100D</u> SERIAL # <u>186888</u> HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____									
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>1-9-18</u> DATE COMPLETED <u>1-18-18</u> MECHANIC <u>ALL</u> <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:50%;">JOB NAME/LOCATION <u>Shop</u></td> <td style="width:50%;">JOB NUMBER</td> </tr> </table>	JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER							
JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER										
PROBLEM: <u>service & check over</u>											
REPAIRED: <u>served, replaced batteries</u>											
<table style="width:100%;"> <tr> <td style="width:33%;">PARTS: <u>Filters</u></td> <td style="width:33%; text-align: center;"><u>93.45</u></td> <td style="width:33%; text-align: center;"><u>TKS</u></td> </tr> <tr> <td><u>2-Gal 65</u></td> <td style="text-align: center;"><u>278.30</u></td> <td style="text-align: center;"><u>Inter-state battery</u></td> </tr> <tr> <td><u>Hyd. Filter</u></td> <td style="text-align: center;"><u>101.00</u></td> <td style="text-align: center;"><u>TKS</u></td> </tr> </table>			PARTS: <u>Filters</u>	<u>93.45</u>	<u>TKS</u>	<u>2-Gal 65</u>	<u>278.30</u>	<u>Inter-state battery</u>	<u>Hyd. Filter</u>	<u>101.00</u>	<u>TKS</u>
PARTS: <u>Filters</u>	<u>93.45</u>	<u>TKS</u>									
<u>2-Gal 65</u>	<u>278.30</u>	<u>Inter-state battery</u>									
<u>Hyd. Filter</u>	<u>101.00</u>	<u>TKS</u>									

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0705

MAKE I.R.

MODEL JD100D

SERIAL # _____

HOUR METER 1396.6 HRS

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS

LABOR

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 1-19-18

MECHANIC Steven B.

JOB NAME/LOCATION

Shop

JOB NUMBER

PROBLEM: gauges bad

REPAIRED: replaced inst. cluster

1,396.6 HRS when replaced

PARTS: cluster

506. ~~EE~~

Scott Equipment

43893445

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0705</u>	HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____			
MAKE <u>Ing Ravel</u>					
MODEL <u>JD100D</u>					
SERIAL # _____					
HOUR METER _____					
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>4-26-18</u> MECHANIC <u>Charles</u> JOB NAME/LOCATION _____ JOB NUMBER _____			
PROBLEM: <u>faulty propulsion control</u>					
REPAIRED: <u>replaced alternator, checked wiring machine working</u>					
PARTS: <u>Alternator</u> <u>208.56</u> <u>Crest</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0705
MAKE Ing. Rand
MODEL JD100D
SERIAL # _____
HOUR METER _____
MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
REASON _____
PARTS _____ LABOR _____
OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 5-30-18

MECHANIC Charles

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: front crossbar bolts bad

REPAIRED: replaced bolts

PARTS: bolts & nuts 4/1/63 Capital City bolt.

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0705MAKE Ingersoll RandMODEL JD1000

SERIAL # _____

HOUR METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON _____

PARTS _____

LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: 7-3-18DATE COMPLETED 7-6-18MECHANIC Charles

JOB NAME/LOCATION

Cargill

JOB NUMBER

PROBLEM: park brake problemsREPAIRED: replaced brake solenoid coil and adjustedRPMPARTS: Coil25 ft. ILScott Equipment

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0705

MAKE I.R.

MODEL JD1000

SERIAL # _____

HOUR METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: 9-25-18 DATE COMPLETED _____

MECHANIC Charles

JOB NAME/LOCATION

Cargill

JOB NUMBER

PROBLEM: _____

REPAIRED: Front bumper bolts

replaced front bumper bolts

PARTS:

bolts

32, 45

Capitol City Bolt.

bolts & nuts

90, 15

LDC

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0705

MAKE Ing. Rand

MODEL SD100D

SERIAL # _____

HOURLY METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS

LABOR

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 2-18-19

MECHANIC Charles

JOB NAME/LOCATION

JOB NUMBER

MCH

PROBLEM: no back up alarm

REPAIRED: replaced missing switch

PARTS: Switch

49.52

Scott Equipment

#13266895

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0705
 MAKE Ingr. Rand
 MODEL SD1000
 SERIAL # _____
 HOUR METER 21K HRS
 MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
 REASON _____
 PARTS _____ LABOR _____
 OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
 POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
 COMPONENT LOCATION
 FRONT REAR LEFT RIGHT UPPER LOWER
 OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
 OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
 SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 2-25-19
 MECHANIC Chalker

JOB NAME/LOCATION

JOB NUMBER

MCH

PROBLEM: service

no power to dash

REPAIRED: serviced

power restored acc. solenoid rusted

PARTS: All Filters 207.⁶⁹

Tenn. Filter sales

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0705
MAKE Ing. Rand
MODEL JD100D
SERIAL # _____
HOUR METER _____
MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
REASON _____
PARTS _____ LABOR _____
OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER
OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SMOKES SHORTED VIBRATE OTHER _____

DATE 3-1-19 DATE COMPLETED 3-29-19

MECHANIC Charles

JOB NAME/LOCATION

JOB NUMBER

MKT to shop

PROBLEM: Many electrical

REPAIRED: repaired all electrical problems

PARTS: Delay Timer 261.⁵⁰ Scott Equipment
Alt. repair 28.⁴¹ Crook's Auto

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0705
MAKE Ing. Rand
MODEL JD1000
SERIAL # _____
HOUR METER _____
MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
REASON _____
PARTS _____ LABOR _____
OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER
OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 5-7-19

MECHANIC Charles

JOB NAME/LOCATION

MCH

JOB NUMBER

PROBLEM: bad fuel cap

REPAIRED: replaced fuel cap

PARTS: CAP 103.49 Scott Equipment

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0705
 MAKE Log. Road
 MODEL SD1000
 SERIAL # _____
 HOUR METER _____
 MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
 REASON _____
 PARTS _____ LABOR _____
 OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
 POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
 OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
 SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 6-13-19

MECHANIC James

JOB NAME/LOCATION

JOB NUMBER

Journey

PROBLEM: won't start

REPAIRED: replaced batteries

PARTS: 2-MTP 65 403.00 Interstate Battery

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0705

MAKE Ing. Ravel

MODEL SD160D

SERIAL # 185885

HOUR METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 9-11-19

MECHANIC Math

JOB NAME/LOCATION

JOB NUMBER

Journey Church

PROBLEM: broken fuel cap

REPAIRED: replaced broken fuel cap

PARTS: Fuel Cap

102.⁰⁰

Scott Equipment

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0705
MAKE Ingersoll Rand
MODEL JD100D
SERIAL # _____
HOUR METER _____
MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
REASON _____
PARTS _____ LABOR _____
OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 3-12-2020

MECHANIC Charles Byrnes & James

JOB NAME/LOCATION

JOB NUMBER

Shop

PROBLEM: Electrical problem
needs new tires

REPAIRED: replaced rear tires
repaired wiring at alternator

PARTS: 2-23.6-26 H TL TR390 2324.30 Gateway

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0705

MAKE Ing. Rand

MODEL JD100D

SERIAL # _____

HOUR METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS

LABOR

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE 5-8-20 DATE COMPLETED 6-10-20

MECHANIC James P Mac

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: service

REPAIRED: serviced

PARTS: All Filters

Ten Filter sales

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0705
MAKE Ing. Ravel
MODEL JD1000
SERIAL # _____
HOUR METER _____
MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
REASON _____
PARTS _____ LABOR _____
OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER
OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 8-5-20

MECHANIC Ben

JOB NAME/LOCATION

JOB NUMBER

Cedar Coasting

PROBLEM: stops moving

REPAIRED: replaced stop/park switch & coil

PARTS: switch & coil 275.⁴⁷ Scott Equipment

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0705</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Inv. Ravel</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>JD100P</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>3022 HRS</u>				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE <u>2-5-21</u> DATE COMPLETED <u>2-9-21</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION _____	
				JOB NUMBER _____	

PROBLEM: Hyd tank broken and service.

REPAIRED: removed hydraulic tank and repaired
serviced

PARTS: Filters \$ 206.68 Naps
bolts 47.00 Naps

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0705
 MAKE Ing. Ravel
 MODEL 5D100
 SERIAL # _____
 HOUR METER _____
 MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
 REASON _____
 PARTS _____ LABOR _____
 OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
 POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER
 OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
 OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
 SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 3-23-21

MECHANIC Ben

JOB NAME/LOCATION

Eastgate

JOB NUMBER

PROBLEM: blown hose

REPAIRED: replaced steering hose

PARTS: hose

57.87

IR+G

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0705

MAKE Inv, Ravel

MODEL _____

SERIAL # _____

HOUR METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS

LABOR

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: 4-1-21 DATE COMPLETED 4-1-21

MECHANIC Ben

JOB NAME/LOCATION

Eastgate

JOB NUMBER

PROBLEM: blown hose & bad hose

REPAIRED: replaced two main hoses to right side of drum.

PARTS: 2-hoses 540.00 Nashville Rubber & Basket

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # #0705
 MAKE Inv. Rand
 MODEL SD162
 SERIAL # _____
 HOUR METER _____
 MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
 REASON _____
 PARTS _____ LABOR _____
 OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
 POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER
 OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
 OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
 SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 4-1-21

MECHANIC Ben

JOB NAME/LOCATION

East gate

JOB NUMBER

PROBLEM: blown hose + bad hose

REPAIRED: replaced two main hoses to drum

PARTS: 2-hoses

565

Nashville Rubber & Gasket

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0705

MAKE Ing. Lind

MODEL JD100

SERIAL # _____

HOUR METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS

LABOR

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVETRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 4-29-21

MECHANIC Ben

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: bad batteries

REPAIRED: replaced batteries

PARTS: 2-g.p. 24FAGM

417.03

Advance Auto Parts

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0705
MAKE Ing. Rand
MODEL JD100D
SERIAL # _____
HOUR METER _____
MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
REASON _____
PARTS _____ LABOR _____
OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: 6-2-21 DATE COMPLETED 6-9-21

MECHANIC Ben

JOB NAME/LOCATION

Eastgate

JOB NUMBER

PROBLEM: won't run

REPAIRED: replaced fuel filters
repaired wiring at key switch

PARTS: 2 fuel filters

40.81

NAPA

3231 main

3722 sep.

Fuel cap

109.69

Scott Equipment

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0705
MAKE Ing. Rand
MODEL JD100
SERIAL # _____
HOUR METER _____
MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
REASON _____
PARTS _____ LABOR _____
OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SMOKES SHORTED VIBRATE OTHER _____

DATE: 8-15-22 DATE COMPLETED 8-16-22

MECHANIC Ben

JOB NAME/LOCATION

Steve Trace

JOB NUMBER

PROBLEM: not charging

REPAIRED: replaced Alternator

PARTS: Alternator 228.28

Cook's Auto Electric

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0705
 MAKE Ing. Rand
 MODEL 5D1000
 SERIAL # _____
 HOUR METER _____
 MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
 REASON _____
 PARTS _____ LABOR _____
 OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
 POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
 OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
 SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 11-16-22

MECHANIC Chad

JOB NAME/LOCATION
West Trinity

JOB NUMBER

PROBLEM: broken fuel cap

REPAIRED: replaced fuel cap

PARTS: Cap

121.53

Scott Equipment

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0705

MAKE Tug, Rand

MODEL JD100D

SERIAL # _____

HOURLY METER 3500 HRS

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: 8-31-23 DATE COMPLETED 9-9-23

MECHANIC Anthony

JOB NAME/LOCATION

Stone Trace

JOB NUMBER

PROBLEM: Service

REPAIRED: Serviced

PARTS: filters

270.63

Term Filter

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0705
 MAKE Ing. Rand
 MODEL JD100D
 SERIAL # _____
 HOUR METER _____
 MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
 REASON _____
 PARTS _____ LABOR _____
 OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
 POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
 COMPONENT LOCATION
 FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
 OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
 SMOKES SHORTED VIBRATE OTHER _____

DATE: 5-20-24 DATE COMPLETED 6-4-24
 MECHANIC Ben & Anthony

JOB NAME/LOCATION

JOB NUMBER

To Shop

PROBLEM: leak between propulsion pump & hyd. pump

REPAIRED: removed cab and hydraulic pump,
replaced pump & mount seals

PARTS: seal & o-ring
seals & o-ring
seal kit

\$6.39

Scott Equipment

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

PARTS: filters 287.11 Tenn Filter