

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 805

MAKE CAT

MODEL D8R

SERIAL # _____

HOURLY METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 7-11-13

MECHANIC JAMES

JOB NAME/LOCATION

JOB NUMBER

PROBLEM:

TRANS. oil leak, check over

REPAIRED:

replaced hose from trans filter housing to
trans. casing

PARTS:

Hose Assembly + O-rings \$105.52
4-light mounts

Thompson
Machinery

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>905</u>	HOURS _____ DAYS _____	REASON	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>			POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>D8R</u>	PARTS _____ LABOR _____	OTHER _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: _____ DATE COMPLETED <u>8-23-14</u> MECHANIC <u>JAMES</u>	
			JOB NAME/LOCATION <u>5 Bravo Dump</u>	JOB NUMBER
PROBLEM: <u>batteries stolen</u> <u>cross over cables stolen</u>				
REPAIRED: <u>replaced all four batteries</u> <u>made up two cross over cables</u>				
PARTS: <u>Gap 29</u> <u>471.74</u> <u>Interstate Battery</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>905</u>	REASON PARTS LABOR OTHER	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>D8R</u>				
SERIAL # _____				
HOOR METER _____				
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: _____ DATE COMPLETED <u>5-6-14</u> MECHANIC <u>JAMES</u>	
			JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____	
PROBLEM: <u>light leak at right side of radiator</u>				
REPAIRED: <u>replaced rubber mounts on right black cylinder light.</u> <u>removed & straightened main cap</u> <u>put sealer in radiator</u>				
PARTS: <u>stop leak 2.5.00 Advance Auto Parts</u>				

EQUIPMENT
REPAIRS

DATE 7-7-14

MILEAGE/HOURS 7K HRS

EQUIPMENT REPAIRED #905 DSR

REPAIRS MADE serviced -

starter rebuilt, no. 5 & no. 6 injector lines
replaced

HOURS WORKED _____

PARTS USED

~~Fit~~ ~~Parts~~ \$166.99 Tenn Filter Sales

~~Hyd. Filter~~ ~~Parts~~ \$59.21 NAPA

Starter Rebuild \$184.63 Crook's
no. 5 & no. 6 injector lines 385.23 Thompson Cat

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>905</u>	HOURS _____ DAYS _____ REASON PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>CAT</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>DPR</u>		COMPONENT LOCATION		
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>10-31-14</u>	MECHANIC <u>James</u>	
		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER	
PROBLEM: <u>Transmission leaks</u> <u>check over</u>				
REPAIRED: <u>replaced two transmission hoses.</u> <u>replaced o-rings in steer/brake control valve</u> <u>Adjusted throttle pedal, lubed trans. lode control.</u> <u>sealed behind left transion o-ring was broken</u> <u>Topped off fluids</u>				
PARTS: <u>O-rings</u> <u>55.29</u> <u>Thompson Machinery</u> <u>Hoses + O-rings</u> <u>268.33</u> <u>Thompson Machinery</u>				

TEC
THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>905</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>Cat</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>D8R</u>	PARTS _____ LABOR _____	COMPONENT LOCATION		
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER <u>7500 HRS</u>		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED _____		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>James + Stephen D</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____	
PROBLEM: <u>Service & check over</u>				
REPAIRED: <u>serviced</u>				
PARTS: <u>All Filters</u> <u>270.⁰⁰</u> <u>Two Filter sales</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 905

MAKE Cat

MODEL D8R

SERIAL # _____

HOUR METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS

LABOR

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 10-30-15

MECHANIC Steven

JOB NAME/LOCATION

JOB NUMBER

Smith Travel

PROBLEM: Blow on tilt cylinder hose

REPAIRED: replaced hose

PARTS:

hose

118.50

Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>905</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>D8R</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 10-30-15

MECHANIC James Hester

JOB NAME/LOCATION

Smith Travel

JOB NUMBER

PROBLEM: starter solenoid

REPAIRED: replaced starter

PARTS: <u>solenoid</u>	<u>63.39</u>	<u>Crook's</u>
<u>starter rebuilt</u>	<u>184.63</u>	<u>Crook's</u>

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 905

MAKE Cat

MODEL D8R

SERIAL # _____

HOUR METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS

LABOR

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 3-9-16

MECHANIC JAMES

JOB NAME/LOCATION

Cats

JOB NUMBER

PROBLEM: Alt locked up

REPAIRED: replaced alt. & belt

PARTS: Alt + belt 490¹⁰ Thompson Machine

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>905</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Cat</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>D8R</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER <u>8K</u>		OTHER _____
MILES _____		

REASON FOR FAILURE: ☐ BROKEN ☐ WORN ☐ ABUSE ☐ LOOSE ☐ SEIZED
☐ OVERHEAT ☐ PLANNED ☐ CONTAM ☐ LEAKING ☐ NOISY ☐ SCRATCH
☐ SMOKES ☐ SHORTED ☐ VIBRATE ☐ OTHER _____

DATE: _____ DATE COMPLETED 6-22-16
 MECHANIC JAMES + STEVE

JOB NAME/LOCATION Shop JOB NUMBER _____

PROBLEM: Service, equilizer bar, check over

REPAIRED: replaced all equilizer bar pins & bearings serviced, replaced no. 5 & no. 6 injector adapters through head, new lower rear valve cover & gaskets.

PARTS: <u>Bolts & nuts</u>	171. ⁷⁹	Thompson
<u>All Pins & bushings</u>		White Horse Equipment
<u>Seals</u>	42. ⁰⁴	Thompson
<u>Adapters</u>	106. ⁹⁶	Thompson
<u>Seals & O-rings</u>	130. ¹⁹	Thompson
<u>lower valve cover</u>		

TEC
THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 905

MAKE CAT

MODEL D8R

SERIAL # _____

HOUR METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON _____

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 7-28-16

MECHANIC Charles

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: pump came apart

REPAIRED: replaced pump

Hand pumps

126.44

Thompson

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>905</u>	HOURS _____ DAYS _____ REASON PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>CAT</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>D8R</u>		COMPONENT LOCATION		
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>7-13-17</u> MECHANIC <u>James & Steven B.</u> JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____		
PROBLEM: <u>radiator leak</u>				
REPAIRED: <u>Repaired radiator. Tightened blade</u>				
PARTS: <u>3 cores</u> <u>\$2,000.00</u> <u>Thompson</u> <u>Hoses & seals</u> <u>Hardware</u> <u>73.13</u> <u>Fastenal</u> <u>pins & bushings</u> <u>White Horse Equipment</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>905</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Cat</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>DFR</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE: <u>7-31-17</u> DATE COMPLETED <u>8-4-17</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC <u>All</u>
SMOKES SHORTED VIBRATE OTHER _____	JOB NAME/LOCATION <u>Shops</u> JOB NUMBER _____

PROBLEM: Drive line noise

REPAIRED: replaced u-joints, replaced key switch
cut open filters, replaced Trans. & hyd. filters.
checked all pickup screens

PARTS: 2 u-joints & gaskets 217.⁴⁹ Thompson
seals 71.⁹³ Thompson
switch 121.⁶¹ Thompson

TEC
THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>905</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>D8R</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>8-28-17</u> MECHANIC <u>Charles</u>
		JOB NAME/LOCATION <u>Town Center</u> JOB NUMBER _____
PROBLEM: <u>seat belt broken</u>		
REPAIRED: <u>replaced seat belt</u>		
PARTS: <u>seat belt</u> <u>206.00</u> <u>Thompson</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1004 (905)</u>	HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____		
MAKE <u>Cat</u>				
MODEL <u>D8R</u>				
SERIAL # <u>7X114139</u>				
HOUR METER _____				
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>10-24-17</u> DATE COMPLETED <u>11-2-17</u> MECHANIC <u>James & Steven</u> JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____		
PROBLEM: <u>anti-freeze leak, exhaust leak, broken manifold bolts.</u>				
REPAIRED: <u>removed water pump</u> <u>removed exhaust manifold</u>				
PARTS: <u>Water Pump 640.⁰⁰ Thompson</u> <u>bearings, bushings & Gaskets 709.⁵⁰ Thompson</u> <u>& stack Pipe</u> <u>Tool steels & Gaskets 725.⁶¹ Thompson</u> <u>Coolant Hose 84.³² Nashville Rubber & Gasket</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>1004</u>		HOURS _____ DAYS _____		BASIC MACHINE	HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Cat</u>		REASON _____		POWER TRAIN	ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>D8R</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT . REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____				DATE: _____	DATE COMPLETED <u>12-14-17</u>
				MECHANIC <u>Steven B.</u>	
				JOB NAME/LOCATION <u>PFG Extension</u>	JOB NUMBER _____
PROBLEM: <u>Hyd Tank Cap Broken</u>					
REPAIRED: <u>replaced cap</u>					
PARTS: <u>cap</u> <u>80.1</u> <u>thompson</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>905 1004</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>DFR</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>1-26-18</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>STEVEN B.</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Sparta PK</u>	JOB NUMBER _____
PROBLEM: <u>Heater motor locked up</u>				
REPAIRED: <u>swapped heaters</u>				
PARTS: <u>Hardware</u> <u>3.4L</u> <u>4DS</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC


SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1004</u>	HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>CAT</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>DPR</u>		COMPONENT LOCATION		
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>4-17-18</u> MECHANIC <u>Charles</u>		
PROBLEM: <u>Radiator leak</u>		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER	
REPAIRED: <u>removed cores, replaced seals</u>				
PARTS: <u>seals</u> <u>560.99</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1004</u>	HOURS _____ DAYS _____ REASON PARTS LABOR OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>CAT</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>DPR</u>		COMPONENT LOCATION		
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>6-7-18</u> MECHANIC <u>JAMES & Tony</u>		
		JOB NAME/LOCATION <u>Cargill</u>	JOB NUMBER	
PROBLEM: <u>blown hose , needs seat back & head rest.</u>				
REPAIRED: <u>replaced main Hyd. hose from pump to valve body.</u> <u>replaced seat back & head rest</u>				
PARTS: <u>hose Assembly</u> <u>240.²⁰</u> <u>Thompson</u> <u>seat cushions</u> <u>423.⁷⁵</u> <u>Thompson</u>				



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>1004</u>	REASON PARTS LABOR OTHER	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>CAT</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>D8R</u>		COMPONENT LOCATION	
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>9500 HRS</u>		OTHER _____	
MILES _____			

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SMOKES SHORTED VIBRATE OTHER _____

DATE 11-8-18 DATE COMPLETED 12-20-18

MECHANIC CHARLES

JOB NAME/LOCATION

MCH To Shop

JOB NUMBER

PROBLEM: needs serviced
Fix leaks

REPAIRED: serviced, replaced all leaking hoses
replaced broken blade connector
replaced leaking fuel lines

PARTS: All Filters

245.¹⁴

Tenn Fitter Jakes

Fuel Hose & clamps

623.⁰⁶

Thompson

Hose

201.⁵⁹

Thompson

Two Hoses & clamps

313.⁹¹

Thompson

connector & pins

885.⁰⁰

Thompson

Trans. Filter

7.⁵⁰

NAPA

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>1004</u> MAKE <u>CAT</u> MODEL <u>DPR</u> SERIAL # _____ HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____									
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>6-12-19</u> MECHANIC <u>Charles</u> JOB NAME/LOCATION <u>Ashland Farms</u> JOB NUMBER _____									
PROBLEM: <u>Anti-freeze leak</u> 											
REPAIRED: <u>replaced cross tube & elbows on front of Engine Topped off Anti-freeze.</u> 											
<table style="width:100%; border-collapse: collapse;"> <tr> <td style="width:30%;">PARTS</td> <td style="width:40%;"><u>Gaskets & bolts 78.⁶⁸</u></td> <td style="width:30%;"><u>Thompson</u></td> </tr> <tr> <td></td> <td><u>Tube & Elbows 560.³⁹</u></td> <td><u>Thompson</u></td> </tr> <tr> <td></td> <td><u>Anti-freeze 183.²⁸</u></td> <td><u>Advance</u></td> </tr> </table>			PARTS	<u>Gaskets & bolts 78.⁶⁸</u>	<u>Thompson</u>		<u>Tube & Elbows 560.³⁹</u>	<u>Thompson</u>		<u>Anti-freeze 183.²⁸</u>	<u>Advance</u>
PARTS	<u>Gaskets & bolts 78.⁶⁸</u>	<u>Thompson</u>									
	<u>Tube & Elbows 560.³⁹</u>	<u>Thompson</u>									
	<u>Anti-freeze 183.²⁸</u>	<u>Advance</u>									

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1004</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>D8R</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: _____ DATE COMPLETED <u>7-11-19</u> MECHANIC <u>Charles</u>	
			JOB NAME/LOCATION <u>Ashland Farms</u>	JOB NUMBER _____
PROBLEM: <u>needs fan belts</u>				
REPAIRED: <u>replaced fan belts</u>				
PARTS: <u>3 belt set</u> <u>124.93</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1004</u>	HOURS _____ DAYS _____ REASON PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>CAT</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>D8R</u>		COMPONENT LOCATION		
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER <u>10K HRS</u>		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: <u>6-28-19</u> DATE COMPLETED <u>6-29-19</u>	
			MECHANIC _____	
			JOB NAME/LOCATION <u>Ashland Farms</u> JOB NUMBER _____	
PROBLEM: <u>Service</u>				
REPAIRED: <u>Serviced</u>				
PARTS: <u>All Filters</u> <u>355 cc</u> <u>Thompson</u>				

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>1004</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS			
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED			
MODEL <u>DFR</u>	PARTS _____ LABOR _____	COMPONENT LOCATION			
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER			
HOUR METER <u>10,300 HRS</u>		OTHER _____			
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>9-2-19</u> DATE COMPLETED <u>10-4-19</u> MECHANIC <u>Ali</u>			
		JOB NAME/LOCATION <u>Shop</u>		JOB NUMBER	
PROBLEM: <u>oil pan leaking, hose leaking</u>					
REPAIRED: <u>sealed some oil pan bolts</u> <u>had starter rebuilt</u> <u>replaced one Trans hose</u> <u>washed</u> <u>Dropped All belly pans</u>					
PARTS: <u>Hose & Gaskets 217.29</u> <u>Starter rebuild 245.00</u> <u>Thompson</u> <u>Crocker Auto Electric</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1004</u>	HOURS _____ DAYS _____ REASON PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>CAT</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>DFR</u>		COMPONENT LOCATION		
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>10-21-19</u> DATE COMPLETED <u>10-22-19</u>	MECHANIC <u>Charles</u>	
		JOB NAME/LOCATION <u>Tower Brummett</u>	JOB NUMBER	
PROBLEM: <u>blown hose</u>				
REPAIRED: <u>replaced hose assembly</u>				
PARTS: <u>Hose Assembly</u> <u>238.75</u> <u>Thompson Machinery</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>1004</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON _____		POWER TRAIN ELECTRIC DRIVETRAIN UNEXPLAINED	
MODEL <u>DFK</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>12-9-19</u>			
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Charles</u>			
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Jones Brummett</u>		JOB NUMBER _____	
PROBLEM: <u>blown oil cooler hose</u>					
REPAIRED: _____					
PARTS: <u>2-bolts</u> <u>28.42</u> <u>Thompson</u>					
<u>hose</u> <u>138.00</u> <u>Nashville Rubber + Gasket</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1004</u>	MAKE <u>CAT</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MODEL <u>DPR</u>	SERIAL # _____	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
HOUR METER <u>10,430 HRS</u>	MILES _____	PARTS _____ LABOR _____	COMPONENT LOCATION	
		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
			OTHER _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>11-13-19</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Charks</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Jones Brummett</u> JOB NUMBER _____		
PROBLEM: <u>turbo locked up & broken</u>				
<u>muffler rusted out, intake cover bad</u>				
REPAIRED: <u>replaced Turbo, exhaust, support, muffler and intake cover.</u>				
<u>changed engine oil</u>				
<u>5T</u>				
<u>\$7.10</u>				
PARTS: <u>Turbo</u>	<u>2600.⁰⁰</u>	<u>Thompson</u>		
<u>Intake cover</u>	<u>564.²¹</u>	<u>Thompson</u>		
<u>oil Filter</u>	<u>26.⁹⁹</u>	<u>Thompson</u>		
<u>Gasket & seals</u>	<u>72.⁹²</u>	<u>Thompson</u>		
<u>Bolts, Gaskets & clamp - m. Aker</u>	<u>984.⁷⁴</u>	<u>Thompson</u>		
<u>couplings, support hardware</u>	<u>910.⁹⁰</u>	<u>Thompson</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1004</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>DPR</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # <u>7XM4139</u>		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>10900 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: _____ DATE COMPLETED <u>2-21-2020</u> MECHANIC <u>ALL</u>	
			JOB NAME/LOCATION <u>Jones Brummett</u> JOB NUMBER _____	
PROBLEM: <u>Service + repair</u>				
REPAIRED: <u>2-17-2020 replaced alt. belt + adjuster rod.</u> <u>serviced</u> <u>replaced bottom radiator hose clamp at w/pump</u>				
PARTS: <u>All Filters</u> <u>464.65</u> <u>All Filters Tank Filter</u> <u>belt + rod</u> <u>114.5L</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1004</u>	HOURS _____ DAYS _____ REASON PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>CAT</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>DPR</u>		COMPONENT LOCATION		
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>4-2-00</u>		
		MECHANIC <u>Ben</u>		
		JOB NAME/LOCATION <u>Jones Brummett</u>	JOB NUMBER _____	
PROBLEM: <u>broken belt tensioner spring</u>				
REPAIRED: <u>replaced spring</u>				
PARTS: <u>spring</u> <u>67.54</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1004</u>	REASON PARTS LABOR OTHER	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>D8R</u>		COMPONENT LOCATION		
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: _____	DATE COMPLETED <u>7-21-20</u>
			MECHANIC <u>Ben</u>	
			JOB NAME/LOCATION <u>Jones Brummet</u>	JOB NUMBER _____
PROBLEM: <u>needs batteries</u>				
REPAIRED: <u>replaced all four batteries</u>				
PARTS: <u>4- 3T5760</u> <u>787.13</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1004</u>	HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>CAT</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>D8R</u>		COMPONENT LOCATION		
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>10-1-20</u>	DATE COMPLETED <u>10-2-20</u>	
		MECHANIC <u>Ben</u>		
		JOB NAME/LOCATION <u>Water Run Farm</u>	JOB NUMBER	
PROBLEM: <u>Damaged belts</u>				
REPAIRED: <u>replaced all belts</u>				
PARTS: <u>All belts</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>1004</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>D8R</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____				DATE: <u>4-19-21</u> DATE COMPLETED <u>4-19-21</u>	
				MECHANIC <u>Ben</u>	
				JOB NAME/LOCATION <u>Carver Station</u>	
				JOB NUMBER _____	
PROBLEM: <u>slow crank</u>					
REPAIRED: <u>replaced all four batteries</u>					
PARTS: <u>4-Grip 29H-UHD</u> <u>482-68</u> <u>Interstate battery</u>					