



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>301</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>924G</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: _____ DATE COMPLETED <u>4-7-11</u> MECHANIC <u>JAMES</u>	
			JOB NAME/LOCATION _____ JOB NUMBER _____	
PROBLEM: <u>hydraulic leak in cab pressure switch</u> <u>leaking</u>				
REPAIRED: <u>replaced switch.</u>				
PARTS: <u>switch & o-ring</u> <u>\$80.25</u> <u>Thompson</u>				



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>301</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>924G</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # <u>95W2241</u>		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>5-19-11</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>JAMES</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>THORNE Tressler</u>	JOB NUMBER
PROBLEM: <u>blown hose</u>				
REPAIRED: <u>replaced right tilt cylinder hose on top of boom.</u> <u>cleaned glass</u>				
PARTS: <u>hose assembly</u> <u>224.03</u> <u>Thompson</u>				



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>301</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON PARTS _____ LABOR _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>924G</u>			COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>7,400 HRS</u>		OTHER _____	OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: _____ DATE COMPLETED <u>12-22-11</u>	
			MECHANIC <u>JAMES</u>	
			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>Heater & A/C fan won't blow</u>				
REPAIRED: <u>fan motor bad</u> <u>replaced motor assembly</u>				
PARTS: <u>motor assembly 160.00 Thompson Machinery</u>				



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>301</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>924G</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>3-15-12</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>JAMES</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>bucket cracked at brackets</u>				
<u>needs serviced</u>				
REPAIRED: <u>welded cracks on bucket</u>				
<u>serviced</u>				
<u>washed</u>				
PARTS: <u>All Filters #264, P3</u> <u>Tenn Filter sales</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>301</u>	HOURS _____ DAYS _____	REASON PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cot</u>			POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>924G</u>			COMPONENT LOCATION	
SERIAL # _____			FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: _____ DATE COMPLETED <u>8-2-13</u>	
			MECHANIC <u>James</u>	
			JOB NAME/LOCATION <u>Murphy Oil</u>	JOB NUMBER _____
PROBLEM: <u>bucket cylinder hose leaking</u>				
REPAIRED: <u>replaced hose</u>				
PARTS: <u>Hose Assembly 245. ^{1/2} Thompson</u>				

EQUIPMENT
REPAIRS

DATE 8-7-13

MILEAGE/HOURS 8K

EQUIPMENT REPAIRED #301 Cat 924G

REPAIRS MADE Serviced

HOURS WORKED _____

PARTS USED

All Filters 267.⁸⁵ Tenn Filtk sales

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>301</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>924G</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>10-18-13</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>JAMES</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION/ <u>Larkin</u>	JOB NUMBER _____
PROBLEM: <u>starter stuck</u>				
REPAIRED: <u>removed starter, starter not repairable</u> <u>replaced starter system O.K.</u>				
PARTS: <u>Denso starter 245.00</u> <u>CROOKS</u> <u>Reman. Denso</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>301</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>924G</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>8500 NRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>5-29-14</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>James Jeff</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>needs new tires</u>				
REPAIRED: <u>replaced all four tires</u>				
<u>serviced & greased</u>				
PARTS: <u>4 tires</u> <u>5,900.00</u> <u>Robison tire</u>				
<u>4-Orings</u> <u>\$22.00</u> <u>O'Reilly Auto Parts</u>				
<u>filters</u> <u>Tenn filter socks</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>301</u> MAKE <u>Cat</u> MODEL <u>924G</u> SERIAL # _____ HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>7-24-14</u> MECHANIC <u>James</u> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 70%; padding: 2px;">JOB NAME/LOCATION <u>Speedway</u></td> <td style="width: 30%; padding: 2px;">JOB NUMBER</td> </tr> </table>	JOB NAME/LOCATION <u>Speedway</u>	JOB NUMBER
JOB NAME/LOCATION <u>Speedway</u>	JOB NUMBER			
PROBLEM: <u>step rubber broken on left side</u>				
REPAIRED: <u>replaced and made up step rubbers on both steps left hand side.</u>				
PARTS: <u>cut out of used conveyor belt.</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>301</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>924G</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: _____ DATE COMPLETED <u>10-22-14</u> MECHANIC <u>James</u>	
			JOB NAME/LOCATION <u>Speedway</u>	JOB NUMBER
PROBLEM: <u>bucket tilt hose blown under cab.</u>				
REPAIRED: <u>replaced hose</u>				
PARTS: <u>hose assembly</u> <u>126.00</u> <u>NAPA</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>301</u>	MAKE <u>CAT</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MODEL <u>9246</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
SERIAL # _____		PARTS _____ LABOR _____	COMPONENT LOCATION	
HOUR METER <u>8,943 HRS</u>		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
MILES _____			OTHER _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: _____ DATE COMPLETED <u>12-15-14</u>	
			MECHANIC <u>James</u>	
			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>Anti-freeze leak on engine</u>				
REPAIRED: <u>Tightened all hoses</u> <u>replaced all three belts</u> <u>sealant in radiator</u>				
PARTS: <u>3 belts & sealant</u> <u>103.00</u> <u>NAPA</u>				
<u>(2 9530HD AIT)</u>				
<u>1 9476 ALC</u>				

EQUIPMENT
REPAIRS

DATE 1-21-15

MILEAGE/HOURS 9K HRS

EQUIPMENT REPAIRED #301 9246 cat

REPAIRS MADE serviced

HOURS WORKED _____

PARTS USED

Filters 321.27 Tenn Filter sales

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>301</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>924G</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>11-25-15</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>James & Steven</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Smith Travel</u>	JOB NUMBER _____
PROBLEM: <u>door latch broken</u>				
REPAIRED: _____				
PARTS: <u>latch + pins</u> <u>\$175.00</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>301</u> MAKE <u>CAT</u> MODEL <u>924G</u> SERIAL # _____ HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>2-26-16</u> MECHANIC <u>JAMES</u> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 70%;">JOB NAME/LOCATION <u>Smith Travel</u></td> <td style="width: 30%;">JOB NUMBER</td> </tr> </table>	JOB NAME/LOCATION <u>Smith Travel</u>	JOB NUMBER
JOB NAME/LOCATION <u>Smith Travel</u>	JOB NUMBER			
PROBLEM: <u>wheel tilt not working and leaking oil</u>				
REPAIRED: <u>replaced tilt cylinder</u>				
PARTS: <u>cylinder</u> <u>58.12</u> <u>thompson Machinery</u>				

EQUIPMENT
REPAIRS

DATE 3-31-16

MILEAGE/HOURS 9500 HRS

EQUIPMENT REPAIRED #301 Cab 9246

REPAIRS MADE serviced, cleaned, replaced two signals

HOURS WORKED _____

PARTS USED

All Filters	285. ⁰⁰	Ten Fille sales
Two signals	44. ⁹⁹	Thompson Machinery