

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>907</u>	HOURS _____ DAYS _____ REASON PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>CAT</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>D6K</u>		COMPONENT LOCATION		
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER <u>1500 HRS</u>		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>3-23-16</u>	MECHANIC <u>JAMES</u>	
		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____	
PROBLEM: <u>bought at Richie Bros.</u>				
REPAIRED: <u>checked over adjusted tracks</u> <u>replaced front & side wiper blades</u>				
PARTS: <u>3 blades</u> <u>32.56</u> <u>NAPA</u>				

EQUIPMENT

REPAIRS

DATE 10-18-16

MILEAGE/HOURS 2K HRS

EQUIPMENT REPAIRED #907 D6K CAT

REPAIRS MADE Serviced

HOURS WORKED _____

PARTS USED

All Filters 480.93 Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>907</u>	MAKE <u>CAT</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MODEL <u>D6K</u>	SERIAL # _____	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
HOOR METER <u>2500 HRS</u>	MILES _____	PARTS _____ LABOR _____	COMPONENT LOCATION	
		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
			OTHER _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>3-27-17</u> DATE COMPLETED <u>4-25-17</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC: <u>JAMES & STEVEN</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION	JOB NUMBER
			<u>Legends Dr.</u>	
PROBLEM: <u>serviced</u>				
REPAIRED: <u>4-5-17 replaced all air filters</u>				
<u>replaced all other filters 4-25-17</u>				
PARTS: <u>All Filters</u> <u>432.10</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>907</u> MAKE <u>CAT</u> MODEL <u>D6K</u> SERIAL # _____ HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>6-8-17</u> MECHANIC <u>JAMES + Steven</u>		
		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 70%;">JOB NAME/LOCATION <u>Legends Dr.</u></td> <td style="width: 30%;">JOB NUMBER</td> </tr> </table>	JOB NAME/LOCATION <u>Legends Dr.</u>	JOB NUMBER
JOB NAME/LOCATION <u>Legends Dr.</u>	JOB NUMBER			
PROBLEM: <u>flip cutting edge</u>				
REPAIRED: <u>Flipped center edges + replaced end edges</u>				
PARTS: <u>End bit, bolts + nuts 283.36 Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

1006

EQUIPMENT INFORMATION EQUIP. # <u>907</u> MAKE <u>CAT</u> MODEL <u>D6K</u> SERIAL # _____ HOUR METER <u>3500 HRS</u> MILES _____		EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____		COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____				DATE: <u>9-14-17</u> DATE COMPLETED <u>10-3-17</u> MECHANIC <u>All & Thompson</u> JOB NAME/LOCATION _____ JOB NUMBER _____	
PROBLEM: <u>service, flashing codes</u>					
REPAIRED: <u>changed Air Filters 9-19-17</u> <u>changed all Filters 10-3-17</u> <u>Thompson Found broken wire + repaired</u> <u>new Horn</u> <u>new angle pin</u>					
PARTS: <u>All Filters \$474.00 Thompson</u> <u>sensor 45.11 Thompson</u> <u>sensor (Indicator) \$19.11 Thompson</u> <u>w/sep. Air Indicator 175.00 Thompson</u> <u>sensor 130.16 Thompson</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1006</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>D6K</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>4,100 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE <u>5-17-18</u> DATE COMPLETED <u>6-29-18</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>All</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>Service</u>				
REPAIRED: <u>Serviced</u>				
PARTS: <u>All Filters</u> <u>418.25</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1006</u>	REASON HOURS _____ DAYS _____ PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>CAT</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>D6K</u>		COMPONENT LOCATION		
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER <u>4500 HRS</u>		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>9-5-18</u> DATE COMPLETED <u>9-13-18</u> MECHANIC <u>Charles</u>		
PROBLEM: <u>service</u>		JOB NAME/LOCATION <u>Legends Dr</u> JOB NUMBER _____		
REPAIRED: <u>Service call</u> <u>replaced electric fuel pump</u>				
PARTS: <u>All Fitted</u> <u>423.41</u> <u>Thompson</u> <u>Fuel Pump</u> <u>307.30</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1006</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>D6K</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>5k</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE <u>2-15-19</u>	DATE COMPLETED <u>2-18-19</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Charles</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>MCH</u>	JOB NUMBER _____
PROBLEM: <u>Service</u>				
REPAIRED: <u>Serviceed</u>				
PARTS: <u>All Filters</u> <u>473.81</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES																			
EQUIP. # <u>1006</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS																				
MAKE <u>Cat</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED																				
MODEL <u>D6K2</u>	PARTS _____ LABOR _____	COMPONENT LOCATION																				
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER																				
HOUR METER <u>5600 HRS</u>		OTHER _____																				
MILES _____																						
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: <u>5-29-19</u> DATE COMPLETED <u>6-10-19</u>																				
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC _____																				
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Ashland Farms</u>	JOB NUMBER _____																			
PROBLEM: <u>needs service</u> <u>brought to shop</u>																						
REPAIRED: <u>DPF at Emissions & Cooling solutions</u> <u>520 Central Ave. 377-8080</u> <u>serviced & cleaned</u>																						
<table border="0"> <tr> <td>PARTS: <u>All Filters</u></td> <td><u>\$505.90</u></td> <td><u>Thompson Machinery</u></td> </tr> <tr> <td><u>Clean DPF</u></td> <td><u>\$454.75</u></td> <td><u>Cumberland International</u></td> </tr> <tr> <td><u>Hyd Filters</u></td> <td><u>\$93.00</u></td> <td><u>Thompson Machinery</u></td> </tr> <tr> <td><u>Hose</u></td> <td><u>57.28</u></td> <td><u>Nashville Rubber & Gasket</u></td> </tr> <tr> <td><u>Bolts</u></td> <td><u>7.12</u></td> <td><u>Fastenal</u></td> </tr> <tr> <td><u>Alarm</u></td> <td><u>59.00</u></td> <td><u>Thompson</u></td> </tr> </table>					PARTS: <u>All Filters</u>	<u>\$505.90</u>	<u>Thompson Machinery</u>	<u>Clean DPF</u>	<u>\$454.75</u>	<u>Cumberland International</u>	<u>Hyd Filters</u>	<u>\$93.00</u>	<u>Thompson Machinery</u>	<u>Hose</u>	<u>57.28</u>	<u>Nashville Rubber & Gasket</u>	<u>Bolts</u>	<u>7.12</u>	<u>Fastenal</u>	<u>Alarm</u>	<u>59.00</u>	<u>Thompson</u>
PARTS: <u>All Filters</u>	<u>\$505.90</u>	<u>Thompson Machinery</u>																				
<u>Clean DPF</u>	<u>\$454.75</u>	<u>Cumberland International</u>																				
<u>Hyd Filters</u>	<u>\$93.00</u>	<u>Thompson Machinery</u>																				
<u>Hose</u>	<u>57.28</u>	<u>Nashville Rubber & Gasket</u>																				
<u>Bolts</u>	<u>7.12</u>	<u>Fastenal</u>																				
<u>Alarm</u>	<u>59.00</u>	<u>Thompson</u>																				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>1006</u> MAKE <u>CAT</u> MODEL <u>D6K2</u> SERIAL # _____ HOUR METER <u>5,800 HRS</u> MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>8-29-19</u> DATE COMPLETED <u>9-3-19</u> MECHANIC <u>Charles</u> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%;">JOB NAME/LOCATION <u>Shop</u></td> <td style="width: 50%;">JOB NUMBER</td> </tr> </table>	JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER			
PROBLEM: <u>EGR cooler leaking</u>				
REPAIRED: <u>replaced EGR cooler & Engine oil & Filter</u>				
PARTS: <u>Seals</u> <u>26.63</u> <u>Thompson</u> <u>Cooler & Gaskets</u> <u>2269.66</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1006</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>D6K 2XL</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOOR METER <u>6K HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE <u>10-28-19</u> DATE COMPLETED <u>11-6-19</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Charles</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Jones Brummett</u>	JOB NUMBER _____
PROBLEM: <u>Service</u>				
REPAIRED: <u>Serviced</u>				
PARTS: <u>All Filters</u> <u>351.50</u> <u>Thompson</u>				
<u>Air & Hyd Filters</u> <u>145.25</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1006</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>D6K-2</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # <u>WMR 00459</u>		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>6,500 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>1-8-20</u> DATE COMPLETED <u>1-17-2020</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>All</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Jones Brummett</u>	JOB NUMBER
PROBLEM: <u>Service</u>				
REPAIRED: <u>Serviced</u>				
PARTS: <u>All Filters</u> <u>\$449.73</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1006</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>D6K</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>3-17-2020</u> MECHANIC <u>BEN</u>	
		JOB NAME/LOCATION <u>Joes Brummett</u>	JOB NUMBER
PROBLEM: <u>bad battery</u>			
REPAIRED: <u>replaced batteries</u>			
PARTS: <u>MT-27</u> <u>273.63</u> <u>Ingersoll Battery</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1006</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>DSK</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: _____ DATE COMPLETED <u>4-3-2020</u> MECHANIC <u>Al</u>	
			JOB NAME/LOCATION <u>Jones Burnett</u> JOB NUMBER _____	
PROBLEM: <u>Detaching cab</u>				
REPAIRED: <u>replaced cab filters</u>				
PARTS: <u>cab filters</u> \$ <u>75.25</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1006</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>D6K2</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>7K HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>4-14-2020</u> DATE COMPLETED <u>4-20-2020</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Charles</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Jones Burnett</u>	JOB NUMBER
PROBLEM: <u>Service</u>				
REPAIRED: <u>Serviced</u>				
PARTS: <u>All Filters</u> <u>413.30</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1006</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>D6k-2</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>7500 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE <u>8-17-20</u> DATE COMPLETED <u>8-18-20</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Bert James</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>James Brunnet</u>	JOB NUMBER _____
PROBLEM: <u>Service</u>				
REPAIRED: <u>serviced</u>				
<u>changed out door leak RT rear door</u>				
PARTS: <u>All Filters</u> <u>483.⁶⁶</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1006</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>D6K-2</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>8K HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>11-16-20</u> DATE COMPLETED <u>11-17-20</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>All</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>Tilt cylinder & pitch rod bearings loose.</u> <u>Service</u>				
REPAIRED: <u>replaced Tilt cylinder and pitch rod</u> <u>bearings & pins</u> <u>serviced</u>				
PARTS: <u>Pins, bearings & Filters 1192.44 Thompson</u> <u>Filters & Pins 1151.13 Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>1006</u> MAKE <u>Cat</u> MODEL <u>D6K-2</u> SERIAL # _____ HOUR METER <u>8,500 HRS</u> MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE <u>3-3-21</u> DATE COMPLETED <u>3-5-21</u> MECHANIC <u>Ben</u> JOB NAME/LOCATION <u>Eastgate</u> JOB NUMBER _____
PROBLEM: <u>Service</u> _____ _____		
REPAIRED <u>Service</u> _____ _____ _____ _____ _____ _____		
PARTS: <u>All Filters</u> <u>503.64</u> <u>Thompson</u> _____ _____ _____ _____		

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1006</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>D6K-2</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>3-30-21</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Eastgate</u>	JOB NUMBER
PROBLEM: <u>Anti-Freeze leak</u>				
REPAIRED: <u>plastic coolant tank cracked. replaced tank and two hoses</u>				
PARTS: <u>Tank & 2 hoses</u> <u>417.92</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1006</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>D6K-2</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>9K NRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>5-7-21</u> DATE COMPLETED <u>5-18-21</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Eastgate</u>	JOB NUMBER _____
PROBLEM: <u>Service</u>				
REPAIRED: <u>Serviced</u>				
PARTS: <u>All Filters</u> <u>457.56</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1006</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>D6K</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>11K HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>5-2-22</u> DATE COMPLETED <u>5-5-22</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>All</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>service & service DPF</u>				
REPAIRED: <u>serviced, serviced DPF, replaced both door seals</u>				
PARTS: <u>DPF Clean</u> <u>454.75</u> <u>Emissions solutions</u>				
<u>ALL Filters</u> <u>521.31</u> <u>Thompson</u>				
<u>2-door seals</u> <u>298.52</u> <u>Thompson</u>				
<u>Silicone</u> <u>17.98</u> <u>Advance</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1006</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>DGK-2</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: <u>7-1-21</u> DATE COMPLETED <u>7-2-21</u> MECHANIC <u>Ben</u>	
PROBLEM: <u>monitor warning.</u>			JOB NAME/LOCATION <u>Cave Station</u>	JOB NUMBER
REPAIRED: <u>replaced blade sensor + blade control handle</u>				
PARTS: <u>Sensor</u> <u>453.25</u> <u>Thompson</u> <u>RT hand control</u> <u>938.55</u> <u>Thompson</u> <u>266-7632</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1006</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>D6K-2</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>9,600 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>8-26-21</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>ALL</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>A/C quit, needs sprockets & rails</u> <u>pitch arm bearings worn out</u>				
REPAIRED: <u>replaced pitch arm pins & bearings.</u> <u>replaced A/C comp. accumulator & orifice tube.</u> <u>washed out evaporator new alt. A/C belt.</u> <u>greased</u>				
PARTS: <u>pins & bearings</u> <u>574.95</u> <u>Thompson</u>				
<u>Accumulator</u> <u>125.54</u> <u>Thompson</u>				
<u>Compressor</u>				
<u>Hardware</u> <u>12.55</u> <u>Thompson</u>				
<u>Belt</u> <u>57.07</u> <u>Thompson</u>				
<u>Orifice</u> <u>39.54</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1006</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>D6K-2</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>10K HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE <u>11-9-21</u> DATE COMPLETED <u>11-12-21</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>All</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____	
PROBLEM: <u>Service</u>				
REPAIRED: <u>Serviced</u>				
PARTS: <u>All Filters</u> <u>442.175</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1006</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>D6K-2</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>1-4-22</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC _____		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION _____		
		JOB NUMBER _____		
PROBLEM: <u>hyd. line busted from rust</u>				
REPAIRED: <u>replaced line</u>				
PARTS: <u>Tube & seals</u> <u>408.312</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1006</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>D6K-2</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>11,119 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE <u>6-13-22</u> DATE COMPLETED <u>6-24-22</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>To Shop</u>	JOB NUMBER
PROBLEM: <u>Anti-freeze in oil</u>				
<u>water pump bad</u>				
REPAIRED: <u>replaced water pump, thermostat & radiator hoses, flushed engine, washed machine</u>				
PARTS: <u>w/pump & Thermostat 473.⁴⁰</u> <u>Thompson</u>				
<u>hoses 134.¹⁵</u> <u>Thompson</u>				
<u>stat 113.⁶⁷</u> <u>Thompson</u>				
<u>Gasket 86.⁵²</u> <u>Thompson</u>				
<u>Filter Housing 158.⁴⁴</u> <u>Thompson</u>				
<u>Filter & sensor 246.⁷⁵</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1006</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>D6K-2</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: <u>7-6-22</u> DATE COMPLETED <u>7-22-22</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Ben</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>To Shop</u> JOB NUMBER _____		
PROBLEM: <u>A/C Quit</u>				
REPAIRED: <u>replaced comp. driver & orifice tube</u>				
<u>blower motor cond. fan. flushed system</u>				
PARTS: <u>Blower motor</u> <u>713.⁹⁹</u> <u>Thompson</u>				
<u>Accum & O. Tube</u> <u>225.⁷²</u> <u>Thompson</u>				
<u>Condenser Fan</u> <u>431.²¹</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1006</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>DSK</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>11,500 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: <u>9-8-22</u> DATE COMPLETED <u>9-19-22</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Anthony + Brian</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Limestone</u>	JOB NUMBER	
PROBLEM: <u>Service</u>				
REPAIRED: <u>Serviced</u>				
PARTS: <u>All Filters</u> <u>599.82</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 1006

MAKE Cat

MODEL D6K

SERIAL # _____

HOUR METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 10-12-22

MECHANIC Anthony

JOB NAME/LOCATION

Limestone

JOB NUMBER

PROBLEM: needs batteries

REPAIRED: replaced batteries

PARTS: 2-MT 27

244.49

Interstate battery

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1006</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>D6K-2</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: <u>10-31-22</u> DATE COMPLETED <u>11-1-22</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Ben</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Carter Town Homes</u> JOB NUMBER _____		
PROBLEM: <u>hyd leak</u>				
REPAIRED: <u>replaced Trans. cooler hose</u>				
PARTS: <u>hose and adapters</u> <u>373.⁰⁸</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 1006

MAKE Cat

MODEL D6K

SERIAL # _____

HOUR METER 12K HRS

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON _____

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 2-28-23

MECHANIC A. Thompson

JOB NAME/LOCATION
Sub Station

JOB NUMBER _____

PROBLEM: Service

REPAIRED: serviced

PARTS: Filters

614 LE

Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1006</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>D6K-2</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>12,500 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE <u>5-30-23</u> DATE COMPLETED <u>6-20-23</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC _____	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>Service, A/C system</u>				

REPAIRED: Serviced, replaced condenser, one fan and sensors. Put Dye in system.
Tightened comp clutch relay tabs in fuse box.

PARTS: <u>Filter</u>	<u>611.79</u>	<u>Thompson</u>
<u>condenser, fan motor & sensors</u>	<u>2205.44</u>	<u>Thompson</u>
<u>6</u>	<u>1200 20</u>	<u>Thompson</u>
<u>relays - 3</u>	<u>175.15</u>	<u>Thompson</u>

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 1006

MAKE CAT

MODEL D6K-2

SERIAL # _____

HOUR METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON _____

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: 7-7-23 DATE COMPLETED _____

MECHANIC Anthony & Justin

JOB NAME/LOCATION

To stop

JOB NUMBER

PROBLEM: A/C leak

REPAIRED: replaced evaporator, drier & hoses.
Filled system

PARTS: haver + Drie 595.69

Evaporator + orifice tube 538.14
52.54

Thompson
Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1006</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>D6K</u>		PARTS LABOR	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>13K HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE <u>2-2-24</u> DATE COMPLETED <u>3-20-24</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Anthony</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION	JOB NUMBER
PROBLEM: <u>Service</u>				
REPAIRED: <u>serviced</u>				
PARTS: <u>Filters</u> <u>624.07</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>1006</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>D6K-2</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>13500 HRS</u>				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE: _____ DATE COMPLETED <u>4-2-25</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC <u>Bryon</u>	
SMOKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION <u>Quail Run</u>	
				JOB NUMBER _____	
PROBLEM: <u>Service</u>					
REPAIRED: <u>serviced</u>					
PARTS: <u>filters</u> <u>1,178.26</u> <u>Thomson</u>					