

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0519

MAKE Volvo

MODEL EC380

SERIAL # _____

HOOR METER 1K HRS

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 1-23-23

MECHANIC Anthony

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: Service

REPAIRED: serviced

PARTS: Filters

628.12

Scott Equipment

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0519</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Volvo</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>EC 380</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>1500 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE <u>5-19-23</u> DATE COMPLETED <u>5-22-23</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Anthony + Brian</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Stone Trace</u>	
PROBLEM: <u>Service</u>			JOB NUMBER _____	
REPAIRED: <u>Serviced</u>				
PARTS: <u>Scooter Filters 313.28</u> <u>Scott Equipment</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
UP: # <u>0519</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Volvo</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>EC380</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>2K HRS</u>				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE <u>8-10-23</u> DATE COMPLETED <u>8-17-23</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC <u>Anthony</u>	
SMOKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION <u>Stone Trace</u>	
PROBLEM: <u>Service</u>				JOB NUMBER _____	

REPAIRED: Serviceed

PARTS: Filters

1339.11

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0519

MAKE Volvo

MODEL EC380

SERIAL # _____

HOURLY METER 2500 HR

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE 10-31-23 DATE COMPLETED 11-2-23

MECHANIC _____

JOB NAME/LOCATION

Stone Trace

JOB NUMBER

PROBLEM: Service

REPAIRED: Service

PARTS: Filters

324, ²³

Scott Equipment

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0519</u>	HOURS _____ DAYS _____	REASON	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Volvo</u>			POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>EC380</u>	PARTS	LABOR	COMPONENT LOCATION	
SERIAL # _____	OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
OUR METER <u>3500 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>10-28-24</u> DATE COMPLETED <u>10-29-24</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Anthony</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION	JOB NUMBER
			<u>Quail Run</u>	
PROBLEM: <u>Service</u>				
REPAIRED: <u>serviced</u>				
PARTS: <u>Filters</u> <u>615. 87</u> <u>Scott Equipment</u>				

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
IP. #	0519	HOURS	DAYS	BASIC MACHINE	HYDRAULIC ENGINE IMPLEMENTS
VE	Volvo	REASON		POWER TRAIN	ELECTRIC DRIVE TRAIN UNEXPLAINED
DEL	EC380	PARTS	LABOR	COMPONENT LOCATION	
IAL #		OTHER		FRONT	REAR LEFT RIGHT UPPER LOWER
OUR METER	4K HRS			OTHER	
ES					
ASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: DATE COMPLETED 8-13-25		
ERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC		
OKES SHORTED VIBRATE OTHER			JOB NAME/LOCATION		
			JOB NUMBER		
BLEM: Service					
EPAIRED: serviced					
RTS: Filters 1057.4 Scott Equipment					

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
IP. # <u>0519</u>	HOURS _____ DAYS _____ REASON PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS			
MAKE <u>Volvo</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED			
MODEL <u>EC380</u>		COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER			
SERIAL # _____		OTHER _____			
HOUR METER _____					
REMARKS _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>8-25-20</u>			
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Bryan</u>			
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>TCAT</u>		JOB NUMBER	
PROBLEM: <u>Def Failure</u>					

REPAIRED: replaced def armature

PARTS: Armature 1751.30 Scott Equipment

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

PARTS: Amature 1,715.38

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0519</u>	REASON PARTS LABOR OTHER	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Volvo</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>EC380</u>		COMPONENT LOCATION	
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____	OTHER _____		
MILES _____			

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE <u>1-29-26</u> DATE COMPLETED <u>2-4-26</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC <u>Ben</u>
SMOKES SHORTED VIBRATE OTHER _____	JOB NAME/LOCATION <u>Mint Substation</u> JOB NUMBER _____

PROBLEM: Tree branch went into cab. Battery not charging.

REPAIRED: Lawrence Glass replaced front upper and lower windows. Straightened travel controls. Replaced broken monitor Display. Replaced bad Alt. belt.

PARTS: <u>Seal strip</u>	<u>139.³⁴</u>	<u>Scott Equipment</u>
<u>upper and lower front glass</u>	<u>514.⁷³</u>	<u>Lawrence glass</u>
<u>V-belt</u>	<u>91.²⁸</u>	<u>Scott Equipment</u>
<u>Display</u>	<u>2757.⁰⁸</u>	<u>Scott Equipment</u>