

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0114</u>	MAKE <u>Chevy</u>	HOURS _____ DAYS _____	BASIC MACHINE	HYDRAULIC ENGINE IMPLEMENTS
MODEL <u>03' 3500</u>	SERIAL # _____	REASON _____	POWER TRAIN	ELECTRIC DRIVE TRAIN UNEXPLAINED
HOUR METER _____	MILES <u>323,580 mi</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
			OTHER <u>6092.00</u>	
			<u>171.66</u>	<u>Reparts</u>
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE <u>10-25-23</u> DATE COMPLETED <u>11-21-23</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Bryan & All</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____		
PROBLEM <u>(rebuild Engine) removed engine re. mixed</u> <u>new valve seals & new oil pump & water pump.</u> <u>new injection pump & injector. replaced carrier bearing.</u>				
REPAIRED: <u>rebuild engine</u> <u>2 batteries 330.00</u> <u>replaced Trans oil & filter</u> <u>Interstate</u> <u>bearing</u> <u>55.35</u> <u>Advance</u> <u>switch, bearing & oil</u> <u>141.18</u> <u>Advance</u> <u>pump</u> <u>main seal</u> <u>51.66</u> <u>Advance</u> <u>3257.25</u> <u>Advance</u> <u>hoses</u> <u>34.49</u> <u>Advance</u> <u>Trj.</u> <u>Thermostat Kit</u> <u>46.73</u> <u>Advance</u>				
PARTS: <u>Engine Kit</u> <u>1800.00</u> <u>Nash Engine Parts</u> <u>Oil pump</u> <u>252.41</u> <u>Auto Zone</u> <u>Mounts & w/pump</u> <u>248.69</u> <u>Advance</u> <u>Trj's seal Kit</u> <u>62.67</u> <u>Advance</u> <u>Filter</u> <u>Sealing Unit</u> <u>300.00</u> <u>Advance</u> <u>19.92</u> <u>Space plate</u> <u>60.00</u> <u>Ebay</u> <u>Filters</u> <u>116.97</u> <u>Tenn Filter</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0114</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Chery</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>3500</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>1-29-29</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Lawrence</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>broken windshield</u>				
REPAIRED: <u>replaced windshield</u>				
PARTS: <u>glass</u> <u>394.⁰⁰</u> <u>Lawrence Glass</u>				

TEC

THORNES EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # 0114		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE Chevy		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL 03 3500		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER		OTHER _____		OTHER _____	
MILES 329,291 mi		DATE: 4-23-24		DATE COMPLETED	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		MECHANIC Bryan & All		JOB NAME/LOCATION	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		JOB NUMBER		Shop	
SMOKES SHORTED VIBRATE OTHER		PROBLEM: upper control arm bushings loose			

REPAIRED: Replaced upper control arm on both sides
 New front tires Alignment
 Replaced lower ball joints, pitman arm & idle air,
 New steer shock.

PARTS: Upper Arms 157.43 Advance
 2.60H K.i.t.s 94.45 Advance
 2-Tires alignment 492.34 Charles Tire
 alignment 186.52 Charles Tire
 lower ball joints & pitman idls 296.17 Advance

52.95 Steer shock Advance

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0114</u>	HOURS _____ DAYS _____ REASON PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>Cheng</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>3500</u>		COMPONENT LOCATION		
SERIAL # <u>Bryan</u>		FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>8-22-24</u>	MECHANIC <u>Charlie's Tire</u>	
		JOB NAME/LOCATION <u>Charlie's Tire</u>	JOB NUMBER	
PROBLEM: <u>Tires</u>				
REPAIRED: <u>replaced 4 tires</u>				
PARTS: <u>4 - LT 215/85-16 Firestone 984.60 Charlie's Tire</u>				