

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 02017
 MAKE Rogers
 MODEL 55T
 SERIAL # 31793
 HOUR METER Trailer
 MILES new

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
 REASON _____
 PARTS _____ LABOR _____
 OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
 POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER
 OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
 OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
 SMOKES SHORTED VIBRATE OTHER _____

DATE 1-28-21 DATE COMPLETED _____

MECHANIC ALL

JOB NAME/LOCATION

Shop

JOB NUMBER

PROBLEM: set up

REPAIRED: Installed center deck boards

changed hydr quick connects to match Truck
TEC decals + numbers

Made rear wide load sign brackets

Installed storage screen in front center of deck

PARTS: hydr quick connects 172.42 Nashville Rubber & Gasket
5100 - \$2.16B

Decals

wide load sign

boards

121.58

230.00

ADVANCE signs

My Tee supply

lowes

Hard ware

chains

40.00

75.75

TSC

GIS

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0207

MAKE Rogers

MODEL 55T

SERIAL # Trailer

HOURLY METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON _____

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 7-12-23

MECHANIC CSK

JOB NAME/LOCATION

JOB NUMBER

shop

PROBLEM: new binders chains & hooks

REPAIRED: _____

PARTS: Binders chains & hooks 3,543.75

CIJ

TEC

THORNE'S EXCAVATING COMPANY, LLC SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0207</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Rogers</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>55T Trailer</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE <u>6-29-23</u> DATE COMPLETED <u>8-29-23</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC <u>All</u>	
SMOKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION <u>shop</u> JOB NUMBER _____	
PROBLEM: <u>needs deck boards</u>					

REPAIRED: replaced all deck boards, put deck boards in middle.

PARTS: boards
Hardware
1/2 x 4 1/2

215.40

Saw mill Sparta PK.
Action bolt

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIPMENT DOWNTIME

COMPONENT CODES

EQUIP. # 0207
 MAKE Rogers SST
 MODEL SST
 SERIAL # _____
 HOUR METER _____
 MILES _____

HOURS _____ DAYS _____
 REASON _____
 PARTS _____ LABOR _____
 OTHER _____

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
 POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
 COMPONENT LOCATION
 FRONT REAR LEFT RIGHT UPPER LOWER
 OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
 OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
 SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 5-9-25
 MECHANIC Ben

JOB NAME/LOCATION
TCAT

JOB NUMBER

PROBLEM: 2 broken hoses

REPAIRED: replaced two brake hoses.

PARTS 2 brake hoses 187.76 Nashville Rubber & Gasket

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
IP. # <u>0207</u>		HOURS _____ DAYS _____		BASIC MACHINE	HYDRAULIC ENGINE IMPLEMENTS
NAME <u>Rogers</u>		REASON _____		POWER TRAIN	ELECTRIC DRIVE TRAIN UNEXPLAINED
DEL <u>55-T</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
IAL # <u>Trailer</u>		OTHER _____		FRONT	REAR LEFT RIGHT UPPER LOWER
OUR METER _____				OTHER _____	
ES _____					
ASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>7-10-25</u>		
ERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Twider</u>		
OKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Twider</u>		
			JOB NUMBER _____		
BLEM: <u>hole in tire, can't repair</u>					
E PAIRED: <u>replaced 2 left center Axle</u>					
RTS: <u>275 70R22.5 16R. 685.58 Twider Tire</u>					

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
IP. # <u>0207</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
NAME <u>Rogers</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>55T Trailer</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
REMARKS _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>7-25-25</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Snider</u>	
SHORTS SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Snider</u>	JOB NUMBER
PROBLEM: <u>Tires</u>				

REPAIRED: replaced six tires

PARTS: 6 Tires 1950.00 Snider