

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0305</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>420F</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # <u>HWC01147</u>	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: <u>11-13-17</u>	DATE COMPLETED <u>11-14-17</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>James</u>	
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>Smashed hydraulic line on right stabilizer</u>			
REPAIRED: _____ _____ _____ _____ _____ _____			
PARTS: <u>lined o-rings</u> <u>60. ER</u> <u>Thompson</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963


EQUIPMENT INFORMATION EQUIP. # <u>0305</u> MAKE <u>CAT</u> MODEL <u>420F</u> SERIAL # _____ HOUR METER <u>LOW MRS</u> MILES _____		EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>2-1-18</u> MECHANIC <u>Steven B</u>		
PROBLEM: <u>Service</u>		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER	
REPAIRED: <u>serviced</u>				
PARTS: <u>All Filters</u>		<u>343.50</u>	<u>Thompson Machinery</u>	

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0305</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>470F</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>3-9-18</u> MECHANIC <u>Eric</u>	
PROBLEM: <u>Teeth pins retainers</u>		JOB NAME/LOCATION <u>Town Center</u>	JOB NUMBER
REPAIRED: _____ _____ _____ _____ _____ _____			
PARTS: <u>Teeth, pins, & retainers 92.78 Thompson</u> _____ _____ _____			



THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

<p>EQUIPMENT INFORMATION</p> <p>EQUIP. # <u>0305</u></p> <p>MAKE <u>CAT</u></p> <p>MODEL <u>420F</u></p> <p>SERIAL # _____</p> <p>HOUR METER _____</p> <p>MILES _____</p>	<p>EQUIPMENT DOWNTIME</p> <p>HOURS _____ DAYS _____</p> <p>REASON</p> <p>PARTS _____ LABOR _____</p> <p>OTHER _____</p>	<p>COMPONENT CODES</p> <p>BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS</p> <p>POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED</p> <p>COMPONENT LOCATION</p> <p>FRONT REAR LEFT RIGHT UPPER LOWER</p> <p>OTHER _____</p>
<p>REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED</p> <p>OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH</p> <p>SMOKE SHORTED VIBRATE OTHER _____</p>	<p>DATE: _____ DATE COMPLETED <u>10-11-18</u></p> <p>MECHANIC <u>Charles</u></p> <p>JOB NAME/LOCATION <u>Beckwith west</u></p> <p>JOB NUMBER _____</p>	
<p>PROBLEM: <u>needs front tires</u></p>		
<p>REPAIRED: <u>new front tires</u></p>		
<p>PARTS: <u>2-12.5/80-18</u> <u>524.40</u> <u>Gateway Tire</u></p> <p><u>Dee Stone</u></p>		

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0305</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>420F2</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>1500 HRS</u>		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE <u>10-22-18</u>	DATE COMPLETED _____
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC _____	
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Beckwith</u>	JOB NUMBER _____
PROBLEM: <u>Needs serviced</u>			
REPAIRED: <u>Serviced</u>			
PARTS: <u>All Filters</u> <u>274.⁷⁶</u> <u>Thompson</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0305</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>420F</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>1-28-19</u> DATE COMPLETED <u>1-28-19</u>	MECHANIC <u>Charles</u>
PROBLEM: <u>vandalism</u>		JOB NAME/LOCATION <u>Legends Dr</u>	JOB NUMBER
REPAIRED: <u>replaced rear view mirror & RT turn signal lamp</u>			
PARTS: <u>mirror</u>		<u>25.87</u>	<u>Thompson</u>

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>305</u> MAKE <u>CAT</u> MODEL <u>420F</u> SERIAL # _____ HOUR METER _____ MILES _____	HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: _____ DATE COMPLETED <u>3-5-19</u> MECHANIC <u>Charles</u> JOB NAME/LOCATION <u>Kenne Place</u> JOB NUMBER _____	
PROBLEM: <u>missing teeth on rear bucket</u>		
REPAIRED: <u>replaced missing teeth</u>		
PARTS: <u>Teeth</u> <u>121.00</u> <u>Thompson</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>0305</u> MAKE <u>CAT</u> MODEL <u>420FL</u> SERIAL # _____ HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE <u>6-12-19</u> DATE COMPLETED <u>6-20-19</u> MECHANIC <u>Charles</u>	JOB NAME/LOCATION <u>Towne Place</u> JOB NUMBER _____
PROBLEM: <u>Tilt cylinder not holding</u>		
REPAIRED: <u>replaced cylinder</u>		
PARTS: <u>Cylinder Kit</u> <u>58.32</u> <u>Thompson</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0305</u> MAKE <u>CAT</u> MODEL <u>420F</u> SERIAL # _____ HOUR METER _____ MILES _____	HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: _____ DATE COMPLETED <u>10-10-19</u> MECHANIC <u>BRYAN</u>	
JOB NAME/LOCATION		JOB NUMBER
PROBLEM: <u>Bucket teeth</u>		
REPAIRED: <u>replaced missing teeth</u>		
PARTS: <u>4-teeth 8-pins + 8-retainers 172.31 Thompson</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0305</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>420F</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>2500 HRS</u>		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>12-2-19</u> DATE COMPLETED <u>12-7-19</u> MECHANIC <u>Bryan & Ben</u>	
		JOB NAME/LOCATION <u>Ashland Farms</u>	JOB NUMBER
PROBLEM: <u>Service</u>			
REPAIRED: <u>serviced</u>			
PARTS: <u>All Filters</u> <u>301.49</u> <u>Thompson</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0305</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>420F</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>8-24-20</u>	
		MECHANIC <u>Caleb</u>	
		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>seat bottom split all the way across</u>			
REPAIRED: <u>replaced seat bottom</u>			
PARTS: <u>bottom</u> <u>170.⁰⁵</u> <u>Thompson</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0305</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>420F</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>9-21-20</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Shops Gateway</u>	JOB NUMBER
PROBLEM: <u>needs steer tires</u>			
REPAIRED: <u>replaced steer tires</u>			
PARTS: <u>2- steer tires 480.⁰⁰</u> <u>Gateway Tire</u>			
<u>12.5/80-18</u>			
<u>12PL</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0305</u> MAKE <u>CAT</u> MODEL <u>420F</u> SERIAL # _____ HOUR METER _____ MILES _____	HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: <u>10-19-20</u> DATE COMPLETED <u>10-20-20</u> MECHANIC <u>Ben</u>	
JOB NAME/LOCATION _____		JOB NUMBER _____
PROBLEM: <u>blown hose and bad hose to front bucket</u>		
REPAIRED: <u>replaced both hoses</u>		
PARTS: <u>2 hoses</u>		<u>Thompson</u>

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0305</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>420F</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER <u>3K HRS</u>	OTHER _____	OTHER _____
MILES _____	OTHER _____	OTHER _____
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE <u>5-19-21</u> DATE COMPLETED <u>6-4-21</u>	
	MECHANIC <u>James</u>	
JOB NAME/LOCATION _____	JOB NUMBER _____	
PROBLEM: <u>service</u>		
REPAIRED: <u>serviced replaced missing back up alarm replaced RT front valve stem.</u>		
PARTS: <u>All Filters 291.⁰⁰ Thompson</u> <u>back up alarm 54.⁰⁰ Napa</u> <u>speed sensor 173.⁴⁸ Thompson</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>0305</u> MAKE <u>CAT</u> MODEL <u>0305 420F</u> SERIAL # _____ HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: <u>4-25-22</u> DATE COMPLETED <u>5-18-22</u> MECHANIC <u>James</u>	JOB NAME/LOCATION: <u>Shop</u> JOB NUMBER _____
PROBLEM: <u>needs cutting edge</u>		
REPAIRED: <u>replaced edge</u>		
PARTS: <u>Edges and bolts</u> <u>471.86</u> <u>Thompson</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0305</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Cat</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>410F</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER <u>3,500 HRS</u>		OTHER _____
MILES _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>9-12-22</u> MECHANIC <u>Anthony</u>
JOB NAME/LOCATION		JOB NUMBER
<u>shop</u>		
PROBLEM: <u>bael pedal service</u>		
REPAIRED: <u>replaced pedal, serviced and washed</u>		
PARTS: <u>Pedal</u>	<u>241.34</u>	<u>Thompson</u>
<u>All Fitters</u>	<u>395.15</u>	<u>Thompson</u>

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0305</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>420F</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>12-5-22</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Anthony</u>
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>West Trinity</u>
		JOB NUMBER _____
PROBLEM: <u>needs rear tires</u>		
REPAIRED: <u>replaced rear tires</u>		
PARTS <u>2 - 19.5-24 Goodyear 1736.81</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0305</u> MAKE <u>Cat</u> MODEL <u>420F</u> SERIAL # _____ HOUR METER <u>4K HRS</u> MILES _____	HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: <u>1-23-23</u> DATE COMPLETED <u>1-24-23</u> MECHANIC <u>Anthony</u> JOB NAME/LOCATION <u>Limestone Trail</u> JOB NUMBER _____	
PROBLEM: <u>Service</u>		
REPAIRED: <u>serviced</u>		
PARTS: <u>Filter</u> <u>357. PC</u> <u>Thompson</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0305</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MAKE <u>CAT</u>	REASON _____	COMPONENT LOCATION	
MODEL 420F <u>420F</u>	PARTS _____ LABOR _____	FRONT REAR LEFT RIGHT UPPER LOWER	OTHER _____
SERIAL # _____	OTHER _____	OTHER _____	
HOUR METER _____		DATE <u>5-7-24</u> DATE COMPLETED <u>5-8-24</u>	
MILES _____		MECHANIC <u>Brian</u>	JOB NAME/LOCATION
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		JOB NUMBER	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		<u>Shop</u>	
SMOKES SHORTED VIBRATE OTHER _____		PROBLEM: <u>needs batteries</u>	
		REPAIRED: <u>replaced batteries</u>	
		PARTS: <u>2-MTP-65D</u> <u>335²²</u> <u>IB5</u>	

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	
EQUIP. #	HOURS	REASON	DAYS
0305			
MAKE	PARTS	LABOR	OTHER
CAT			
MODEL	SERIAL #		
420F			
HOUR METER		MILES	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			
SMOKES SHORTED VIBRATE OTHER			
JOB NAME/LOCATION		JOB NUMBER	
Wilson Justice			
MECHANIC		DATE	
Ben		4-29-25	
DATE COMPLETED		6-16-25	
COMPONENT CODES			
BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS			
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED			
COMPONENT LOCATION			
FRONT REAR LEFT RIGHT UPPER LOWER			
OTHER			
PROBLEM: broken flow selector			
REPAIRED: replaced switch			
PARTS: switch			
46.00			
Thompson			