

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>2601</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Power screen</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>Crusher</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE: <u>2-5-25</u> DATE COMPLETED _____	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION	
				<u>Shop</u>	
JOB NUMBER					
PROBLEM: <u>Tension rod repair</u>					
REPAIRED: <u>replaced saddle, tension rod and bushings.</u>					
PARTS: <u>bush assembly, sleeve & bolt 751.88</u> 751.88					
<u>5/16" + pins 1279.45 Power screen</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>2601</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Power Screen</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>400</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # <u>Crusher</u>		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: _____ DATE COMPLETED <u>10-13-2020</u> MECHANIC <u>Ben</u>	
			JOB NAME/LOCATION <u>Water Town Farm</u>	JOB NUMBER _____
PROBLEM: <u>one battery bad</u>				
REPAIRED: <u>replaced bad battery</u>				
PARTS: <u>1-4DLT-VHD</u> <u>164.57</u> <u>Interstate Battery</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>2601</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Power screen</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>400</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # <u>Crusher</u>		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>1800 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: ☐ BROKEN ☐ WORN ☐ ABUSE ☐ LOOSE ☐ SEIZED		DATE <u>5-3-21</u> DATE COMPLETED <u>5-5-21</u>		
☐ OVERHEAT ☐ PLANNED ☐ CONTAM ☐ LEAKING ☐ NOISY ☐ SCRATCH		MECHANIC <u>Ben + Caleb</u>		
☐ SMOKES ☐ SHORTED ☐ VIBRATE ☐ OTHER _____		JOB NAME/LOCATION <u>Eastgate</u>	JOB NUMBER _____	
PROBLEM: <u>Service</u>				
REPAIRED: <u>serviced</u>				
PARTS: <u>All Filters</u> <u>963.39</u> <u>Powerscreen Parts & Service</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>2601</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Power Screen</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>Crusher</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>1-12-22</u> DATE COMPLETED _____	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC _____	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION _____	JOB NUMBER _____
PROBLEM: <u>needs batteries</u>				
REPAIRED: <u>replaced batteries</u>				
PARTS: <u>2-4DLT</u> <u>329.14</u> <u>Interstate battery</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>2601</u> MAKE <u>Power Sreen</u> MODEL <u>400 Crusher</u> SERIAL # _____ HOUR METER _____ MILES _____		EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____		COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____				DATE: _____ DATE COMPLETED <u>3-15-22</u> MECHANIC <u>Ben</u>	
PROBLEM: <u>blown hyd hose</u>				JOB NAME/LOCATION <u>West Trinity</u> JOB NUMBER _____	
REPAIRED: <u>replaced hose</u>					
PARTS: <u>hose</u> <u>301. GP</u> <u>IR+G</u>					

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>2601</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Powerscreen</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>400 Crusher</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: ☐ BROKEN ☐ WORN ☐ ABUSE ☐ LOOSE ☐ SEIZED			DATE: <u>1-11-22</u> DATE COMPLETED _____	
OVERHEAT ☐ PLANNED ☐ CONTAM ☐ LEAKING ☐ NOISY ☐ SCRATCH			MECHANIC _____	
SMOKES ☐ SHORTED ☐ VIBRATE ☐ OTHER _____			JOB NAME/LOCATION <u>Stone Trace</u>	JOB NUMBER _____
PROBLEM: <u>hopper cylinder rod bent</u>				
REPAIRED: <u>rebuilt cylinder</u>				
PARTS: <u>Mid south hydraulics</u> <u>\$1,100⁰⁰</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>2601</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Power screen</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>400 Crusher</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>2200 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>1-24-23</u> DATE COMPLETED <u>1-28-23</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC _____	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Stone Trace</u> JOB NUMBER _____	
PROBLEM: <u>Service</u>				
REPAIRED: <u>Serviced</u>				
PARTS: <u>Filters</u> <u>Power screen</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. #	2601	HOURS	DAYS	BASIC MACHINE	HYDRAULIC ENGINE IMPLEMENTS
MAKE	Powerscreen	REASON		POWER TRAIN	ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL	400 Crusher	PARTS	LABOR	COMPONENT LOCATION	
SERIAL #		OTHER		FRONT	REAR LEFT RIGHT UPPER LOWER
HOUR METER	2540 HRS			OTHER	
MILES					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE	5-11-23
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				DATE COMPLETED	
SMOKES SHORTED VIBRATE OTHER				MECHANIC	Ben & Brian
PROBLEM: return roller, bad speed wheel, weld hopper bars.				JOB NAME/LOCATION	Stone Trace
				JOB NUMBER	

REPAIRED: replaced one return roller, speed wheel And welded hopper bars. Jammed

PARTS	QUANTITY	PRICE
roller + wheel	1	155.00
filter in stock		
Eg. cooler repair	1	392.31
		Powerscreen