

EQUIPMENT
REPAIRS

DATE 5-9-07

MILEAGE/HOURS 2290

EQUIPMENT REPAIRED #108 518

REPAIRS MADE Bolts, Lock washers, Nuts, Adapters

HOURS WORKED _____

PARTS USED

Bolts
Nuts
washers \$212.91
Adapters

Pins
Retainers) \$58.28
10 Tips - \$193.16
4T-2203

8-Tips \$154.53

8-Pin's
4- Lockwasher
4- NUTS
4- capscrews
4- Adapters
1- filter \$180.00

EQUIPMENT
REPAIRS

DATE 10-11-07

MILEAGE/HOURS _____

EQUIPMENT REPAIRED ~~710~~ #108 815

REPAIRS MADE Complete Service Pack

Both steering cylinders replace valve
cover gasket & Breather changed hydro
oil.

HOURS WORKED _____

PARTS USED

All Filters \$ 140.78

Bolt Seal \$ 17.00

2 Seal Kits \$ 186.39

(cap screw
seal ring
Gasket
Breather \$ 70.96

(o-ring
Gasket
Gasket \$ 4.85

EQUIPMENT
REPAIRS

DATE 12-8-07

MILEAGE/HOURS _____

EQUIPMENT REPAIRED #108 518 compactor

REPAIRS MADE replaced electric fuel pump.

HOURS WORKED _____

PARTS USED

pump \$71.⁰⁶ Crooks

EQUIPMENT
REPAIRS

DATE 2-4-08

MILEAGE/HOURS _____

EQUIPMENT REPAIRED #108 515 skidder

REPAIRS MADE Removed and sealed steering valve.
welded it. step. replaced oil line to
press. gauge.

HOURS WORKED _____

PARTS USED

Steer valve o-rings \$ 38.29 Thompson
oil line kit 11.46 NAPA

EQUIPMENT
REPAIRS

DATE 10-1-08

MILEAGE/HOURS _____

EQUIPMENT REPAIRED #108 578 Skidder

REPAIRS MADE Replaced o-ring and back ring
on left steer cylinder

HOURS WORKED _____

PARTS USED

2-o-ring	\$17.39	Thompson
2-back ring		

EQUIPMENT
REPAIRS

DATE 12-3-08

MILEAGE/HOURS _____

EQUIPMENT REPAIRED #108 518 Cat

REPAIRS MADE replaced water pump

HOURS WORKED _____

PARTS USED

water-pump

520.⁰⁰

Anti-freeze

\$62.⁸²

Thompson

EQUIPMENT
REPAIRS

DATE 1-20-08

MILEAGE/HOURS _____

EQUIPMENT REPAIRED #108 518 Skidder

REPAIRS MADE _____

HOURS WORKED _____

PARTS USED

Hyd Filter	13. ⁷⁸	Thompson
Seals	10. ³⁹	
Pumps	767. ⁰⁴	

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963


EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>108</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS			
MAKE <u>CAT</u>	REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED			
MODEL <u>518 skidder</u>	PARTS LABOR	COMPONENT LOCATION			
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER			
HOUR METER <u>2,750</u>		OTHER _____			
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____		DATE COMPLETED <u>3-26-09</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Daniel & Janet</u>			
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION		JOB NUMBER	
PROBLEM: <u>oil in Air system, leaks, service</u>					
REPAIRED: <u>Serviced. Replaced comp. removed dryer removed All dryer lines. Sealed blade control valve. Cleaned out Front belly pan.</u>					
PARTS: <u>Filters seals, Bearings 233.29 Thompson</u>					
<u>Air comp. 488.50 + shipping White House Equipment</u>					
<u>Filter seal 34.00 Thompson</u>					
<u>Seal 6.22 Thompson</u>					
<u>Dryer kit 134.47 credit Thompson</u>					
<u>Hoses 266.17 NAPA</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>108</u>	HOURS _____ DAYS _____	REASON PARTS _____ LABOR _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>			POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>518</u>	OTHER _____	OTHER _____	COMPONENT LOCATION	
SERIAL # _____			FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: _____ DATE COMPLETED <u>10-24-09</u> MECHANIC <u>James</u>	
			JOB NAME/LOCATION <u>MT Juliet</u>	JOB NUMBER
PROBLEM: <u>bad solenoid</u>				
REPAIRED: <u>replaced starter solenoid</u>				
PARTS: <u>Solenoid</u> <u>86.34</u> <u>Crooks</u>				




THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>108</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>518</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____				DATE: _____ DATE COMPLETED <u>11-12-09</u>	
				MECHANIC <u>JAMES</u>	
				JOB NAME/LOCATION <u>Hearthside</u>	
				JOB NUMBER _____	
PROBLEM: <u>driveshaft at hitch broken</u>					
REPAIRED: <u>repaired drive shaft, drilled out broken bolts</u>					
PARTS: <u>y joints capst + bolts</u> <u>106.50</u> <u>Truck Pro</u>					
<u>yoke</u> <u>321.59</u> <u>Thompson</u>					



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>108</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>518 skidder</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>5-28-10</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>JAMES</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>hyd line leaking at pump</u>				
REPAIRED: <u>removed line and welded.</u>				
<u>refilled hyd system</u>				
PARTS: _____				



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>108</u>		HOURS _____ DAYS _____		BASIC MACHINE	HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Ing. rand</u>		REASON		POWER TRAIN	ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>DA-50</u>		PARTS	LABOR	COMPONENT LOCATION	
SERIAL # <u>6348P</u>		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE: _____ DATE COMPLETED _____	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC <u>JAMES</u>	
SMOKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION	JOB NUMBER
				<u>Shop</u>	
PROBLEM: <u>starter bad.</u>					
<u>Service</u>					
<u>hyd. line leak</u>					
REPAIRED: <u>replaced started repaired switch wire.</u>					
<u>replaced case drain line on center pump.</u>					
<u>serviced - replaced all filters</u>					
<u>replaced steering cylinders end bearings</u>					
PARTS: <u>starter rebuilt</u> 180. ²⁶ <u>Crocks</u>					
<u>Filter + Line</u> > <u>Hose</u> 40. ¹⁶ <u>NAPA</u>					
<u>Filters</u> 72. ¹⁹ <u>NAPA</u>					
<u>Bearings</u> \$176. ⁵⁶ <u>Applied Ind. Tech.</u>					
<u>TORR 125F20</u>					



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>108</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>CAT</u>	REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>518 skidder</u>	PARTS _____ LABOR _____	COMPONENT LOCATION		
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED _____		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>JAMES</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER	
PROBLEM: <u>service & check front end noise, blade</u> <u>won't stay up, check master switch</u> <u>scrapers need repair</u>				
REPAIRED: <u>washed out radiator</u> <u>sealed blade lift cylinders</u> <u>replaced u-joints in front drive shaft</u> <u>replaced Trans mounts</u> <u>worked on scrapers</u>				
PARTS: <u>blade cylinder seal kits</u> <u>u-joints & mounts</u> <u>Hardware + paint 49.00</u> <u>TSC</u> <u>White House Equipment</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>108</u>	HOURS _____ DAYS _____	REASON	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>			POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>518 skidder</u>	PARTS	LABOR	COMPONENT LOCATION	
SERIAL # _____	OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: _____	DATE COMPLETED <u>9-20-13</u>
			MECHANIC <u>James</u>	
			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>old batteries</u> <u>won't stay charged</u>				
REPAIRED: <u>replaced batteries</u>				
PARTS: <u>2 - Gp 31A</u> <u>2181 4P</u> <u>Advance</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>108</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>518</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE [✓] LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>7-9-14</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>JAMES</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Seedway</u>	JOB NUMBER
PROBLEM: <u>left steering cylinder leaking</u>				
REPAIRED: <u>packed left steering cylinder</u>				
<u>Topped off oil</u>				
PARTS: <u>Packing Kit</u> <u>84.⁰⁰</u> <u>Thompson Machinery</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>108</u> MAKE <u>CAT</u> MODEL <u>518</u> SERIAL # _____ HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____												
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>8-8-15</u> MECHANIC <u>JAMES & Shawn B</u> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%;">JOB NAME/LOCATION <u>Shop</u></td> <td style="width: 50%;">JOB NUMBER</td> </tr> </table>	JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER										
JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER													
PROBLEM: <u>check over service needs seat</u>														
REPAIRED: <u>replaced seat made AN universal seat bracket, serviced, replaced tube & hose on right blade cylinder with hose. removed & Threadlock All oil pan bolts.</u> <u>replaced worn scraper teeth</u>														
<table style="width: 100%;"> <tr> <td style="width: 33%;">PARTS: <u>seat & wire</u></td> <td style="width: 33%; text-align: right;"><u>185.⁶⁸</u></td> <td style="width: 33%; text-align: right;"><u>TSC</u></td> </tr> <tr> <td><u>all filters</u></td> <td style="text-align: right;"><u>103.⁴⁵</u></td> <td style="text-align: right;"><u>NAPA</u></td> </tr> <tr> <td><u>hose</u></td> <td style="text-align: right;"><u>120.³³</u></td> <td style="text-align: right;"><u>NAPA</u></td> </tr> <tr> <td><u>Teeth</u></td> <td style="text-align: right;"><u>125.⁶⁴</u></td> <td style="text-align: right;"><u>White Horse Equipment</u></td> </tr> </table>			PARTS: <u>seat & wire</u>	<u>185.⁶⁸</u>	<u>TSC</u>	<u>all filters</u>	<u>103.⁴⁵</u>	<u>NAPA</u>	<u>hose</u>	<u>120.³³</u>	<u>NAPA</u>	<u>Teeth</u>	<u>125.⁶⁴</u>	<u>White Horse Equipment</u>
PARTS: <u>seat & wire</u>	<u>185.⁶⁸</u>	<u>TSC</u>												
<u>all filters</u>	<u>103.⁴⁵</u>	<u>NAPA</u>												
<u>hose</u>	<u>120.³³</u>	<u>NAPA</u>												
<u>Teeth</u>	<u>125.⁶⁴</u>	<u>White Horse Equipment</u>												

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>108</u>	MAKE <u>Cat</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MODEL <u>578 Skidder</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
SERIAL # _____		PARTS _____ LABOR _____	COMPONENT LOCATION	
HOUR METER _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
MILES _____			OTHER _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: _____ DATE COMPLETED <u>10-6-15</u>	
			MECHANIC <u>James + Steven</u>	
			JOB NAME/LOCATION <u>Vesta</u>	JOB NUMBER
PROBLEM: <u>Oil leak at Air comp.</u>				
REPAIRED: <u>replaced oil line to block</u>				
PARTS: <u>Hose</u> <u>417.59</u> <u>Napa</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>108</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Log Power CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>340 518</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE <u>10-13-15</u> DATE COMPLETED <u>10-14-15</u> MECHANIC <u>JAMES + Steven</u>	
			JOB NAME/LOCATION <u>Sub station</u>	JOB NUMBER
PROBLEM: <u>starter spinning</u>				
REPAIRED: <u>replaced starter, fuel filter & fuel pump</u>				
PARTS: <u>starter rebuild 206.48</u> <u>Crook's Auto</u> <u>fuel filter</u> <u>in stock</u> <u>fuel pump</u> <u>Crook's Auto</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>108</u>	HOURS _____ DAYS _____ REASON PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>Cat</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>518</u>		COMPONENT LOCATION		
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>3-8-16</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>James</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Cato</u>	JOB NUMBER	
PROBLEM: <u>blown hose</u>				
REPAIRED: <u>replaced left steer hose</u>				
PARTS: <u>hose</u> <u>110.69</u> <u>Nashville Rubber + Basket</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>108</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>518</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
 OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
 SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 5-3-16

MECHANIC JAMES + Steven B

JOB NAME/LOCATION

JOB NUMBER

Shop

PROBLEM: need serviced + fix leaks, check hydraulics

REPAIRED: serviced, sealed black lift valve, steer valve + Hyd. Tank. Packed steering cylinders.

PARTS: seals & sample bottles 297.⁰⁹

All Filters

107.⁰¹

Thompson Machinery

Muffler

104.⁷⁴

Tenn Filter

seals + joints

268.⁷⁵

Thompson

Gasket

15.²²

Thompson

2 O-rings

7.⁹³

Thompson

Tube

61.³⁵

Thompson

O-rings

30.⁶¹

Nashville Rubber + Gasket

Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>108</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>CAT</u>	REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>518 Skidder</u>	PARTS LABOR	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER <u>3600 HRS</u>		OTHER _____
MILES _____		

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE <u>2-3-17</u> DATE COMPLETED _____ MECHANIC <u>JAMES STEVEN</u> <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:50%;">JOB NAME/LOCATION <u>Shop from Jimmy</u></td> <td style="width:50%;">JOB NUMBER</td> </tr> </table>	JOB NAME/LOCATION <u>Shop from Jimmy</u>	JOB NUMBER
JOB NAME/LOCATION <u>Shop from Jimmy</u>	JOB NUMBER		

PROBLEM: Air tank blown, oil pan cracked, needs some scraper teeth

REPAIRED: replaced air tank, oil pan sealed top oil pan plate. replaced one air line + Governor. patched one air line.

Tips, Pins & retainers 223.⁴³ Thompson

PARTS: <u>Tank</u>	106. ⁴⁶	Thompson
<u>Oil Pan</u>	615. ⁴¹	Thompson
<u>Belts + Gaskets</u>	\$32. ⁰⁸ 95. ³⁴	Thompson
<u>Fitter</u>	\$8. ⁵⁵	NAPA
<u>Gaskets</u>	17. ¹⁴ 7. ⁰⁵	Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES																
EQUIP. # <u>108</u>	HOURS _____ DAYS _____ REASON PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS																	
MAKE <u>CAT</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED																	
MODEL <u>518</u>		COMPONENT LOCATION																	
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER																	
HOUR METER _____		OTHER _____																	
MILES _____																			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: <u>2-24-17</u> DATE COMPLETED <u>3-8-17</u>																	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>JAMES & Steve B</u>																	
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>W. Jean to shop</u>	JOB NUMBER																
PROBLEM: <u>center Driveshaft broken</u>																			
REPAIRED: <u>Thru shaft broken, replaced one battery</u>																			
<table border="0"> <tr> <td>1-battery</td> <td>109.²⁵</td> <td>Advance Auto Parts</td> </tr> <tr> <td>bolts & shims</td> <td>16.⁷³</td> <td>Thompson</td> </tr> <tr> <td>Plug</td> <td>116.⁶²</td> <td>Thompson</td> </tr> <tr> <td>Hardware</td> <td>13.⁰⁶</td> <td>Fastenal</td> </tr> <tr> <td>shaft</td> <td>739.⁰⁰</td> <td>Thompson</td> </tr> </table>					1-battery	109. ²⁵	Advance Auto Parts	bolts & shims	16. ⁷³	Thompson	Plug	116. ⁶²	Thompson	Hardware	13. ⁰⁶	Fastenal	shaft	739. ⁰⁰	Thompson
1-battery	109. ²⁵	Advance Auto Parts																	
bolts & shims	16. ⁷³	Thompson																	
Plug	116. ⁶²	Thompson																	
Hardware	13. ⁰⁶	Fastenal																	
shaft	739. ⁰⁰	Thompson																	
<table border="0"> <tr> <td>PARTS: 40-joints & strap</td> <td>186.⁹³</td> <td>Thompson</td> </tr> <tr> <td>cover</td> <td>25.⁷³</td> <td>Thompson</td> </tr> <tr> <td>bolts</td> <td>14.⁶²</td> <td>Thompson</td> </tr> <tr> <td>seals & cone</td> <td>67.⁴⁶</td> <td>Thompson</td> </tr> <tr> <td>seal</td> <td>142.⁶¹</td> <td>Thompson</td> </tr> </table>					PARTS: 40-joints & strap	186. ⁹³	Thompson	cover	25. ⁷³	Thompson	bolts	14. ⁶²	Thompson	seals & cone	67. ⁴⁶	Thompson	seal	142. ⁶¹	Thompson
PARTS: 40-joints & strap	186. ⁹³	Thompson																	
cover	25. ⁷³	Thompson																	
bolts	14. ⁶²	Thompson																	
seals & cone	67. ⁴⁶	Thompson																	
seal	142. ⁶¹	Thompson																	

Seal, Cyl & Cone 121.¹⁴ Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>108</u> MAKE <u>CAT</u> MODEL <u>518 skidder</u> SERIAL # _____ HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____									
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>3-28-17</u> MECHANIC <u>JAMES + STEVEN</u> <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:50%;">JOB NAME/LOCATION <u>Shop</u></td> <td style="width:50%;">JOB NUMBER</td> </tr> </table>	JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER							
JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER										
PROBLEM: <u>drive line noise</u>											
REPAIRED: <u>replaced yoke flange - u-joint & Transfer case seal. Replaced Transmission oil</u>											
<table style="width:100%;"> <tr> <td style="width:30%;">PARTS: <u>Flange</u></td> <td style="width:30%; text-align: right;"><u>521.31</u></td> <td style="width:40%; text-align: right;"><u>Thompson</u></td> </tr> <tr> <td><u>u-joint & yoke</u></td> <td style="text-align: right;"><u>85.10</u></td> <td style="text-align: right;"><u>Thompson</u></td> </tr> <tr> <td></td> <td style="text-align: right;"><u>319.94</u></td> <td></td> </tr> </table>			PARTS: <u>Flange</u>	<u>521.31</u>	<u>Thompson</u>	<u>u-joint & yoke</u>	<u>85.10</u>	<u>Thompson</u>		<u>319.94</u>	
PARTS: <u>Flange</u>	<u>521.31</u>	<u>Thompson</u>									
<u>u-joint & yoke</u>	<u>85.10</u>	<u>Thompson</u>									
	<u>319.94</u>										

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP # <u>0701</u> MAKE <u>CAT</u> MODEL <u>518</u> SERIAL # _____ HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>1-7-19</u> MECHANIC <u>Charles</u>
		JOB NAME/LOCATION JOB NUMBER <u>MCH</u> _____
PROBLEM: <u>No fuel</u>		
REPAIRED: <u>Pump in stock</u> <u>Primed fuel & started</u>		
PARTS: <u>Pump</u> <u>57.63</u> <u>Cook Auto Electric</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0701</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>578</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: <u>10-17-19</u> DATE COMPLETED <u>10-18-19</u> MECHANIC <u>Charles</u>	
			JOB NAME/LOCATION <u>Jones Brummett</u>	JOB NUMBER
PROBLEM: <u>went start.</u>				
REPAIRED: <u>replaced batteries</u>				
PARTS <u>2-Grp 31 Batteries 293. ⁰⁰ IBS</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>0701</u> MAKE <u>CAT</u> MODEL <u>318</u> SERIAL # _____ HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____															
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>11-3-20</u> MECHANIC <u>Ben</u> <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:70%;">JOB NAME/LOCATION <u>Ashland Farms</u></td> <td style="width:30%;">JOB NUMBER</td> </tr> </table>	JOB NAME/LOCATION <u>Ashland Farms</u>	JOB NUMBER													
JOB NAME/LOCATION <u>Ashland Farms</u>	JOB NUMBER																
PROBLEM: <u>Bad battery</u>																	
REPAIRED: <u>replaced battery and other battery</u> <u>had starter rebuilt</u>																	
<table style="width:100%;"> <tr> <td style="width:33%;">PARTS: <u>BATT 24</u></td> <td style="width:33%; text-align: right;"><u>161.32</u></td> <td style="width:33%; text-align: right;"><u>Advance</u></td> </tr> <tr> <td><u>31P30</u></td> <td></td> <td></td> </tr> <tr> <td><u>1st replacement</u></td> <td></td> <td></td> </tr> <tr> <td><u>31P30</u></td> <td style="text-align: right;"><u>131.69</u></td> <td style="text-align: right;"><u>Advance</u></td> </tr> <tr> <td><u>Starter rebuild</u></td> <td style="text-align: right;"><u>207.43</u></td> <td style="text-align: right;"><u>Crook Auto Electric</u></td> </tr> </table>			PARTS: <u>BATT 24</u>	<u>161.32</u>	<u>Advance</u>	<u>31P30</u>			<u>1st replacement</u>			<u>31P30</u>	<u>131.69</u>	<u>Advance</u>	<u>Starter rebuild</u>	<u>207.43</u>	<u>Crook Auto Electric</u>
PARTS: <u>BATT 24</u>	<u>161.32</u>	<u>Advance</u>															
<u>31P30</u>																	
<u>1st replacement</u>																	
<u>31P30</u>	<u>131.69</u>	<u>Advance</u>															
<u>Starter rebuild</u>	<u>207.43</u>	<u>Crook Auto Electric</u>															

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>0701</u> MAKE <u>CAT</u> MODEL <u>518 Skidder</u> SERIAL # _____ HOUR METER <u>4100 HRS</u> MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>4-14-21</u> MECHANIC <u>Ben</u> <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:50%;">JOB NAME/LOCATION <u>Shop</u></td> <td style="width:50%;">JOB NUMBER</td> </tr> </table>	JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER			
PROBLEM: _____ _____ _____				
REPAIRED: <u>Serviced</u> _____ _____ _____ _____ _____ _____				
PARTS: <u>Oil, Hyd & Trans.</u> <u>55.53</u> <u>Aspa</u> _____ _____ _____				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0701</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>518</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____				DATE: _____ DATE COMPLETED <u>1-11-22</u>	
				MECHANIC <u>Ben</u>	
				JOB NAME/LOCATION <u>West Trinity</u>	
				JOB NUMBER _____	
PROBLEM: <u>Top post burned off of 1 battery</u>					
REPAIRED: <u>replaced battery</u>					
PARTS: <u>1- 31P30</u> <u>139.01</u> <u>Advance</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0701</u>	HOURS _____ DAYS _____	REASON	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>			POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>578</u>	PARTS _____ LABOR _____	OTHER _____	COMPONENT LOCATION	
SERIAL # _____			FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____	OTHER _____	OTHER _____	OTHER _____	
MILES _____			OTHER _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>4-3-24</u>	DATE COMPLETED <u>4-8-24</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>ALL</u>	
SMOKES SHORTED VIBRATE OTHER _____			JQB NAME/LOCATION <u>IN SHOP</u>	JOB NUMBER
PROBLEM: <u>Fix leaks</u>				
REPAIRED: <u>sealed leaks, installed all pans & scrapers</u>				
PARTS: <u>seals + hardware</u> <u>247.³⁰</u> <u>Thompson</u>				
<u>solenoid</u> <u>52.⁶⁸</u> <u>Cook's</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0701
MAKE Cat
MODEL 518
SERIAL # _____
HOUR METER _____
MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
REASON _____
PARTS _____ LABOR _____
OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER
OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SMOKES SHORTED VIBRATE OTHER _____

DATE: 9-16-23 DATE COMPLETED 4-P-24
MECHANIC ALL

JOB NAME/LOCATION
Shop

JOB NUMBER

PROBLEM: broken axle tube

REPAIRED: removed broken spindle disc assembled
RT front hub, assembled

PARTS: <u>spindle</u>	<u>900.⁰⁰</u>	<u>Thompson</u>
<u>seals</u>	<u>166.⁶⁹</u>	<u>Thompson</u>
<u>Fitters</u>	<u>90.²⁷</u>	<u>NAPA</u>

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0701</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>518</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE <u>11-4-24</u> DATE COMPLETED <u>11-5-24</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Anthony</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>High Park</u>	JOB NUMBER _____
PROBLEM: <u>won't start</u>				
REPAIRED: <u>rebuild starter</u>				
PARTS: <u>starter</u> <u>246.94</u> <u>Crook Auto Electric</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0701</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>518</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE: _____ DATE COMPLETED <u>3-11-25</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION <u>Sub station</u>	
				JOB NUMBER _____	
PROBLEM: <u>blown hose</u>					
REPAIRED: <u>replaced hose</u>					
PARTS: <u>hose</u> <u>1105, 14</u> <u>Thompson</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0701</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>518</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
 OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
 SMOKES SHORTED VIBRATE OTHER _____

DATE: 3-5-25 DATE COMPLETED 4-2-25

MECHANIC Ben

JOB NAME/LOCATION
Sub station

JOB NUMBER

PROBLEM: blade cylinders leaking

REPAIRED: packed cylinders

PARTS: 2 seal kits 331.25 Thompson