

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0514</u>	HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>CAT</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>323F</u>		COMPONENT LOCATION		
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>10-4-19</u>	MECHANIC <u>ALL</u>	
		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER	
PROBLEM: <u>54" bucket</u>				
REPAIRED: <u>new bucket</u>				
PARTS: <u>54" bucket 2 pins 87586.26 Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0514</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>323FL</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE: <u>9-20-19</u> DATE COMPLETED <u>10-2-19</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC <u>James & Bryan</u>
SMOKES SHORTED VIBRATE OTHER _____	JOB NAME/LOCATION _____ JOB NUMBER _____

PROBLEM: Service check over
bought used

REPAIRED: Serviced, removed decals
Replaced final drive plug.
purchased 54" bucket

PARTS: <u>All Filters</u>	<u>\$449.48</u>	<u>Thompson</u>
<u>DPF clean out</u>	<u>Did not Do.</u>	<u>Emissions & Coasting Stations</u>
<u>Plug</u>	<u>28.65</u>	<u>Thompson</u>
<u>bucket teeth</u>	<u>614.00</u>	<u>Thompson</u>
<u>bucket 54"</u>	<u>\$7,200.00</u>	<u>Thompson</u>

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0514</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>323F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>11-16-19</u> MECHANIC <u>Charles</u>		
		JOB NAME/LOCATION <u>Ashland Farms</u> JOB NUMBER _____		
PROBLEM: <u>Quick connect broken going to Hammer bought extra.</u>				
REPAIRED: <u>replaced boom to stick hose on left side</u>				
PARTS: <u>hose</u> <u>453.01</u> <u>Nashville Rubber & Gasket</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0514</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>323F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE <u>12-4-19</u> DATE COMPLETED <u>12-4-19</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>BEN</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Bethel Farms</u>	JOB NUMBER _____
PROBLEM: <u>blown hose between stick & boom</u>				
REPAIRED: <u>replaced hose</u>				
PARTS: <u>hose</u> <u>321.34</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0514</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>323F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>5K HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE <u>1-30-2020</u> DATE COMPLETED <u>2-3-2020</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Charles</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION	JOB NUMBER
			<u>Jones Brummett</u>	
PROBLEM: <u>Service</u>				
REPAIRED: <u>revised</u>				
PARTS <u>All Filters</u> <u>506.21</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0514</u>	HOURS _____ DAYS _____ REASON PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>CAT</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>323F</u>		COMPONENT LOCATION		
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____	DATE COMPLETED <u>3-30-2020</u>	
		MECHANIC <u>Charles</u>		
		JOB NAME/LOCATION <u>Jones Brummett</u>	JOB NUMBER _____	
PROBLEM: <u>won't start needs batteries</u>				
REPAIRED: <u>replaced batteries</u>				
PARTS: <u>4-115-2422 774.49 Thompson</u>				
<u>Grp 31</u>				
<u>1000 amp offset</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0514</u>	HOURS _____ DAYS _____ REASON PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>CAT</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>323F</u>		COMPONENT LOCATION		
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____	DATE COMPLETED <u>4-3-2020</u>	
		MECHANIC <u>ALL</u>		
		JOB NAME/LOCATION <u>Jones Brummett</u>	JOB NUMBER	
PROBLEM: <u>Detoxing cab</u>				
REPAIRED: <u>replaced cab filters</u>				
PARTS: <u>cab filters</u> \$ <u>79.40</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0514</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>323F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>5500 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>5-21-20</u> DATE COMPLETED <u>6-29-20</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Jones Brummet</u>	JOB NUMBER _____
PROBLEM: <u>Service</u>				
REPAIRED: <u>Serviced</u>				
PARTS: <u>All Filters</u> <u>496.62</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0514</u>	REASON PARTS LABOR OTHER	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>323F</u>				
SERIAL # _____				
HOUR METER <u>5,687 HRS</u>				
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE <u>10-23-20</u> DATE COMPLETED <u>11-9-20</u> MECHANIC <u>James + Ben</u>	
PROBLEM: <u>bucket drift</u>			JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____	
REPAIRED: <u>cylinder beyond repair replaced with after market cylinder cleaned out hydraulic tank replaced all hydraulic filters replaced bucket cylinder relief valves</u>				
PARTS: <u>valve 352-17122 24P.25 Thompson</u> <u>flanges gaskets seal 99.33 Thompson</u> <u>valve O-rings 441.87 Thompson</u> <u>Bucket cylinder 4400.00 Thompson</u> <u>After market</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0514</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>323F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>11-24-20</u>	MECHANIC <u>ALI</u>	
PROBLEM: <u>broken RT Track pin</u>		JOB NAME/LOCATION <u>W. Town Farm</u>	JOB NUMBER _____	
REPAIRED: <u>replaced RT track pin</u>				
PARTS: <u>pin, bolts & nuts 56.⁰⁰ Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0514</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>323F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>6K HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>3-29-21</u> DATE COMPLETED <u>4-14-21</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>ALL</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>Service cylinder repair</u>				
REPAIRED: <u>Serviced, had bucket cylinder repaired</u>				
PARTS: <u>All Filters</u> <u>498.⁰⁰</u> <u>Thompson</u>				
<u>cylinder repair</u> <u>793.¹⁶</u> <u>Mid South Hydraulics</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0514</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>323F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>6,400 HRS.</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: <u>6-28-21</u> DATE COMPLETED <u>7-13-21</u>	
MECHANIC <u>ALL</u>			JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____	
PROBLEM: <u>needs rails</u>				
REPAIRED: <u>replaced rails & sprockets</u>				
PARTS: <u>rails, sprockets & hardware 5318.05 Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0514</u>	HOURS _____ DAYS _____	REASON _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>			POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>323F</u>			COMPONENT LOCATION	
SERIAL # _____	PARTS _____	LABOR _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>6500 HRS</u>	OTHER _____	OTHER _____	OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE <u>8-17-21</u> DATE COMPLETED <u>8-20-21</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC _____		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____		
PROBLEM: <u>serviced</u>				
REPAIRED: <u>serviced</u>				
PARTS: <u>Filters</u> <u>444.56</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0514</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>323F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>10-27-21</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Lawrence Glass</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION	JOB NUMBER
PROBLEM: <u>both front windows broken</u>			<u>West Trinity</u>	
REPAIRED: <u>replaced both windows</u>				
PARTS: <u>2. Glass & labor</u> <u>487.00</u> <u>Lawrence Glass</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0574</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>323F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>7K HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE <u>12-14-21</u> DATE COMPLETED <u>2-1-22</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>West Trinity</u>	JOB NUMBER _____
PROBLEM: <u>Service</u>				
REPAIRED: <u>serviced</u>				
PARTS: <u>All Filters</u> <u>494.85</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0514</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Cat</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>323F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____			OTHER _____
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>12-18-21</u> MECHANIC <u>Ben</u>	
PROBLEM: _____		JOB NAME/LOCATION <u>West Trinity</u> JOB NUMBER _____	
REPAIRED: <u>replaced hose</u>			
PARTS: <u>hose</u> <u>308.72</u> <u>Thompson</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0514</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>323F</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE: _____ DATE COMPLETED <u>4-8-22</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC <u>Ben + Anthony</u>	
SMOKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION <u>Antken</u> JOB NUMBER _____	
PROBLEM: <u>blown hose + bad hood cylinder</u>					
REPAIRED: <u>replaced hose & cylinder</u>					
PARTS: <u>hose</u> <u>317.16</u>					
<u>cylinder</u> <u>222.73</u> <u>Thompson</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0514</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>323F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE <u>5-3-22</u> DATE COMPLETED _____		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Anthony</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>West Trinity</u> JOB NUMBER _____		
PROBLEM: <u>Lower Front Glass broken</u>				
REPAIRED: <u>replaced Glass</u>				
PARTS: <u>Glass</u> <u>177.99</u> <u>Thompson</u>				

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

TEC

TEC

THORNE'S EXCAVATING COMPANY, LLC SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0514</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>323F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>8K HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>9-21-22</u> DATE COMPLETED <u>9-24-22</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Anthony</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION	JOB NUMBER
PROBLEM: <u>Service</u>				
REPAIRED: <u>Serviced</u>				
PARTS: <u>All Filters</u> <u>5/16. LB</u> <u>Thompson</u>				

CVP40, CVP75, CVP110 Vibratory Plate Compactor

323F

Vibratory Plate Compactor Specifications



		CVP40 205 - 5900	CVP75 205 - 5901	CVP110 205 - 5902
Backfill Blade		211 - 8200	212 - 3450	212 - 0789
Weight (w/o Bracket or Blade)	lbs (kg)	884 (401)	1765 (801)	2319 (1052)
Impulse Force	lbs (kg)	8928 (4050)	16508 (7488)	24669 (11190)
Impact Frequency	blows/min	2200	2200	2200
Plate Dimensions	in (mm)	23 x 38 (584 x 965)	29 x 43 (737 x 109)	34 x 47 (864 x 1194)
Plate Area	ft² (m²)	6.1 (0.567)	8.6 (0.799)	11.1 (1.031)
Height	in (mm)	24.5 (622)	30.3 (770)	35.5
Width	in (mm)	23 (584)	29 (737)	34 (864)
Base Plate Pressure	psi (kPa)	10.16 (70.05)	13.33 (91.91)	15.43 (106.39)
Machine Requirements				
Carrier Weight	lbs (kg)	10000 - 25000 (4536 - 11340)	16000 - 42000 (7258 - 19051)	30000 - 75000 (13608 - 34020)
Flow	gpm (lpm)	18 - 22 (68 - 83)	28 - 32 (106 - 121)	38 - 42 (144 - 159)
Pressure	psi (kPa)	1800 - 2200 (12411 - 15168)	2000 - 2500 (13790 - 17237)	2000 - 2500 (13790 - 17237)

OIL CAPACITY - 4L / 4.2 qts

OIL TYPE - 4C-6767 synthetic

FILL HOUSING THRU FILLER PLUG (TOP) UNTIL
OIL RUNS OUT OF DRAIN PLUG (BOTTOM)

CVP75

C5600905

Serial 205-5901

ISO

Hyper 550 220
194.78

www.CAT.com

© 2001 Caterpillar

Materials and specifications are subject to change without notice.
Featured machine in photos may include additional equipment.
See your Caterpillar dealer for available options.

GEHQ0181 (09-01)

CATERPILLAR

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0804</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>323F</u>	PARTS _____ LABOR _____	COMPONENT LOCATION		
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER <u>9K HRS</u>		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE <u>8-28-23</u>	DATE COMPLETED <u>8-31-23</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Anthony & Justin</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>4151</u>	JOB NUMBER	
PROBLEM: <u>Service</u>				
REPAIRED: <u>serviced</u>				
PARTS: <u>filters</u> <u>574.29</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0514</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>323F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
OUR METER <u>9100 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>10-27-23</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Thompson</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME LOCATION <u>Antler</u>	JOB NUMBER _____
PROBLEM: <u>Knock sensor bad</u>				
REPAIRED: <u>replaced knock sensor ended up being</u>				
<u>not sensors. Thompson replaced both sensors.</u>				
<u>Flashed system.</u>				
PARTS: <u>Sensor</u> <u>114.82</u> <u>Thompson</u>				
<u>two sensors & brackets</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>0514</u> MAKE <u>Cat</u> MODEL <u>323F</u> SERIAL # _____ HOUR METER <u>9500 HRS</u> MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____ _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>5-2-24</u> DATE COMPLETED <u>5-16-24</u> MECHANIC <u>Anthony</u> <table style="width:100%;"> <tr> <td style="width:70%;">JOB NAME/LOCATION <u>415P</u></td> <td style="width:30%;">JOB NUMBER</td> </tr> </table>	JOB NAME/LOCATION <u>415P</u>	JOB NUMBER
JOB NAME/LOCATION <u>415P</u>	JOB NUMBER			
PROBLEM: <u>Service</u> _____ _____ _____				
REPAIRED: <u>Serviced</u> _____ _____ _____ _____ _____ _____				
PARTS: <u>Filters</u> <u>541.45</u> _____ _____ _____ _____				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0574</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>323F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>8-20-24</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Aubrey's</u>	JOB NUMBER _____
PROBLEM: <u>shut down</u>				
REPAIRED: <u>bad fuel sensor & fuel pump shutting off.</u>				
PARTS <u>All Filters</u> <u>595.05</u> <u>Thompson</u>				
<u>Sensor</u> <u>186.00</u> <u>Thompson</u>				
<u>pump & inline filter</u> <u>460.00</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0514</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>323F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>9-23-24</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Lawrence Glass</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION / <u>Aubrey's</u>	
PROBLEM: <u>front glass broken</u>			JOB NUMBER _____	
REPAIRED: <u>replaced glass</u>				
PARTS: <u>glass + labor</u> <u>362.10</u> <u>Lawrence Glass</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		REASON		LABOR		PARTS		COMPONENT CODES	
EQUIP. # 0514		HOURS		DAYS		BASIC MACHINE		HYDRAULIC		ENGINE IMPLEMENTS	
MAKE CAT		REASON		POWER TRAIN		ELECTRIC		DRIVE TRAIN		UNEXPLAINED	
MODEL 323F		PARTS		COMPONENT LOCATION		FRONT		REAR		LEFT	
SERIAL #		LABOR		OTHER		RIGHT		UPPER		LOWER	
HOUR METER 10K MRS		REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: 4-2-25		DATE COMPLETED		MECHANIC Bryan		JOB NAME/LOCATION Shop	
MILES		OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		SMOKES SHORTED VIBRATE OTHER		JOB NUMBER					

PROBLEM: Service

REPAIRED: Revised

PARTS: F. Hays

653. B

Thompson

EQUIPMENT INFORMATION		IP. # 0514		DATE 3/23/14		DEL. 323F		TAL #		OUR METER		ES	
EQUIPMENT DOWNTIME		HOURS		REASON		PARTS		LABOR		OTHER		FRONT REAR LEFT RIGHT UPPER LOWER	
COMPONENT CODES		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		COMPONENT LOCATION		OTHER		DATE COMPLETED 6-26-25		MECHANIC Bryan	
JOB NAME/LOCATION		WILSON INDUSTRIAL		JOB NUMBER		PROBLEM: hyd. system gauge pegged out		REPAIRS: replaced tank temp sensor		DATE 7/1/21		TECHNICIAN Thompson	