

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>301</u>		HOURS _____ DAYS _____		BASIC MACHINE	HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Cat</u>		REASON		POWER TRAIN	ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>924G</u>		PARTS	LABOR	COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT	REAR LEFT RIGHT UPPER LOWER
HOUR METER _____				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____				DATE: _____ DATE COMPLETED <u>7-5-16</u>	
				MECHANIC <u>Charles</u>	
				JOB NAME/LOCATION <u>Smith Travel</u>	JOB NUMBER
PROBLEM: <u>broken Fitting at coupling cylinder</u>					
REPAIRED: <u>replaced Fitting</u>					
PARTS: <u>Fitting + O-rings</u> <u>33.14</u> <u>Thompson</u> <u>Filter</u> <u>271.83</u> <u>Team Fitter</u> <u>Cab Filter</u> <u>20.52</u> <u>NAPA</u>					

TEC
THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>301</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Cat</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>924G</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>5-19-17</u> MECHANIC <u>James & Steven</u> JOB NAME/LOCATION <u>My Place Motel</u> JOB NUMBER _____
PROBLEM: <u>Service</u>		
REPAIRED: <u>serviced</u>		
PARTS: <u>All Filters</u> <u>347.19</u> <u>Tenn Filter sales</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1401</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>924G</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>11K HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>2-16-18</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>James</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>Service</u>				
REPAIRED: <u>Serviced</u>				
PARTS: <u>All Filters</u> <u>367.10</u> <u>TF5</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1401</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>924G</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # <u>loader</u>		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE <u>5-17-18</u>	DATE COMPLETED <u>5-6-18</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Charles</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Childrens Family</u>	JOB NUMBER _____
PROBLEM: <u>Temp sender bad (constant)</u>				
REPAIRED: <u>replaced sensor</u>				
PARTS: <u>Temp. sender</u> <u>149.11</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1401</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>924G</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE <u>7-13-18</u> DATE COMPLETED <u>7-20-18</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC _____	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION	JOB NUMBER
PROBLEM: <u>broken door glass</u>				
REPAIRED: <u>replaced water pump</u> <u>replaced broken door glass</u> <u>serviced</u>				
PARTS: <u>glass</u> 130.00 Thompson				
<u>bits</u> 43.00 Thompson				
<u>filters</u> 383.59 Tenn Fitter				
<u>water pump</u> 308.17 Thompson				
<u>bolts</u> 32.51 Thompson				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>1401</u> MAKE <u>Cat</u> MODEL <u>924G</u> SERIAL # _____ HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>8-28-18</u> DATE COMPLETED: <u>8-30-18</u> MECHANIC: <u>Charles</u>
		JOB NAME/LOCATION: <u>Maple Crossing</u> JOB NUMBER: _____
PROBLEM: _____ _____ _____		
REPAIRED: <u>replaced seat</u> _____ _____ _____ _____ _____ _____		
PARTS: <u>Seat & Parts</u> <u>389.00</u> <u>Thompson</u> _____ _____ _____ _____		

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963


EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1401</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>924G</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>9-21-18</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Charles</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Beckwith</u>	JOB NUMBER
PROBLEM: <u>oil leak</u>				
REPAIRED: <u>broken parts on bucket disconnect cylinder replaced</u>				
PARTS: <u>bow, Tee & seat 62.72 Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>1401</u> MAKE <u>Cat</u> MODEL <u>924G</u> SERIAL # _____ HOUR METER _____ MILES _____		EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____		COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____				DATE <u>10-16-18</u> DATE COMPLETED <u>10-24-18</u> MECHANIC <u>Charles</u>	
PROBLEM: <u>no heat</u>				JOB NAME/LOCATION <u>Beckwith</u> JOB NUMBER _____	
REPAIRED: <u>bad control cable replaced</u>					
PARTS: <u>cable assembly 90.95 Thompson</u>					



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1401</u>	HOURS _____ DAYS _____ REASON PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>CAT</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>924G</u>		COMPONENT LOCATION		
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>10-31-18</u> MECHANIC <u>James</u>		
PROBLEM: <u>1 bad battery</u>		JOB NAME/LOCATION: <u>Maple Crossing</u> JOB NUMBER _____		
REPAIRED: <u>replaced left battery</u>				
PARTS: <u>1 battery</u> <u>127.32</u> <u>Interstate battery</u> <u>29H-VHD</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 1401
MAKE CAT
MODEL 924G
SERIAL # _____
HOUR METER 12K HRS
MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
REASON _____
PARTS _____ LABOR _____
OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER
OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SMOKES SHORTED VIBRATE OTHER _____

DATE 11-8-18 DATE COMPLETED 12-10-18

MECHANIC Charles

JOB NAME/LOCATION

Shop

JOB NUMBER

PROBLEM: needs serviced, Anti-freeze leak

REPAIRED: Serviced

replaced Thermostat & Rad cap
washed

PARTS: All Filters

383.54

Tenn Filter

Rad. cap

20.00

Thompson



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1001</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>D4C</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>9,430 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>12-19-18</u> DATE COMPLETED <u>4-11-19</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>James</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>Service & repair</u>				
REPAIRED: <u>Replaced Idlers, rollers, sprockets & Tracks</u> <u>new parts</u> <u>serviced</u>				
PARTS <u>Idlers, rollers & Tracks</u> <u>8047 64</u> <u>Thompson</u>				
<u>All Filters</u> <u>11/4 97</u> <u>Tenn Filter</u>				

TEC
THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1401</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>924G</u>	PARTS _____ LABOR _____	COMPONENT LOCATION		
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: <u>4-12-19</u> DATE COMPLETED _____		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Charles</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Ward's Parcelin</u>	JOB NUMBER _____	
PROBLEM: <u>broken seat belt.</u>				
REPAIRED: <u>seat belt on standby</u>				
PARTS: <u>seat belt</u> <u>216.22</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1401</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>924G</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>12,500 HRS</u>			OTHER _____	
MILES/ _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: <u>7-26-19</u> DATE COMPLETED <u>7-30-19</u> MECHANIC <u>Charles</u>	
			JOB NAME/LOCATION <u>Preserves</u>	JOB NUMBER
PROBLEM: <u>Service</u>				
REPAIRED: <u>Serviced</u>				
PARTS: <u>All Filters</u> <u>391.56</u> <u>Tenn Filter sales</u>				