

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0708</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>IR</u>		REASON		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>DD118</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE: <u>1-7-2020</u>	DATE COMPLETED: <u>6-9-20</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC: <u>All</u>	
SMOKES SHORTED VIBRATE OTHER _____	JOB NAME/LOCATION: <u>Shop</u>	JOB NUMBER: _____

PROBLEM: Bought used check over

REPAIRED: <u>serviced, replaced controller, park brake release problem</u>		
<u>Replaced seat, replaced fuel lines to tank</u>		
<u>replaced resistor under dash 250 ohm on/black</u>		
<u>like switches</u>	<u>122.58</u>	<u>Scott Equipment</u>
<u>water sensor</u>	<u>50.23</u>	<u>Scott Equipment</u>
<u>key switch</u>	<u>75.25</u>	<u>Thompson</u>
<u>Hosey Filter</u>	<u>64.08</u>	<u>NAPA</u>
PARTS: <u>All filters</u>	<u>186.41</u>	<u>Tenn Filter Sales</u>
<u>Park brake switches</u>	<u>145.49</u>	<u>Scott Equipment</u>
<u>Travel hose</u>	<u>184.84</u>	<u>Thompson</u>
<u>controller</u>	<u>957.60</u>	<u>Scott Equipment</u>
<u>seat</u>	<u>700.00</u>	<u>White Horse Equipment</u>
<u>resistors</u>	<u>228.98</u>	<u>Scott Equipment</u>
<u>resistors</u>	<u>31.28</u>	<u>Digi Key.com</u>

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0708</u> MAKE <u>Ingr. Rand</u> MODEL <u>DD118</u> SERIAL # _____ HOUR METER _____ MILES _____	HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE <u>10-9-20</u> DATE COMPLETED <u>11-14-20</u> MECHANIC <u>All</u>	
JOB NAME/LOCATION <u>A.P. to shop</u>		JOB NUMBER _____
PROBLEM: <u>won't start</u>		
REPAIRED: <u>had starter rebuilt, broken neutral safety bracket bad neutral safety switch (Diode) ordered for backup alarm too.</u>		
PARTS: <u>starter 137.19</u> <u>Cooks</u> <u>Battery 131.69</u> <u>Advance</u> <u>2-switches (Diodes)</u> <u>Scott Equipment</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0708</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>I.R.</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>DD118HF</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>3-4-21</u> DATE COMPLETED <u>3-10-21</u> MECHANIC <u>Ben & James</u> JOB NAME/LOCATION: <u>Eastgate to shop</u> JOB NUMBER _____
PROBLEM: <u>Engine smoking</u> <u>Injection pump leaking</u>		
REPAIRED: <u>replaced air filters & injection pump gasket</u>		
PARTS: <u>Engine Air Filters 56.⁰⁰</u> <u>Temp. Filter sales</u> <u>Injection pump gasket 6.⁰⁰</u> <u>Taylor Diesel</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES															
EQUIP. # <u>0708</u> MAKE <u>Inq. Isuel</u> MODEL <u>DD118</u> SERIAL # _____ HOUR METER _____ MILES _____	HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____															
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: <u>4-6-21</u> DATE COMPLETED: <u>5-21-21</u> MECHANIC <u>James</u> JOB NAME/LOCATION: <u>Shop</u> JOB NUMBER: _____																
PROBLEM: <u>Fuel system repair</u>																	
REPAIRED: <u>had fuel pump & injectors rebuilt.</u> <u>replaced water pump & 2 oil cooler hoses</u> <u>changed engine oil. New front main seal</u>																	
<table border="0"> <tr> <td>PARTS: <u>Seals</u></td> <td><u>57.¹³</u></td> <td><u>Cummins</u></td> </tr> <tr> <td><u>Pump & injectors</u></td> <td><u>1,997.⁰⁹</u></td> <td><u>Taylor diesel</u></td> </tr> <tr> <td><u>hoses</u></td> <td><u>210.⁰⁴</u></td> <td><u>Nashville Rubber & Gasket</u></td> </tr> <tr> <td><u>bolts</u></td> <td><u>20.⁰⁸</u></td> <td><u>FASTENAL</u></td> </tr> <tr> <td><u>water pump</u></td> <td><u>66.⁰⁰</u></td> <td><u>Advance</u></td> </tr> </table>			PARTS: <u>Seals</u>	<u>57.¹³</u>	<u>Cummins</u>	<u>Pump & injectors</u>	<u>1,997.⁰⁹</u>	<u>Taylor diesel</u>	<u>hoses</u>	<u>210.⁰⁴</u>	<u>Nashville Rubber & Gasket</u>	<u>bolts</u>	<u>20.⁰⁸</u>	<u>FASTENAL</u>	<u>water pump</u>	<u>66.⁰⁰</u>	<u>Advance</u>
PARTS: <u>Seals</u>	<u>57.¹³</u>	<u>Cummins</u>															
<u>Pump & injectors</u>	<u>1,997.⁰⁹</u>	<u>Taylor diesel</u>															
<u>hoses</u>	<u>210.⁰⁴</u>	<u>Nashville Rubber & Gasket</u>															
<u>bolts</u>	<u>20.⁰⁸</u>	<u>FASTENAL</u>															
<u>water pump</u>	<u>66.⁰⁰</u>	<u>Advance</u>															

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>0708</u> MAKE <u>Ing. Rad</u> MODEL <u>DD11F</u> SERIAL # _____ HOUR METER <u>1,500 HRS.</u> MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
---	---	--

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: <u>12-6-22</u> DATE COMPLETED <u>2-10-23</u> MECHANIC <u>Ben Jones + Anthony</u> JOB NAME/LOCATION: <u>West Talnith</u> JOB NUMBER _____
---	--

PROBLEM: Turbo broken

REPAIRED: replaced Turbo bringing to shop fuel/oil leaks. Removed fuel pump. rebuilt fuel pump. serviced

PARTS: <u>Turbo + nuts</u>	<u>2,159.⁰³</u>	<u>Cummins</u>
<u>4089320RX</u>		
<u>Fuel pump</u>		
<u>Filters</u>	<u>214.⁴⁵</u>	<u>Tenn Filter sales</u>