

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0506</u>	REASON PARTS LABOR OTHER _____	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>323F</u>		COMPONENT LOCATION		
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER <u>4K HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>3-23-2020</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Ben Bryan</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Jones Brummett</u>	JOB NUMBER
PROBLEM: <u>needs service</u>				
REPAIRED: <u>Serviced</u>				
PARTS: <u>All Filters</u> <u>518.27</u> <u>Thompson Machinery</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0506</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON _____	POWER TRAIN ELECTRIC DRIVETRAIN UNEXPLAINED	
MODEL <u>323F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>9-28-19</u> DATE COMPLETED <u>10-29-19</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Charles & Bryan</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Cargill</u>	JOB NUMBER _____
PROBLEM: <u>Service</u>				
REPAIRED: <u>serviced</u>				
PARTS: <u>All Filters</u> <u>449.48</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963


EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0806</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>323F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>3K WRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>6-29-19</u> DATE COMPLETED <u>7-1-19</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Charles</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Cumberland</u>	JOB NUMBER
PROBLEM: <u>service</u>				
REPAIRED: <u>serviced</u>				
PARTS: <u>All Filters</u> <u>447.90</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0506</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>323F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>2600 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>3-4-19</u> DATE COMPLETED: <u>3-23-19</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Charles & James</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION	JOB NUMBER
PROBLEM: <u>Service</u>			<u>Thorne Place</u>	
REPAIRED: <u>Serviced</u>				
PARTS: <u>Filters</u> <u>251.⁹⁹</u> <u>Thompson</u>				
<u>Filters</u> <u>249.²³</u> <u>Thompson</u>				



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0506</u>	HOURS _____ DAYS _____	REASON PARTS _____ LABOR _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>			POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>323F</u>	OTHER _____	OTHER _____	COMPONENT LOCATION	
SERIAL # _____			FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: _____ DATE COMPLETED <u>7-19-18</u>	
			MECHANIC <u>James</u>	
			JOB NAME/LOCATION <u>Beckwith west</u> JOB NUMBER _____	
PROBLEM: <u>Service</u>				
REPAIRED: <u>serviced</u>				
PARTS: <u>All Filter</u> <u>506.12</u> <u>Thompson</u>				
<u>after Air</u> <u>5F. 22</u> <u>Thompson</u>				

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>506</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____			
MAKE <u>CAT</u>	REASON _____				
MODEL <u>323F</u>	PARTS _____ LABOR _____				
SERIAL # _____	OTHER _____				
HOUR METER _____					
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>1-10-18</u> DATE COMPLETED <u>1-11-18</u>			
		MECHANIC <u>Steven B.</u>			
		JOB NAME/LOCATION <u>Town Center II</u>		JOB NUMBER	
PROBLEM: <u>Fuel Filter indicator on.</u>					
REPAIRED: <u>replaced filters still coming on</u> <u>replaced sensor light not on now.</u>					
PARTS: <u>filters</u> <u>53.46</u> <u>Thompson</u> <u>Sensor</u> <u>133.57</u> <u>Thompson</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0506</u>	HOURS _____ DAYS _____ REASON PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>CAT</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>323F</u>		COMPONENT LOCATION		
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER <u>600HRS</u>		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>11-13-17</u> MECHANIC <u>James & Steven</u>		
		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER	
PROBLEM: <u>Service</u>				
REPAIRED: <u>Serviced</u>				
PARTS: <u>All Filters & Sample Kits 6171^{co} Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>314</u>	HOURS _____ DAYS _____ REASON PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>CAT</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>323F</u>		COMPONENT LOCATION		
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>2-20-17</u>	MECHANIC _____	
		JOB NAME/LOCATION <u>Legends</u>	JOB NUMBER	
PROBLEM: <u>replacement Tips & Pins</u>				
REPAIRED: _____				
PARTS: <u>Tip & Pins</u> <u>\$264.47</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0506</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>323F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>5500 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>9-16-21</u> DATE COMPLETED <u>10-2-21</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC _____	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION	JOB NUMBER
PROBLEM: <u>Service</u>				
REPAIRED: <u>Serviced</u>				
PARTS: <u>All Filters</u> <u>510.85</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0506</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>323F</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>4990 HRS</u>				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE: <u>6-18-21</u> DATE COMPLETED _____	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC <u>James & Thompson</u>	
SMOKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION <u>To Shop</u> JOB NUMBER _____	
PROBLEM: <u>Service</u>					
REPAIRED: <u>Serviced</u>					
PARTS: <u>All Filters</u> <u>369.51</u> <u>Thompson</u>					
<u>Det injector & Thompson Mechanic</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0506</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>323F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>5-7-21</u> DATE COMPLETED <u>5-10-21</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Carver Station</u>	JOB NUMBER
PROBLEM: <u>broken lower front glass</u>				
REPAIRED: <u>replaced glass</u>				
PARTS: <u>glass</u> <u>165.53</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0506</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>323F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>3-5-21</u> DATE COMPLETED <u>3-5-21</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>East Gate</u>	JOB NUMBER _____
PROBLEM: <u>broken clamp</u>				
REPAIRED: <u>bucket cylinder Tube clamp missing. replaced</u>				
PARTS: <u>clamp & bolts</u> <u>63.72</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0506</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>323F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>4,500 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>12-15-20</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Ashland Farms</u>	JOB NUMBER _____
PROBLEM: <u>Service</u>				
REPAIRED: <u>Serviced</u>				
PARTS: <u>All Filters</u> <u>542.1¹²</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0506</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>323F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>12-9-21</u> MECHANIC <u>Anthony</u> JOB NAME/LOCATION <u>West Trivinity</u> JOB NUMBER _____		
PROBLEM: <u>Teeth</u>				
REPAIRED: <u>Teeth</u>				
PARTS: <u>4 Tips & locks</u> <u>474.03</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0506</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>323F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>6K HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE <u>3-31-22</u> DATE COMPLETED <u>4-2-22</u> MECHANIC <u>Ben + Anthony</u>	
PROBLEM: <u>Service</u>			JOB NAME/LOCATION <u>Vintage Edge</u> JOB NUMBER _____	
REPAIRED: <u>Serviced</u>				
PARTS: <u>All Filters</u> <u>533, 23</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0506</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>323F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOURLY METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: _____ DATE COMPLETED <u>8-18-22</u>	
			MECHANIC <u>Anthony</u>	
PROBLEM: <u>missing teeth 54" bucket</u>			JOB NAME/LOCATION <u>Violet Edge</u> JOB NUMBER _____	
REPAIRED: <u>replaced missing teeth</u>				
PARTS: <u>4 Teeth, pins + locks</u> <u>672.46</u> <u>Thompson</u>				
<u>Tip 143352</u>				
<u>Pin 114-0358</u>				
<u>lock 114-0359</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0516</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Volvo</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>EC350</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOOR METER <u>3K HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: <u>4-19-22</u> DATE COMPLETED <u>4-23-22</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Ben Anthony</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>West Trinity</u>	JOB NUMBER	
PROBLEM: <u>Service</u>				
REPAIRED: <u>Serviced</u>				
PARTS: <u>All Filters</u> <u>612.57</u> <u>Scott Equipment</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0506</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>323F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>6,500 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE <u>6-20-22</u> DATE COMPLETED <u>6-29-22</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Ben + Anthony</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Stone Trace</u> JOB NUMBER _____		
PROBLEM: <u>service</u>				
REPAIRED: <u>replaced broken track pin,</u> <u>serviced</u>				
PARTS <u>All Filters</u> <u>563.0</u> <u>Thompson</u>				
<u>Master pin</u> <u>59.44</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0506</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>323F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>7048 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE <u>7-11-22</u> DATE COMPLETED <u>7-12-22</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>ALL</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____		
PROBLEM: <u>Det. issue & needs rails</u>				
REPAIRED: <u>new det injector & calibration Thompson</u> <u>replaced rails & sprockets 2-Track pins</u>				
PARTS: <u>Inj. & labor</u> <u>1,145.²⁸</u> <u>Thompson</u>				
<u>Rails & sprockets</u> <u>6200.⁰⁰</u> <u>Thompson</u>				
<u>Paul labor</u> <u>1,975.⁵⁰</u> <u>Thompson</u>				
<u>2-pins & bolts</u> <u>264.²³</u> <u>Thompson</u>				
<u>2-seals</u> <u>24.⁰²</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0506

MAKE Cat

MODEL 323F

SERIAL # _____

HOURLY METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 10-13-22

MECHANIC Ben

JOB NAME/LOCATION

Hawthorn

JOB NUMBER

PROBLEM: bad batteries

REPAIRED: replaced batteries

PARTS: 4-29H-VHD

\$530.97

Interstate Battery

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0506</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>323F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>7K HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>12-6-22</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Anthony</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>service</u>				
REPAIRED: <u>serviced</u>				
PARTS: <u>All Filters</u> <u>672.09</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0506</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>323F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>11-21-22</u> DATE COMPLETED <u>12-2-22</u> MECHANIC <u>Anthony</u>		
PROBLEM: <u>left hand control broken</u>		JOB NAME/LOCATION <u>Limestone Trail</u> JOB NUMBER _____		
REPAIRED: <u>replaced broken hand control</u>				
PARTS: <u>Hand control</u> <u>1148.47</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIPMENT DOWNTIME

COMPONENT CODES

EQUIP. # 0506

HOURS _____ DAYS _____

MAKE CAT

REASON _____

MODEL 323F

PARTS _____ LABOR _____

SERIAL # _____

OTHER _____

HOUR METER 7600 HRS

MILES _____

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE 5-19-23 DATE COMPLETED 5-22-23

MECHANIC Anthony & Bryan

JOB NAME/LOCATION

Vintage Edge

JOB NUMBER

PROBLEM: Service

REPAIRED: Serviced

PARTS: Filters

685. 57

Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0506</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>323F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>4-5-2020</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>ALL</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Jones Brummett</u>	JOB NUMBER
PROBLEM: <u>Detoxing cab</u>				
REPAIRED: <u>replaced cab filters</u>				
PARTS: <u>cab filters</u> \$ <u>79.40</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>0506</u> MAKE <u>CAT</u> MODEL <u>323F</u> SERIAL # _____ HOUR METER <u>4500 HRS</u> MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____												
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>7-27-20</u> DATE COMPLETED <u>8-27-20</u> MECHANIC <u>Ben & Thompson</u> <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:50%;">JOB NAME/LOCATION <u>To Shop</u></td> <td style="width:50%;">JOB NUMBER</td> </tr> </table>	JOB NAME/LOCATION <u>To Shop</u>	JOB NUMBER										
JOB NAME/LOCATION <u>To Shop</u>	JOB NUMBER													
PROBLEM: <u>Service & EGR cooler leaking</u>														
REPAIRED: <u>Serviced, removed EGR cooler & replaced</u> <u>Thompson did software reboot</u>														
<table style="width:100%;"> <tr> <td style="width:33%;">PARTS: <u>All Filters</u></td> <td style="width:33%; text-align: right;"><u>497.³⁸</u></td> <td style="width:33%; text-align: right;"><u>Thompson</u></td> </tr> <tr> <td><u>Gaskets & seals</u></td> <td style="text-align: right;"><u>108.⁸⁶</u></td> <td style="text-align: right;"><u>Thompson</u></td> </tr> <tr> <td><u>EGR cooler</u></td> <td style="text-align: right;"><u>2177.⁷³</u></td> <td style="text-align: right;"><u>Thompson</u></td> </tr> <tr> <td><u>2-wk sensors</u></td> <td style="text-align: right;"><u>1700.⁰⁰</u></td> <td style="text-align: right;"><u>Thompson</u></td> </tr> </table>			PARTS: <u>All Filters</u>	<u>497.³⁸</u>	<u>Thompson</u>	<u>Gaskets & seals</u>	<u>108.⁸⁶</u>	<u>Thompson</u>	<u>EGR cooler</u>	<u>2177.⁷³</u>	<u>Thompson</u>	<u>2-wk sensors</u>	<u>1700.⁰⁰</u>	<u>Thompson</u>
PARTS: <u>All Filters</u>	<u>497.³⁸</u>	<u>Thompson</u>												
<u>Gaskets & seals</u>	<u>108.⁸⁶</u>	<u>Thompson</u>												
<u>EGR cooler</u>	<u>2177.⁷³</u>	<u>Thompson</u>												
<u>2-wk sensors</u>	<u>1700.⁰⁰</u>	<u>Thompson</u>												

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0506</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>323F</u>	PARTS _____ LABOR _____	COMPONENT LOCATION		
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER <u>FK HRS</u>		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE <u>10-2-23</u> DATE COMPLETED _____		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Anthony & Ben</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>To Shop</u>	JOB NUMBER _____	
PROBLEM: <u>EGR & DPF</u>				
REPAIRED: <u>removed DPF and had cleaned.</u>				
<u>replaced bal EGR module assembly.</u>				
<u>re-calibrate system</u>				
<u>replaced hose on top of boom.</u>				
<u>replaced broken temp. sensors</u>				
PARTS: <u>EGR</u> <u>685.83</u> <u>Returned</u> <u>Thompson</u>				
<u>hose</u> <u>342.11</u> <u>Thompson</u>				
<u>Temp. sensor</u> <u>494.98</u> <u>Thompson</u>				
<u>DPF clean</u> <u>1775.00</u> <u>Emission coding</u>				
<u>Module Air</u> <u>2068.07</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0506</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>323F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>8500 HAS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>3-18-24</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Anthony</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>STONE TRACE</u>	JOB NUMBER _____
PROBLEM: <u>Service</u>				
REPAIRED: <u>Serviced</u>				
PARTS: <u>Filters</u> <u>467.12</u> <u>Thompson</u>				
<u>2-Filter</u> <u>118.42</u> <u>Thompson</u>				

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

24 bolts & nut	206. ⁷⁷	Scott Equipment
36 bolts & nuts	310. ⁰⁰	Scott Equipment

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0506</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>323F</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>9K HRS</u>				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE <u>10-8-24</u> DATE COMPLETED <u>10-8-24</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC <u>Anthony</u>	
SMOKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION	
				<u>Quail Run</u>	
				JOB NUMBER	
PROBLEM: <u>Service</u>					
REPAIRED: <u>Service</u>					
PARTS: <u>Filters</u> <u>652.01</u> <u>Thompson</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0506</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>323F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>8K NRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>9-28-23</u> DATE COMPLETED <u>9-26-23</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Arthur & Justin</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>41st Ave</u>	JOB NUMBER _____
PROBLEM: <u>Service</u>				
REPAIRED: <u>serviced</u>				
PARTS: <u>Filters</u> <u>5P3.05</u> <u>Thompson</u>				