



SCOTT EQUIPMENT

HEAVY-DUTY COMMITMENT

Scott Equipment Company, LLC

140 Waldron Rd.

Lavergne, TN 37086

Ph: 615-793-3888 • Fax: (615) 793-9655

www.scottcompanies.com

Ship to

Thorne Excavating
1039 Maple Hill Rd
Lebanon, TN 37087

Invoice to:

THORNE'S EXCAVATING CO
624 OLD HORN SPRINGS RD
LEBANON TN 37087

Branch NASHVILLE		
Date 08/15/24	Time 07:08:57 (O)	Page 02
Account No. THORN006	Phone No. 6154445142	Invoice No. X49331
Ship Via	Purchase Order NEEDED	
Sales Tax License No.	Federal Exemption No.	
		Salesperson

Attention: MARK THORNE

DESCRIPTION

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS	
242761	A40G VOLVO	7057	VCE0A40GA00352147	07/29/20	2500 FM
	A40	896336		07/29/23	5000 PR
Picked up new IECU and drove back to job. Tractor trailer was on its side in middle of road. Got blocked in and had to wait until the wrecker got there to get into jobsite. Got into jobsite and found machine. Removed test IECU. Installed new one and programmed. Performed regen. No codes came back. Spoke to them on site about parking brake issue. Machine is good to go.					
<u>ADDITIONAL DESCRIPTION:</u>					
Ben 931-310-4950					
1039 Maple Hill Rd Lebanon, TN 37087					
FRTIN	FRT		1	64.22	64.22
17509773	INSTRUMENT CLUS		1 N	1257.89	1257.89
				PARTS	1322.11
				LABOR	2144.15
10400089			SEGMENT TOTAL==>		3466.26

***** WORK ORDER TOTALS *****

PARTS	1322.11
LABOR	2144.15
DISPOSAL FEE	25.00
ENVIRONMENT FEE	25.00
MILEAGE	504.00
SUPPLIES	89.09
SUB TOTAL==>	4109.35
TN STATE TAX 7.00%	287.65
LAVERGNE 2.75%	113.01
CUSTOMER TOTAL	4510.01

SCOTT EQUIPMENT COMPANY, LLC TERMS:

PAYABLE ON THE 10th OF MONTH FOLLOWING MONTH OF PURCHASE.
ALL ACCOUNTS NOT PAID IN FULL BY THE DUE DATE MAY BE SUBJECT TO A LATE CHARGE UP TO THE MAXIMUM AMOUNT ALLOWED BY STATE LAW/
CREDIT CARD PAYMENTS ARE SUBJECT TO A 3% CONVENIENCE FEE.

SIGN _____

RECEIVED BY _____



SCOTT EQUIPMENT

HEAVY-DUTY COMMITMENT

Scott Equipment Company, LLC

140 Waldron Rd.
Lavergne, TN 37086

Ph: 615-793-3888 • Fax: (615) 793-9655

www.scottcompanies.com

Ship to:

Thorne Excavating
1039 Maple Hill Rd
Lebanon, TN 37087

Invoice to:

THORNE'S EXCAVATING CO
624 OLD HORN SPRINGS RD
LEBANON TN 37087

1204

Attention: MARK THORNE

Branch NASHVILLE		
Date 08/15/24	Time 07:08:57 (O)	Page 01
Account No. THORN006	Phone No. 6154445142	Invoice No. X49331
Ship Via	Purchase Order NEEDED	
Sales Tax License No.	Federal Exemption No.	
		Salesperson

DESCRIPTION

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
242761	A40G VOLVO	7057	VCE0A40GA00352147	07/29/20	2500 FM
	A40		896336	07/29/23	5000 PR

SEGMENT# 1 S S5401 NA 08/02/24 08/09/24 08/30/24

Multiple codes

COMPLAINT:

Customer states the DEF gauge bounces from full to empty and back again. Has multiple codes listed below.

EF2579-14 The engine control unit (E-ECU) registers:

Malfunction in the aftertreatment system.

EF3600-9 Minor bus communication failure

EF3602-9 Critical bus communication failure

CAUSE:

Bad IMCU

Parking brake is not working - Customer aware as it has been an ongoing issue.

CORRECTION:

Drove to jobsite. Machine had 29 inactive errors, checked fuses, all were good. Checked over wiring and for loose connections, didn't find any. Machine had several errors for the display, didn't find when checked can bus, I had a test IECU with me. Installed it and updated all ECUs and did a service regen. Regen went through with no issue. Test ran truck, it did ok until I parked the truck. After stopping truck, setting the parking break and shutting the truck off it started to roll. I was able to get the truck started and stopped before it hit anything. Talked to 2 of the guys on site, they said they know the parking break is bad and has been for about 1 1/2 years. Ordered new IMCU. Did not have in stock. Leaving test computer on the machine so they can use it until the new one comes in.

JOSH JR. SAID

CONTINUED ON PAGE 02

SCOTT EQUIPMENT COMPANY, LLC TERMS:

PAYABLE ON THE 10th OF MONTH FOLLOWING MONTH OF PURCHASE.

ALL ACCOUNTS NOT PAID IN FULL BY THE DUE DATE MAY BE SUBJECT TO A LATE CHARGE UP TO THE MAXIMUM AMOUNT ALLOWED BY STATE LAW.

CREDIT CARD PAYMENTS ARE SUBJECT TO A 3% CONVENIENCE FEE

SIGN _____

RECEIVED BY _____

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
IP. # <u>1206</u>		HOURS _____	DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Volvo</u>		REASON		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>A40G</u>		PARTS _____	LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>7,500 HRS</u>				OTHER _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE: _____	DATE COMPLETED <u>8-13-25</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC <u>Bryan</u>	
ROCKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION	JOB NUMBER
				<u>TCAT</u>	

PROBLEM: service

REPAIRED: serviced

PARTS: Filters 868.92 Scott Equipment

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 1206

MAKE Volvo

MODEL A40G

SERIAL # _____

HOUR METER 5K HRS

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 1-17-23

MECHANIC Anthony

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: service bought used

REPAIRED: serviced

PARTS: Filters 1,539.⁰³

TEC

THORNE'S EXCAVATING COMPANY, LLC SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 1206
MAKE Volvo
MODEL A40G
SERIAL # _____
HOUR METER 5500 HRS
MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
REASON _____
PARTS _____ LABOR _____
OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER
OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SMOKES SHORTED VIBRATE OTHER _____

DATE: 3-27-23 DATE COMPLETED _____

MECHANIC _____

JOB NAME/LOCATION
Stave Trace

JOB NUMBER _____

PROBLEM: Service

REPAIRED: Service'd

PARTS: filters 261.94 Scott Equipment

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 1206
MAKE _____
MODEL _____
SERIAL # _____
HOUR METER GK HRS
MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
REASON _____
PARTS _____ LABOR _____
OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER
OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 7-12-23

MECHANIC Anthony

JOB NAME/LOCATION Steve Trace

JOB NUMBER _____

PROBLEM: Service

REPAIRED: Service

PARTS: Filters \$ 1,067.⁶³ Scott Equipment

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>1206</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Volvo</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>A40G</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
OUR METER <u>6500 HRS</u>		OTHER _____
MILES _____		

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE <u>10-6-23</u> DATE COMPLETED <u>10-19-23</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC <u>Anthony & Justin</u>
SMOKE SHORTED VIBRATE OTHER _____	JOB NAME/LOCATION <u>Stone Track</u> JOB NUMBER _____

PROBLEM: Service

REPAIRED: serviced

PARTS: oil & Air Filters 266.96 Term Filter sales

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 1206

MAKE Volvo

MODEL A40G

SERIAL # _____

HOUR METER 7,000 HRS

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE 5-24-24 DATE COMPLETED _____

MECHANIC _____

JOB NAME/LOCATION
Stone Trace

JOB NUMBER _____

PROBLEM: Service

REPAIRED: Service

PARTS: filters

8017.38

Scott Equipment

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1206</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Volvo</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>A40G</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE <u>8-22-24</u>	DATE COMPLETED <u>8-15-24</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Ben + Scott Equipment</u>	
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION	JOB NUMBER
		<u>Trail Run</u>	
PROBLEM: <u>det pick up bad ECM failure</u>			
<u>Scott Equipment installed shop ECM</u>			
REPAIRED: _____			
PARTS: <u>det pick up</u> <u>1549.22</u> <u>Scott Equipment</u>			
<u>Inst. dust & install</u> <u>4510.01</u> <u>Scott Equipment</u>			