

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>#1004</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL _____		PARTS LABOR		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>6,300 HRS</u>				OTHER _____	
MILES _____					

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED _____
MECHANIC James, Steven, Mark & Charles
JOB NAME/LOCATION Shop JOB NUMBER _____

PROBLEM: check over, bought used

REPAIRED: scrubbed, changed Transmission oil & hydraulic oil, Mark straightened panels & made lower grill, changed 5 leaking hoses. replaced all three belts, bleed brake system, made up exhaust from Turbo to muffler.

3-Hoses 550.⁰⁰ Nashville Rubber & Gasket

PARTS: Filters 493.⁷² Tenn Filter
Clamps & Rubber 30.⁰⁰ Nashville Rubber & Gasket
pipe & flex pipe 236.³² Tenn Filter
paint 29.⁰² Advance Auto Parts

2-Hoses 300.⁰⁰ Nashville Rubber & Gasket

Pipe 54.⁰⁰ Tenn Filter

All belts 159.⁴⁷ NAPA
rest Parts 514.⁹² Power Equipment

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1004</u>	HOURS _____ DAYS _____ REASON PARTS LABOR OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>Komatsu</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>HM300-1</u>		COMPONENT LOCATION		
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>11-15-16</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>JAMES + STEVEN B</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER	

PROBLEM: needs seat repaired

REPAIRED: removed seat having seat re-covered
4- used rear tires & rims. removed A/otations
1 side wall cut
seat belt replaced

4- Tires & rims \$12,000.⁰⁰ White Horse Equipment
 1- seat repair \$400.³⁶ Finishing Touch Upholstery
 seat belt & O-rings \$469.²¹ Power Equipment

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1004</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>HM300-1</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>12-1-16</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Steven + James</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Legend's Drive</u>	JOB NUMBER
PROBLEM: <u>Fuel leak</u>				
REPAIRED: <u>replaced a return fuel hose</u>				
PARTS: <u>hose</u> <u>200.00</u> <u>1/2" water hose + Gasket</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1004</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>HM300-1</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>12-7-16</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Steven B</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Legends Drive</u>	JOB NUMBER _____
PROBLEM: <u>blown hose</u>				
REPAIRED: <u>replaced hose at hitch</u>				
PARTS: <u>Hose</u> <u>320.00</u> <u>Nashville Rubber Gasket</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1004</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>Hm300-1</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # <u>1114</u>		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>6600 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: <u>1-13-17</u> DATE COMPLETED _____ MECHANIC <u>JAMES & STEVEN</u>	
			JOB NAME/LOCATION <u>Legends Dr.</u>	JOB NUMBER _____
PROBLEM: <u>Fuel leaking off</u>				
REPAIRED: <u>replaced fuel pump and main fuel filter</u>				
PARTS: <u>Pump & Orings</u> <u>\$196.52</u> <u>Power Equipment</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>#1001</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>Am300-1</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED _____	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC _____	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Legends Drive</u>	JOB NUMBER _____
PROBLEM: <u>Tire</u>				
REPAIRED: <u>replaced cut side wall</u>				
PARTS: <u>23.5x25</u> <u>2089.96</u> <u>GATEWAY</u>				
<u>Makam</u>				
<u>M5301</u>				
<u>E3/23 TL</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1004</u>	HOURS _____ DAYS _____	REASON PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>			POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>WM300-1</u>			COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER	
SERIAL # _____			OTHER _____	
HOUR METER _____				
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: _____ DATE COMPLETED <u>4-16-17</u> MECHANIC <u>ALL</u>	
			JOB NAME/LOCATION <u>Legends Dr</u>	JOB NUMBER
PROBLEM: <u>cut front tire</u>				
REPAIRED: <u>replaced front tire</u>				
PARTS: <u>Maxam 23.5X25</u> <u>2089.96</u> <u>Gatun, Tire</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1004</u>	HOURS _____ DAYS _____	REASON	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>KOMATSU</u>			POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>NM 300-1</u>	PARTS	LABOR	COMPONENT LOCATION	
SERIAL # _____	OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>6-15-17</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>JAMES & STEEN B.</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION	JOB NUMBER
			<u>legends Dr</u>	
PROBLEM: <u>Brake filter housing leaking.</u>				
REPAIRED: <u>replaced O-ring & back-up ring</u>				
PARTS: <u>O-rings & element</u> <u>184.78</u> <u>Power Equipment</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1004</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>HM 300-1</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>7-18-17</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Steven B & James</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shops</u>	JOB NUMBER
PROBLEM: <u>Fuel system stopped up. Clogged with rust.</u>				
REPAIRED: <u>Flushed fuel tank replaced main supply hose. cleaned out screens & sp. filters</u>				
PARTS: <u>Hose & fittings 65.00 Nashville Rubber Gasket</u>				

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>1201</u>		HOURS _____ DAYS _____		BASIC MACHINE	HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Komatsu</u>		REASON _____		POWER TRAIN	ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>HM300-1</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>7500 HRS</u>				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>2-21-18</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>James</u>		
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>		JOB NUMBER _____
PROBLEM: <u>Service</u>					
REPAIRED: <u>serviced</u>					
PARTS: <u>All Filters</u> <u>465.55</u> <u>TF5</u>					
<u>2 - A Filters</u> <u>85.02</u> <u>TF5</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963


EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1201</u>	HOURS _____ DAYS _____ REASON PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>Komatsu</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>HM300-1</u>		COMPONENT LOCATION		
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>4-18-18</u> MECHANIC <u>Charles</u> JOB NAME/LOCATION <u>Beckwith west</u> JOB NUMBER _____		
PROBLEM: <u>blown hose</u>				
REPAIRED: <u>replaced dump hose</u>				
PARTS: <u>hose assembly</u> <u>750.00</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>1201</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>HM300</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>OK HRS</u>				OTHER _____	
MILES _____					
REASON FOR FAILURE: ☐ BROKEN ☐ WORN ☐ ABUSE ☐ LOOSE ☐ SEIZED				DATE: <u>7-23-18</u> DATE COMPLETED <u>7-26-18</u>	
☐ OVERHEAT ☐ PLANNED ☐ CONTAM ☐ LEAKING ☐ NOISY ☐ SCRATCH				MECHANIC _____	
☐ SMOKES ☐ SHORTED ☐ VIBRATE ☐ OTHER _____				JOB NAME/LOCATION <u>Legends Dr</u> JOB NUMBER _____	
PROBLEM: <u>needs serviced</u>					
REPAIRED: _____					
PARTS: <u>All Filters</u> <u>505.5</u> <u>Tenn Filter</u>					



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1201</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>HM300-1</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>1-10-19</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Charles</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>MCH</u>	JOB NUMBER
PROBLEM: _____				
REPAIRED: <u>replaced missing fuel cap + bed control knob</u>				
PARTS: <u>cap</u> <u>\$2.14</u> <u>Power Equipment</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1201</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>Hm300-1</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>2,500 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE <u>2-7-19</u> DATE COMPLETED <u>2-27-19</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Charles</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>MCH</u>	JOB NUMBER
PROBLEM: <u>Service</u>				
REPAIRED: <u>serviced</u>				
PARTS: <u>Filters</u> <u>B48, 1B</u> <u>Term. Filter</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1201</u>	HOURS _____ DAYS _____	BASIC MACHINE	HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Komatsu</u>	REASON _____	POWER TRAIN	ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>HM300-1</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____	DATE COMPLETED <u>3-21-19</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Charles</u>	
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Cargill</u>	JOB NUMBER _____
PROBLEM: <u>blown steering hose</u>			
REPAIRED: <u>replaced steering hose pump to filter</u>			
PARTS: <u>hose</u> <u>\$111.23</u> <u>Industrial Rubber & Gasket</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1201</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>Hm300-1</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>4-25-19</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Charles</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Ashland Farms</u>	JOB NUMBER _____
PROBLEM: <u>Broken Trans sight glass</u>				
REPAIRED: <u>Replaced sight glass</u>				
PARTS: <u>sight glass</u> <u>34⁷⁰</u> <u>Power Equipment</u>				

TEC


THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>1201</u> MAKE <u>Komatsu</u> MODEL <u>HM300-1</u> SERIAL # _____ HOUR METER <u>9K HRS</u> MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____												
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE <u>8-12-19</u> DATE COMPLETED <u>9-4-19</u> MECHANIC <u>Charles</u> JOB NAME/LOCATION <u>Abland Farms</u> JOB NUMBER _____												
PROBLEM: <u>Service</u> <u>needs u-joint</u>														
REPAIRED: <u>serviced, pulled radiator for repair</u> <u>replaced u-joints on rear drive shaft.</u>														
<table style="width:100%; border: none;"> <tr> <td style="width:30%;">PARTS: <u>All Filters</u></td> <td style="width:30%; text-align: right;"><u>506.13</u></td> <td style="width:40%; text-align: right;"><u>Tenn Filter sales</u></td> </tr> <tr> <td><u>Radiator repair</u></td> <td style="text-align: right;"><u>\$2600.10</u></td> <td style="text-align: right;"><u>Emission & cooling solutions</u></td> </tr> <tr> <td><u>2 u-joints</u></td> <td style="text-align: right;"><u>638.79</u></td> <td style="text-align: right;"><u>Power Equipment</u></td> </tr> <tr> <td><u>Rad cap</u></td> <td style="text-align: right;"><u>58.67</u></td> <td style="text-align: right;"><u>Power Equipment</u></td> </tr> </table>			PARTS: <u>All Filters</u>	<u>506.13</u>	<u>Tenn Filter sales</u>	<u>Radiator repair</u>	<u>\$2600.10</u>	<u>Emission & cooling solutions</u>	<u>2 u-joints</u>	<u>638.79</u>	<u>Power Equipment</u>	<u>Rad cap</u>	<u>58.67</u>	<u>Power Equipment</u>
PARTS: <u>All Filters</u>	<u>506.13</u>	<u>Tenn Filter sales</u>												
<u>Radiator repair</u>	<u>\$2600.10</u>	<u>Emission & cooling solutions</u>												
<u>2 u-joints</u>	<u>638.79</u>	<u>Power Equipment</u>												
<u>Rad cap</u>	<u>58.67</u>	<u>Power Equipment</u>												

TEC
THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>1201</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Komatsu</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>HM300-1</u>	PARTS LABOR	COMPONENT LOCATION
SERIAL # <u>1114</u>	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE <u>10-4-19</u> DATE COMPLETED <u>10-9-19</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Charles</u>
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION JOB NUMBER
		<u>Jones Brummett</u>
PROBLEM: <u>park brake problems</u>		
REPAIRED: <u>replaced park brake Actuator</u>		
PARTS: <u>Actuator valve</u> <u>1,023.⁹¹</u> <u>Power Equipment</u>		



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1201</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL _____		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>12-10-19</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Charles</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Jones Brummett</u>	JOB NUMBER _____	
PROBLEM: <u>Hyd tube off at manifold cracked</u>				
REPAIRED: <u>replaced tube & O-rings</u>				
PARTS <u>Tube And O-rings \$1,010.03</u> <u>Power Equipment</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1201</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>HM300-1</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>12-14-19</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Charles</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: _____				

REPAIRED: <u>spare starter</u>				

PARTS: <u>After market</u> <u>315.⁷³</u> <u>Crook Auto Electric</u>				
<u>starter</u>				
<u>CE2 5W1</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1201</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>HM300-1</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>12-12-19</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Charles</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Jones Brummett</u> JOB NUMBER _____		
PROBLEM: <u>won't start</u>				
REPAIRED: <u>replaced fuel filter & bad hard pump.</u>				
<u>replaced bad starter</u>				
PARTS: <u>2-Fuel Filters</u> <u>124.76</u> <u>Powe Equipment</u>				
<u>Hard pump</u> <u>1284.14</u> <u>Powe Equipment</u>				
<u>Starter</u> <u>1284.14</u> <u>Powe Equipment</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>120B</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>HM300-1</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>9500 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>12-19-19</u> DATE COMPLETED <u>1-17-2020</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Ali</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Jones Brummett</u>	JOB NUMBER
PROBLEM: <u>Service</u>				
REPAIRED: <u>Serviced</u>				
PARTS: <u>All Filters</u> <u>564.91</u> <u>Two Filter Saks</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1201</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>HM300-1</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: _____ DATE COMPLETED <u>9-21-20</u> MECHANIC <u>Ben</u>	
			JOB NAME/LOCATION <u>Farm</u>	JOB NUMBER
PROBLEM: <u>won't start, old batteries</u>				
REPAIRED: <u>replaced batteries</u>				
PARTS: <u>2-4D-XHD</u> <u>397.19</u> <u>Interstate Battery</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1201</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>HM300-1</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>10K HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>2-2-21</u> DATE COMPLETED <u>2-8-21</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>EAST GATE</u>	JOB NUMBER
PROBLEM: <u>Service</u>				
REPAIRED: <u>serviced</u>				
PARTS: <u>All Filters</u> <u>626.32</u> <u>Tenn Filter</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1201</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>HM300-1</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: <u>5-13-21</u> DATE COMPLETED <u>5-14-21</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Ben</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>MT Juliet Substation</u> JOB NUMBER _____		
PROBLEM: <u>battery fell in battery box</u>				
REPAIRED: <u>repaired box & replaced bad battery.</u>				
<u>Repaired wiring.</u>				
PARTS: <u>4D battery</u> <u>198.60</u> <u>Interstate battery</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1201</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>HM300-1</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOURLY METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>9-9-21</u> DATE COMPLETED <u>10-1-21</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC _____	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>seal & fix leaks</u>				
REPAIRED: <u>replaced seal, sealed accumulators</u>				
<u>replaced final covers on center axle</u>				
PARTS:				
<u>O-rings & seals</u>	<u>175.³⁵</u>	<u>Power Equipment</u>		
<u>seals</u>	<u>1175.⁰⁰</u>	<u>Power Equipment</u>		
<u>seal</u>	<u>2000.⁴⁹</u>	<u>Thompson</u>		
<u>charge valves</u>	<u>166.⁰⁰</u>	<u>Power Equipment</u>		
<u>rack accumulators</u>	<u>327.⁰⁰</u>	<u>Mid South Hydraulics</u>		
<u>Carrie kit</u>	<u>2483.⁰⁰</u>	<u>Power Equipment</u>		
<u>Carrier kit</u>	<u>2537.⁹⁹</u>	<u>Power Equipment</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1201</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>KOMATSU</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>HM300L</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>10,390 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE <u>10-18-21</u> DATE COMPLETED <u>10-20-21</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>shop</u>	JOB NUMBER _____
PROBLEM: <u>front L.H. left seal leaking</u>				
REPAIRED: <u>replaced left yoke seal</u>				
PARTS: <u>seal & o-ring 100 \$</u> <u>Power Equipment</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>1261</u> MAKE <u>Komatsu</u> MODEL <u>HM300-1</u> SERIAL # _____ HOUR METER <u>10,500 HRS</u> MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED _____ MECHANIC _____ JOB NAME/LOCATION _____ JOB NUMBER _____
PROBLEM: <u>Service</u>		
REPAIRED: <u>Serviced</u>		
PARTS: <u>All Filters</u> <u>75-7.09</u> <u>Tenn Filte sales</u>		

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>1201</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>HM300-1</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____				DATE <u>7-21-22</u> DATE COMPLETED _____ MECHANIC <u>Ben</u>	
PROBLEM: <u>batteries stolen, cables cut & rods broken</u>				JOB NAME/LOCATION <u>West Trinity</u> JOB NUMBER _____	
REPAIRED: _____ _____ _____ _____ _____ _____ _____ _____ _____					
PARTS: <u>red cable</u> <u>black cable</u> <u>Rods & nuts</u> <u>2-4D-XHD</u>		<u>69.25</u> <u>98.75</u> <u>91.65</u> <u>397.18</u>		<u>Crooks</u> <u>Napa</u> <u>Power Equipment</u> <u>Interstate battery</u>	

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1201</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>HM300-1</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>HK HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>4-4-22</u> DATE COMPLETED <u>4-11-22</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>retarder sensors</u>				
<u>2 - KM 7861-93-3320</u>				
REPAIRED: <u>replaced sensors</u>				
PARTS: <u>Retarder sensors 344.65</u> <u>Power Equipment</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1201</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>HM300-1</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
OUR METER <u>11K WRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>4-1-22</u> DATE COMPLETED <u>4-15-22</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>ALL</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>Service</u>				
REPAIRED: <u>Serviceed</u>				
PARTS: <u>474.72</u> <u>Tenn Filter</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1201</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>HM300-1</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOOR METER <u>11,500 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE <u>8-31-22</u>	DATE COMPLETED <u>9-2-22</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Anthony</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Line Stone Trail</u>	JOB NUMBER _____
PROBLEM: <u>Service</u>				
REPAIRED: <u>Serviced</u>				
PARTS: <u>Filters</u> <u>824.01</u> <u>Tenn Filter sales</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 1201

MAKE Komatsu

MODEL Hm300-1

SERIAL # _____

HOURLY METER 12K Hrs

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON _____

PARTS _____

LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE 3-2-23 DATE COMPLETED 28-23

MECHANIC Anthony

JOB NAME/LOCATION

Sub Station

JOB NUMBER

PROBLEM: service

REPAIRED: serviced

PARTS: Filters

765.28

Team Filler Sales

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 1201
MAKE Komatsu
MODEL HM300-1
SERIAL # _____
HOUR METER _____
MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
REASON _____
PARTS _____ LABOR _____
OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
COMPONENT LOCATION
FRONT REAR LEFT RIGHT UPPER LOWER
OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SMOKES SHORTED VIBRATE OTHER _____

DATE: 7-17-23 DATE COMPLETED 10-18-23

MECHANIC Ben + All

JOB NAME/LOCATION

JOB NUMBER

To Shop

PROBLEM bad front drum bar bearing

REPAIRED: replaced Three tires both rear & RT center
packed RT front suspension cylinder
packed LF rear suspension cylinder
repaired RT first step. replaced front drum bar bearing
sealed amp flow valve

PARTS:

bearing

842.⁰⁰

Power Equipment

2 boots

339.¹³

Power Equipment

cylinder seals

715.⁹²

Power Equipment

3 Tires

2400.⁰⁰ EA

Gateway Tire

rear cylinder seals

785.²¹

Power Equipment

AMP flow seals

468.

Power Equipment

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1201</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>HM300-L</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>12,500 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE <u>12-15-23</u> DATE COMPLETED <u>12-21-23</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC _____	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Sparta PK</u>	JOB NUMBER _____
PROBLEM: <u>Service</u>				
REPAIRED: <u>Service</u>				
PARTS: <u>Filters</u> <u>767.45</u> <u>Thorn Filtre</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1201</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>HM300-1</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>1-22-24</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Anthony</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>91st Ave</u>	JOB NUMBER
PROBLEM: <u>won't start</u>				
REPAIRED: <u>replaced weak batteries</u>				
PARTS <u>Z-4D-XHD</u> <u>468.00</u> <u>Interstate batteries</u>				

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
IP. # <u>1201</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Komatsu</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>HM300-1</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
VES _____		

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE: <u>6-19-25</u> DATE COMPLETED _____		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC <u>Bryan</u>		
ROCKES SHORTED VIBRATE OTHER _____	<table border="1"> <tr> <td data-bbox="730 766 1104 829">JOB NAME/LOCATION <u>Shop</u></td> <td data-bbox="1104 766 1347 829">JOB NUMBER</td> </tr> </table>	JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER		

PROBLEM: Anti-freeze in oil.

REPAIRED: replaced water pump

PARTS: <u>Pump, Thermostat & gaskets</u>	<u>1,375.⁵¹</u>	<u>Power Equipment</u>
<u>return some parts</u>	<u>-</u>	<u>Power</u>
<u>hose</u>	<u>148.⁹⁶</u>	<u>Crack Electric</u>