

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>2901</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Lay Mar</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>JM 300</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # <u>Broom</u>		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE <u>3-4-21</u> DATE COMPLETED <u>4-19-21</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>James</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>shop</u>	JOB NUMBER _____
PROBLEM: <u>won't run</u>				
REPAIRED: <u>replaced module & sending unit</u>				
PARTS: <u>module & strap</u> <u>400.²⁹</u> <u>Thompson</u>				
<u>sending unit</u> <u>30.¹²</u> <u>Thompson</u>				
<u>fuel solenoid</u> <u>AMALON</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>2901</u> MAKE <u>Lay Mor</u> MODEL <u>300</u> SERIAL # <u>broom</u> HOUR METER <u>500 HRS</u> MILES _____		EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____		COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____				DATE: <u>9-24-20</u> DATE COMPLETED <u>11-2-20</u> MECHANIC <u>All</u> JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____	
PROBLEM: <u>bought used, check over,</u> <u>no sweeper pressure (new pump installed on Brush, Did Not fix</u> <u>stopping of Brush.</u>					
REPAIRED: <u>serviced, replaced rear tires. Hyd. drain plug</u> <u>loose, washed</u> <u>replaced broom motor</u> <u>removed valve body cleaned out valve body</u> <u>found piece of metal in check valve.</u>					
PARTS: <u>Oil Filter</u> <u>4.41</u> <u>Napa</u> <u>Air & Hyd Filters</u> <u>36.93</u> <u>Napa</u> <u>2-205/70-14 Tires</u> <u>193.93</u> <u>Charlies Tire</u> <u>valve & Filter</u> <u>285.19</u> <u>Thompson Rental</u> <u>New pump motor / Hydro</u> <u>1,008.00</u> <u>Thompson Rental</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>2901</u> MAKE <u>Layman</u> MODEL <u>300</u> SERIAL # <u>6000</u> HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>9-23-21</u> DATE COMPLETED <u>9-24-21</u> MECHANIC <u>Ben</u>
		JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____
PROBLEM: <u>Travel slow, low press.</u>		
REPAIRED: <u>replaced main hydraulic pump.</u>		
PARTS: <u>Main Pump</u> <u>2475.00</u> <u>Thompson</u> <u>hose</u> <u>12.35</u> <u>Crooks</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>2901</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Laymor</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>300</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>2-5-24</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Bryan</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shops</u>	JOB NUMBER _____
PROBLEM: <u>bad battery</u>				
REPAIRED: <u>replaced battery</u>				
PARTS: <u>75 FT3 battery</u> <u>183.83</u> <u>Advance</u>				