

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>336F 0508</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>336F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>500 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>9-11-18</u> MECHANIC <u>James & Charles</u>		
PROBLEM: <u>Service</u>		JOB NAME/LOCATION <u>Legendi Dr</u> JOB NUMBER _____		
REPAIRED: <u>Service</u>				
PARTS: <u>All Filters</u>		<u>487.10</u> <u>Thompson</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>0508</u> MAKE <u>Cat</u> MODEL <u>336F</u> SERIAL # _____ HOUR METER _____ MILES _____		EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____		COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____				DATE: _____ DATE COMPLETED <u>1-10-19</u> MECHANIC _____	
PROBLEM: <u>needs fuel filters</u>				JOB NAME/LOCATION: <u>Waxler Porcelain</u> JOB NUMBER _____	
REPAIRED: <u>replaced fuel filters</u>					
PARTS: <u>Fuel filters</u> <u>91.00</u> <u>Thompson</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0508</u>	HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>CAT</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>336F</u>		COMPONENT LOCATION		
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER <u>1K HRS</u>		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>3-21-19</u> DATE COMPLETED <u>3-26-19</u>	MECHANIC <u>JAMES & CHARLES</u>	
		JOB NAME/LOCATION <u>MC H</u>	JOB NUMBER	
PROBLEM: <u>Service</u>				
REPAIRED: <u>Serviced & sampled</u>				
PARTS: <u>All Filters</u> <u>527, 21</u> <u>Thompson Machinery</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0508</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>336F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>1600 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>6-29-19</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC _____	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Ashland Farms</u>	JOB NUMBER _____
PROBLEM: <u>Service</u>				
REPAIRED: <u>serviced</u>				
PARTS: <u>All</u> <u>486.98</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0508

MAKE CAT

MODEL 336F

SERIAL # _____

HOUR METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: 7-17-19 DATE COMPLETED 7-20-19

MECHANIC _____

JOB NAME/LOCATION

Ashland Farms

JOB NUMBER

PROBLEM:

bucket needs teeth

REPAIRED:

replaced all Teeth + locks

PARTS:

8-Teeth 286-2110 \$1,565.30

Thompson

8-locks 467-9823

~~Parts~~

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0508</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>336F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>2K HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>9-12-19</u> DATE COMPLETED <u>9-14-19</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC _____	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Ashland Farms</u>	JOB NUMBER _____
PROBLEM: <u>Service</u>				
REPAIRED: <u>Serviced</u>				
PARTS: <u>All Filters</u> <u>540, 39</u> <u>Thompson Machinery</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. <u>#0508</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>336F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>2,500 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE <u>11-22-19</u> DATE COMPLETED <u>11-27-19</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>All</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Jones Brummett</u>	JOB NUMBER _____	
PROBLEM: <u>Service</u>				
REPAIRED: <u>Serviced</u>				
PARTS: <u>All Filters</u> <u>540.30</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0508</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>336F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>3K HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE <u>2-21-2020</u> DATE COMPLETED <u>2-25-2020</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Charles & Bryan</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Jones Brummett</u>	JOB NUMBER _____
PROBLEM: <u>Service</u>				
REPAIRED: <u>Serviced</u>				
PARTS: <u>All Filters</u> <u>545.7L</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0508</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>336F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: _____ DATE COMPLETED <u>4-3-2020</u> MECHANIC <u>ALL</u>	
			JOB NAME/LOCATION <u>Jones Brummett</u> JOB NUMBER _____	
PROBLEM: <u>Detoxing cab</u>				
REPAIRED: <u>replaced cab filters Have two extra</u>				
PARTS: <u>Cab filters</u> <u>178.00</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0508</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>336F</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>4-16-2020</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Jones Drummeth</u> JOB NUMBER _____	
PROBLEM: _____			
REPAIRED: <u>missing Teeth</u>			
PARTS: <u>2x Teeth 4-bolts 457.99 Thompson</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0508</u>	HOURS _____ DAYS _____ REASON PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>CAT</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>336F</u>		COMPONENT LOCATION		
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER <u>3,460 HRS</u>		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>5-12-20</u>	DATE COMPLETED: <u>5-12-20</u>	
		MECHANIC: <u>Charles</u>		
		JOB NAME/LOCATION: <u>Tower Brummett</u>	JOB NUMBER: _____	
PROBLEM: <u>Wont regen.</u>				
REPAIRED: <u>replaced sensor, manually regen.</u>				
PARTS: <u>Air intake Temp sensor 47.89 Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0508</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>Cat</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>336F</u>	PARTS _____ LABOR _____	COMPONENT LOCATION		
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER <u>3500 HRS</u>		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: <u>5-13-20</u>	DATE COMPLETED <u>5-14-2020</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Charles</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION	JOB NUMBER	
		<u>Jones Brummett</u>		
PROBLEM: <u>Service</u>				
REPAIRED: <u>Service</u>				
PARTS: <u>All Filters</u> <u>561.75</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0508</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>336F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>4K HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE <u>11-16-20</u> DATE COMPLETED <u>12-10-20</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>James + Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>Service</u>				
REPAIRED: <u>serviced & washed</u>				
PARTS: <u>All Filters</u> <u>550.04</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0508</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>336F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>1-28-21</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Eastgate</u>	JOB NUMBER _____
PROBLEM: <u>needs Two teeth</u>				
REPAIRED: _____				
PARTS: <u>467-9821 Tip</u> <u>463.3#</u> <u>Thompson</u>				
<u>286-2110 lock</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0508</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>336F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>4500 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: <u>4-1-21</u> DATE COMPLETED _____		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>James & Cole</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Eastgate</u>	JOB NUMBER _____	
PROBLEM: <u>Service</u>				
REPAIRED: <u>Serviced</u>				
PARTS: <u>All Filters</u> <u>552.20</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0508</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>336F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
OUR METER <u>4000 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>4-2-21</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Eastgate</u>	JOB NUMBER _____
PROBLEM: <u>blown hose</u>				
REPAIRED: <u>replaced one stick cylinder hose</u>				
PARTS: <u>hose</u> <u>451.87</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0508</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>336F</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>5K HRS</u>				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____				DATE: <u>6-18-21</u> DATE COMPLETED <u>6-19-21</u>	
				MECHANIC <u>Bert + Caleb</u>	
				JOB NAME/LOCATION <u>Eastgate</u>	
				JOB NUMBER _____	
PROBLEM: <u>Service</u>					
REPAIRED: <u>serviced</u>					
PARTS <u>All Filters</u> <u>452.01</u> <u>Thompson</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0508</u>	MAKE <u>Cat</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MODEL <u>336F</u>	SERIAL # _____	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
HOURLY METER <u>5178 HRS</u>	MILES _____	PARTS _____ LABOR _____	COMPONENT LOCATION	
		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
			OTHER _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>7-10-21</u>	DATE COMPLETED <u>7-20-21</u>	
		MECHANIC <u>Ben</u>		
PROBLEM: <u>need Egr cooler + system flush</u> <u>2-damaged travel motor hoses</u>		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____	
REPAIRED: <u>replaced hoses replaced EGR cooler, flushed</u> <u>cooling system, changed oil in final drives</u>				
PARTS: <u>Cooler & gaskets 2730.⁶³ Thompson</u> <u>2-motor hoses 1523.¹² Nashville Rubber & Gasket</u> <u>coolant tank 591.⁸⁶ Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0508</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>336F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOOR METER <u>5500 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>9-3-21</u> DATE COMPLETED <u>9-3-21</u> MECHANIC <u>Ben</u>		
PROBLEM: <u>Service</u>		JOB NAME/LOCATION <u>Cover Station</u> JOB NUMBER _____		
REPAIRED: <u>Serviced</u>				
PARTS: <u>All Filters</u> <u>643.19</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0508</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>336F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>6K HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE <u>12-14-21</u> DATE COMPLETED <u>1-27-22</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>West Trinity</u>	JOB NUMBER
PROBLEM: <u>Service</u>				
REPAIRED: <u>Serviced</u>				
PARTS: <u>All Filters</u> <u>583.07</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0508</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>336F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>6,300 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>3-29-22</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Ben</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>West Trinity</u>	JOB NUMBER _____	
PROBLEM: <u>blown bucket cylinder hose on left side</u>				
REPAIRED: <u>replaced hose</u>				
PARTS: <u>hose</u> <u>460.19</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0508</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>336F</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____				DATE: _____ DATE COMPLETED <u>4/22</u>	
MECHANIC <u>Ben</u>				JOB NAME/LOCATION <u>West Trinity</u>	
JOB NUMBER _____					
PROBLEM: <u>won't start</u>					
REPAIRED: <u>batteries + starter</u>					
PARTS: <u>2- Gp 29</u> <u>241.32</u> <u>Inter-State Battery</u>					
<u>starter</u> <u>688.10</u> <u>ARB Electric</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0508</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>336F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>6600 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: <u>5-13-22</u> DATE COMPLETED <u>5-16-22</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Ben</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>West Trinity</u> JOB NUMBER _____		
PROBLEM: <u>Service</u>				
REPAIRED: <u>Service</u>				
PARTS: <u>Filters</u> <u>724.58</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0508</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>336F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>7K HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>7-27-22</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Anthony & Brian</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>West Trinity</u>	JOB NUMBER _____
PROBLEM: <u>Service</u>				
REPAIRED: <u>serviced</u>				
PARTS <u>All Filters</u> <u>858.47</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0125</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>336F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>9,500 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>8-9-22</u> MECHANIC <u>Anthony</u>		
PROBLEM: <u>Service</u>		JOB NAME/LOCATION <u>Limestone</u> JOB NUMBER _____		
REPAIRED: <u>Service</u>				
PARTS: <u>Filters</u> <u>678.82</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0508</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>336F</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>6,984 HRS</u>				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____				DATE: <u>8-3-22</u> DATE COMPLETED <u>8-8-22</u> MECHANIC <u>Ben</u>	
PROBLEM: <u>Fuel in engine oil</u>				JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____	
REPAIRED: <u>Replaced injector + tube o-rings on all 5 & 6 cylinders</u> <u>New valve cover gasket. changed oil twice</u>					
PARTS: <u>Seals + 2 oil fitters 280.00</u> <u>Seals & switch 330.00</u> <u>Thompson</u> <u>Thompson</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0508</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>336F</u>	PARTS _____ LABOR _____	COMPONENT LOCATION		
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: <u>12-14-22</u> DATE COMPLETED <u>12-15-22</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Ben & Anthony</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Hawthorne</u>	JOB NUMBER	
PROBLEM: <u>broken track pin.</u>				
REPAIRED: <u>replaced broken track pin</u>				
PARTS: <u>pin & bolts</u> <u>161.42</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0508</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>336F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>1-13-22</u> DATE COMPLETED <u>1-24-23</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Ben + Anthony</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Hawthorne</u>	JOB NUMBER _____
PROBLEM: <u>Oil hose leaking going to oil filter base</u>				
REPAIRED: <u>replaced hoses going to oil filter base</u>				
PARTS: <u>2 hoses</u> <u>586.14</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>050P</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>336F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>2-9-23</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>James</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Hawthorne</u>	JOB NUMBER _____
PROBLEM: <u>bucket broken, needs teeth and end shank.</u>				
REPAIRED: <u>welded bucket, replaced shank all new teeth</u>				
PARTS: <u>Teeth & locks</u> <u>1714.95</u> <u>Thompson</u>				
<u>Shank</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0508

MAKE Cat

MODEL 336F

SERIAL # _____

HOURLY METER 7500 HRS

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON _____

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: 3-2-23 DATE COMPLETED 3-3-23

MECHANIC Anthony & Larry

JOB NAME/LOCATION

Haw Thorne

JOB NUMBER

PROBLEM: Service

REPAIRED: Service

PARTS: Filters

67P. 18

Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0508

MAKE CAT

MODEL 336F

SERIAL # _____

HOUR METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON _____

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 4-10-23

MECHANIC Lawrence glass

JOB NAME/LOCATION
41st Ave

JOB NUMBER _____

PROBLEM: broken rt. glass

REPAIRED: replaced broken RT window

PARTS: glass

labor

1200.⁰⁰
299.⁶²

Thompson
Lawrence glass

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0508</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>Cat</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>336F</u>	PARTS _____ LABOR _____	COMPONENT LOCATION		
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>9-27-23</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Anthony</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>41st Ave</u>	JOB NUMBER _____	
PROBLEM: <u>Oil leak</u>				
REPAIRED: <u>replaced heavy lift solenoid</u>				
PARTS: <u>solenoid</u> <u>515-25</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0508</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>336F</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>9K HRS</u>		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>11-28-23</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Anthony & Justin</u>	
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>41st Ave</u>	JOB NUMBER _____
PROBLEM: <u>Service</u>			
REPAIRED: <u>Serviced</u>			
PARTS: <u>Filters</u> <u>678.12</u> <u>Thompson</u>			

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>05708</u>	HOURS _____ DAYS _____	BASIC MACHINE	HYDRAULIC	ENGINE IMPLEMENTS
MAKE <u>Cat</u>	REASON _____	POWER TRAIN	ELECTRIC	DRIVE TRAIN UNEXPLAINED
MODEL <u>336F</u>	PARTS _____ LABOR _____	COMPONENT LOCATION		
SERIAL # _____	OTHER _____	FRONT	REAR	LEFT RIGHT UPPER LOWER
HOUR METER <u>9200 HRS</u>		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE <u>2-6-24</u> DATE COMPLETED <u>2-8-24</u> MECHANIC <u>James & Ben</u>		
		JOB NAME/LOCATION <u>To Shop</u>	JOB NUMBER	
PROBLEM: <u>no det pressure</u> <u>missing swing drive dipstick</u> <u>2-leaking hoses at pump</u>				
REPAIRED: <u>replaced manifold & purged.</u> <u>replaced DPI= injector</u> <u>Thompson reset the system.</u>				
PARTS: <u>Det manifold</u> <u>809.⁴³</u> <u>Thompson</u> <u>Dip stick</u> <u>73.⁸⁹</u> <u>Thompson</u> <u>2-hoses</u> <u>319.⁸¹</u> <u>Thompson</u> <u>Injector</u> <u>437.²⁵</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0508</u>	HOURS _____ DAYS _____ REASON PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>CAT</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>336F</u>		COMPONENT LOCATION		
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER <u>9,500 HRS</u>		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>7-2-24</u> DATE COMPLETED <u>7-2-24</u> MECHANIC <u>Anthony</u> JOB NAME/LOCATION _____ JOB NUMBER _____		
PROBLEM: <u>Service</u>				
REPAIRED: <u>Serviced</u>				
PARTS: <u>Filters</u> <u>597, 73</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0508</u>	HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>336F Cat</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>336F</u>		COMPONENT LOCATION		
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>7-19-24</u> MECHANIC <u>Ben</u>		
		JOB NAME/LOCATION <u>Aubrey's</u>	JOB NUMBER _____	
PROBLEM: <u>ARD system not working. wait regen.</u>				
REPAIRED: <u>rebuild system.</u>				
PARTS: <u>head assembly</u> <u>2200.00</u> <u>Thompson</u>				
<u>coil</u> <u>219.95</u> <u>Thompson</u>				
<u>plug</u> <u>23.17</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0508</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>336F</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>8950 HRS</u>				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE: <u>11-5-24</u> DATE COMPLETED <u>11-6-24</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC <u>Ben & The boys</u>	
SMOKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION <u>High Park</u> JOB NUMBER _____	
PROBLEM: <u>pump flow on #2 pump low</u>					
REPAIRED: <u>serviced & replaced pump control valve</u>					
PARTS: <u>filter & valve 1896.50 Thompson</u>					

IEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0508</u>	HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>Cat</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>336F</u>		COMPONENT LOCATION		
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>6-11-25</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Bryan & Ben</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>TCAT</u>	JOB NUMBER	
PROBLEM: <u>starter clicking</u>				
REPAIRED: <u>replaced starter</u>				
PARTS: <u>rebuilt starter</u> <u>404.98</u> <u>Carguest</u>				

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
IP. # <u>0508</u>		HOURS _____ DAYS _____		BASIC MACHINE	HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>CAT</u>		REASON _____		POWER TRAIN	ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>336F</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SN # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
REMARKS _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>7-2-25</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Bryan</u>		
CHECKS SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>		
PROBLEM: <u>broken foot glass</u>			JOB NUMBER _____		

REPAIRED: replaced glass

PARTS: Foot glass 221. ~~84~~ 97 Thompson
Fuel pump & filter 1313. 97 Thompson