

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0117

MAKE Kenworth

MODEL 23' T880

SERIAL # _____

HOURLY METER _____

MILES 30k mi.

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS

LABOR

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE 3-28-24 DATE COMPLETED 4-4-24

MECHANIC _____

JOB NAME/LOCATION

JOB NUMBER

Shop

PROBLEM: Service

REPAIRED: Serviced

PARTS: Filters, no Engine Air 217.56

MHC

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0117

MAKE Mack

MODEL 17 GU713

SERIAL # _____

HOUR METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS

LABOR

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 6-11-24

MECHANIC Anthony

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: needs PTO pump

REPAIRED: replaced pump

PARTS: pump

601.05

OK Boely

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0117

MAKE Kenworth

MODEL Lowboy

SERIAL # _____

HOUR METER _____

MILES 35k mi

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON _____

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 7-29-24

MECHANIC Cakeb

JOB NAME/LOCATION

Shop

JOB NUMBER

PROBLEM: Service

REPAIRED: serviced

PARTS: All Filters

410.44

MHC

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0117

MAKE Kenworth

MODEL 23' 880

SERIAL # _____

HOURLY METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS

LABOR

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 9-10-24

MECHANIC James + Justin

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: RT front wheel seal leaking

REPAIRED: replaced seal on RT steer.

PARTS: 2 seals 12P. 02 Truck Pro

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0117</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Kenworth</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>23 T880</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES <u>45K mi</u>					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE: <u>5-16-25</u> DATE COMPLETED _____	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC <u>Bryce & Justin</u>	
SMOKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____	
PROBLEM: <u>Service, All four rear tires</u>					

REPAIRED: replaced all four rear tires.
serviced

PARTS: Oil, / fuel steering 319.47 MHC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION

IP. # 0117

MAKE Kenworth

MODEL 23' TPPD

SERIAL # _____

HOUR METER _____

MILES 45k mi

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON _____

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SHAKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 7-25-25

MECHANIC Snider

JOB NAME/LOCATION

Snider

JOB NUMBER

PROBLEM: 4-11R245

REPAIRED: replaced all 4 center axle tires

REMARKS: 4-11R24.5 RMR51 1,956.90 Snider Fleet

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
IP. # <u>0117</u>		HOURS _____ DAYS _____		BASIC MACHINE	HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Mack</u>		REASON _____		POWER TRAIN	ELECTRIC DRIVE TRAIN UNEXPLAINED
DEL <u>17 6U713</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
IAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
OUR METER _____				OTHER _____	
ES _____					
ASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>7-31-25</u> DATE COMPLETED <u>8-4-25</u>		
ERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Ben + Bryan</u>		
OKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>		
			JOB NUMBER _____		
BLEM: <u>sensor and air leak</u>					

REPAIRED: replaced lag axle valve, Trans. sensor and repaired air line.

PARTS: valve \$43.67 Fleetpride
Turbine sensor \$150.36 McMahon Trucks

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
IP. # <u>0117</u>		HOURS _____ DAYS _____		BASIC MACHINE	HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Mack</u>		REASON _____		POWER TRAIN	ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>17' 64713</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE: _____ DATE COMPLETED <u>8-12-25</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC <u>Snider</u>	
SHOCKS SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION <u>Snider</u>	JOB NUMBER _____
PROBLEM: <u>needs tires</u>					

REPAIRED: replaced two steer and 5/8 rear tires

RTS 2-38565 22.5 P490 4,225 317 Snider Fleet
6.11R-24.5
Rakon RMRS1

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION QUIP. # <u>0117</u> MAKE <u>Kenworth</u> MODEL <u>T850 23'</u> SERIAL # _____ HOUR METER _____ MILES <u>50K mi.</u>	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>8-15-25</u> DATE COMPLETED <u>8-26-25</u> MECHANIC <u>Caleb</u> JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____
PROBLEM: <u>Service</u>		

REPAIRED: serviced

PARTS: Filters 414.96 MHC
1 - FF5971NNFLG
1 - LF14000NNFLG
1 - K37-1029
1 - P640017
1 - J37-1007