

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0509</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>PC210LC-11</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>2K HRS</u>				OTHER _____	
MILES <u>Bought used 6-7-18</u>					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE: _____ DATE COMPLETED <u>6-18-18</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC <u>James & Tony</u>	
SMOKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION <u>Shop</u>	
PROBLEM: <u>service check over</u>				JOB NUMBER _____	
REPAIRED: <u>serviced</u>					
<u>adjusted Tracks</u>					
PARTS: <u>All Filters</u> <u>233.12</u> <u>Ten Filter</u>					
<u>P550909 Oil</u>		<u>P777639 IH</u>			
<u>P550774 Fuel</u>		<u>P781039 OH</u>			
<u>P551864 Fuel</u>		<u>PA5328 Cab Air</u>			
<u>P550787</u>		<u>59475 Hyd</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0509</u>	HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>Komatsu</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>PC210LC-11</u>		COMPONENT LOCATION		
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>6-27-18</u>		
		MECHANIC _____		
		JOB NAME/LOCATION _____	JOB NUMBER _____	
PROBLEM: _____ _____ _____ _____				
REPAIRED: <u>All books</u> _____ _____ _____ _____ _____ _____ _____ _____				
PARTS: <u>All books</u> <u>985.04</u> <u>Power Equipment</u> _____ _____ _____ _____				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0509</u>		HOURS _____	DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>PC210 LC</u>		PARTS _____	LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>2360 HRS</u>				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE: _____ DATE COMPLETED <u>8-7-18</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC <u>Charles</u>	
SMOKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION <u>Cargill</u>	
PROBLEM: <u>left control leaking</u>				JOB NUMBER _____	
REPAIRED: <u>replaced control seals</u>					
PARTS: <u>seals</u> <u>48.28</u> <u>Power Equipment</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0509</u>	HOURS _____ DAYS _____ REASON PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>Komatsu</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>PC210</u>		COMPONENT LOCATION		
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER <u>2520 HRS</u>		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>9-21-18</u>	DATE COMPLETED <u>9-21-18</u>	
		MECHANIC <u>James + Charles</u>		
PROBLEM: <u>needs resets, service</u> <u>needs belt</u>		JOB NAME/LOCATION <u>Maple Crossings</u>	JOB NUMBER	
REPAIRED: <u>serviced</u> <u>replaced fan belt</u>				
PARTS: <u>Filters</u> <u>175.87</u> <u>Tenn Filter sales</u> <u>Hyd Filter</u> <u>in stock</u> <u>belt + inner cab filter</u> <u>92.56</u> <u>Power Equipment</u> <u>belt</u> <u>Napa</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>0509</u> MAKE <u>Komatsu</u> MODEL <u>PC210LC</u> SERIAL # _____ HOUR METER _____ MILES _____		EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____		COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____				DATE <u>10-2-18</u> DATE COMPLETED <u>10-10-18</u> MECHANIC <u>Charles</u>	
PROBLEM: <u>Door seal</u>				JOB NAME/LOCATION <u>Maple Crossing</u> JOB NUMBER _____	
REPAIRED: <u>replaced sun vision shield</u>					
PARTS: <u>Seal</u> <u>261.74</u> <u>Power Equipment</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0509

MAKE Komatsu

MODEL PC210

SERIAL # _____

HOURLY METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON _____

PARTS _____

LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 11-16-18

MECHANIC Chucky

JOB NAME/LOCATION

Beckwith

JOB NUMBER

PROBLEM: blown Hase

REPAIRED: replaced hase

PARTS: Hase

36, 3L

Nashville Rubber & Gasket

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0509</u>	HOURS _____ DAYS _____ REASON PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>Komatsu</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>PC210</u>		COMPONENT LOCATION		
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER <u>3K HRS</u>		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>2-7-19</u>	DATE COMPLETED <u>2-21-19</u>	
		MECHANIC <u>Charles</u>		
		JOB NAME/LOCATION <u>Cargill</u>	JOB NUMBER	
PROBLEM: <u>service</u>				
REPAIRED: <u>serviced</u>				
PARTS: <u>All Filters</u> <u>297.14</u> <u>Tenn Filter sales</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0509</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>PC210LC</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>4-7-19</u> DATE COMPLETED <u>4-9-19</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Bryan</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION	JOB NUMBER
PROBLEM: <u>broken cab mirror</u>			<u>Journey Church</u>	
REPAIRED: <u>replaced mirror</u>				
PARTS: <u>mirror</u> \$ <u>115.00</u> <u>Power Equipment</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0509</u>	HOURS _____ DAYS _____ REASON PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>Komatsu</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>PC210</u>		COMPONENT LOCATION		
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____	DATE COMPLETED <u>4-29-19</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Charles</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Burney</u>	JOB NUMBER	
PROBLEM: <u>Hyd leak</u>				
REPAIRED: <u>replaced blown Hyd hose</u>				
<u>Pilot line under cab</u>				
PARTS: <u>hose</u> <u>\$71.04</u> <u>IR+G</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0509</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>PC210LC</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: _____ DATE COMPLETED <u>7-24-19</u> MECHANIC <u>Charles</u>	
			JOB NAME/LOCATION <u>Journey</u>	JOB NUMBER
PROBLEM: <u>blown Pilot hose</u>				
REPAIRED: <u>replaced Pilot hose under cab</u>				
PARTS: <u>hose</u> <u>29.54</u> <u>Nashville Rubber & Gasket</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0509</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>PC210LC</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>3,500 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE <u>5-20-19</u> DATE COMPLETED <u>6-10-19</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Charles</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Townes</u>	JOB NUMBER _____
PROBLEM: <u>needs service</u>				
REPAIRED: <u>Services</u>				
<u>changed seals in right joystick</u>				
PARTS: <u>All Filters</u> <u>243.27</u> <u>Tenn Filter</u>				
<u>seals</u> <u>\$154.45</u> <u>Pave Equipment</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0509</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>PC210LC</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>6-29-19</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Charles</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Journey</u>	JOB NUMBER
PROBLEM: <u>leaking hose going to oil Filter housing</u>				
REPAIRED: <u>replaced hose</u>				
PARTS: <u>Hose Assembly</u> <u>124.00</u> <u>T.R. & G</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>0509</u> MAKE <u>Komatsu</u> MODEL <u>PC210LC</u> SERIAL # _____ HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____						
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>7-16-19</u> DATE COMPLETED <u>7-18-19</u> MECHANIC <u>Bryan</u> <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:70%; padding: 2px;">JOB NAME/LOCATION <u>Bryan, Tawney</u></td> <td style="width:30%; padding: 2px;">JOB NUMBER</td> </tr> </table>	JOB NAME/LOCATION <u>Bryan, Tawney</u>	JOB NUMBER				
JOB NAME/LOCATION <u>Bryan, Tawney</u>	JOB NUMBER							
PROBLEM: <u>broken wiper arm</u>								
REPAIRED: <u>replaced arm assembly and wiper</u>								
<table style="width:100%;"> <tr> <td style="width:40%;">PARTS: <u>Arm Assembly</u></td> <td style="width:20%; text-align: center;"><u>51.65</u></td> <td style="width:40%; text-align: center;"><u>Power Equipment</u></td> </tr> <tr> <td><u>wiper & adapter</u></td> <td style="text-align: center;"><u>44.52</u></td> <td style="text-align: center;"><u>Power Equipment</u></td> </tr> </table>			PARTS: <u>Arm Assembly</u>	<u>51.65</u>	<u>Power Equipment</u>	<u>wiper & adapter</u>	<u>44.52</u>	<u>Power Equipment</u>
PARTS: <u>Arm Assembly</u>	<u>51.65</u>	<u>Power Equipment</u>						
<u>wiper & adapter</u>	<u>44.52</u>	<u>Power Equipment</u>						

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0509</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>PC210</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>8-21-19</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Charles</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>NO A/C</u>				
<u>FAN QUIT</u>				
REPAIRED: <u>replaced fan motor welded bucket</u>				
PARTS: <u>Motor</u> <u>415.63</u> <u>Power Equipment</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0509</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>KOMATSU</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>PC210 LC</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>4K HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>11-1-19</u> DATE COMPLETED <u>11-5-19</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>ALL</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>JONES Brummett</u>	JOB NUMBER
PROBLEM: <u>Service</u>				
REPAIRED: <u>Serviced</u>				
PARTS: <u>All Filters</u> <u>297.14</u> <u>Tenn Filter Saks</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0509</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>Komatsu</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>PC 210</u>	PARTS _____ LABOR _____	COMPONENT LOCATION		
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER		
OUR METER _____		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>12-4-19</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Charles</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Jones Brummett</u>	JOB NUMBER _____	
PROBLEM: <u>crushed Tube going to thumb</u>				
REPAIRED: <u>replaced steel tube</u>				
PARTS: <u>Make up steel line 132. ²⁴ Nashville Rubber & Gasket</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>0509</u> MAKE <u>Komatsu</u> MODEL <u>PC210LC</u> SERIAL # _____ HOUR METER <u>4500 HRS</u> MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____												
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>1-30-2020</u> DATE COMPLETED <u>2-14-2020</u> MECHANIC <u>Ben & Bryan & Charles</u> JOB NAME/LOCATION <u>Jones Brummett</u> JOB NUMBER _____												
PROBLEM: <u>Service, repair thumb</u>														
REPAIRED: <u>Serviced,</u> <u>removed Thumb cylinder for repair</u> <u>replaced two boom lines</u>														
<table style="width:100%; border: none;"> <tr> <td style="width:33%;">PARTS: <u>All Filters</u></td> <td style="width:33%; text-align: right;"><u>295.¹⁵</u></td> <td style="width:33%;"><u>Ten Filter</u></td> </tr> <tr> <td><u>2 steel lines</u></td> <td style="text-align: right;"><u>271.⁰⁰</u></td> <td><u>Nashville Rubber & Gasket</u></td> </tr> <tr> <td><u>cylinder repair</u></td> <td style="text-align: right;"><u>\$1500.⁰⁰</u></td> <td><u>Mid South Hydraulics</u></td> </tr> <tr> <td><u>Pin</u></td> <td style="text-align: right;"><u>235.²¹</u></td> <td><u>Power Equipment</u></td> </tr> </table>			PARTS: <u>All Filters</u>	<u>295.¹⁵</u>	<u>Ten Filter</u>	<u>2 steel lines</u>	<u>271.⁰⁰</u>	<u>Nashville Rubber & Gasket</u>	<u>cylinder repair</u>	<u>\$1500.⁰⁰</u>	<u>Mid South Hydraulics</u>	<u>Pin</u>	<u>235.²¹</u>	<u>Power Equipment</u>
PARTS: <u>All Filters</u>	<u>295.¹⁵</u>	<u>Ten Filter</u>												
<u>2 steel lines</u>	<u>271.⁰⁰</u>	<u>Nashville Rubber & Gasket</u>												
<u>cylinder repair</u>	<u>\$1500.⁰⁰</u>	<u>Mid South Hydraulics</u>												
<u>Pin</u>	<u>235.²¹</u>	<u>Power Equipment</u>												

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0509</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MAKE <u>Komatsu</u>	REASON _____	COMPONENT LOCATION		
MODEL <u>PC210LC</u>	PARTS _____ LABOR _____	FRONT REAR LEFT RIGHT UPPER LOWER		
SERIAL # _____	OTHER _____	OTHER _____		
HOUR METER _____				
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKE SHORTED VIBRATE OTHER _____		DATE: <u>3-30-2020</u>	DATE COMPLETED <u>4-7-2020</u>	
		MECHANIC _____	JOB NAME/LOCATION <u>Dover Brummett</u>	JOB NUMBER _____
PROBLEM: <u>leaking hose</u>				
REPAIRED: <u>replaced hose and Top roller</u>				
PARTS: <u>hose</u> <u>\$275.⁰⁰/₇₂</u> <u>Power Equipment</u>				
<u>Top roller</u> <u>Power Equipment</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0509</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>Komatsu</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>PC210-6C</u>	PARTS _____ LABOR _____	COMPONENT LOCATION		
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER <u>4900 HRS</u>		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>6-12-20</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Power</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Airport Logistics</u>	JOB NUMBER	
PROBLEM: <u>DPF Service</u>				
REPAIRED: <u>replaced DPF & reprogram</u>				
PARTS: <u>DPF Service 1,116.81</u> <u>Power Equipment</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0509</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>PC210LC</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
OUR METER <u>5K HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>6-25-20</u> DATE COMPLETED <u>6-30-20</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Farm</u>	JOB NUMBER
PROBLEM: <u>Service</u>				
REPAIRED: <u>Serviced</u>				
PARTS: <u>All Filters</u> <u>295 LF</u> <u>Tenn Filter</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0509</u>	HOURS _____ DAYS _____	REASON PARTS _____ LABOR _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>			POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>PC210HC</u>	OTHER _____	OTHER _____	COMPONENT LOCATION	
SERIAL # _____			FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: <u>8-27-20</u>	DATE COMPLETED <u>8-27-20</u>
			MECHANIC <u>Ben</u>	
			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>won't start</u>				
REPAIRED: <u>replaced batteries, replaced Turntable seal.</u>				
PARTS: <u>2 - 4D-XHD batteries 436.89 Interstate Battery</u> <u>seal 165.75 Power Equipment</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0509</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>Komatsu</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>PC210LC</u>	PARTS _____ LABOR _____	COMPONENT LOCATION		
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER <u>5500 HRS</u>		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: <u>12-18-20</u> DATE COMPLETED <u>12-7-21</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>All mainly Ben</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER	
PROBLEM: <u>Service and repair bucket</u>				
REPAIRED: <u>serviced repaired old bucket swapped with new bucket. Sent new bucket to man. for repair. Replaced one top roller.</u>				
PARTS: <u>Filters</u>		<u>Tenn. filter</u>		
<u>Roller</u>		<u>White House equipment</u>		
<u>bucket</u>		<u>Warranty</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0509</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>PC210 LC</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>1-14-21</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Sub-Station</u>	JOB NUMBER
PROBLEM: <u>missing teeth on Easco bucket</u>				
REPAIRED: _____				
PARTS: <u>3-4355 Teeth</u> <u>346.40</u> <u>Power Equipment</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0509</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>PC210 LC</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>2-6-21</u> DATE COMPLETED <u>2-8-21</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Caleb</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>MT Juliet Sub station</u> JOB NUMBER _____	
PROBLEM: <u>been burning brush piles</u>				
<u>needs new air filters</u>				
REPAIRED: <u>replaced all air filters</u>				
PARTS: <u>All Air filters</u> <u>236.97</u> <u>Tenn Filter</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>0509</u> MAKE <u>KOMATSU</u> MODEL <u>PC210LC</u> SERIAL # _____ HOUR METER <u>5,500 HRS</u> MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____												
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>3-2-21</u> DATE COMPLETED <u>3-8-21</u> MECHANIC <u>ALL</u> <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:50%;">JOB NAME/LOCATION <u>Shop</u></td> <td style="width:50%;">JOB NUMBER</td> </tr> </table>	JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER										
JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER													
PROBLEM: <u>Service, swap buckets, Top rollers</u>														
REPAIRED: <u>Serviced, swapped buckets, replaced two bad top rollers, replaced oil pressure test port</u>														
<table style="width:100%;"> <tr> <td style="width:33%;">PARTS <u>2-Tips & Hose</u></td> <td style="width:33%; text-align: center;"><u>281.⁰¹</u></td> <td style="width:33%;">Power Equipment</td> </tr> <tr> <td><u>All Filters</u></td> <td style="text-align: center;"><u>289.⁸⁴</u></td> <td>Tenn Filter</td> </tr> <tr> <td><u>Top rollers</u></td> <td></td> <td>White House Equipment</td> </tr> <tr> <td><u>Test port</u></td> <td style="text-align: center;"><u>84.⁷⁷</u></td> <td>Power Equipment</td> </tr> </table>			PARTS <u>2-Tips & Hose</u>	<u>281.⁰¹</u>	Power Equipment	<u>All Filters</u>	<u>289.⁸⁴</u>	Tenn Filter	<u>Top rollers</u>		White House Equipment	<u>Test port</u>	<u>84.⁷⁷</u>	Power Equipment
PARTS <u>2-Tips & Hose</u>	<u>281.⁰¹</u>	Power Equipment												
<u>All Filters</u>	<u>289.⁸⁴</u>	Tenn Filter												
<u>Top rollers</u>		White House Equipment												
<u>Test port</u>	<u>84.⁷⁷</u>	Power Equipment												

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0509</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>PC210LC</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>4-23-21</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>James</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Mt. Juliet Sub</u>	JOB NUMBER _____
PROBLEM: <u>melted battery post</u>				
REPAIRED: <u>replaced one battery</u>				
PARTS: <u>1- 4D-XHD</u> <u>198.00</u> <u>Interstate Battery</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0509</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL _____		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>6K HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>8-17-21</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Carver Lane</u>	
PROBLEM: <u>Service</u>			JOB NUMBER _____	
REPAIRED: <u>Serviced</u>				
PARTS: <u>All Filters</u> <u>305-45</u> <u>Tenn Filter</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0509</u>		HOURS _____ DAYS _____		BASIC MACHINE	HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Komatsu</u>		REASON _____		POWER TRAIN	ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>PC210LC</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE <u>11-22-21</u> DATE COMPLETED <u>11-23-21</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>James</u>		
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>shop</u> JOB NUMBER _____		
PROBLEM: <u>needs new bucket</u>					
REPAIRED: <u>installed new bucket & stick to bucket pin</u>					
PARTS: <u>bucket</u> <u>7800.00</u> <u>Power Equipment</u>					
<u>Pin</u> <u>971.40</u> <u>Power Equipment</u>					
<u>seals</u> <u>102.06</u> <u>Power Equipment</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0509</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>KOMATSU</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>PC210 LC</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>2-8-12</u>	MECHANIC <u>Ben</u>	
PROBLEM: <u>blown pilot hose going to main pump</u>		JOB NAME/LOCATION <u>Vintage Edge</u>	JOB NUMBER _____	
REPAIRED: <u>replaced hose</u>				
PARTS: <u>hose</u> <u>73.97</u> <u>IR & G</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0509</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>KOMATSU</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>PC210LC</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>6K MRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: <u>1-27-22</u> DATE COMPLETED <u>1-31-22</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Ben</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Vintage Edge</u> JOB NUMBER _____		
PROBLEM: <u>Service</u>				
REPAIRED: <u>serviced replaced oil Filter lines</u>				
PARTS: <u>Filters</u> <u>305.21</u> <u>Tenn Filter</u>				
<u>Oil Filter lines</u> <u>269.13</u> <u>IR & G</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0509</u>	HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____		
MAKE <u>Komatsu</u>				
MODEL <u>PC210LC</u>				
SERIAL # _____				
HOUR METER <u>7K HRS</u>				
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>4-22-22</u> DATE COMPLETED <u>6-3-22</u> MECHANIC <u>Al</u>		
PROBLEM: <u>Service</u>		JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____		
REPAIRED: <u>serviced</u> <u>replaced A/C belt.</u> <u>removed tracks replaced rails & sprockets</u> <u>Replaced RT Joystick</u>				
PARTS: <u>All Filters</u> <u>348.53</u> <u>Tenn Filter sales</u> <u>belt</u> <u>47.00</u> <u>Power Equipment</u> <u>rails & sprockets & hardware</u> <u>Thompson</u> <u>Joystick</u> <u>487.40</u> <u>Power Equipment</u> <u>hose</u> <u>123.61</u> <u>Crook Auto Electric</u> <u>Rails</u> <u>7268.00</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0509</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>PC210-LC</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____				DATE: _____ DATE COMPLETED <u>8-11-22</u>	
				MECHANIC <u>Ben</u>	
				JOB NAME/LOCATION <u>Stone Trace</u>	
				JOB NUMBER _____	
PROBLEM: <u>left joystick leaking</u>					
REPAIRED: <u>replaced stems and seals</u>					
PARTS: <u>stems & seals</u> <u>399.74</u> <u>Power Equipment</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0509</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>KOMATSU</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>PC210LC</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE <u>8-31-22</u> DATE COMPLETED <u>9-3-22</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Anthony</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Line Stone</u> JOB NUMBER _____		
PROBLEM: <u>Service</u>				
REPAIRED: <u>Serviced</u>				
PARTS: <u>Filters</u> <u>349.51</u> <u>Ten Filter Sales</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0509</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>PC210LC</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>8K HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>1-28-23</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Anthony</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Stone Trace</u>	JOB NUMBER
PROBLEM: <u>Service</u>				
REPAIRED: <u>serviced</u>				
PARTS: <u>All Filters</u> <u>348.11</u> <u>Tenn. Filter Saker</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0509</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>PC210</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>8340 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>4-10-23</u> DATE COMPLETED <u>4-24-23</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>All</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>To Shop</u>	JOB NUMBER
PROBLEM: <u>hyd pressure problem</u>				
REPAIRED: <u>drained Tank replaced strainer & filter</u>				
<u>replaced lower stick & lower H link bushings.</u>				
<u>replaced 2 pilot hoses</u>				
<u>repaired antibody step.</u>				
PARTS: <u>strainer Element & orings 219.²⁰</u> <u>Power Equipment</u>				
<u>2 Hoses & adapts 293.¹⁶</u> <u>Nashville Rubber & Gasket</u>				
<u>2 Hoses 160.⁹⁰</u> <u>Nashville Rubber & Gasket</u>				
<u>Valve</u> <u>Power Equipment</u>				
<u>pins & bushings 2070.¹²</u> <u>Power Equipment</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0509</u> MAKE <u>Komatsu</u> MODEL <u>PC210-LC</u> SERIAL # _____ HOUR METER _____ MILES _____		HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____				DATE: <u>6-5-23</u> DATE COMPLETED <u>6-7-23</u> MECHANIC <u>All</u>	
PROBLEM: <u>stick cylinder leak and drift.</u>				JOB NAME/LOCATION <u>10 shop</u> JOB NUMBER _____	

REPAIRED: packed cylinder

PARTS: seal kit & bushing 343.35 Power Equipment

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

SERIAL # 0509

MAKE Komatsu

MODEL PC210

SERIAL # _____

HOUR METER 8500 HRS

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON _____

PARTS _____

LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE 6-27-23

DATE COMPLETED 7-7-23

MECHANIC Anthony

JOB NAME/LOCATION
Eastgate

JOB NUMBER _____

PROBLEM: Service

REPAIRED: serviced

PARTS: Filters

313.00

Team Filter sales-

TEC

THORNE'S EXCAVATING COMPANY, LLC SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0509

MAKE Komatsu

MODEL PC210LC-11

SERIAL # _____

HOURLY METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON _____

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: 7-12-23 DATE COMPLETED 7-12-23

MECHANIC Ben

JOB NAME/LOCATION

Eastgate

JOB NUMBER

PROBLEM: bad top roller & Dipstick

REPAIRED: replaced top roller

PARTS: roller & Dipstick \$259.⁰⁰ Power Equipment

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0509</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>KOMATSU</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>PC210 LC</u>	PARTS _____ LABOR _____	COMPONENT LOCATION		
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER <u>9K HRS</u>		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: <u>4-25-24</u> DATE COMPLETED _____		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>ALL</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>To Shop</u>	JOB NUMBER _____	
PROBLEM: <u>service oil leak & steps</u>				
REPAIRED: <u>serviced welded cracks on bucket.</u>				
<u>repaired/replaced roller frame steps. Both sides.</u>				
<u>replaced left joystick hoses & right roller side.</u>				
PARTS: <u>Filters</u> <u>350.⁴⁴</u> <u>Tenn Filter sales</u>				
<u>6. hoses</u> <u>469.⁵⁸</u> <u>Power Equipment</u>				
<u>1. hose</u> <u>69.²⁹</u> <u>Power Equipment</u>				
<u>5. hoses</u> <u>390.⁶⁰</u> <u>Power Equipment</u>				
<u>switch, spring & knob</u> <u>390.⁶⁰</u> <u>Power Equipment</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0509</u>	HOURS _____ DAYS _____	REASON _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>			POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>PC210LC</u>	PARTS _____ LABOR _____	OTHER _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>9,500 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>9-13-24</u> DATE COMPLETED <u>9-19-24</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Anthony</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>Service</u>				
REPAIRED: <u>Serviced</u>				
PARTS: <u>Filters</u> <u>365.72</u> <u>Tenn Filter Sales</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0509
 MAKE Komatsu
 MODEL PC210LC-11
 SERIAL # _____
 HOUR METER 9,047 HRS
 MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
 REASON _____
 PARTS _____ LABOR _____
 OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
 POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER
 OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
 OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
 SMOKES SHORTED VIBRATE OTHER _____

DATE 5-21-25 DATE COMPLETED 5-23-25

MECHANIC Ben

JOB NAME/LOCATION

Shop

JOB NUMBER

PROBLEM: SCR system malfunction

REPAIRED: replaced def. pump, element and smart box

PARTS: Def. pump.
Element
smart box

1648.52
216.97

Power Equipment
Power Equipment