

EQUIPMENT
REPAIRS

DATE 6-6-16

MILEAGE/HOURS 500 HRS

EQUIPMENT REPAIRED #312 336F CAT

REPAIRS MADE Serviced

HOURS WORKED _____

PARTS USED

All Filters

Thompson Machinery

TEC
THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION ID # <u>312</u> MAKE <u>CAT</u> MODEL <u>336F</u> SERIAL # _____ HOUR METER <u>5004HRS</u> MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>6-6-16</u> MECHANIC <u>CAT</u> JOB NAME/LOCATION <u>Smith Travel</u> JOB NUMBER _____
PROBLEM: <u>noise at fan belt drive</u>		
REPAIRED: <u>Cat going to re-route belt drive to stop noise</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>312</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>336F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>1000 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>10-18-16</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>James & Steven</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>need serviced</u>				
REPAIRED: <u>Serviced</u>				
PARTS: <u>All Filters</u> <u>\$590.17</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>312</u>	HOURS _____ DAYS _____	REASON PARTS _____ LABOR _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>			POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>336F</u>	OTHER _____	OTHER _____	COMPONENT LOCATION	
SERIAL # _____			FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>1,500 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: _____ DATE COMPLETED <u>2-16-17</u> MECHANIC <u>JAMES + STEVEN B.</u>	
			JOB NAME/LOCATION <u>Legends Drive</u>	JOB NUMBER
PROBLEM: <u>need serviced</u>				
REPAIRED: <u>Serviced</u>				
PARTS: <u>All Filters</u> <u>524.33</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>312</u>	REASON PARTS LABOR OTHER _____	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>336F</u>		COMPONENT LOCATION		
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>2-20-17</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC _____	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Legend's Dr</u>	JOB NUMBER
PROBLEM: <u>replacement tips & pins</u>				
REPAIRED: _____				
PARTS: <u>2-Tips - 4-retainers</u> \$ <u>318.03</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>312</u>	REASON PARTS LABOR OTHER	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>336F</u>		COMPONENT LOCATION		
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: _____ DATE COMPLETED <u>4-3-17</u>	
			MECHANIC <u>All</u>	
			JOB NAME/LOCATION <u>Legends Dr.</u>	JOB NUMBER
PROBLEM: <u>Teeth + locks</u>				
REPAIRED: <u>2 Teeth + 4 locks</u>				
PARTS: <u>Teeth + locks</u> <u>318.02</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>312</u>	REASON PARTS LABOR OTHER	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>336F</u>				
SERIAL # _____				
HOUR METER <u>2K Hrs.</u>				
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: _____ DATE COMPLETED <u>5-15-17</u> MECHANIC <u>James & Steven</u>	
			JOB NAME/LOCATION <u>Smith Springs</u> JOB NUMBER _____	
PROBLEM: <u>2K HRS Service</u> <u>Final Drives and swing drive need changed</u>				
REPAIRED: <u>serviced</u> <u>6-7-17 changed final drives & swing drive</u>				
PARTS: <u>All Fitters</u> <u>686.89</u> <u>Thompson</u>				

TEC
THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>312</u> MAKE <u>Cat</u> MODEL <u>336F</u> SERIAL # _____ HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____ _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>8-28-17</u> MECHANIC <u>James & Steven</u> <table border="1" style="width: 100%; border-collapse: collapse;"><tr><td style="width: 50%;">JOB NAME/LOCATION <u>Kitrell</u></td><td style="width: 50%;">JOB NUMBER</td></tr></table>	JOB NAME/LOCATION <u>Kitrell</u>	JOB NUMBER
JOB NAME/LOCATION <u>Kitrell</u>	JOB NUMBER			
PROBLEM: <u>Top roller broken</u> _____ _____				
REPAIRED: <u>replaced top roller</u> _____ _____ _____ _____ _____ _____				
PARTS: <u>Top Roller</u> <u>281 LE</u> <u>Thompson</u> <u>300-4545</u> _____ _____ _____				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>0505</u> MAKE <u>CAT</u> MODEL <u>336 F</u> SERIAL # _____ HOUR METER <u>2500 HR</u> MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____												
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE <u>10-6-17</u> DATE COMPLETED _____ MECHANIC <u>James & Steven</u> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 70%;">JOB NAME/LOCATION <u>Water Tower</u></td> <td style="width: 30%;">JOB NUMBER</td> </tr> </table>	JOB NAME/LOCATION <u>Water Tower</u>	JOB NUMBER										
JOB NAME/LOCATION <u>Water Tower</u>	JOB NUMBER													
PROBLEM: <u>blown hose</u> <u>need serviced</u>														
REPAIRED: <u>replaced left bucket cylinder hose</u> <u>serviced</u>														
<table style="width: 100%;"> <tr> <td style="width: 40%;">PARTS: <u>All Filters but air</u></td> <td style="width: 20%; text-align: right;"><u>513.18</u></td> <td style="width: 40%; text-align: right;"><u>Thompson</u></td> </tr> <tr> <td><u>Hose</u></td> <td style="text-align: right;"><u>400.43</u></td> <td style="text-align: right;"><u>Thompson</u></td> </tr> <tr> <td><u>Hyd oil</u></td> <td style="text-align: right;"><u>190.54</u></td> <td style="text-align: right;"><u>Thompson</u></td> </tr> <tr> <td><u>Air filters</u></td> <td style="text-align: right;"><u>155.00</u></td> <td style="text-align: right;"><u>Thompson</u></td> </tr> </table>			PARTS: <u>All Filters but air</u>	<u>513.18</u>	<u>Thompson</u>	<u>Hose</u>	<u>400.43</u>	<u>Thompson</u>	<u>Hyd oil</u>	<u>190.54</u>	<u>Thompson</u>	<u>Air filters</u>	<u>155.00</u>	<u>Thompson</u>
PARTS: <u>All Filters but air</u>	<u>513.18</u>	<u>Thompson</u>												
<u>Hose</u>	<u>400.43</u>	<u>Thompson</u>												
<u>Hyd oil</u>	<u>190.54</u>	<u>Thompson</u>												
<u>Air filters</u>	<u>155.00</u>	<u>Thompson</u>												

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES		
EQUIP. # <u>505</u>	HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT . REAR LEFT RIGHT UPPER LOWER OTHER _____			
MAKE <u>CAT</u>		SERIAL # _____ HOUR METER _____ MILES _____			
MODEL <u>336F</u>					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE <u>12-19-17</u> DATE COMPLETED <u>12-22-17</u> MECHANIC <u>James & Steven</u> JOB NAME/LOCATION <u>PPG Extension</u> JOB NUMBER			
PROBLEM: <u>broken windshields</u>					
REPAIRED: <u>removed window straightened frame</u> <u>Bluegrass glass replaced glass</u>					
PARTS: <u>small glass</u> \$ <u>114.97</u> <u>Thompson</u> <u>large glass</u> \$ <u>424.63</u> <u>Thompson</u>					

TEC
THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0505

MAKE CAT

MODEL 336F

SERIAL # _____

HOURLY METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS

LABOR

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: 3-12-18 DATE COMPLETED 4-4-18

MECHANIC _____

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: Service

REPAIRED: serviced

PARTS: All Filters

532, 13

Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0505</u>	HOURS _____ DAYS _____ REASON PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>CAT</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>336F</u>		COMPONENT LOCATION		
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____	DATE COMPLETED <u>4-28-18</u>	
		MECHANIC <u>Linden</u>		
		JOB NAME/LOCATION <u>Pinewood Sub.</u>	JOB NUMBER _____	
PROBLEM: <u>Tooth missing</u>				
REPAIRED: <u>replaced tooth</u>				
PARTS: <u>2-Teeth 3-locks 402.10 Thompson</u> <u>305.62</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>0505</u> MAKE <u>CAT</u> MODEL <u>336F</u> SERIAL # _____ HOURLY METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>10-3-18</u> MECHANIC <u>Charles</u>
		JOB NAME/LOCATION: <u>Beckwith</u> JOB NUMBER: _____
PROBLEM: <u>Dipstick Tube Broken</u>		
REPAIRED: <u>replaced tube with new style and Dipstick</u>		
PARTS: <u>Hardware</u> \$ <u>11.01</u> <u>Thompson</u> <u>Tube + stick</u> <u>257.90</u> <u>Thompson</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 336F 0505

MAKE CAT

MODEL 336F

SERIAL # _____

HOOR METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON _____

PARTS _____

LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE 10-12-18

DATE COMPLETED 10-12-18

MECHANIC Charles

JOB NAME/LOCATION

Beckwith

JOB NUMBER

PROBLEM:

need Teeth & lock


REPAIRED:

replaced teeth & lock

PARTS:

2-Teeth

12-locks



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0505</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>336F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>1-9-19</u> DATE COMPLETED <u>1-9-19</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Charles</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>MCH</u>	JOB NUMBER
PROBLEM: <u>needs fuel filters</u>				
REPAIRED: <u>replaced fuel filters</u>				
PARTS <u>Fuel Filters</u> <u>91.00</u> <u>Thompson Machinery</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0505</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>336F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>4500 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE <u>2-15-19</u> DATE COMPLETED _____	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>JAMES + Thompson</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>WCH TO Shop</u>	JOB NUMBER _____
PROBLEM: <u>Service</u>				
<u>repair warning system going off.</u>				
REPAIRED: <u>Serviced, replaced NOx sensors</u>				
<u>replaced water in fuel sensor</u>				
<u>Thompson updated computer software</u>				
Oil level sensor		94.56	Thompson	
NOx sensor II		860.00	Thompson	
PARTS: All Filters		798.64	Thompson	
Fuel sensor		136.90	Thompson	
NOx sensor		860.00	Thompson	
codes check			Thompson	
codes (E1389)(3547-3)(3609-12)				

Apt. #1 outlet #1 NOx lever sensor malfunction
water in fuel switch on separator filter

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0505</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>336F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: _____ DATE COMPLETED <u>3-6-19</u> MECHANIC <u>Charles</u> JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____	
PROBLEM: <u>missing tooth</u>				
REPAIRED: <u>replaced tooth</u>				
PARTS: <u>Teeth & locks</u> <u>430.00</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0505</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>336F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>4-11-19</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Janden</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Warden Parcelia</u>	JOB NUMBER _____
PROBLEM: <u>Missing Teeth</u>				
REPAIRED: <u>replaced missing teeth</u>				
PARTS: <u>2 Teeth & locks</u> <u>344.42</u> <u>Thompson</u>				

TEC
THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0505

MAKE CAT

MODEL 336F

SERIAL # _____

HOUR METER 5K HRS

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON _____

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: 7-17-19 DATE COMPLETED 7-20-19

MECHANIC _____

JOB NAME/LOCATION _____

JOB NUMBER _____

PROBLEM: Service

REPAIRED: serviced

PARTS: All Filters 567-15 Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0505</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>336F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>8-16-19</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Bryan</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Ashland Farms</u>	JOB NUMBER _____
PROBLEM: <u>broken cover</u>				
REPAIRED: <u>replaced broken filter cover in cab.</u>				
PARTS: <u>Filter cover</u> <u>58.67</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>0505</u> MAKE <u>Cat</u> MODEL <u>336F</u> SERIAL # _____ HOUR METER <u>5500 HRS</u> MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>10-4-19</u> DATE COMPLETED <u>10-16-19</u> MECHANIC _____ JOB NAME/LOCATION <u>To Shop</u> JOB NUMBER _____
PROBLEM: <u>stick bushings worn</u> <u>service</u> <u>leaking hose</u>		
REPAIRED: <u>serviced, replaced leaking swing motor</u> <u>hose lower stick bushing and both bucket</u> <u>pins replaced</u>		
PARTS: <u>bushings & seals</u> <u>539.49</u> <u>Thompson</u> <u>hose</u> <u>348.18</u> <u>Thompson</u> <u>All filters</u> <u>544.62</u> <u>Thompson</u> <u>Pins 1037.17 & 658.50</u> <u>Thompson</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0505

MAKE CAT

MODEL 336F

SERIAL # _____

HOUR METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS

LABOR

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE 10-17-19 DATE COMPLETED 10-18-19

MECHANIC _____

JOB NAME/LOCATION

Jones Brummett

JOB NUMBER

PROBLEM: bucket needs teeth

REPAIRED: replaced teeth

PARTS: 8-Teeth, 10-locks 1,242.98 Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>2505</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>336F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>12-2-19</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Charles</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Jones Brummett</u> JOB NUMBER _____	
PROBLEM: <u>missing tooth on bucket</u>				
REPAIRED: _____				
PARTS: <u>1-Tooth 2-laks 172.21 Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0505</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>336F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: _____ DATE COMPLETED <u>1-3-20</u> MECHANIC <u>Eric</u>	
			JOB NAME/LOCATION <u>Jones Brummett</u>	
			JOB NUMBER	
PROBLEM: <u>needs bucket teeth</u>				
REPAIRED:				
PARTS: <u>3-Teeth 6-lock 686.98 Thompson</u>				

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0505</u>		HOURS _____ DAYS _____		BASIC MACHINE	HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>CAT</u>		REASON _____		POWER TRAIN	ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>336F</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>5K HRS</u>				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>1-8-20</u> DATE COMPLETED <u>1-8-2020</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>ALL</u>		
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Jones Brummett</u> JOB NUMBER _____		
PROBLEM: <u>Service</u>					
REPAIRED: <u>serviced</u>					
<u>Tightened collars & side cutter bolts</u>					
PARTS: <u>All Filters</u> <u>463.95</u> <u>Thompson</u>					
<u>bolts for bucket</u> <u>42.00</u> <u>Thompson</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0505</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>336 F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: <u>1-23-2020</u> DATE COMPLETED: <u>1-24-2020</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Bryan</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Jones Burnett</u> JOB NUMBER _____		
PROBLEM: <u>blown stick cylinder hose</u>				
REPAIRED: <u>replaced RT stick cylinder hose on top of the boom</u>				
PARTS: <u>hose</u> <u>436.94</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0505</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>336F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>6,500 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>3-17-2020</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC _____	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Jones Rummert</u>	JOB NUMBER
PROBLEM: <u>Service</u>				
REPAIRED: <u>Serviced</u>				
PARTS: <u>All Filters</u> <u>692.72</u> <u>Thompson</u>				

TEC
THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0505</u>	HOURS _____ DAYS _____ REASON PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____		
MAKE <u>CAT</u>				
MODEL <u>336F</u>				
SERIAL # _____				
HOUR METER _____		MILES _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>4-3-2020</u> MECHANIC <u>ALL</u> JOB NAME/LOCATION <u>Jawor Brummett</u> JOB NUMBER _____		
PROBLEM: <u>Detoxing cab</u>				
REPAIRED: <u>replaced cab filters</u>				
PARTS: <u>Cab filters</u> \$ <u>79.40</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0505</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>336F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>6,900 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>6-3-20</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Charles</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Jones Brummett</u>	JOB NUMBER _____
PROBLEM: <u>bad batteries</u>				
REPAIRED: <u>replaced batteries</u>				
PARTS: <u>4 Gyp 31 115-2422 911.14 Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0505</u>	REASON PARTS LABOR OTHER _____	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>336F</u>		COMPONENT LOCATION		
SERIAL # _____			FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>7K Hours</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE <u>6-17-20</u> DATE COMPLETED <u>6-29-20</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>J.B. To Shop</u>	JOB NUMBER
PROBLEM: <u>Service + DPF</u>				
REPAIRED: <u>Serviced</u>				
<u>Thompson servicing DPF</u>				
PARTS: <u>All Filters</u> <u>550.04</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0508</u>		HOURS _____ DAYS _____		BASIC MACHINE	HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>CAT</u>		REASON _____		POWER TRAIN	ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>336.F</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>7500 HRS</u>				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: <u>10-14-20</u> DATE COMPLETED <u>12-17-20</u> MECHANIC <u>BEN</u>		
PROBLEM: <u>Service</u>			JOB NAME/LOCATION <u>A.F. to shop</u>		JOB NUMBER
REPAIRED: <u>Serviced</u>					
PARTS: <u>All Filters</u> <u>546.48</u> <u>Thompson</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0505</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>336F</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER <u>7500 HRS</u>		OTHER _____
MILES _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>2-2-21</u> DATE COMPLETED <u>2-4-21</u> MECHANIC <u>Ben</u>
		JOB NAME/LOCATION <u>EAST Gate</u> JOB NUMBER _____
PROBLEM: <u>Service & blown hose</u>		
REPAIRED: <u>Serviced & replaced hose next to boom</u>		
PARTS: <u>All Filters 556.59</u> <u>Tenn Filter</u> <u>Hose & Tube with 864.72</u> <u>Thompson</u> <u>Install Parts</u> <u>Doc no. 00C749085</u> <u>2/04/21</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0505</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>336F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>3-2-21</u> DATE COMPLETED: <u>3-3-21</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Eastgate</u>	JOB NUMBER
PROBLEM: <u>wiper arm broken</u>				
REPAIRED: <u>replaced arm</u>				
PARTS: <u>Arm assembly</u> <u>124.92</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0505</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>336F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>3-9-21</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Eastgate</u>	JOB NUMBER
PROBLEM: <u>blown hose</u>				
REPAIRED: <u>replaced bucket cylinder hose</u>				
PARTS: <u>hose</u> <u>357.28</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0505</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>336F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
OUR METER <u>8K HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>4-1-21</u> DATE COMPLETED <u>4-1-21</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>James & Caleb</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Eastgate</u>	JOB NUMBER _____
PROBLEM: <u>Service</u>				
REPAIRED: <u>Serviced</u>				
PARTS: <u>All Filters</u> <u>632. II</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>0505</u> MAKE <u>Cat</u> MODEL <u>336F</u> SERIAL # _____ HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>4-13-21</u> DATE COMPLETED <u>4-20-21</u> MECHANIC <u>Ben</u> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%; padding: 2px;">JOB NAME/LOCATION <u>North Lake</u></td> <td style="width: 50%; padding: 2px;">JOB NUMBER</td> </tr> </table>	JOB NAME/LOCATION <u>North Lake</u>	JOB NUMBER
JOB NAME/LOCATION <u>North Lake</u>	JOB NUMBER			
PROBLEM: <u>bad fuel sender</u>				
REPAIRED: <u>replaced sender</u>				
PARTS: <u>Sender</u> <u>95.24</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0505</u>	HOURS _____ DAYS _____ REASON PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>Cat</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>336F</u>		COMPONENT LOCATION		
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER <u>8500 HRS</u>		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: <u>8-5-21</u> DATE COMPLETED <u>8-17-21</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>All & Thompson</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Cane station</u>	JOB NUMBER	
PROBLEM: <u>Service DPf system malfunction</u>				
REPAIRED: <u>serviced, Thompson working on DPf system replaced diverter valve and transfer pump programmed system</u>				
PARTS: <u>All Filters 562.97 Thompson</u>				
<u>valve pump & program Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>0505</u> MAKE <u>CAT</u> MODEL <u>336F</u> SERIAL # _____ HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>11-22-21</u> MECHANIC <u>Ben</u> <table style="width: 100%; border: none;"> <tr> <td style="border: none; width: 70%;">JOB NAME/LOCATION <u>West Trinity</u></td> <td style="border: none; width: 30%;">JOB NUMBER </td> </tr> </table>	JOB NAME/LOCATION <u>West Trinity</u>	JOB NUMBER
JOB NAME/LOCATION <u>West Trinity</u>	JOB NUMBER 			
PROBLEM: <u>blown hose to pump</u> _____ _____				
REPAIRED: <u>replaced hose</u> _____ _____ _____ _____ _____ _____				
PARTS: <u>hose assembly</u> <u>349.49</u> <u>Thompson</u> _____ _____ _____ _____				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. #	0505	HOURS	DAYS	BASIC MACHINE	HYDRAULIC ENGINE IMPLEMENTS
MAKE	CAT	REASON		POWER TRAIN	ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL	336F	PARTS	LABOR	COMPONENT LOCATION	
SERIAL #		OTHER		FRONT	REAR LEFT RIGHT UPPER LOWER
HOUR METER	8,650 HRS			OTHER	
MILES					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER				DATE: 9-23-21	DATE COMPLETED 11-11-21
				MECHANIC	All
				JOB NAME/LOCATION	JOB NUMBER
PROBLEM: Tube broken Main supply pump bad				Carter Station to shop	
REPAIRED: replaced main supply pump & both relays replaced H Link removed stick bushings sent to Thompson for line bore. replaced dipstick tube					
PARTS: Dipstick Tube 93.62 Thompson					
Supply pump 968.00 Thompson					
H-link 2,948.00 Thompson					
line bore Thompson					

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0505</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>336F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>12-16-21</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>900 Dickerson</u>	JOB NUMBER
PROBLEM: <u>Missing Teeth</u>				
REPAIRED: <u>replaced teeth</u>				
PARTS: <u>3-Tips 6-retainers 625.64 Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0505</u>		HOURS _____ DAYS _____		BASIC MACHINE	HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>CAT</u>		REASON _____		POWER TRAIN	ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>336F</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>9K ARS</u>				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____				DATE: <u>2-1-22</u> DATE COMPLETED <u>5-26-22</u> MECHANIC <u>ALL</u>	
PROBLEM: <u>Service metal in main control valve</u>				JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____	

REPAIRED: serviced - replaced main relief hosed out stick control spool, replaced both pump dead end hoses. new hyd. tank cap. changed hyd. oil replaced two sleeves in main valve body, removed broken metal

VALUES & seals	1422. ⁷⁰	Thompson
3 sleeves	379. ⁹⁸	Thompson
PARTS: <u>Filters</u>	548. ⁹³	Thompson
<u>Oil Filter</u>	38. ⁷⁷	Thompson
<u>hoses, Tube & seals</u>	1379. ³⁵	Thompson
<u>Exhaust elbow</u>	184. ⁶⁰	Thompson
<u>main relief valve</u>	362. ³³	Thompson
<u>Hyd Tank cap</u>	113. ³⁰	Thompson
<u>O-ring</u>	13. ⁷⁵	Thompson
<u>2-seals</u>	26. ⁸⁷	Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0505

MAKE Cat

MODEL 336F

SERIAL # _____

HOUR METER 9568 mi

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON _____

PARTS _____

LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 8-18-22

MECHANIC Thompson

JOB NAME/LOCATION

Limestone

JOB NUMBER

PROBLEM: won't regen

REPAIRED: replaced main fuse box, Thompson reset machine

PARTS: Panel & relay

600.75

Thompson