

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0802</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>246</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>1074 HRS</u>		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>7-23-19</u> DATE COMPLETED _____	
		MECHANIC <u>All</u>	
PROBLEM: <u>Engine swap</u>		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
REPAIRED: <u>installed used cat remain out of older 246</u>			
PARTS: <u>4-18-19 Battery 127.00 Interstate Battery</u> <u>belt 38.12 Napa</u> <u>2-Hoses & breather 20.99 + 75.67 Thompson</u> <u>Regulator & Gasket 7.01 + Thompson</u> <u>Filters 161.35 Tenn Filter</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP # <u>0802</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>246</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>1,075 HRS</u>		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: <u>8-5-21</u>	DATE COMPLETED <u>8-10-21</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>James</u>	
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION	JOB NUMBER
		<u>Shop</u>	
PROBLEM: <u>service</u>			
REPAIRED: <u>serviced</u>			
PARTS: <u>All Filters</u>			
<u>175.00</u>			
<u>Tenn Fitter</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES					
EQUIP. # <u>0802</u>	HOURS _____ DAYS _____	BASIC MACHINE	HYDRAULIC	ENGINE	IMPLEMENTS		
MAKE <u>CAT</u>	REASON	POWER TRAIN	ELECTRIC	DRIVE TRAIN	UNEXPLAINED		
MODEL <u>246</u>	PARTS	COMPONENT LOCATION					
SERIAL # _____	LABOR	FRONT	REAR	LEFT	RIGHT	UPPER	LOWER
HOUR METER _____	OTHER _____	OTHER _____					
MILES _____							
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____	DATE COMPLETED <u>3-17-22</u>				
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>James</u>					
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER				
PROBLEM: <u>bad battery</u>							
REPAIRED: <u>replaced battery</u>							
PARTS <u>Gip 24 battery 184.⁰⁰</u>							
<u>3yr Free Repl</u>							
<u>Advice</u>							

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES					
EQUIP. # <u>0802</u>		HOURS _____	DAYS _____	BASIC MACHINE	HYDRAULIC	ENGINE	IMPLEMENTS		
MAKE <u>CAT</u>		REASON		POWER TRAIN	ELECTRIC	DRIVE TRAIN	UNEXPLAINED		
MODEL <u>246</u>		PARTS _____	LABOR _____	COMPONENT LOCATION					
SERIAL # _____		OTHER _____		FRONT	REAR	LEFT	RIGHT	UPPER	LOWER
HOUR METER _____				OTHER _____					
MILES _____									
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE: _____	DATE COMPLETED <u>5-26-22</u>				
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC <u>Calcb</u>					
SMOKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____				
PROBLEM: <u>front engine seal leaking</u>									
REPAIRED: <u>replaced seal & belt.</u>									
PARTS: <u>seal & belt</u> <u>49.50</u> <u>Thompson</u>									

EQUIPMENT
REPAIRS

DATE 4-11-05

MILEAGE/HOURS _____

EQUIPMENT REPAIRED #206 246 skid steer

REPAIRS MADE check over gears, put
master switch on, foam fill
tires.
change hourmeter at 800 hrs.

HOURS WORKED _____

PARTS USED

switch \$ 58.79
foam fill tires \$ 667.00

EQUIPMENT
REPAIRS

DATE 1-13-06

MILEAGE/HOURS 1000
200

EQUIPMENT REPAIRED 246 - ~~#~~ 206

REPAIRS MADE Complete Service

oil, fuel, & hydra filters. Belcon

air filter

HOURS WORKED _____

PARTS USED

filters \$ 104.99
45.87

EQUIPMENT REPAIRS

DATE 11-17-06

MILEAGE HOURS 500

EQUIPMENT REPAIRED 206 246 S.S.

REPAIRS MADE Complete Service
changed oil, fuel, hydra filters
Blow ~~out~~ air filters.

HOURS WORKED _____

PARTS USED

all filters @ 101.47

EQUIPMENT
REPAIRS

DATE 11-29-06

MILEAGE/HOURS 540

EQUIPMENT REPAIRED #206

REPAIRS MADE 4 new tires + foam fill

HOURS WORKED _____

PARTS USED

4 - tires) \$ 1710.09
& fill

Tires \$ 200.58 each
Mount & Dismount \$ 20.00 each
Disposal \$ 3.00 each
Valve stem \$ 3.00 each
foam fill \$ 165.00 each
1.00 per pound

EQUIPMENT
REPAIRS

DATE 11-5-07

MILEAGE/HOURS _____

EQUIPMENT REPAIRED #206 246 cat

REPAIRS MADE Replaced bad glow plugs

HOURS WORKED _____

PARTS USED

1 Glow Plug Thompson 32.00

EQUIPMENT
REPAIRS

DATE 7-15-08

MILEAGE/HOURS _____

EQUIPMENT REPAIRED #206 246 cat

REPAIRS MADE Made step for forks

HOURS WORKED _____

PARTS USED

$\frac{1}{8}$ " SCRAP Treadplate

5" x 5 $\frac{1}{2}$ "

5" x 6"

EQUIPMENT
REPAIRS

DATE 5-14-08

MILEAGE/HOURS 1000 HRS

EQUIPMENT REPAIRED #206 246 Scid Steer

REPAIRS MADE serviced

HOURS WORKED _____

PARTS USED

Filters

161.01

7.84

168.85 Total

Thompson

EQUIPMENT
REPAIRS

DATE 9-3-08

MILEAGE/HOURS _____

EQUIPMENT REPAIRED #206

REPAIRS MADE repaired armrest cylinder mount


HOURS WORKED _____

PARTS USED

2-ball studs
1-spring Ag

\$44.00

Thompson




THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>206</u> MAKE <u>CAT</u> MODEL <u>246</u> SERIAL # _____ HOUR METER _____ MILES <u>1,900</u>	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: _____ DATE COMPLETED <u>6-17-09</u> MECHANIC <u>JAMES DANIEL</u> JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____	
PROBLEM: <u>cutting edge broken on 73" bucket</u>		
REPAIRED: <u>replaced edge.</u>		
PARTS: <u>Edge</u> <u>209.38</u> <u>Thompson</u>		



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>206</u> MAKE <u>CAT</u> MODEL <u>246</u> SERIAL # _____ HOUR METER <u>1,439 HRS</u> MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: _____ DATE COMPLETED <u>9-2-10</u> MECHANIC <u>JAMES</u> JOB NAME/LOCATION <u>Watertown Farm</u> JOB NUMBER _____	
PROBLEM: <u>service, having to jump start</u>		
REPAIRED: <u>serviced</u> <u>replaced bad battery</u>		
PARTS: <u>Gyp 24 battery \$94.⁹⁹</u> <u>Interstate battery</u> <u>Filters 127.⁰⁰</u> <u>Tenn Filter</u>		



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>206</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>246</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>1,600 HRS</u>		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>12-8-11</u>	MECHANIC <u>JAMES</u>
		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>seat worn out check over</u>			
REPAIRED: <u>replaced seat cushion</u> <u>replaced alternator belt</u> <u>washed</u>			
PARTS: <u>cushion kit</u> <u>155.⁰⁰</u> <u>Thompson Machinery</u> <u>Alternator belt</u> <u>\$22.⁵⁰</u> <u>NAPA</u>			



THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>206</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>246</u>		PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>10-1-12</u> DATE COMPLETED <u>10-2-12</u>	MECHANIC <u>JAMES</u>
		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>service, wash & check over</u>			
REPAIRED: <u>serviced, washed</u> <u>replaced hour meter,</u>			
PARTS: <u>filters</u> <u>103.75</u> <u>NAPA</u> <u>hour meter</u> <u>69.37</u> <u>Thompson</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>206</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>246</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES <u>260 HRS</u>			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: _____ DATE COMPLETED <u>9-5-13</u> MECHANIC <u>James</u>		
	JOB NAME/LOCATION <u>Shes</u>	JOB NUMBER	
PROBLEM: <u>Needs new tires</u>			
REPAIRED: <u>replaced all four & foam filled</u>			
PARTS: <u>4-Tires</u> <u>2,433.52</u> <u>Solidal USA</u>			
<u>Soldal</u>			
<u>12-16.5 lifemaster</u>			
<u>10pk Hauler</u>			

EQUIPMENT
REPAIRS

DATE 12-13-13

MILEAGE/HOURS 270 HRS

EQUIPMENT REPAIRED #206 246 Skid Steer

REPAIRS MADE Service

changed fuel filters on 12-11-13

HOURS WORKED _____

PARTS USED

All Filters 125.⁰⁰ Tenn Filter sales

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>206</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>246</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>2-24-14</u>	
		MECHANIC <u>JAMES</u>	
		JOB NAME/LOCATION <u>Water Town</u>	JOB NUMBER
PROBLEM: <u>won't start</u>			
REPAIRED: <u>replaced battery, dead cell in battery</u>			
<u>alternator charging wide open, removed alternator</u>			
<u>for repair</u>			
<u>jumped power in fuse box for dash indicators</u>			
PARTS: <u>Gap 24 battery 82.87</u> <u>Interstate Battery</u>			
<u>alternator rebuilt 120.18</u> <u>Crooks</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>206</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>246</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>5-1-14</u> MECHANIC <u>JAMES</u>	
		JOB NAME/LOCATION <u>Water Town</u>	JOB NUMBER
PROBLEM: <u>oil pressure light flashing AT idle</u>			
REPAIRED: <u>replaced oil pressure switch</u> <u>light not coming on now</u>			
PARTS: <u>switch</u> <u>28.65</u> <u>Thompson</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>206</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MAKE <u>Cat</u>	REASON	COMPONENT LOCATION	
MODEL <u>246</u>	PARTS _____ LABOR _____	FRONT REAR LEFT RIGHT UPPER LOWER	OTHER _____
SERIAL # _____	OTHER _____	_____	
HOUR METER _____	_____	_____	
MILES _____	_____	_____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>6-2-14</u>	MECHANIC <u>JAMES</u>
_____		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>electrical problem</u>			

REPAIRED: <u>fuse box losing connection in rear</u>			
<u>linked power from front of fuse box</u>			
<u>Rew it.</u>			

PARTS: _____			

EQUIPMENT
REPAIRS

DATE 10-13-14

MILEAGE/HOURS 460 HRS

EQUIPMENT REPAIRED #208 Cat 248 Skidsteer

REPAIRS MADE Changed oil, fuel, + Air filters

HOURS WORKED _____

PARTS USED

Air Filters	43.53	NAPA
Oil Filter	17.47	O'Reilly Auto Parts
Fuel Filter	in stock	Tron Filter Sales

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>206</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>246</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE: _____ DATE COMPLETED <u>2-23-15</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC <u>James + Steve</u>
SMOKES SHORTED VIBRATE OTHER _____	JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____

PROBLEM: no back up alarm check oil pressure

REPAIRED: replaced back up alarm, checked oil pressure 17 @ idle 40 wot. Replaced oil pressure switch again. checked monitor wiring, replaced air filters, replaced back-up alarm pressure switch.

PARTS: <u>Air filter + Alarm</u>	<u>64.09</u>	<u>NAPA</u>
<u>oil switch</u>	<u>28.65</u>	<u>Thompson</u>
<u>pressure switch</u>	<u>74.45</u>	<u>Thompson</u>

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>206</u> MAKE <u>Cat</u> MODEL <u>246</u> SERIAL # _____ HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
---	---	--

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED _____

MECHANIC: James & Steven

JOB NAME/LOCATION

JOB NUMBER

Shop

PROBLEM: Throttle cable bad

REPAIRED: replaced throttle cable with after market cable.
washed

PARTS: cable 301.55 Thompson Retrieved
cable 199.16 Fleetpride

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>206</u> MAKE <u>Cat</u> MODEL <u>246</u> SERIAL # _____ HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: _____ DATE COMPLETED <u>7-1-15</u> MECHANIC <u>James & Steven B</u>	JOB NAME/LOCATION <u>Shops</u> JOB NUMBER _____
PROBLEM: <u>Throttle sticking</u>		
REPAIRED: <u>replaced aftermarket throttle cable with cat cable</u>		
PARTS: <u>cable 246.00 Thompson</u>		

EQUIPMENT
REPAIRS

DATE 10-6-15

MILEAGE/HOURS 700 HRS

EQUIPMENT REPAIRED #206 CAT 246

REPAIRS MADE Changed oil Air & fuel filters

HOURS WORKED _____

PARTS USED

Oil & Air Filters

51.⁰⁰

NAPA

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>206</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>246</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>9-28-15</u> MECHANIC <u>JAMES</u>	
PROBLEM: <u>Engine shutting down</u>		JOB NAME/LOCATION <u>To Shop</u>	JOB NUMBER
REPAIRED: <u>replaced fuel filters & still shutting down. Funky fuel tank drained tank cleaned out and treated. Running O.K.</u>			
PARTS: <u>2 fuel filters</u> <u>32.00</u> <u>Fuel cap</u>		<u>Tenn Filter</u> <u>Thompson</u>	

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>206</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>246</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER <u>FW</u>		OTHER _____
MILES _____		

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: _____ DATE COMPLETED <u>10-10-15</u> MECHANIC <u>Skiver</u>
	JOB NAME/LOCATION <u>Shops</u> JOB NUMBER _____

PROBLEM: Anti-freeze leak

REPAIRED: replaced water pump gaskets

PARTS Gaskets & Thermostat 81.49 Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 206

MAKE CAT

MODEL 246

SERIAL # _____

HOUR METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
 POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER
 OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
 OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
 SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 1-26-16

MECHANIC James

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: Broken fuel cap

REPAIRED: replaced cap

PARTS: Fuel cap 31.00 Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>206</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>246</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____	DATE COMPLETED <u>4-27-16</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC _____	
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: _____ _____ _____			
REPAIRED: <u>New Tires - will mount when needed</u> _____ _____ _____ _____ _____			
PARTS: <u>4- Tires & Rims 104L. 63 Thompson Machinery</u> _____ _____ _____			

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>206</u> MAKE <u>CAT</u> MODEL <u>2816</u> SERIAL # _____ HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
--	---	--

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: _____ DATE COMPLETED <u>4-3-16</u> MECHANIC <u>Steven</u>
	JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____

PROBLEM: Key switch broken

REPAIRED: replaced key switch

PARTS: switch 96.⁰⁰ Thompson Machinery
