



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>904</u>	MAKE <u>CAT</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MODEL <u>D512</u>	SERIAL # <u>74414123</u>	REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
HOUR METER <u>3,361 HRS</u>	MILES _____	PARTS _____ LABOR _____	COMPONENT LOCATION	
		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
			OTHER _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>1-21-13</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>JAMES</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION	JOB NUMBER
			<u>James Shop</u>	
PROBLEM: <u>Check over, batteries</u>				
REPAIRED: <u>replaced all four batteries, replaced comp. rings in exhaust adapter serviced removed broken exhaust manifold bolt in head replaced missing bolts in upper radiator tank.</u>				
PARTS: <u>comp. rings 16.81 Thompson</u>				
<u>univerts 5.00 Napa</u>				
<u>4-29H-UHD Batteries 458.63 Interstate battery</u>				
<u>Filters 154.50 NAPA</u>				



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>904</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>DFR</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # <u>7XMY123</u>		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>3364</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>2-12-13</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>JAMES</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION	JOB NUMBER
PROBLEM: <u>Anti-freeze coming out of belly pan</u>				
REPAIRED: <u>coolant hose going to bottom of oil cooler leaking</u> <u>changed out two hoses</u> <u>topped off system</u> <u>lubed transmission control and brake pedal cam.</u>				
PARTS: <u>2 Hoses</u> <u>88.72</u> <u>NAPA</u>				



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>904</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>D8R</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>3-29-13</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC _____	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>Make up cable ends.</u>				
REPAIRED: _____				
PARTS: <u>Battery terminals 50.00 Naps</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>904</u>	HOURS _____ DAYS _____	REASON PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>			POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>D8K</u>			COMPONENT LOCATION	
SERIAL # _____			FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: _____ DATE COMPLETED <u>7-18-14</u>	
			MECHANIC <u>James</u>	
			JOB NAME/LOCATION <u>PFG</u>	JOB NUMBER
PROBLEM: <u>starter solenoid not turning starter.</u>				
REPAIRED: <u>replaced solenoid starter o.k.</u>				
PARTS: <u>solenoid \$63.⁰⁰ Crook's Auto Electric</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>904</u>	MAKE <u>D8R CAT</u> MODEL <u>D8R</u> SERIAL # _____ HOUR METER _____ MILES _____	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
		PARTS LABOR	COMPONENT LOCATION	
		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
			OTHER _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: _____ DATE COMPLETED <u>9-4-14</u>	
			MECHANIC <u>Nick</u>	
			JOB NAME/LOCATION <u>Cedarstone Bank</u>	JOB NUMBER _____
PROBLEM: <u>Fuel filter leaking</u>				
REPAIRED: <u>replaced fuel filter</u>				
PARTS: <u>Fuel filter + wrench \$23.00 Tenn Filters sales</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>904</u> MAKE <u>Cst</u> MODEL <u>D8R</u> SERIAL # _____ HOUR METER <u>3,765 HRS</u> MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____															
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>11-20-14</u> MECHANIC <u>JAMES</u> <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:50%;">JOB NAME/LOCATION <u>Shop</u></td> <td style="width:50%;">JOB NUMBER</td> </tr> </table>	JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER													
JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER																
PROBLEM: <u>Fix leaks, serviced</u>																	
REPAIRED: <u>replaced three leaking hoses</u> <u>sealed steer & brake valve</u> <u>repaired seat back & headrest</u> <u>serviced (all fittings replaced)</u> <u>replaced two leaking quick disconnects</u> <u>2-bushings \$14.11 Thompson</u> <u>nipples & seals \$143.12 Thompson</u>																	
<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:30%;">PARTS: <u>valves seals</u></td> <td style="width:20%; text-align: right;"><u>\$76.98</u></td> <td style="width:50%;"><u>Thompson</u></td> </tr> <tr> <td><u>drain seals</u></td> <td style="text-align: right;"><u>25.29</u></td> <td><u>Thompson</u></td> </tr> <tr> <td><u>O-rings</u></td> <td style="text-align: right;"><u>23.15</u></td> <td><u>Thompson</u></td> </tr> <tr> <td><u>seat back</u></td> <td style="text-align: right;"><u>151.98</u></td> <td><u>Thompson</u></td> </tr> <tr> <td><u>Hoses</u></td> <td style="text-align: right;"><u>390.10</u></td> <td><u>Thompson</u></td> </tr> </table>			PARTS: <u>valves seals</u>	<u>\$76.98</u>	<u>Thompson</u>	<u>drain seals</u>	<u>25.29</u>	<u>Thompson</u>	<u>O-rings</u>	<u>23.15</u>	<u>Thompson</u>	<u>seat back</u>	<u>151.98</u>	<u>Thompson</u>	<u>Hoses</u>	<u>390.10</u>	<u>Thompson</u>
PARTS: <u>valves seals</u>	<u>\$76.98</u>	<u>Thompson</u>															
<u>drain seals</u>	<u>25.29</u>	<u>Thompson</u>															
<u>O-rings</u>	<u>23.15</u>	<u>Thompson</u>															
<u>seat back</u>	<u>151.98</u>	<u>Thompson</u>															
<u>Hoses</u>	<u>390.10</u>	<u>Thompson</u>															
<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:30%;">Fitters</td> <td style="width:20%; text-align: right;"><u>97.12</u></td> <td style="width:50%;">Tenn fitter sales</td> </tr> </table>			Fitters	<u>97.12</u>	Tenn fitter sales												
Fitters	<u>97.12</u>	Tenn fitter sales															

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES												
EQUIP. # <u>904</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS												
MAKE <u>Cat</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED												
MODEL <u>D8R</u>	PARTS _____ LABOR _____	COMPONENT LOCATION												
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER												
HOUR METER _____		OTHER _____												
MILES _____														
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>11-28-14</u> MECHANIC <u>JAMES K COREY</u>												
		JOB NAME/LOCATION <u>Franklin</u> JOB NUMBER _____												
PROBLEM: <u>blown hose,</u>														
REPAIRED: <u>replaced left cylinder hose on blade</u> <u>lift. from manifold to cylinder tube, replaced</u> <u>both right hoses from manifold to cylinder</u> <u>drilled out all broken bolts</u>														
<table style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 33%;">PARTS: <u>1-hose</u></td> <td style="width: 33%; text-align: right;"><u>\$183.23</u></td> <td style="width: 34%; text-align: right;"><u>Thompson</u></td> </tr> <tr> <td><u>2-hoses</u></td> <td style="text-align: right;"><u>\$398.47</u></td> <td style="text-align: right;"><u>Thompson</u></td> </tr> <tr> <td><u>2 clamps</u></td> <td style="text-align: right;"><u>24.03</u></td> <td style="text-align: right;"><u>Thompson</u></td> </tr> <tr> <td><u>Tap</u></td> <td style="text-align: right;"><u>9.00</u></td> <td style="text-align: right;"><u>Napa</u></td> </tr> </table>			PARTS: <u>1-hose</u>	<u>\$183.23</u>	<u>Thompson</u>	<u>2-hoses</u>	<u>\$398.47</u>	<u>Thompson</u>	<u>2 clamps</u>	<u>24.03</u>	<u>Thompson</u>	<u>Tap</u>	<u>9.00</u>	<u>Napa</u>
PARTS: <u>1-hose</u>	<u>\$183.23</u>	<u>Thompson</u>												
<u>2-hoses</u>	<u>\$398.47</u>	<u>Thompson</u>												
<u>2 clamps</u>	<u>24.03</u>	<u>Thompson</u>												
<u>Tap</u>	<u>9.00</u>	<u>Napa</u>												

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>964</u> MAKE <u>Cat</u> MODEL <u>D8R</u> SERIAL # _____ HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>2-12-15</u> MECHANIC <u>James + Jose</u> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 70%; padding: 2px;">JOB NAME/LOCATION <u>Reid Hill</u></td> <td style="width: 30%; padding: 2px;">JOB NUMBER</td> </tr> </table>	JOB NAME/LOCATION <u>Reid Hill</u>	JOB NUMBER
JOB NAME/LOCATION <u>Reid Hill</u>	JOB NUMBER			
PROBLEM: <u>blown hydraulic hose from pump to control valve</u>				
REPAIRED: <u>replaced hose</u>				
PARTS: <u>hose assembly 169.⁰⁸ Thompson Machinery</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>904</u> MAKE <u>CAT</u> MODEL <u>DPR</u> SERIAL # _____ HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>7-31-15</u> MECHANIC <u>James + Steven</u> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 70%;">JOB NAME/LOCATION <u>Touch Stone</u></td> <td style="width: 30%;">JOB NUMBER</td> </tr> </table>	JOB NAME/LOCATION <u>Touch Stone</u>	JOB NUMBER
JOB NAME/LOCATION <u>Touch Stone</u>	JOB NUMBER			
PROBLEM: <u>Fuel tank sending unit came apart, leaking diesel fuel.</u>				
REPAIRED: <u>replaced sending unit</u> <u>changed connector</u>				
PARTS: <u>sendig unit</u> <u>240.83</u> <u>Thompson</u>				

157-3210

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>904</u> MAKE <u>Cat</u> MODEL <u>D8R</u> SERIAL # _____ HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>12-16-15</u> MECHANIC <u>JAMES</u> JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____
PROBLEM: <u>left track popping.</u>		
REPAIRED: <u>removed recoil & track adjuster, reseated thompson checked spring all ok Equilizer bar bearings bad.</u>		
Hardware Sealant Wedges	347. ⁷⁶ 15. ²¹ 28. ²⁹	Thompson Napa Thompson
PARTS: All Filters bolts, wedges & washers seals recoil spring repair caps	245. ⁸⁸ 126. ⁰⁰ 525. ⁵⁰ 56. ¹³	Tenn Filter sales Thompson Thompson Thompson Thompson
bolts & nuts wrench nuts	86. ⁴² 75. ⁰⁰ 32. ⁵³	Thompson Napa Truck Pro

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>904</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>D8R</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>1-26-16</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Nick</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Wilson Bank</u>	JOB NUMBER
PROBLEM: <u>TRANS. lock knob missing</u>				
REPAIRED: <u>replaced knob</u>				
PARTS: <u>Knob</u> <u>17.96</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>904</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Cat</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>125R</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 7-16-16

MECHANIC James + Steven

JOB NAME/LOCATION

Cainsville Rd

JOB NUMBER

PROBLEM:

Muffler + stack rusted out

REPAIRED:

replaced muffler + stack

PARTS

Muffler, Stack + clamps 894.78 Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>904</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Cat</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>D8R</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____

DATE COMPLETED 9-9-16

MECHANIC Steven B

JOB NAME/LOCATION

JOB NUMBER

Shop

PROBLEM: Engine oil & fuel leaks

REPAIRED:

replaced all six injector line adapters
replaced both lower rocker boxes adjusted
valves, Replaced arm rests replaced roller on
steer valve

Seat 1600, ⁰⁰ Thompson

PARTS:

<u>Gaskets orings & adapters</u>	<u>305. ⁰⁴</u>	<u>Thompson</u>
<u>Curbier 3 & roller</u>	<u>233. ⁵⁶</u>	<u>Thompson</u>
<u>2-lane ^{well} valve covers</u>	<u>351. ²⁹</u>	<u>Thompson</u>
<u>Gaskets & regulator</u>	<u>98. ²³</u>	<u>Thompson</u>
<u>Hardware & Top</u>	<u>88. ²⁵</u>	<u>Thompson</u>
<u>Helicall</u>	<u>33. ²⁹</u>	<u>NAPA</u>

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>904</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>DFR</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>11-7-16</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>James + Steve</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>#2 injector line</u>				
REPAIRED: _____				
PARTS: <u>injector line</u> <u>189.84</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>904</u>	REASON PARTS LABOR OTHER _____	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>D8R</u>		COMPONENT LOCATION		
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>1-23-17</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>James + Steven</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>Rear idler, flip cutting edges</u>				
REPAIRED: _____				
PARTS: <u>Idler</u> <u>1,258.83</u> <u>Thompson</u>				
<u>End bits, bolts & nuts</u> <u>White House Equipment</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>904</u>	MAKE <u>CAT</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MODEL <u>DPR</u>		REASON PARTS _____ LABOR _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
SERIAL # _____		OTHER _____	COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE <u>7-4-17</u> DATE COMPLETED _____	
			MECHANIC <u>JAMES & Steven B</u>	
			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>Tilt cylinder leaking</u>				
REPAIRED: <u>sealed tilt cylinder</u>				
PARTS: <u>seal kit</u> <u>233.35</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES																						
EQUIP. # <u>904 (1003)</u>	HOURS _____ DAYS _____ REASON PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS																							
MAKE <u>CAT</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED																							
MODEL <u>DPR</u>		COMPONENT LOCATION																							
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER																							
HOUR METER _____		OTHER _____																							
MILES _____		_____																							
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>7-31-17</u>	DATE COMPLETED <u>11-22-17</u>																						
		MECHANIC <u>All</u>																							
		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____																						
PROBLEM: <u>lift cylinders leaking, Radiator</u> <u>blade links, Exhaust leaks, Tilt cylinder leak</u>																									
REPAIRED: <u>replaced Radiator cores, repaired exhaust, packed</u> <u>tilt cylinder, replaced push arm blocks & pins</u> <u>Packed blade lift cylinders</u>																									
<table border="0"> <tr> <td>seat belt</td> <td>206.⁰⁰</td> <td>Thompson</td> </tr> <tr> <td>Filters</td> <td>143.⁰⁵</td> <td>Tenn Filler Saks</td> </tr> <tr> <td>Radiator cores & Fan + Pins Connectors</td> <td>6,236.⁵⁴</td> <td>White House Equipment</td> </tr> </table>					seat belt	206. ⁰⁰	Thompson	Filters	143. ⁰⁵	Tenn Filler Saks	Radiator cores & Fan + Pins Connectors	6,236. ⁵⁴	White House Equipment												
seat belt	206. ⁰⁰	Thompson																							
Filters	143. ⁰⁵	Tenn Filler Saks																							
Radiator cores & Fan + Pins Connectors	6,236. ⁵⁴	White House Equipment																							
<table border="0"> <tr> <td>PARTS: 2-seal kits</td> <td>250.⁰⁰</td> <td>Thompson</td> </tr> <tr> <td>pins & bars</td> <td>38.⁹⁹</td> <td>Thompson</td> </tr> <tr> <td>Hoses</td> <td>426.²⁹</td> <td>Thompson</td> </tr> <tr> <td>Exhaust Parts</td> <td>1,175.⁸⁰</td> <td>Thompson</td> </tr> <tr> <td>belts & u-joints</td> <td>371.⁷⁷</td> <td>Thompson</td> </tr> <tr> <td>seal kit</td> <td>219.²⁵</td> <td>Thompson</td> </tr> <tr> <td>Pin & bearings, Press. switch</td> <td>78.⁰⁴</td> <td>Thompson</td> </tr> </table>					PARTS: 2-seal kits	250. ⁰⁰	Thompson	pins & bars	38. ⁹⁹	Thompson	Hoses	426. ²⁹	Thompson	Exhaust Parts	1,175. ⁸⁰	Thompson	belts & u-joints	371. ⁷⁷	Thompson	seal kit	219. ²⁵	Thompson	Pin & bearings, Press. switch	78. ⁰⁴	Thompson
PARTS: 2-seal kits	250. ⁰⁰	Thompson																							
pins & bars	38. ⁹⁹	Thompson																							
Hoses	426. ²⁹	Thompson																							
Exhaust Parts	1,175. ⁸⁰	Thompson																							
belts & u-joints	371. ⁷⁷	Thompson																							
seal kit	219. ²⁵	Thompson																							
Pin & bearings, Press. switch	78. ⁰⁴	Thompson																							

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1003</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>D8R</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>3-14-18</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Charles</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Maple Crossing</u>	JOB NUMBER _____
PROBLEM: <u>Flow light on, Alt. not charging</u>				
REPAIRED: <u>replaced coolant flow switch</u>				
<u>replaced Alternator</u>				
PARTS: <u>Alternator</u> <u>240.35</u> <u>Crook</u>				
<u>Switch & Gasket</u> <u>182.62</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>1003</u> MAKE <u>CAT</u> MODEL <u>DFR</u> SERIAL # _____ HOUR METER _____ MILES _____		EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____		COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____				DATE: _____ DATE COMPLETED <u>7-31-18</u> MECHANIC <u>James + Tony</u> JOB NAME/LOCATION <u>Cargill</u> JOB NUMBER _____	
PROBLEM: <u>blown hose</u>					
REPAIRED: <u>replaced hose + 15 gal oil</u>					
PARTS <u>Hose</u> <u>281.53</u> <u>Thompson</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES																						
EQUIP. # <u>1003</u>	HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS																							
MAKE <u>Cat</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED																							
MODEL <u>D8R</u>		COMPONENT LOCATION																							
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER																							
HOUR METER _____		OTHER _____																							
MILES _____																									
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>9-3-18</u>	DATE COMPLETED <u>11-1-18</u>																						
		MECHANIC <u>Charles</u>																							
		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____																						
PROBLEM: <u>pivot shaft seal leaking</u>																									
REPAIRED: _____																									
<table border="0"> <tr> <td><u>Spacer</u></td> <td><u>21.³⁷</u></td> <td><u>Thompson</u></td> </tr> <tr> <td><u>2-Hoses</u></td> <td><u>302.³⁵</u></td> <td><u>Thompson</u></td> </tr> <tr> <td><u>Seal</u></td> <td><u>162.³³</u></td> <td><u>Thompson</u></td> </tr> <tr> <td><u>Plate</u></td> <td><u>265.³⁰</u></td> <td><u>Thompson</u></td> </tr> </table>					<u>Spacer</u>	<u>21.³⁷</u>	<u>Thompson</u>	<u>2-Hoses</u>	<u>302.³⁵</u>	<u>Thompson</u>	<u>Seal</u>	<u>162.³³</u>	<u>Thompson</u>	<u>Plate</u>	<u>265.³⁰</u>	<u>Thompson</u>									
<u>Spacer</u>	<u>21.³⁷</u>	<u>Thompson</u>																							
<u>2-Hoses</u>	<u>302.³⁵</u>	<u>Thompson</u>																							
<u>Seal</u>	<u>162.³³</u>	<u>Thompson</u>																							
<u>Plate</u>	<u>265.³⁰</u>	<u>Thompson</u>																							
<table border="0"> <tr> <td>PARTS <u>bearings, seals & plugs</u></td> <td><u>\$2630.⁴⁸</u></td> <td><u>Thompson</u></td> </tr> <tr> <td><u>Plate</u></td> <td><u>162.³³</u></td> <td><u>Thompson</u></td> </tr> <tr> <td><u>Plate & rubbers</u></td> <td></td> <td><u>Thompson</u></td> </tr> <tr> <td><u>Packs</u></td> <td><u>1535.⁰⁹</u></td> <td><u>Thompson</u></td> </tr> <tr> <td><u>Bolts, etc</u></td> <td><u>60.⁷¹</u></td> <td><u>Thompson</u></td> </tr> <tr> <td><u>Hardware & Hoses</u></td> <td><u>702.⁴⁷</u></td> <td><u>Thompson</u></td> </tr> <tr> <td><u>Idle</u></td> <td><u>1970.⁰¹</u></td> <td><u>Thompson</u></td> </tr> </table>					PARTS <u>bearings, seals & plugs</u>	<u>\$2630.⁴⁸</u>	<u>Thompson</u>	<u>Plate</u>	<u>162.³³</u>	<u>Thompson</u>	<u>Plate & rubbers</u>		<u>Thompson</u>	<u>Packs</u>	<u>1535.⁰⁹</u>	<u>Thompson</u>	<u>Bolts, etc</u>	<u>60.⁷¹</u>	<u>Thompson</u>	<u>Hardware & Hoses</u>	<u>702.⁴⁷</u>	<u>Thompson</u>	<u>Idle</u>	<u>1970.⁰¹</u>	<u>Thompson</u>
PARTS <u>bearings, seals & plugs</u>	<u>\$2630.⁴⁸</u>	<u>Thompson</u>																							
<u>Plate</u>	<u>162.³³</u>	<u>Thompson</u>																							
<u>Plate & rubbers</u>		<u>Thompson</u>																							
<u>Packs</u>	<u>1535.⁰⁹</u>	<u>Thompson</u>																							
<u>Bolts, etc</u>	<u>60.⁷¹</u>	<u>Thompson</u>																							
<u>Hardware & Hoses</u>	<u>702.⁴⁷</u>	<u>Thompson</u>																							
<u>Idle</u>	<u>1970.⁰¹</u>	<u>Thompson</u>																							

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1003</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>D8R</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>400 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE <u>10-11-18</u> DATE COMPLETE <u>10-17-18</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>All</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____	
PROBLEM: <u>needs serviced</u>				
REPAIRED: <u>Serviced</u>				
PARTS: <u>All Filters</u> <u>245.14</u> <u>Tenn Filter</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1003</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>DFR</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>0</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: <u>12-13-18</u> DATE COMPLETED: <u>5-7-19</u> MECHANIC: _____ JOB NAME/LOCATION: <u>MCH to Ashland Farms</u> JOB NUMBER: _____	
PROBLEM: <u>linkage broke</u> <u>At Thompson to be rebuilt</u>				
REPAIRED: <u>new hour meter</u>				
PARTS: <u>linkage parts</u> <u>147.31</u> <u>Thompson</u> <u>valves</u> <u>66.14</u> <u>Thompson</u> <u>Platform</u> <u>5,000.00</u> <u>Vulcan</u> <u>Rops</u> <u>2,000.00</u> <u>Vulcan</u> <u>Refurbish</u> <u>217R</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1003</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>DPR</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>6-24-19</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Charles</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Ashland Farms</u>	JOB NUMBER
PROBLEM: <u>blown Tilt cylinder hose</u>				
REPAIRED: <u>replaced hose</u>				
PARTS: <u>hose Assembly</u> <u>443.18</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1003</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>DFR</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>6-26-19</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Charles</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Ashland Farms</u>	JOB NUMBER _____
PROBLEM: <u>blown Tilt cylinder hose</u>				
REPAIRED: <u>replaced hose</u>				
PARTS: <u>Hose</u> <u>150.54</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1003</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>DPR</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>1K HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>1-30-2020</u> DATE COMPLETED <u>2-21-2020</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Charles</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Jones Brummett</u>	JOB NUMBER _____
PROBLEM: <u>Service</u>				
REPAIRED: <u>serviced</u>				
PARTS: <u>All Filters</u> <u>25.3. 21</u> <u>Tenn. Filter sales</u>				
<u>clamps</u> <u>35.54</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>1003</u> MAKE <u>CAT</u> MODEL <u>D8R</u> SERIAL # <u>refurb.</u> HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____															
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>4-21-2020</u> DATE COMPLETED <u>4-24-2020</u> MECHANIC <u>Charles</u> JOB NAME/LOCATION <u>Jones Brunswick</u> JOB NUMBER _____															
PROBLEM: <u>row Tank to pivot shaft housing cracked</u> <u>safety lock shaft bad.</u>																	
REPAIRED: <u>replaced batteries, repaired ends. replaced</u> <u>lock out rod and ball joint. replaced row</u> <u>Tank</u>																	
<table style="width:100%; border-collapse: collapse;"> <tr> <td style="width:33%;">PARTS: <u>TANK</u></td> <td style="width:33%; text-align: center;"><u>138.75</u></td> <td style="width:33%; text-align: center;"><u>Thompson</u></td> </tr> <tr> <td><u>Pin</u></td> <td style="text-align: center;"><u>34.47</u></td> <td style="text-align: center;"><u>Thompson</u></td> </tr> <tr> <td><u>Spring</u></td> <td style="text-align: center;"><u>11.26</u></td> <td style="text-align: center;"><u>Thompson</u></td> </tr> <tr> <td><u>rod ends ball joint</u></td> <td style="text-align: center;"><u>39.34</u></td> <td style="text-align: center;"><u>Thompson</u></td> </tr> <tr> <td><u>4 batteries</u></td> <td style="text-align: center;"><u>52 P. 51</u></td> <td></td> </tr> </table>			PARTS: <u>TANK</u>	<u>138.75</u>	<u>Thompson</u>	<u>Pin</u>	<u>34.47</u>	<u>Thompson</u>	<u>Spring</u>	<u>11.26</u>	<u>Thompson</u>	<u>rod ends ball joint</u>	<u>39.34</u>	<u>Thompson</u>	<u>4 batteries</u>	<u>52 P. 51</u>	
PARTS: <u>TANK</u>	<u>138.75</u>	<u>Thompson</u>															
<u>Pin</u>	<u>34.47</u>	<u>Thompson</u>															
<u>Spring</u>	<u>11.26</u>	<u>Thompson</u>															
<u>rod ends ball joint</u>	<u>39.34</u>	<u>Thompson</u>															
<u>4 batteries</u>	<u>52 P. 51</u>																

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1003</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>D8R</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>1500 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>7-20-20</u> DATE COMPLETED <u>7-23-20</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>BEN & MATT</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Drop site</u>	JOB NUMBER _____
PROBLEM: <u>Service, blown tilt cylinder hose</u>				
REPAIRED: <u>serviced replaced Tilt cylinder hose</u>				
PARTS: <u>All Filters</u> <u>253. ^{FL}</u> <u>Tenn Filter sales</u>				
<u>hose</u> <u>173. ^{FZ}</u> <u>Thompson</u>				
<u>Hardware</u> <u>38. ^{FZ}</u> <u>Thompson</u>				
<u>Muffler & Champ</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1003</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>D8R</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>2K HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>3-11-21</u> DATE COMPLETED: <u>5-4-21</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Ben Catb</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Eastgate</u>	JOB NUMBER
PROBLEM: <u>service</u>				
REPAIRED: <u>serviced</u>				
PARTS: <u>All Filters</u> <u>268.44</u> <u>Tenn Filter</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1003</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>D8R</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>9-25-21</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Ben</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Vintage Edge</u>	JOB NUMBER _____	
PROBLEM: <u>Hydraulic Tank relief broken off</u>				
REPAIRED: <u>replaced relief vent.</u>				
PARTS: <u>Vent</u> <u>181.00</u> <u>Thompson</u>				

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1003</u>	MAKE <u>CAT</u>	HOURS _____ DAYS _____	BASIC MACHINE	HYDRAULIC ENGINE IMPLEMENTS
MODEL <u>D8R</u>	SERIAL # _____	REASON _____	POWER TRAIN	ELECTRIC DRIVE TRAIN UNEXPLAINED
HOUR METER <u>2500 NRS</u>	MILES _____	PARTS _____ LABOR _____	COMPONENT LOCATION	
		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
			OTHER _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE <u>10-7-21</u> DATE COMPLETED <u>10-27-21</u> MECHANIC <u>Ben & Anthony</u>		
PROBLEM: <u>Service</u>		JOB NAME/LOCATION <u>West Trinity</u>	JOB NUMBER	
REPAIRED: <u>serviced</u> <u>replaced broken hydraulic Tank cap</u>				
PARTS: <u>All Filters</u> <u>285.⁶¹</u> <u>Tenn Filter sales</u> <u>Oil Filter</u> <u>26.⁹²</u> <u>Thompson</u> <u>Hyd cap</u> <u>97.⁰¹</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1003</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>DPR</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>2838.4 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: <u>3-16-22</u> DATE COMPLETED <u>8-29-22</u> MECHANIC <u>Thompson</u>	
PROBLEM: <u>Oil leak on Engine</u>			JOB NAME/LOCATION: <u>Thompson</u> JOB NUMBER _____	
REPAIRED: <u>Thompson repair 4-19-22 - 8-29-22</u>				
PARTS: <u>re-sealed front gear train housing.</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>1003</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>D8R</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>3K HRS</u>		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE <u>12-8-22</u> DATE COMPLETED <u>12-9-22</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Anthony</u>	
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Stone Trace</u> JOB NUMBER <u>Ant them</u>	
PROBLEM: <u>Service</u>			
REPAIRED: <u>Service</u>			
PARTS: <u>Fitters</u> <u>337.39</u> <u>Tom Fitter sales</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>1003</u> MAKE <u>Cat</u> MODEL <u>D8R</u> SERIAL # _____ HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____									
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>4-5-23</u> MECHANIC <u>ALL</u> JOB NAME/LOCATION <u>Sparta PK</u> JOB NUMBER _____									
PROBLEM: <u>check over</u>											
REPAIRED: <u>Tightened injection pump bolts. replaced main cap. blew out radiator. new Eq. bar plugs checked oil pan bolts</u>											
<table style="width: 100%;"> <tr> <td style="width: 40%;">PARTS: <u>hose & hardware</u></td> <td style="width: 20%; text-align: right;"><u>219.40</u></td> <td style="width: 40%; text-align: right;"><u>Thompson</u></td> </tr> <tr> <td><u>bottle</u></td> <td style="text-align: right;"><u>189.59</u></td> <td style="text-align: right;"><u>Thompson</u></td> </tr> <tr> <td><u>Ex cap & plugs</u></td> <td style="text-align: right;"><u>164.52</u></td> <td style="text-align: right;"><u>Thompson</u></td> </tr> </table>			PARTS: <u>hose & hardware</u>	<u>219.40</u>	<u>Thompson</u>	<u>bottle</u>	<u>189.59</u>	<u>Thompson</u>	<u>Ex cap & plugs</u>	<u>164.52</u>	<u>Thompson</u>
PARTS: <u>hose & hardware</u>	<u>219.40</u>	<u>Thompson</u>									
<u>bottle</u>	<u>189.59</u>	<u>Thompson</u>									
<u>Ex cap & plugs</u>	<u>164.52</u>	<u>Thompson</u>									

TEC

THORNE'S EXCAVATING COMPANY, LLC SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 1003

MAKE CAT

MODEL DPR

SERIAL # _____

HOUR METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON _____

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 4-14-23

MECHANIC Ben

JOB NAME/LOCATION

JOB NUMBER

Sparta PK

PROBLEM: injector line leak

REPAIRED: replaced no. 5 injector line

PARTS: no. 5 line

294.⁸⁵

Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1003</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>DPR</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>4-14-23</u> DATE COMPLETED <u>4-15-23</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Spartan AK.</u>	JOB NUMBER _____
PROBLEM: <u>oil leak + fuel leak</u>				
REPAIRED: <u>plug came out of injection pump.</u>				
PARTS: <u>3 adapters</u> <u>181.58</u> <u>Thompson</u>				
<u>Plugs</u> <u>15.00</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 1003

MAKE Cat

MODEL D8R

SERIAL # _____

HOUR METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON _____

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: 7-18-23 DATE COMPLETED 7-19-23

MECHANIC Ben

JOB NAME/LOCATION

JOB NUMBER

Shop Yard

PROBLEM:

Radiator leak

REPAIRED:

removed cores had them cleaned and tested
Assembled

PARTS:

clean & repair 2166.25 Emission & cooling solutions
seals, gasket & hoses 1022.29 Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>1003</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>DFR</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE: _____ DATE COMPLETED <u>7-20-13</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION <u>New Shop</u>	
PROBLEM: <u>Coolant leak</u>				JOB NUMBER _____	

REPAIRED: Leaking core, removed all 9. Had cleared repaired and tested. Installed.

PARTS: Leak hoses & clamps 1073.32 Thompson
Cores clean & repair 2,273.75 Emission & Cooling

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1003</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>Cat</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>D8R</u>	PARTS _____ LABOR _____	COMPONENT LOCATION		
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER <u>3504 HRS</u>		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>9-27-24</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>All</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION		JOB NUMBER
PROBLEM: <u>leaks</u>				
REPAIRED: <u>resealed all fuel line adapters. Replaced two injector lines Thompson replaced two broken valve spring caps. repaired boost pressure tube going to goubler</u>				
PARTS: <u>no. 6 inj. line 278.⁸⁷</u> <u>Thompson</u>				
<u>seals, gaskets & 3 adapters 905.²⁷</u> <u>Thompson</u>				
<u>Thompson After Adapter repair 785.¹⁸</u> <u>Thompson</u>				
<u>no. 3 inj. line 281.⁷⁵</u> <u>Thompson</u>				
<u>cover & elbow 37.⁹⁹</u> <u>Thompson</u>				
<u>Thompson Valve cap repair 1,774.⁰⁰</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>1003</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Cat</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>D8R</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
 OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
 SMOKES SHORTED VIBRATE OTHER _____

DATE: 1-28-25 DATE COMPLETED 1-28-25

MECHANIC Ben

JOB NAME/LOCATION
Sub station

JOB NUMBER

PROBLEM: left push arm bolts out.

REPAIRED: replaced push arm bolts + shims

PARTS: hardware 252.52 Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 1003

MAKE CAT

MODEL D8R

SERIAL # _____

HOUR METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS

LABOR

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: 4-22-25 DATE COMPLETED 4-25-25

MECHANIC Bryan

JOB NAME/LOCATION

FARM

JOB NUMBER

PROBLEM: muffler cracked

REPAIRED: replaced muffler

PARTS: muffler

\$43.92

Thompson

Thompson



INVOICE

THOMPSON MACHINERY/THOMPSON POWER

DIVISIONS OF

THOMPSON MACHINERY COMMERCE CORPORATION

LaVERGNE, TN (615) 256-2424	MEMPHIS, TN (901) 332-3051	COLUMBUS, MS (662) 327-3083	GREENWOOD, MS (662) 453-5233	TUPELO, MS (662) 844-1634	CAMDEN, TN (731) 584-2732	CLARKSVILLE, TN (931) 552-5496	JACKSON, TN (731) 988-4240
--------------------------------	-------------------------------	--------------------------------	---------------------------------	------------------------------	------------------------------	-----------------------------------	-------------------------------

SOLD TO

SHIP TO



THORNES EXCAVATING
COMPANY LLC
624 OLD HORN SPRINGS RD
LEBANON TN

37087-1811

INVOICE NUMBER	INVOICE DATE	CUSTOMER NUMBER	CUSTOMER ORDER NUMBER	STORE	DIV	SALESMAN	TERMS	PAGE
LV02669	04-24-19	848650		00	G	84	2	9
PSO/NO-NO	DOC DATE	PG	LC	MG	SHIP VIA		INV SEQ. NO.	
LV02669	02-01-19	10	10	10				
MAKE	MODEL	SERIAL NUMBER	EQUIPMENT NUMBER	METER READING			MACH. ID NO.	
AA	D8R	07XM04123	1003	524.0				
QUANTITY	ITEM	N/R	DESCRIPTION	UNIT PRICE			EXTENSION	

* * * PROFORMA INVOICE * * *

1-		CORE RETURN	S	1763.95	1763.95-
1	0R-5511	CORE AS-OIL	S	994.54	
		DISCOUNT 10.00%		99.45-	895.09
1		CORE DEPOSIT	S	444.92	444.92
1-		CORE RETURN	S	444.92	444.92-
1	0R-5549	CORE GP-OIL	S	1837.11	
		DISCOUNT 10.00%		183.71-	1653.40
1		CORE DEPOSIT	S	821.83	821.83
1-		CORE RETURN	S	821.83	821.83-
1	0R-9697	PUMP GP OIL	N	787.26	
		DISCOUNT 10.00%		78.73-	708.53
1		CORE DEPOSIT	N	1293.40	1293.40
1-		CORE RETURN	N	1293.40	1293.40-
6	0R-9847	CYL PACK	S	672.42	
		DISCOUNT 10.00%		67.24-	3631.08
6		CORE DEPOSIT	S	301.77	1810.62
6-		CORE RETURN	S	301.77	1810.62-
2	0R-9943	NOZZLE AY	S	103.50	
		DISCOUNT 10.00%		10.35-	186.30
2		CORE DEPOSIT	S	92.73	185.46
2	0R-9943	NOZZLE AY	S	103.50	
		DISCOUNT 10.00%		10.35-	186.30
2		CORE DEPOSIT	S	92.73	185.46
2	0R-9943	NOZZLE AY	S	103.50	
		DISCOUNT 10.00%		10.35-	186.30
2		CORE DEPOSIT	S	92.73	185.46
6-		CORE RETURN	S	92.73	556.38-

TERMS: NET CASH WITHIN 10 DAYS AFTER END OF MONTH DURING WHICH PURCHASES WERE MADE.
A SERVICE CHARGE OF 1.5% PER MONTH (18% PER ANNUM), OR THE HIGHEST LEGAL RATE
PERMITTED, WILL BE ADDED ON PAST DUE AMOUNTS UNTIL PAID TO COVER ADDITIONAL
PROCESSING AND HANDLING COST.

* -NOT RETURNABLE ITEMS NOT SHOWN ARE BACK ORDERED

YOU ACKNOWLEDGE AND AGREE THAT AS A CATERPILLAR PRODUCTS DEALER, THOMPSON MACHINERY MAY
SHARE WITH CATERPILLAR INC. ("CATERPILLAR") INFORMATION REGARDING YOU AND YOUR PURCHASE
AND/OR LEASE OF EQUIPMENT, GOODS, PARTS OR OTHER MERCHANDISE AND/OR SERVICES OR REPAIRS FROM
THOMPSON MACHINERY. SUCH INFORMATION MAY INCLUDE, BUT MAY NOT BE LIMITED TO, INFORMATION
ABOUT SPECIFIC EQUIPMENT OR PRODUCTS PURCHASED OR LEASED BY YOU AND YOUR NAME, ADDRESS,
TELEPHONE NUMBER AND EMAIL ADDRESS (COLLECTIVELY, "CUSTOMER INFORMATION"). CATERPILLAR MAY
USE YOUR CUSTOMER INFORMATION AND SHARE IT WITH THIRD PARTIES ON ITS BEHALF TO FACILITATE
EFFORTS TOWARD IMPROVING CUSTOMER EXPERIENCE AND ENABLE CATERPILLAR TO MORE EFFECTIVELY
SUPPORT THOMPSON MACHINERY.

PAY THIS
AMOUNT ►

CONT'D

AMOUNT
CREDIT ►