

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0505</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>336F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>10K 1125</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>10-21-22</u> DATE COMPLETED <u>11-1-22</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Anthony</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Carver Town Homes</u>	JOB NUMBER _____
PROBLEM: <u>Service</u>				
REPAIRED: <u>Serviced</u>				
PARTS: <u>All Filters</u> <u>612.02</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0505

MAKE CAT

MODEL 336F

SERIAL # _____

HOUR METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: 12-6-22 DATE COMPLETED 1-12-23

MECHANIC Mark + James

JOB NAME/LOCATION

JOB NUMBER

Stone Trace

PROBLEM: broken shank cracked bucket

REPAIRED: replaced broken shank, repaired back of bucket.

PARTS: Shank

4717.79

Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0505
MAKE Cat
MODEL 336F
SERIAL # _____
HOUR METER 10,500 HRS
MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
REASON _____
PARTS _____ LABOR _____
OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER
OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SMOKES SHORTED VIBRATE OTHER _____

DATE 3-27-23 DATE COMPLETED 4-12-23

MECHANIC Anthony & Brian

JOB NAME/LOCATION

Stone Trace

JOB NUMBER

PROBLEM: Service

REPAIRED: Service

Thompson did a program

PARTS: Filters

692.4L

Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0505
 MAKE Cat
 MODEL 336F
 SERIAL # _____
 HOUR METER _____
 MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
 REASON _____
 PARTS _____ LABOR _____
 OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
 POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER
 OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
 OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
 SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 4-20-23

MECHANIC Ben + Anthony

JOB NAME/LOCATION
Stone Trace

JOB NUMBER

PROBLEM: broken track pin

REPAIRED: replaced track pin + ave pad.

PARTS: pin + bolts

144.44

Thompson

pad

164.49

Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0505
MAKE CAT
MODEL 336F
SERIAL # _____
HOUR METER 19712 HRF
MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
REASON _____
PARTS _____ LABOR _____
OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER
OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SMOKES SHORTED VIBRATE OTHER _____

DATE: 5-4-23 DATE COMPLETED 5-22-23

MECHANIC ALL

JOB NAME/LOCATION

10 Shop

JOB NUMBER

PROBLEM: DPF clean out, leaks, final drive cover

REPAIRED: had DPF cleaned, replaced RT Final drive cover, changed final drive oil. replaced Engine oil level sensor.

PARTS: <u>Switch + seal</u>	<u>237.²⁵</u>	<u>Thompson</u>
<u>Filter clean</u>	<u>454.⁷⁵</u>	<u>Emission + Cooling Solutions</u>
<u>DPF cover</u>	<u>544.⁴⁶</u>	<u>Thompson</u>
<u>DPF clamps</u>	<u>324.³⁸</u>	<u>Thompson</u>

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
QUIP. #	0505	HOURS	DAYS	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE	Cat	REASON		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL	336F	PARTS	LABOR	COMPONENT LOCATION	
SERIAL #		OTHER		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER	11K HRS			OTHER	
MILES					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE: 8-10-23 DATE COMPLETED: 8-15-23	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC: Anthony	
SMOKES SHORTED VIBRATE OTHER				JOB NAME/LOCATION: High Park	
PROBLEM: Service				JOB NUMBER	
REPAIRED: Serviced					
PARTS: All Filters 683. 65 Thompson					

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0505</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>336F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE <u>1-12-24</u> DATE COMPLETED <u>1-30-24</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Ali</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>SPARTA PK</u>	JOB NUMBER
PROBLEM: <u>needs tracks</u>				
REPAIRED: <u>replaced rails, pads & sprockets</u>				
PARTS: <u>Tracks & sprockets + bolts 17,175.09</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0505</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>336F</u>	PARTS _____ LABOR _____	COMPONENT LOCATION		
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER <u>11,500 HRS</u>		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE <u>5-24-24</u>	DATE COMPLETED <u>6-6-24</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Anthony</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>41st Ave</u>	JOB NUMBER	
PROBLEM: <u>Service</u>				
REPAIRED: <u>Serviced</u>				
PARTS: <u>F. Hies</u> <u>670, 21</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0505</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>336F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>6-26-24</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Whiter creek PK.</u>	JOB NUMBER _____
PROBLEM: <u>check engine fault.</u>				
REPAIRED: <u>changed nox sensors</u>				
PARTS: <u>64A sensor</u> <u>2312.59</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0505</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>Cat</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>336F</u>	PARTS _____ LABOR _____	COMPONENT LOCATION		
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: <u>F-5-24</u> DATE COMPLETED _____		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Bryan</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Windland East</u>	JOB NUMBER _____	
PROBLEM: <u>bad det tank valve</u>				
REPAIRED: _____				
PARTS: <u>valve</u> <u>297.4</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0505</u>	HOURS _____ DAYS _____	REASON	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>			POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>336F</u>			COMPONENT LOCATION	
SERIAL # _____	PARTS _____ LABOR _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____	OTHER _____	OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>11-6-24</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Bryan</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Santa PK</u>	JOB NUMBER _____
PROBLEM: <u>clogged fuel filter code.</u>				
REPAIRED: <u>replaced fuel filter base & sensors</u>				
<u>light out.</u>				
PARTS: <u>2-sensors + filters 630.⁴¹</u> <u>Thompson</u>				
<u>manifold & sensor 1,280.³²</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT DOWNTIME		EQUIPMENT INFORMATION	
HOURS		EQUIP. # 0501	
REASON		MAKE Cat	
PARTS		MODEL 336F	
LABOR		SERIAL #	
OTHER		HOUR METER	
FRONT REAR LEFT RIGHT UPPER LOWER		MILES	
COMPONENT CODES		REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	
BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		SMOKES SHORTED VIBRATE OTHER	
COMPONENT LOCATION		DATE 2-12-28	
OTHER		MECHANIC Ben	
DATE COMPLETED 3-13-25		JOB NAME/LOCATION 10 Shop	
JOB NUMBER			

PROBLEM: Radiator leaking.

REPAIRED: removed radiator, had repaired. Replaced old coolant hoses.

PARTS: Hose & thermostat 298.⁰⁰ Thompson
 Radiator Repair 250.⁰⁰ Thompson
 Tank hoses 180.⁶³ Thompson
 Emitters & Sealing Thompson

IEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
QUIP. # <u>0505</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>Cat</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>336F</u>	REASON _____	COMPONENT LOCATION		
SERIAL # _____	PARTS _____ LABOR _____	FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER <u>12,000 HRS</u>	OTHER _____	OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: <u>5-29-25</u>	DATE COMPLETED <u>6-18-25</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Bryan & Ben</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Wilson Judicial</u>	JOB NUMBER _____	
PROBLEM: <u>Service</u>				
REPAIRED: <u>Serviced</u>				
PARTS: <u>Filters in stock</u>				