

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0110</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>MAK</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>07' CU P13</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # <u>Dump Truck</u>		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____				DATE: _____ DATE COMPLETED <u>2-24-22</u> MECHANIC <u>All</u>	
				JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____	
PROBLEM: <u>Tarp Torn & rod broken</u>					
REPAIRED: <u>replaced tarp and repaired tarp rod system.</u>					
PARTS: <u>Tarp</u> <u>110.13</u> <u>Truck Pro</u> <u>Tarp rod weld</u> <u>Protech Tool</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0110</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Mack</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>07 CU-713</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES <u>405,800 mi</u>					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE <u>3-14-22</u> DATE COMPLETED <u>3-15-22</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>All</u>		
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____		
PROBLEM: <u>Service</u>					
REPAIRED: <u>Serviced</u>					
PARTS <u>All Filters but Air 117.93</u> <u>Tenn Filter sales</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0110</u>	HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____		
MAKE <u>Mack</u>				
MODEL <u>67 CU-713</u>				
SERIAL # _____				
HOUR METER _____				
MILES <u>410K mi.</u>				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>4-7-22</u> DATE COMPLETED <u>4-13-22</u> MECHANIC _____ JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____		
PROBLEM: <u>Service</u>				
REPAIRED: <u>Serviced</u>				
PARTS: <u>All but air filter</u> <u>99.00</u> <u>Tenn. Filter</u> <u>4 Americas P5000</u> <u>\$1766.00</u> <u>Gate way</u> <u>Fuel Tank</u> <u>658.50</u> <u>Howby, used parts</u>				

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0110</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Mack</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>09 CO-713</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: _____ DATE COMPLETED <u>5-18-22</u>	MECHANIC <u>Ben</u>	
PROBLEM: <u>bottom radiator hose leaking</u>	JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____	
REPAIRED: <u>replaced both hose on bottom tube</u>			
PARTS:			
<u>90° hose</u>	<u>96.⁸⁰</u>	<u>McMahon Trucks</u>	
<u>hose & clamps</u>	<u>59.⁴⁰</u>	<u>Napa</u>	
<u>A/C hoses</u>	<u>203.⁵³</u>	<u>IRTG</u>	
<u>A/c hose</u>	<u>82.³⁶</u>	<u>Nashville Rubber & Gasket</u>	
<u>Thermostat</u>	<u>41.³⁹</u>	<u>McMahon Trucks</u>	
<u>All Filters</u>	<u>216.²⁹</u>	<u>Tenn Filter</u>	
<u>A/C hose</u>	<u>175.²³</u>	<u>McMahon Trucks</u>	

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0110</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Mack</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>07' CU'713</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE <u>6-22-22</u> DATE COMPLETED <u>6-23-22</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>All</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>A/C system Quits working</u>				
REPAIRED: <u>replaced Evaporator, Drier, expansion valve & have Filled system</u>				
PARTS: <u>Expansion valve 31.⁵¹ Mc Mahon Trucks</u>				
<u>Drier 68.¹³ Fleet Pride</u>				
<u>Evaporator 242.⁸⁸ Mc Mahon Trucks</u>				
<u>hose 63.⁷⁵ Samples Repair</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0110</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Mack</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>07' CU713</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: <u>7-15-22</u>	DATE COMPLETED <u>7-16-22</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>All</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____	
PROBLEM: <u>Front tandem needs brakes</u>				
<u>2 Tires</u>				
REPAIRED: <u>replaced shoes & drums on center axle</u>				
<u>replaced 2 rear tires</u>				
PARTS: <u>2 brakes & Drums 598.97 Fleet Pride</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0110</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Mack</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>07' CU713</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES <u>420K mi</u>				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>8-4-22</u> DATE COMPLETED <u>8-13-22</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>All</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>Service</u>				
REPAIRED: <u>Serviced</u>				
PARTS: <u>All Filters</u> <u>203.21</u> <u>Ten Filter sales</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0110
 MAKE Mack
 MODEL 07 CU713
 SERIAL # _____
 HOUR METER _____
 MILES 430k mi

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
 REASON _____
 PARTS _____ LABOR _____
 OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
 POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER
 OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
 OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
 SMOKES SHORTED VIBRATE OTHER _____

DATE: 9-22-22 DATE COMPLETED 10-31-22
 MECHANIC ALL

JOB NAME/LOCATION

JOB NUMBER

Shop

PROBLEM: Service

REPAIRED: Serviced

PARTS:

All Filters

218.00

Ten Filter sales

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0110</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Mack</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>09' CV-713</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE <u>5-18-21</u> DATE COMPLETED <u>5-21-21</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>ALL</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>Tag axle brakes problem</u>				
<u>needs tarp</u>				
REPAIRED: <u>replaced tag axle brakes</u>				
<u>replaced tarp Mac washed</u>				
PARTS: <u>shoes kit</u> <u>60.00</u> <u>NAPA</u>				
<u>shoes kit bearing seal</u> <u>275.11</u> <u>Truck Pro</u>				
<u>Tarp</u> <u>Truck Pro</u>				
<u>Fan belt</u> <u>77.93</u> <u>M-Mahon Trucks</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>0110</u> MAKE <u>Mack</u> MODEL <u>07 CU-713</u> SERIAL # _____ HOUR METER _____ MILES <u>375K mi</u>	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>6-11-21</u> DATE COMPLETED <u>6-19-21</u> MECHANIC <u>All</u> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 70%;">JOB NAME/LOCATION <u>Shop</u></td> <td style="width: 30%;">JOB NUMBER</td> </tr> </table>	JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER			
PROBLEM: <u>Service</u> _____ _____				
REPAIRED: <u>Service</u> _____ _____ _____ _____ _____ _____				
PARTS: <u>All Filters</u> <u>181.01</u> <u>Tenn Filter</u> _____ _____ _____ _____				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0110</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Mack</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>07 C0713</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>7-8-21</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>All</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____		
PROBLEM: <u>Two rear Tires</u>				
REPAIRED: <u>replaced two rear tires</u>				
PARTS: <u>2-11R-24.5</u> <u>1080.68</u> <u>Gateway</u>				
<u>Sumitomo</u>				
<u>2-New Rims 24.5 49 EA</u> <u>Truck Pro</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0110</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Mack</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>01 CV-713</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES <u>38015 mi</u>				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED _____	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Ben & James</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>service</u>				
REPAIRED: <u>service</u>				
PARTS: <u>All filters</u> <u>194.40</u> <u>Term Filter</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0110</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Mack</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>07 CU-713</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES <u>385K mi</u>					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____				DATE: <u>8-6-21</u> DATE COMPLETED <u>8-25-21</u>	
				MECHANIC <u>ALL</u>	
				JOB NAME/LOCATION <u>Shop</u>	
				JOB NUMBER _____	
PROBLEM: <u>by pass oil filter housing leaking</u>					
REPAIRED: <u>replaced oil filter by-pass housing serviced.</u>					
<u>front & rear axle brakes & rear slack adjusters</u>					
PARTS: <u>Housing \$118.54</u> <u>McMahon Trucks</u>					
<u>Track bar</u> <u>McMahon Trucks</u>					
<u>2 steel tires 375/60-22.5 1363.⁰⁰</u> <u>Freeman Tire</u>					
<u>2 rear tires 11R-24.5 1000.⁶⁰</u> <u>Gateway</u>					
<u>All Filters 191.⁵⁹</u> <u>Tenn Billa Sales</u>					
<u>Brakes, Drums & Adjusters 1,788.⁰⁰</u> <u>Fleet Pride</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0110</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Mack</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>07' CU 713</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE: <u>9-14-21</u> DATE COMPLETED <u>9-15-21</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____	
PROBLEM: <u>Power steering hoses leaking</u>					
REPAIRED: <u>replaced all hoses and cruise filter</u>					
PARTS: <u>All Hoses</u> <u>351.29</u>					
<u>Filter</u> <u>19.76</u> <u>Turn Filter</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0110</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Mack</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>07 CU713</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES <u>390K mi</u>				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE <u>10-18-21</u> DATE COMPLETED <u>10-25-21</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>All</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Shop</u>		JOB NUMBER _____
PROBLEM: <u>Tarp rod bearing service</u>				
REPAIRED: <u>replaced bearing + serviced</u>				
PARTS: <u>bearing</u> <u>73.58</u> <u>Motion Industries</u>				
<u>All filters</u> <u>194.40</u> <u>Tenn Filter Jakes</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0110</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Mack</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>CU 713</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE <u>12-2-21</u> DATE COMPLETED <u>12-4-21</u> MECHANIC <u>Ben</u>	
			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>Service</u>				
REPAIRED: <u>Serviced</u>				
PARTS: <u>All Filters</u> <u>194.40</u> 194.40 <u>Term Filter</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0110</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Mack</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>07' CU 713</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>12-8-21</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Mark</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Shops</u>	JOB NUMBER _____	
PROBLEM: <u>needs window cranks</u>				
REPAIRED: <u>replaced cranks</u>				
PARTS: <u>2 cranks</u> <u>92.73</u> <u>McMahon Trucks</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0110</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Mack</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>07' CU713</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>12-10-21</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>ALL</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>needs Tires</u>				
REPAIRED: <u>replaced one rear tire</u>				
PARTS: <u>2 Lancaster</u> <u>556.28</u> <u>Gateways Tire</u>				
<u>11R-24.5</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0110</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Mack</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>07' CU713</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>1-20-22</u> MECHANIC <u>All</u>		
PROBLEM: <u>blown Tire</u>		JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____		
REPAIRED: <u>replaced Tire</u>				
PARTS: <u>3-General 11R-24.5 1623.89</u> <u>Swide Fleet solutions</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>0110</u> MAKE <u>Mack</u> MODEL <u>07' C0713</u> SERIAL # <u>Dump Truck</u> HOUR METER _____ MILES <u>400K mi</u>	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>1-11-22</u> DATE COMPLETED <u>2-3-22</u> MECHANIC <u>All</u> JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____
PROBLEM: <u>Service</u> _____ _____		
REPAIRED: <u>serviced</u> _____ _____ _____ _____ _____ _____		
PARTS: <u>All Filters</u> <u>205.82</u> <u>Tenn Filter sales</u> _____ _____ _____		

TEC

THORNE'S EXCAVATING COMPANY, LLC SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0110</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Mack</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>07' CU713</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES <u>400,500 mi</u>				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>2-8-22</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Ben</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>McHARRY</u> JOB NUMBER _____		
PROBLEM: <u>w/pump Tens. pulley locked up. broke belt</u>				
REPAIRED: <u>replaced w/pump belt and tensioner.</u>				
PARTS: <u>2-belts - tensioner 35-2.13</u> <u>McMahon Trucks</u>				
<u>Fan belt 20870671</u>				
<u>w/pump belt 20870833</u>				
<u>w/pump belt Tens. 25195022</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0110</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Mack</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>CU 713</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # <u>Dump Truck</u>		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>2-14-22</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Mark</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>both fuel caps leaking</u>				
REPAIRED: <u>replaced caps</u>				
PARTS: <u>2 - caps</u> <u>165.00</u> <u>McMahon Trucks</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0110</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Mack</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>07 CU-713</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>5-31-24</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Bryan</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Thorp</u>	JOB NUMBER _____
PROBLEM: <u>Bad batteries</u>				
REPAIRED: <u>replaced batteries</u>				
PARTS: <u>3-31-MHD</u> <u>460.79</u> <u>Interstate Battery</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0110</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Mack</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>07' CV213</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE <u>8-30-24</u> DATE COMPLETED <u>9-17-24</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Ali</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>shop</u>	JOB NUMBER _____
PROBLEM: <u>RT Trunion nut backed off.</u>				
REPAIRED: <u>replaced nut & cap</u>				
PARTS: <u>nut cap & bolts 199.71 Mc Mahon Trucks</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0110</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Mack</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>07' GU713</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: <u>4-14-25</u> DATE COMPLETED <u>4-18-25</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>All</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____		
PROBLEM: <u>needs rear brakes & Tag Axle chamber</u>				
REPAIRED: <u>replaced RT tag axle brake chamber. Straightened bracket.</u>				
<u>replaced shoes and drums on both rear axles.</u>				
PARTS: <u>brake chamber</u>				
<u>4-shoe sets</u> <u>856.00</u> <u>Fleetpride</u>				