

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>0023</u> MAKE <u>RAM</u> MODEL <u>17' 1500 4x4</u> SERIAL # _____ HOUR METER _____ MILES <u>new</u>	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____															
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>7-5-17</u> DATE COMPLETED <u>7-28-17</u> MECHANIC <u>All</u> <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:50%;">JOB NAME/LOCATION <u>Steps</u></td> <td style="width:50%;">JOB NUMBER</td> </tr> </table>	JOB NAME/LOCATION <u>Steps</u>	JOB NUMBER													
JOB NAME/LOCATION <u>Steps</u>	JOB NUMBER																
PROBLEM: <u>set up Truck</u>																	
REPAIRED: <u>Installed power converter + steps</u>																	
<table style="width:100%;"> <tr> <td style="width:30%;">PARTS: <u>Floor mats</u></td> <td style="width:20%; text-align: right;"><u>\$60.⁰⁰</u></td> <td style="width:50%;"></td> </tr> <tr> <td><u>Power Inverter</u></td> <td style="text-align: right;"><u>\$174.⁷⁹</u></td> <td><u>NAPA</u></td> </tr> <tr> <td><u>Cable</u></td> <td style="text-align: right;"><u>64.⁰⁰</u></td> <td><u>Advance Auto Parts</u></td> </tr> <tr> <td><u>oval steps</u></td> <td style="text-align: right;"><u>\$274.⁰⁰</u></td> <td><u>Auto zone</u></td> </tr> <tr> <td></td> <td></td> <td><u>Chuck's Truck Ace.</u></td> </tr> </table>			PARTS: <u>Floor mats</u>	<u>\$60.⁰⁰</u>		<u>Power Inverter</u>	<u>\$174.⁷⁹</u>	<u>NAPA</u>	<u>Cable</u>	<u>64.⁰⁰</u>	<u>Advance Auto Parts</u>	<u>oval steps</u>	<u>\$274.⁰⁰</u>	<u>Auto zone</u>			<u>Chuck's Truck Ace.</u>
PARTS: <u>Floor mats</u>	<u>\$60.⁰⁰</u>																
<u>Power Inverter</u>	<u>\$174.⁷⁹</u>	<u>NAPA</u>															
<u>Cable</u>	<u>64.⁰⁰</u>	<u>Advance Auto Parts</u>															
<u>oval steps</u>	<u>\$274.⁰⁰</u>	<u>Auto zone</u>															
		<u>Chuck's Truck Ace.</u>															

TEC

THORNE'S EXCAVATING COMPANY, LLC SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0011</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ram</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>17' 1500</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # <u>Jash</u>		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE: _____ DATE COMPLETED <u>9-21-21</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC <u>Calcb</u>	
SMOKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION <u>Vintage Edge</u> JOB NUMBER _____	
PROBLEM: <u>bad battery</u>					
REPAIRED: <u>replaced bad battery</u>					
<u>9-22-21 4 new 10pl tires</u>					
PARTS: <u>94RH7RP 181.63</u> <u>Advance</u>					
<u>265/70-17 Transforce 1050.53</u> <u>Charles Tire</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0011</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ram</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>17' 1500</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # <u>Josh</u>		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE <u>1-20-23</u> DATE COMPLETED <u>1-21-23</u> MECHANIC <u>Josh</u>		
PROBLEM: <u>Driver door switch bad</u>		JOB NAME/LOCATION <u>Limestone Trail</u> JOB NUMBER _____		
REPAIRED: <u>replaced switch</u>				
PARTS: <u>door switch</u> \$ <u>166.93</u> <u>M^r Juliet Ram</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0011</u>		HOURS _____ DAYS _____		BASIC MACHINE	HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Ram</u>		REASON _____		POWER TRAIN	ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>17' 1500</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____				DATE: <u>8-2-23</u> DATE COMPLETED <u>9-30-23</u>	
				MECHANIC <u>Bryan</u>	
PROBLEM: <u>Exhaust leak RT side</u>				JOB NAME/LOCATION: <u>To shop</u> JOB NUMBER _____	

REPAIRED: replaced at exhaust manifold gasket & bolts.
removed broken bolts

PARTS: <u>Manifold kit</u>	<u>108.⁰⁵</u>	<u>Advance</u>
<u>Hardware</u>	<u>139.¹¹</u>	<u>Advance</u>

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0011</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ram</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>17' 1500</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES <u>80k mi</u>				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>11-27-23</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>AVI</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION	JOB NUMBER
PROBLEM: <u>bad power inverter</u>			<u>Shop</u>	
REPAIRED: <u>replaced inverter</u>				
<u>serviced</u>				
PARTS: <u>Traxite 2k/4k</u> <u>142.66</u> <u>Harbor Freight</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0011</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ran</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>12' 1500</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # <u>Josh</u>		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES <u>83k mi</u>				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE <u>2-27-24</u> DATE COMPLETED <u>2-27-24</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Anthony</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>brake shake</u>				
REPAIRED: <u>replaced front rotors, front & rear pads</u>				
PARTS: <u>rotors & pads</u> <u>278.19</u> <u>Alumac</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0011</u>	HOURS _____ DAYS _____ REASON PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>Ram</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>17' 4x4</u>		COMPONENT LOCATION		
SERIAL # <u>Josh</u>		FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE <u>8-6-24</u>	DATE COMPLETED <u>8-6-24</u>	
		MECHANIC <u>Bryan</u>		
		JOB NAME/LOCATION <u>Quail Run</u>	JOB NUMBER _____	
PROBLEM: <u>bad battery</u>				
REPAIRED: <u>replaced battery</u>				
PARTS: <u>167 AGM</u> <u>230.62</u> <u>Advance</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		REASON		PARTS		LABOR		OTHER	
EQUIP. # 0011		HOURS		DAYS		REASON		PARTS		LABOR	
MAKE Ravn		MODEL 17' 150		SERIAL # James		HOUR METER		MILES		OTHER	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		SMOKES SHORTED VIBRATE OTHER		DATE: 3-10-25		MECHANIC: Bryan		JOB NAME/LOCATION: Shop & farm	
DATE COMPLETED: 4-2-25		JOB NUMBER		PROBLEM: Driver seat belt latch		REPAIRED: Replaced latch.		PARTS: latch		98.32	
COMPONENT CODES		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		COMPONENT LOCATION		FRONT REAR LEFT RIGHT UPPER LOWER		OTHER	