

EQUIPMENT
REPAIRS

DATE 5-13-08

MILEAGE/HOURS 317,605

EQUIPMENT REPAIRED #18 Mack fuel truck

REPAIRS MADE Serviced
rotate grease reels

HOURS WORKED _____

PARTS USED

Filters	\$62.23	O'Reilly
Filters Fuel	57.95	NAPA

EQUIPMENT
REPAIRS

DATE 6-10-08

MILEAGE/HOURS _____

EQUIPMENT REPAIRED #18 Mack Fuel

REPAIRS MADE replaced hose from fuel
pump filter to reel.

HOURS WORKED _____

PARTS USED

28' x 1" Fuel hose \$155.00 Crooks

EQUIPMENT
REPAIRS

DATE 8-18-08

MILEAGE/HOURS _____

EQUIPMENT REPAIRED #18

REPAIRS MADE Fire Extinguisher

HOURS WORKED _____

PARTS USED

Extinguisher @ 40.⁰⁰ ACME Fire

EQUIPMENT
REPAIRS

DATE 9-25-08

MILEAGE/HOURS _____

EQUIPMENT REPAIRED #18 Mack Fuel Truck

REPAIRS MADE Rebuilt fuel pump Graco Husky
1040

HOURS WORKED _____

PARTS USED

Pump kits \$48.40
118.50

Williams lube

EQUIPMENT
REPAIRS

DATE 9-29-08

MILEAGE/HOURS _____

EQUIPMENT REPAIRED #18 Mack

REPAIRS MADE Had pick up tube rethreaded
for fuel tank

HOURS WORKED _____

PARTS USED

rethread

\$3.25

LDC

EQUIPMENT
REPAIRS

DATE 10-16-08

MILEAGE/HOURS 319,600 mi

EQUIPMENT REPAIRED #18 Mack Fuel Truck

REPAIRS MADE replaced both steer tires

HOURS WORKED _____

PARTS USED

2-Tires

262, 25 EA

Woodard

EQUIPMENT
REPAIRS

DATE 1-6-09

MILEAGE/HOURS _____


EQUIPMENT REPAIRED #18 #15

REPAIRS MADE couplers for Air pumps

HOURS WORKED _____


PARTS USED

Male Coupler	5.14 EA	
Female Coupler	12.41 EA	\$53.86 Total
Male Nipple Steel	7.10 EA	IR-G




THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>18</u>	REASON PARTS LABOR OTHER _____	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Mack</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>1996</u>		COMPONENT LOCATION		
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____		OTHER _____		
MILES <u>322,000</u>			OTHER _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>4-6-09</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>JAMES & DANIEL</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>service + check over</u>				
<u>bad right rear brake chamber</u>				
REPAIRED: <u>serviced greasel</u>				
<u>replaced bad right rear brake chamber</u>				
<u>adjusted brakes</u>				
PARTS: <u>Oil filter, fuel, water filter in stock</u>				
<u>w/seperator filter - \$58.98 O'Reilly</u>				



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>18</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Mack</u>		REASON		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>95'</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # <u>057953</u>		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES <u>322K</u>					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE: _____ DATE COMPLETED <u>4-14-09</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC <u>James & Daniel</u>	
SMOKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____	
PROBLEM: _____					
REPAIRED: <u>replaced brake chamber in stock</u>					
PARTS: <u>Brake chamber</u> <u>32.61</u> <u>Truck Pro</u>					




THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>18</u>	HOURS _____ DAYS _____	BASIC MACHINE	HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Mack</u>	REASON	POWER TRAIN	ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>CH613</u>	PARTS LABOR	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES <u>322k</u>			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>4-24-09</u>	
		MECHANIC <u>JAMES & DANIEL</u>	
		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>w/pump leaking</u> <u>fan won't come on,</u> <u>Temp gauge bad.</u>			
REPAIRED: <u>replaced water pump</u> <u>Temp switch fan bad in on 4-27-09</u> <u>Temp gauge replaced</u>			
PARTS:			
<u>Temp Gauge</u> <u>69.63</u>		<u>Mack of Nashville</u>	
<u>FAN switch</u> <u>103.50</u>		<u>Mack of Nashville</u>	
<u>w/pump</u> <u>150.00</u>		<u>Truck Pro</u>	



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>18</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>MAK</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>96 Fuel Truck</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES <u>323,500</u>				
REASON FOR FAILURE: BROKEN <u>WORN</u> ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>7-16-09</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>JAMES & DANIEL</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>Tires</u>				
REPAIRED: <u>replaced both tires on left rear tandem</u>				
PARTS: <u>Wanlee 11R-225 \$280.00 EA charlies Tire</u>				



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>18</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Mack</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>1996 CH613</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: <u>8-4-09</u> DATE COMPLETED _____	
			MECHANIC <u>Daniel R James</u>	
			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>no park brake light, Engine speed control switch bad</u>				
REPAIRED: <u>replaced park brake light switch</u> <u>ordered engine speed control switch</u>				
PARTS: <u>press switch in stock</u> <u>speed switch 36.50</u> <u>Mack of Nashville</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>18</u>	HOURS _____ DAYS _____ REASON PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>Mack</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>CH613</u>		COMPONENT LOCATION		
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____		OTHER _____		
MILES <u>324,344 mi</u>				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____	DATE COMPLETED <u>10-14-09</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>JAMES & DANIEL</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER	
PROBLEM: <u>Tires worn out RT rear</u>				
REPAIRED: <u>Made wand for oil recovery</u>				
<u>replaced both tires on rt rear tandem</u>				
<u>replaced clutch arm spring, built up bracket</u>				
<u>for spring.</u>				
PARTS: <u>Spring</u> <u>5.00</u> <u>Tractor Supply</u>				
<u>2-11R 22.5 Wanh 53073</u> <u>Charlie's Tire</u>				
<u>#558.79</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>18</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Mack</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>Intl Truck</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>12-9-09</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>JAMES</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>Oil hose broken (rot out)</u> <u>on oil recovery reel.</u>				
REPAIRED: <u>replaced hose</u>				
PARTS: <u>Oil recovery hose 35'</u> <u>Wash. Rubber Gasket</u>				



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>18</u>		HOURS _____ DAYS _____		BASIC MACHINE	HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Mack</u>		REASON		POWER TRAIN	ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>Fuel Truck</u>		PARTS	LABOR	COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT	REAR LEFT RIGHT UPPER LOWER
HOUR METER _____				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE: _____ DATE COMPLETED <u>5-14-10</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC _____	
SMOKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION	JOB NUMBER
PROBLEM: <u>blown Hase</u>					
REPAIRED: <u>replace hose on Trans, 30w reel</u>					
PARTS: <u>hose</u> <u>187.89</u> <u>NAPA</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>18</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Mack</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>96'</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # <u>Fuel truck</u>		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: _____ DATE COMPLETED <u>8-9-13</u> MECHANIC <u>James</u> JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____	
PROBLEM: <u>needs batteries</u>				
REPAIRED: <u>replaced all three batteries</u>				
PARTS: <u>3900 31 studs 327.74 Advance Auto Parts</u>				

EQUIPMENT
REPAIRS

DATE 8-18-15

MILEAGE/HOURS 215 K

EQUIPMENT REPAIRED #16 03' TACOMA James

REPAIRS MADE Serviced

HOURS WORKED _____

PARTS USED

Oil Filter 4. ²⁵⁰ Tenn. Filter Sales

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>18</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Mack</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>96' Fuel Truck</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE: _____ DATE COMPLETED _____
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC <u>JAMES B. BRIAN</u>
SMOKES SHORTED VIBRATE OTHER _____	JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____

PROBLEM: check over

REPAIRED: Al's Tire shop replaced all 10 tires
replaced off road fuel hoses from pump to reel
replaced waste oil suction hose

PARTS: <u>10 - 10yo tires</u>	<u>3500.00</u>	<u>Gateway Tire</u>
<u>All Filters</u>	<u>225.00</u>	<u>Ten Filter</u>
<u>10 - Tire mounts</u>	<u>273.00</u>	
<u>hoses</u>		
<u>oil hose</u>	<u>34.44</u>	<u>Mack & Nashville</u>

Reds & blades 173.36 NAPA
hose 34.44 Mack & Nashville
hoses 643.46 Nashville Rubber & Gasket

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>18</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Mack</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>96' CH613</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: _____ DATE COMPLETED <u>8-18-16</u> MECHANIC <u>Charles</u>
JOB NAME/LOCATION <u>Shop</u>	
JOB NUMBER _____	

PROBLEM: check over

REPAIRED: replaced switch at Drier

replaced balance pulley

replaced fan belts

Pulley	70. ⁹⁵	Mack
Switch	71. ⁰⁴	Mack
belt set	84. ⁹⁷	Napa
Fuel Filters	48. ⁷⁰	Napa

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>28</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Mack</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>CH613</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # <u>Fuel Truck</u>		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>1-13-17</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>JAMES</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>15W40 metering handle broken</u>				
REPAIRED: <u>replaced handle</u>				
PARTS: <u>15/40 metering handle</u> <u>426 06</u> <u>NAPA</u>				
<u>part # 715-1667</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>103</u>	HOURS _____ DAYS _____ REASON PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>MAK</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>96' CH613</u>		COMPONENT LOCATION		
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>5-8-17</u>	DATE COMPLETED: <u>5-11-18</u>	
		MECHANIC _____		
		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER	
PROBLEM: <u>no odometer</u>				
REPAIRED: <u>replaced speedometer</u>				
PARTS: <u>speedometer</u> <u>419.44</u> <u>McMahon Mack</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0103</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Mack</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>96'</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # <u>Fuel Truck</u>		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>5-9-18</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>James & All</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>low Pump Quit</u>				
REPAIRED: <u>repaired pump</u>				
PARTS: <u>pump parts</u> <u>125% 96'</u> <u>Parman Equipment</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0103</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Mack</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>96' CH613</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # <u>Fuel Truck</u>		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE: <u>9-6-18</u> DATE COMPLETED _____	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC <u>Charles, James & Tony</u>	
SMOKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____	
PROBLEM: <u>needs seat belt & steering box</u>					
<u>needs turn signal switch</u>					
REPAIRED: <u>replaced seat belt & steering box</u>					
PARTS: <u>seat belt</u> <u>210.⁰⁰</u> <u>Mack of Nashville</u>					
<u>steering box</u> <u>655.⁴⁹</u> <u>Truck Pro</u>					
<u>turn signal lever</u> <u>92.³⁹</u> <u>Mack</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0103</u>	REASON PARTS LABOR OTHER _____	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Mack</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>96' CAG13</u>		COMPONENT LOCATION		
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>1-31-2020</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Charles</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>15W40 pump halt sticking</u>				
REPAIRED: <u>rebuilt top of pump</u>				
PARTS: <u>motor kit</u> <u>143.26</u> <u>Parman Equipment</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0103</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Mack</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>96' CH613</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>2-2-21</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Ben & James</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>check over</u>				
REPAIRED: <u>Topped air off all Tires</u>				
<u>changed engine oil & fuel filters</u>				
PARTS: <u>oil & fuel filters</u> <u>64.14</u> <u>Napa</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0103</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Mack</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>Fuel Tank</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: _____ DATE COMPLETED <u>7-6-22</u> MECHANIC <u>All</u>	
			JOB NAME/LOCATION <u>shop</u>	JOB NUMBER
PROBLEM: _____				

REPAIRED: <u>New 10W Fuel pump</u>				

PARTS <u>813-5163 Pump 12P9.96 Napa</u>				
<u>Pump</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>Big fuel truck</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>Mack</u>	REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>96' CH613</u>	☒ PARTS LABOR	COMPONENT LOCATION		
SERIAL # _____	OTHER _____	FRONT ☒ REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____		OTHER <u>Hose Reel</u>		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: <u>11-06-23</u> DATE COMPLETED <u>11-7-23</u>		
OVERHEAT PLANNED CONTAM <u>LEAKING</u> NOISY SCRATCH		MECHANIC <u>James</u> <u>James</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION	JOB NUMBER	
PROBLEM: <u>Leaking Hose on Reel, ON Big fuel truck Hose Reel</u>				
<u>ON (30 W)</u>				
REPAIRED: <u>new Hose for 30 W Reel</u>				
PARTS: <u>HHC G25100 - 0808 x 2 (fittings) - \$28.34</u>				
<u>HHC 70283 - \$383.46 (Hose)</u>				