

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>10</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Dodge</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>12' 5500 4x4</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES <u>65K mi</u>				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE <u>6-1-17</u> DATE COMPLETED _____	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>ALL</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION	JOB NUMBER
			<u>Shop</u>	
PROBLEM: <u>check over, headlights wet, bed bolts missing, need trailer connector, Gooseneck ball needs replaced, cab guard needs repaired.</u>				
REPAIRED: <u>Serviced, replaced fuel filter housing cap, Installed six wire trailer connector, Dried out headlamps</u>				
<u>Premier Dodge</u>				
<u>Took to Nashville Dodge for transfer case repair.</u>				
<u>Installed safety light switch</u>				
<u>Cab Paint</u>	<u>6101.⁰⁰</u>	<u>Anchor Fleet body Shop</u>		
<u>Primer</u>	<u>30.⁵⁸</u>	<u>Advance</u>		
<u>bed paint</u>	<u>124.⁴⁰</u>	<u>Carquest.</u>		
PARTS: <u>rim</u>	<u>157.⁶⁸</u>	<u>Truck Pro</u>		
<u>Service Supplies</u>	<u>385.⁰⁰</u>	<u>Premier dodge</u>		
<u>Spare key</u>	<u>65.⁰⁰</u>	<u>Harrison's locksmith</u>		
<u>Floor mats</u>	<u>51.⁰⁰</u>	<u>Napa</u>		
<u>Top mount safety light</u>		<u>In stock</u>		

6-Sumitomo
4" oval steps

1595.¹⁰
323.⁰⁰

Gateway Tire
Chuck's Truck

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>0010</u> MAKE <u>Rsm</u> MODEL <u>5500 4x4</u> SERIAL # <u>Flatbed</u> HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____						
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>7-31-17</u> MECHANIC <u>Steven & Charles</u> <table style="width:100%; border: none;"> <tr> <td style="border: none; width: 70%;">JOB NAME/LOCATION <u>Shops</u></td> <td style="border: none; width: 30%;">JOB NUMBER</td> </tr> </table>	JOB NAME/LOCATION <u>Shops</u>	JOB NUMBER				
JOB NAME/LOCATION <u>Shops</u>	JOB NUMBER							
PROBLEM: _____ _____ _____								
REPAIRED: <u>Replaced bad headlamps & crankcase breather</u> _____ _____ _____ _____ _____								
<table style="width:100%; border: none;"> <tr> <td style="border: none; width: 40%;">PARTS: <u>2 - Headlamps</u></td> <td style="border: none; width: 20%; text-align: center;"><u>491.41</u></td> <td style="border: none; width: 40%; text-align: center;"><u>Premier Dodge</u></td> </tr> <tr> <td style="border: none;"><u>crank breather</u></td> <td style="border: none; text-align: center;"><u>130.00</u></td> <td style="border: none; text-align: center;"><u>Premier Dodge</u></td> </tr> </table>			PARTS: <u>2 - Headlamps</u>	<u>491.41</u>	<u>Premier Dodge</u>	<u>crank breather</u>	<u>130.00</u>	<u>Premier Dodge</u>
PARTS: <u>2 - Headlamps</u>	<u>491.41</u>	<u>Premier Dodge</u>						
<u>crank breather</u>	<u>130.00</u>	<u>Premier Dodge</u>						

Google

2016 ram 6.7l fan belt route



Sign in

All

Shopping

Images

Videos


News

More

Settings

Tools




SafeSearch



5.9L DIESEL

WARNING: DISCONNECT OF HIGH SPRING BREAK BUSH. DO NOT ATTEMPT TO DISASSEMBLE AUTOMATIC TENSIONER UNIT IS SERVICED AS AN ASSEMBLY.

1. Position drive belt (refer to 1 - CRANK PULLEY) - clockwise
2. Position tensioner mounting belt and remove tensioner



need assistance to change serpentine...

Diesel Truck Resource - 495 x 423 - Search by image


Name: drivebelt.jpg Views: 464 Size: 45.7 KB

Visit page







View image

Share

Related images:




images may be subject to copyright. - Get help - Send feedback



2006-2008 Dodge 2500 5.9L & 6.7L Diesel

BELT ROUTING



A/C

NO A/C

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>10</u>	HOURS _____ DAYS _____	REASON	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Dodge</u>			POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>12' 5500</u>	PARTS _____ LABOR _____	OTHER _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED _____	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC _____	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION	JOB NUMBER
PROBLEM: <u>Trailer controller</u>				
REPAIRED: <u>replaced trailer controller with after market</u>				
PARTS: <u>controller</u> <u>196.65</u> <u>The Trailer Depot</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963


EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>10</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ram</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>5500 12'</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>8-29-17</u> DATE COMPLETED <u>9-5-17</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>All</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shops</u>	JOB NUMBER
PROBLEM: <u>steering gear to much play</u>				
REPAIRED: <u>replaced steer gear, Had front end alignment.</u>				
PARTS: <u>steering gear 655.⁵⁰ Advance Auto Parts</u>				
<u>bolts 9.⁸³ Fastenal</u>				
<u>Alignment 120.⁰⁰ TCI</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>101</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ram</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>12' 5500</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>12-2-17</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Gateway</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>Front Tire</u>				
REPAIRED: <u>replaced front tires with straight tread</u>				
PARTS: <u>Front tires</u> <u>496.96</u> <u>Gateway</u>				



THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0101</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>RAM</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>12' 3500</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>8-29-18</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>James & Charles</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>belt noise</u>				
REPAIRED: <u>replaced belt</u>				
PARTS: <u>belt</u> <u>62.00</u> <u>NAPA</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>101</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ram</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>12' 5500</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES <u>90K mi</u>				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: _____ DATE COMPLETED <u>5-6-19</u> MECHANIC <u>Gateway</u>	
			JOB NAME/LOCATION <u>Gateway</u>	
			JOB NUMBER	
PROBLEM: <u>needs front tires</u>				
REPAIRED: <u>replaced front tires + balanced</u>				
PARTS: <u>225/70-17.5</u> <u>698.96</u> <u>Gateway tire</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0101</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>RAM</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>12' 5500</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES <u>94510</u>				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: _____ DATE COMPLETED <u>F-1-19</u> MECHANIC <u>Mark Faust</u>	
			JOB NAME/LOCATION <u>Premier Dodge</u>	JOB NUMBER
PROBLEM: _____ _____ _____				
REPAIRED: <u>Fixed recalls & Fuel & Engine lights</u> _____ _____ _____ _____ _____ _____				
PARTS <u>All repair</u> <u>2041.72</u> <u>Premier Dodge</u> _____ _____ _____ _____				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>0101</u> MAKE <u>Ram</u> MODEL <u>12' 5500</u> SERIAL # _____ HOUR METER _____ MILES <u>100,700 mi</u>	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE <u>10-4-19</u> DATE COMPLETED <u>10-10-19</u> MECHANIC <u>Bryan</u> <table style="width:100%;"> <tr> <td style="width:50%;">JOB NAME/LOCATION <u>Shop</u></td> <td style="width:50%;">JOB NUMBER</td> </tr> </table>	JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER			
PROBLEM: <u>check over + service</u>				
REPAIRED: <u>replaced radiator, fan clutch, main fan pulley and shroud.</u> <u>replaced steering shock.</u> <u>serviced</u>				
PARTS: <u>radiator</u> <u>Autocone</u> <u>cylinder</u> <u>50.24</u> <u>Napa</u> <u>radiator fan clutch belt</u> <u>845.16</u> <u>Advance</u> <u>pulley + shroud</u> <u>693 3/2</u> <u>Premier ram</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0101</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ram</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>1C' 5500 4x4</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES <u>105K mi</u>				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>1-15-2020</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>James & Bryan</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>Service , service 4WD</u>				
REPAIRED: <u>Serviced , replaced 4wd pos. sensor</u>				
PARTS: <u>Trans. case sensor 92.⁵⁰</u> <u>Premier Ram</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0101</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ram</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>12' 5500 414</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES <u>110k mi.</u>				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>3-23-2020</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Gateway Tire</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>needs rear tires</u>				
REPAIRED: <u>replaced rear tires</u>				
PARTS: <u>4-225/70-19.5 \$1,194.93</u> <u>Gateway Tire</u>				
<u>Sumitomo ST918</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0101</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ram</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>12' 5500 4x4</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # <u>Flat bed</u>		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>6-10-20</u> DATE COMPLETED <u>6-10-20</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC _____	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Gateway</u>	JOB NUMBER
PROBLEM: <u>needs front tires and alignment</u>				
REPAIRED: <u>replaced front tires</u>				
PARTS: <u>2.225/10-19.5 603.93 Gateway</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0101</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ram</u>		REASON		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>12' 5500</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES <u>118,900 mi</u>					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE: _____ DATE COMPLETED <u>8-4-21</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC <u>James</u>	
SMOKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION <u>Shops</u>	
				JOB NUMBER _____	
PROBLEM: <u>Front end loose</u>					
REPAIRED: <u>replaced Track bar & steer link</u>					
PARTS: <u>bar & link end</u> <u>1116.29</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0101</u>	MAKE <u>Ram</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MODEL <u>12' 5500</u>	SERIAL # _____	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
HOUR METER _____	MILES _____	PARTS _____ LABOR _____	COMPONENT LOCATION	
		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
			OTHER _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: <u>7-14-21</u> DATE COMPLETED <u>7-15-21</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Brian & James</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____		
PROBLEM: <u>Anti-Freeze leak</u>				
<u>4wd light on.</u>				
REPAIRED: <u>replaced bad water pump</u>				
<u>replaced belt and tensioner</u>				
<u>repaired pigtail at Transfer case actuator</u>				
PARTS: <u>water pump</u> <u>82.⁰⁹</u> <u>Advance</u>				
<u>pigtail</u> <u>35.⁴⁶</u> <u>Premier Ram</u>				
<u>belt</u> <u>77.¹⁵</u> <u>Napa</u>				
<u>belt tensioner</u> <u>117.²⁶</u> <u>Advance Auto Parts</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0101</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ram</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>12' 5500</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # <u>Flat bed.</u>		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES <u>120K mi</u>				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE <u>10-25-21</u> DATE COMPLETED <u>11-1-21</u> MECHANIC <u>Bam Bam</u>	
			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>Exhaust leak at manifold</u>				
REPAIRED: <u>replaced Exhaust manifold</u> <u>replaced Engine crankcase breather</u>				
PARTS: <u>manifold, gaskets + shield 1934.63 Premier Ram</u> <u>studs + nuts</u>				
<u>Gasket + studs 96.00 Premier Ram</u> <u>breather 175.60</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0101</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ram</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>12' 5500</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES <u>94,500 mi</u>				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>7-22-19</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Bryan & Matt</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>hard to stop</u>				
REPAIRED: <u>replaced front & rear pads</u>				
PARTS: <u>front & rear pads 128.20</u> <u>Advance</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0101</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ram</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>12' 5500</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES <u>128,331 mi</u>					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____				DATE: _____ DATE COMPLETED <u>7-18-22</u>	
MECHANIC <u>Premier Ram</u>				JOB NUMBER _____	
PROBLEM: <u>Ign. switch</u>				JOB NAME/LOCATION <u>Premier Ram</u>	
REPAIRED: <u>replaced ign. switch + program</u>					
PARTS: <u>Ign switch & program</u> <u>740.37</u> <u>Premier Ram</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0101</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ram</u>		REASON		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>12' 5500</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES <u>129,200 mi</u>					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE: <u>8-23-22</u> DATE COMPLETED <u>8-23-22</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC <u>Brian</u>	
SMOKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION <u>Shop</u>	
PROBLEM: <u>Front hub bearings bad</u>				JOB NUMBER _____	
REPAIRED: <u>replaced both front hub bearings</u>					
PARTS: <u>2. Hub bearings 653.50 Advance</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0101

MAKE Rsm

MODEL 12' 5500

SERIAL # _____

HOURLY METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS

LABOR

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 1-21-23

MECHANIC Ben

JOB NAME/LOCATION

JOB NUMBER

shop

PROBLEM: 1 bad battery

REPAIRED: replaced left battery

PARTS: H7 AGM

230.61

Advance Auto Parts

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	
EQUIP. #	0101	HOURS	DAYS
MAKE	Ram	REASON	
MODEL	12.5TC	PARTS	LABOR
SERIAL #		OTHER	
HOUR METER			
MILES			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: 7-19-23	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC: All	
SMOKES SHORTED VIBRATE OTHER		JOB NAME/LOCATION: <u>Stop</u>	
		JOB NUMBER:	
COMPONENT CODES		DATE COMPLETED: 7-22-23	
BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		COMPONENT LOCATION	
POWER TRAIN ELECTRICAL DRIVE TRAIN UNEXPLAINED		FRONT REAR LEFT RIGHT UPPER LOWER	
OTHER			

PROBLEM: cab leaking, cab make lights bad

REPAIRED: replaced make lights & sealed top of windshield

PARTS: upper marker lamps 9/ea
cab upper seals 383.49
Amazon MT. Juliet Ram

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0101</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ram</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>12 5500</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES <u>135k mi</u>				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>9-13-23</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Bryan</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shops</u>	JOB NUMBER _____
PROBLEM: <u>needs brakes</u>				
REPAIRED: <u>replaced front & rear pads</u>				
PARTS: <u>pads</u> <u>158.50</u> <u>Alumex</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0101</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ram</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>12' 5500</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES <u>134k mi</u>				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>7.F.23</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Bryan</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION	JOB NUMBER
			<u>Shop</u>	
PROBLEM: <u>EGR leaking</u>				
REPAIRED: <u>replaced EGR valve</u>				
PARTS: <u>EGR valve 656.79 MT Juliet Ram</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0101</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ram</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>12' 5500</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>10-2-23</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Lawrence Glass</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>needs windshield</u>				
REPAIRED: <u>replaced windshield</u>				
PARTS: <u>windshield</u> <u>404.98</u> <u>Lawrence Glass</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0101</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ram</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>12' 5500</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE: <u>4-1-24</u> DATE COMPLETED <u>4-2-24</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC <u>Bryan</u>	
SMOKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____	
PROBLEM: <u>Evap. clogged</u>					
REPAIRED: <u>replaced Evaporator & heater core.</u>					
<u>replaced Trailer brake box.</u>					
PARTS: <u>heater core & Evap</u> <u>192.⁰⁰</u> <u>Advance</u>					
<u>plate</u> <u>26.⁴⁰</u> <u>Premier Ram</u>					
<u>Trailer brake box</u> <u>329.⁹²</u> <u>Trailer Depot</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0101</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ran</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>12' 5500</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES <u>150k mi</u>				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE <u>6-10-24</u> DATE COMPLETED <u>6-13-24</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>All</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION	JOB NUMBER
			<u>Shop</u>	
PROBLEM: <u>smoking</u>				
REPAIRED: <u>cleaned out exhaust temp sensor hole & Egn cooler.</u>				
<u>serviced</u>				
PARTS: <u>Temp sensor</u> <u>58.30</u> <u>Aluske</u>				
<u>filter in stock</u>				



Service is our best part.

Store 3434 325 WEST MAIN ST. LEBANON, TN 37087 Phone: (615) 444-3246
Questions? Call 1-877-280-5965 or email us at service@advanceautoparts.com

REMIT:
Advance Auto Parts
AAP Financial Services
P.O. Box 742063
Atlanta, GA 30374-2063

THORN'S Excavating Company
624 old brns springs rd
Lebanon TN 37087
Phone: 615-444-5142
Account ID: 3430027407

PO#: truck 101

Date: 11/04/24
Register: 7
Store/Unit#: 7
Internet Order #:

Invoice/Trans: 3430430976047
Time: 7:53:47AM
Delivery: Yes
Salesperson: Charles
Payment Terms:
Submitter Name:

Product Line	Part #	Description	SKU	Warranty	Qty	List	Cost	Extended
2012 F150 6.7L L6 408CID -CC	603778	COOLANT RESERVOIR 1 PC 11934614 LIMITED LIFETIME REPLACEMENT			1	129.32	99.48	99.48
Domain - C Solutions		Location: PDQ P00142			TO Store: S03430			

*** In store payments on AAP Comm Credit accounts will be applied to oldest invoices by date. ***

#0101



D2Q6R1H36P1FB61BCZ

12' Ram 5500

James

MERCHANDISE SUBTOTAL

T1 Tax @

TOTAL INVOICE

Tender Type

CHANGE

99.48
9.70
109.18
109.18
0.00

9.7500%

AAP Charge Account 119257

Customer's signature below certifies that the tax free purchase items qualify for resale or other permitted tax or fee exemption. Customer will pay all taxes and government fees on taxable purchases, including interest and penalties if applicable. All cores need to be in the original box and in rebuildable condition to receive full core credit. Invoice required as proof of purchase for all returns.

THANK YOU FOR YOUR BUSINESS!

1 of 1

Customer Copy

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>0101</u> MAKE <u>Ram</u> MODEL <u>12' 5500</u> SERIAL # _____ HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>11-5-24</u> MECHANIC <u>Anthony</u> <table style="width:100%;"> <tr> <td style="width:50%;">JOB NAME/LOCATION <u>Shop</u></td> <td style="width:50%;">JOB NUMBER</td> </tr> </table>	JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER			
PROBLEM: _____ _____ _____				
REPAIRED: <u>replaced coolant reservoir</u> _____ _____ _____ _____ _____ _____				
PARTS: <u>coolant reservoir</u> <u>109.10</u> <u>Advance</u> _____ _____ _____ _____				