

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1203</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>HM300-1</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>11-20-19</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>James + Bryan</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>JAMES Brummett</u>	JOB NUMBER _____
PROBLEM: <u>blow hose</u>				
REPAIRED: <u>replaced left dump cylinder hose at hitch</u>				
PARTS: <u>Hose assembly</u> <u>330.29</u> <u>Nashville Rubber & Gasket</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>1203</u> MAKE <u>Komatsu</u> MODEL <u>HM300-1</u> SERIAL # _____ HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVETRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____																														
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE <u>12-2-19</u> DATE COMPLETED <u>12-5-19</u> MECHANIC <u>Charles</u> JOB NAME/LOCATION <u>Jones Brummett</u> JOB NUMBER _____																														
PROBLEM: <u>Exhaust & muffler burned out</u> <u>2 Hydraulic lines need replaced</u>																																
REPAIRED: <u>replaced hydraulic lines, flex section to muffler</u> <u>and muffler replaced. Park brake now working</u> <u>cleaned connections at relays.</u>																																
<table style="width:100%; border-collapse: collapse;"> <tr> <td style="width:30%;">PARTS:</td> <td style="width:40%;"><u>Muffler & Gasket</u></td> <td style="width:20%; text-align: right;"><u>\$1151.⁹¹</u></td> <td style="width:10%;"></td> <td style="width:20%;"><u>Power Equipment</u></td> </tr> <tr> <td></td> <td><u>Hardware</u></td> <td style="text-align: right;"><u>54.⁴⁶</u></td> <td></td> <td><u>Fastenal</u></td> </tr> <tr> <td></td> <td><u>Bands</u></td> <td style="text-align: right;"><u>243.⁴⁷</u></td> <td></td> <td><u>Power Equipment</u></td> </tr> <tr> <td></td> <td><u>2-Hoses</u></td> <td style="text-align: right;"><u>293.⁴⁴</u></td> <td></td> <td><u>Nashville Rubber & Gasket</u></td> </tr> <tr> <td></td> <td><u>Pipe</u></td> <td style="text-align: right;"><u>720.⁰⁰</u></td> <td></td> <td><u>White House Equipment</u></td> </tr> <tr> <td></td> <td><u>2-Gaskets</u></td> <td style="text-align: right;"><u>56.⁴⁶</u></td> <td></td> <td><u>Power Equipment</u></td> </tr> </table>			PARTS:	<u>Muffler & Gasket</u>	<u>\$1151.⁹¹</u>		<u>Power Equipment</u>		<u>Hardware</u>	<u>54.⁴⁶</u>		<u>Fastenal</u>		<u>Bands</u>	<u>243.⁴⁷</u>		<u>Power Equipment</u>		<u>2-Hoses</u>	<u>293.⁴⁴</u>		<u>Nashville Rubber & Gasket</u>		<u>Pipe</u>	<u>720.⁰⁰</u>		<u>White House Equipment</u>		<u>2-Gaskets</u>	<u>56.⁴⁶</u>		<u>Power Equipment</u>
PARTS:	<u>Muffler & Gasket</u>	<u>\$1151.⁹¹</u>		<u>Power Equipment</u>																												
	<u>Hardware</u>	<u>54.⁴⁶</u>		<u>Fastenal</u>																												
	<u>Bands</u>	<u>243.⁴⁷</u>		<u>Power Equipment</u>																												
	<u>2-Hoses</u>	<u>293.⁴⁴</u>		<u>Nashville Rubber & Gasket</u>																												
	<u>Pipe</u>	<u>720.⁰⁰</u>		<u>White House Equipment</u>																												
	<u>2-Gaskets</u>	<u>56.⁴⁶</u>		<u>Power Equipment</u>																												

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>1203</u> MAKE <u>Komatsu</u> MODEL <u>HM300-1</u> SERIAL # _____ HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>1-13-2020</u> MECHANIC <u>Charles</u> JOB NAME/LOCATION <u>Jones Brunnett</u> JOB NUMBER _____
PROBLEM: <u>hose leaking</u> _____ _____		
REPAIRED: <u>replaced two main cooler hoses</u> _____ _____ _____ _____ _____ _____		
PARTS: <u>Fittings</u> <u>105.96</u> <u>Nashville Rubber & Basket</u> <u>2-Hoses</u> <u>400.00</u> <u>Nashville Rubber & Basket</u> _____ _____ _____		

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1203</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>Komatsu</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>HM300-1</u>	PARTS _____ LABOR _____	COMPONENT LOCATION		
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE <u>1-23-2020</u>	DATE COMPLETED <u>1-23-2020</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Bryan</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Jones Brummett</u>	JOB NUMBER _____	
PROBLEM: <u>blown dump hoses</u>				
REPAIRED: <u>replaced both hoses</u>				
PARTS: <u>2 Hoses</u> <u>795.10</u> <u>Nashville Rubber & Gasket</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1202</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>HM300-1</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>3-4-2020</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Charles</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Jones Brummett</u> JOB NUMBER _____	
PROBLEM: <u>Tube cracked</u>				
REPAIRED: <u>replaced tube</u>				
PARTS: <u>Tube & seals</u> <u>911.87</u> <u>Power Equipment</u>				

TEC
THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>1203</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Komatsu</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>Nm300-1</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER <u>8500 HRS</u>		OTHER _____
MILES _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>3-19-2020</u> MECHANIC <u>Ali</u>
		JOB NAME/LOCATION <u>James Brummett</u> JOB NUMBER _____
PROBLEM: <u>Service</u>		
REPAIRED: <u>serviced</u>		
PARTS: <u>all filters</u> <u>582.27</u> <u>Ken Filter sales</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1203</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>Hm350-1</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>9-9-20</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Ben</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Jones Brummet</u>	JOB NUMBER	
PROBLEM: <u>won't start</u>				
REPAIRED: <u>replaced other battery</u>				
PARTS: <u>1-4D-XHD</u> <u>198.59</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1203</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>Hm300-1</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>9-2-20</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Jones Brummet</u>	JOB NUMBER
PROBLEM: <u>bad battery</u>				
REPAIRED: <u>replaced battery</u>				
PARTS: <u>1- 4D battery</u> <u>218.45</u> <u>Interstate battery</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1203</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>HM300-1</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>1-26-21</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>RT bed lift cylinder leaking</u>				
REPAIRED: <u>packed bed cylinder</u>				
PARTS: <u>cylinder repair \$1,104.52 Mid South Hydraulics</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1203</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>HM300-1</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>9K HRS</u>		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: <u>2-9-21</u> DATE COMPLETED <u>2-22-21</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC _____	
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>EAST GAK</u>	JOB NUMBER
PROBLEM: <u>service</u>			
REPAIRED: <u>serviced</u>			
PARTS: <u>All Filters</u> <u>570.3L</u> <u>Term Filter</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1203</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>KOMATSU</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>HM300-1</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>5-14-21</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>BEN</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>CARVER STATION</u>	JOB NUMBER _____
PROBLEM: <u>Park brake error.</u>				
REPAIRED: <u>replaced park brake solenoid valve</u>				
PARTS: <u>Solenoid valve 1706.31</u> <u>Power Equipment</u>				
<u>UC1100675453</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>1203</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Komatsu</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>Hm300-1</u>		PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
OUR METER _____			OTHER _____
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>5-24-21</u> MECHANIC <u>Ben</u>	
PROBLEM: <u>blown hose</u>		JOB NAME/LOCATION <u>Carver Station</u> JOB NUMBER _____	
REPAIRED: <u>replaced hose</u>			
PARTS: <u>hose</u> <u>60' 75'</u> <u>Creeks</u>			

TEC

THORNES EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	
EQUIP. # 1203		HOURS _____ DAYS _____	
MAKE Komatsu		REASON _____	
MODEL HM300-1		PARTS _____ LABOR _____	
SERIAL # _____		OTHER _____	
HOUR METER 9,500 HRS		OTHER _____	
MILES _____		OTHER _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			
SMOKES SHORTED VIBRATE OTHER _____			
PROBLEM: Service			
DATE: 8-17-21			
MECHANIC All			
JOB NAME/LOCATION Shop			
JOB NUMBER _____			
DATE COMPLETED 10-1-21			
COMPONENT CODES			
BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS			
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED			
COMPONENT LOCATION			
FRONT REAR LEFT RIGHT UPPER LOWER			
OTHER _____			

REPAIRED: serviced

replaced one Dump cylinder hose on left side
replaced all d.f. & hub oil, sealed brake
accumulators

PARTS: All Filters

601.02

Team Filter

hose

354.20

Hydro Design

seals

1175.00

lower Equipment

seat

2000.49

Thompson

charge valves

166.00

Power Equipment

Back Accumulators

327.00

mid South hydraulics

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1203</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>KOMATSU</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>HM300-1</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>19090 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: _____ DATE COMPLETED <u>4-1-22</u> MECHANIC <u>Ben + Anthony</u>	
PROBLEM: <u>Service</u>			JOB NAME/LOCATION <u>West Trinity</u> JOB NUMBER _____	
REPAIRED: <u>Serviced</u>				
PARTS: <u>All Filters 549.65</u> <u>Ten Filter</u> <u>but outer Air</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1203</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>HM300-1</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: <u>5-23-22</u> DATE COMPLETED <u>5-23-22</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Ben & Anthony</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>West Trinity</u>	JOB NUMBER _____	
PROBLEM: <u>Tube cracked</u>				
REPAIRED: <u>replaced tube</u>				
<u>Truck wrecked, hit 300 Kom. excavator.</u>				
PARTS: <u>Tube + Orings</u> <u>909.⁰³</u> <u>Power Equipment</u>				

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>1203</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>HM300-1</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____			
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: _____ DATE COMPLETED <u>7-12-22</u> MECHANIC <u>Ben</u>		
PROBLEM: <u>retard sensors Temp Gauge climbing</u>			JOB NAME/LOCATION <u>Aurora</u>		JOB NUMBER
REPAIRED: <u>replaced sensors</u>					
PARTS <u>Sensors</u> <u>367.⁴⁴</u> <u>Paver Equipment</u>					

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>1203</u>		HOURS _____	DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>HM300-1</u>		PARTS _____	LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>10500 HRS</u>				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE: <u>8-31-22</u> DATE COMPLETED <u>9-13-22</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC <u>Anthony & Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION <u>Lime Stone</u>	JOB NUMBER _____
PROBLEM: <u>Service</u>					
REPAIRED: <u>serviced</u>					
<u>replaced park brake solenoid</u>					
PARTS: <u>brake solenoid</u> <u>821.⁰⁰</u> <u>Power Equipment</u>					
<u>Filters</u> <u>784.³⁸</u> <u>Tenn Filter Sales</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 1203

MAKE Komatsu

MODEL HM300-1

SERIAL # _____

HOUR METER 11K HRS

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON _____

PARTS _____

LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: 4-27-23 DATE COMPLETED 5-1-23

MECHANIC Anthony

JOB NAME/LOCATION

To Shop

JOB NUMBER

PROBLEM: service & repairs

REPAIRED: serviced, replaced RT center carrier

Tightened park brake cylinder bolts,

replaced park brake solenoid with repaired solenoid

PARTS: Filters

765.78

Ten Filter socks

Gear Carrier

2231.81

Power Equipment

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 1203

MAKE Komatsu

MODEL LHM300-1

SERIAL # _____

HOUR METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKE SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 7-11-23

MECHANIC Ben

JOB NAME/LOCATION

Eastgate

JOB NUMBER

PROBLEM: hose blown

REPAIRED:

replaced transmission hose

PARTS:

hose

648.79

Volunteer hose

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1203</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>HM300</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>11,500 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>4-22-24</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Anthony</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>41st</u>	JOB NUMBER
PROBLEM: <u>Service</u>				
REPAIRED: <u>Serviced</u>				
PARTS: <u>Filters</u> <u>342.00</u> <u>Tenn Filter</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1203</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>Komatsu</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>HM300-1</u>	PARTS _____ LABOR _____	COMPONENT LOCATION		
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>2-25-25</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Ben</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>41st Ave</u>	JOB NUMBER _____	
PROBLEM: <u>won't start</u>				
REPAIRED: <u>replaced batteries</u>				
PARTS: <u>2-40</u> <u>579.37</u> <u>Interstate battery</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>1203</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Komatsu</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>HM300-1</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # <u>1158</u>	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE <u>2-7-25</u> DATE COMPLETED _____
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC <u>All</u>
SMOKES SHORTED VIBRATE OTHER _____	JOB NAME/LOCATION <u>New Shop</u> JOB NUMBER _____

PROBLEM: Trans. sensors

REPAIRED: replaced sensors and repaired hitch wiring.
packed left front suspension wiring.

PARTS: <u>2 sensors</u>	<u>351.90</u>	<u>Power Equipment</u>
<u>seals & bushings</u>	<u>454.00</u>	<u>Power Equipment</u>