

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 1404

MAKE KOMATSU

MODEL WA200-8

SERIAL # 85957

HOUR METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 4-4-19

MECHANIC KOMATSU

JOB NAME/LOCATION

Shop

JOB NUMBER

PROBLEM: new machine

REPAIRED: 3yr - 2k hrs Full service all but Air Filters

PARTS: _____

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 1404

MAKE Komatsu

MODEL WA200

SERIAL # loader

HOURLY METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON _____

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 5-17-22

MECHANIC Ben

JOB NAME/LOCATION

West Trinity

JOB NUMBER

PROBLEM: cut hoses

REPAIRED: replaced cooler hoses

PARTS: 2-hoses

512.62

J.R.G

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1404</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>	REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>WA200</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>? 2K</u>		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: <u>6-9-22</u>	DATE COMPLETED <u>6-11-22</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION	JOB NUMBER
PROBLEM: <u>Service</u>			
REPAIRED: <u>serviced</u>			
PARTS: <u>All Filters</u> <u>1,500.00</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 1404

MAKE KOMATSU

MODEL WA200

SERIAL # _____

OUR METER 2500 HRS

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SMOKES SHORTED VIBRATE OTHER _____

DATE 8-31-22 DATE COMPLETED 9-1-22

MECHANIC Anthony

JOB NAME/LOCATION
West Trinity

JOB NUMBER

PROBLEM: Service

REPAIRED: serviced

PARTS: Filters 1,160.⁹² Power Equipment

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>1404</u> MAKE <u>Komatsu</u> MODEL <u>WA200</u> SERIAL # _____ HOUR METER _____ MILES _____	HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: <u>9-6-22</u> DATE COMPLETED <u>9-6-22</u> MECHANIC <u>Anthony</u> JOB NAME/LOCATION <u>West Trinity</u> JOB NUMBER _____	
PROBLEM: <u>won't start key broken off in switch</u>		
REPAIRED: <u>replaced batteries + key switch</u>		
PARTS: <u>2-GRP 31P-MHD 283.⁰⁴ Interstate Battery</u> <u>key switch 266.¹⁸ Power Equipment</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 1404

MAKE Komatsu

MODEL WA200

SERIAL # _____

HOURLY METER 3K HRS

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKE SHORTED VIBRATE OTHER _____

DATE 12-6-22 DATE COMPLETED 12-13-22

MECHANIC Anthony

JOB NAME/LOCATION
West Trinity

JOB NUMBER

PROBLEM: Service

REPAIRED: serviced

PARTS: Filters

1,550.⁷¹

Power Equipment

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 1404
MAKE Komatsu
MODEL WA200
SERIAL # _____
HOUR METER _____
MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
REASON _____
PARTS _____ LABOR _____
OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER
OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 3-7-23

MECHANIC Ben

JOB NAME/LOCATION

JOB NUMBER

Arthurs

PROBLEM: _____

REPAIRED: replaced quick connect hose.

PARTS: hose 101.00 Nashville Rubber & Gasket

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>1404</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Komatsu</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>WA 200</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
OUR METER <u>4,500 HRS</u>		OTHER _____
MILES _____		

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE: <u>7-26-23</u>	DATE COMPLETED <u>7-28-23</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC <u>Anthony</u>	
SMOKES SHORTED VIBRATE OTHER _____	JOB NAME/LOCATION <u>Anthem</u>	JOB NUMBER _____

PROBLEM: Service

REPAIRED: serviced

PARTS: Filters 1473⁸⁸ Power Equipment

TEC

THORNE'S EXCAVATING COMPANY, LLC SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>1404</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Komatsu</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>WA200</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
OUR METER _____		OTHER _____
MILES _____		

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE: _____ DATE COMPLETED <u>11-13-23</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC <u>Justin</u>
SMOKES SHORTED VIBRATE OTHER _____	JOB NAME/LOCATION <u>Shop</u>
	JOB NUMBER _____

PROBLEM: bad quick release switch

REPAIRED: replaced switch & hydro lock switch

PARTS: <u>Switch</u>	<u>61.⁷⁹</u>	<u>Power Equipment</u>
<u>Switch</u>	<u>334.⁵⁶</u>	<u>Power Equipment</u>

TEC

THORNE'S EXCAVATING COMPANY, LLC SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1404</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>WA200</u>	PARTS LABOR	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>5K HRS</u>	OTHER _____	OTHER _____	
MILES _____	OTHER _____	OTHER _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE <u>12-15-23</u>	DATE COMPLETED <u>12-20-23</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC _____	
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Stone Trace</u>	JOB NUMBER _____
PROBLEM: <u>Service</u>			
REPAIRED: <u>Service</u>			
PARTS: <u>Filters</u>		<u>731.90</u>	<u>Power Equipment</u>

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>1404</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Komatsu</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>WA200</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER <u>5,500</u>		OTHER _____
MILES _____		

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE: <u>7-11-24</u> DATE COMPLETED _____
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC <u>Anthony</u>
SMOKES SHORTED VIBRATE OTHER _____	JOB NAME/LOCATION <u>Aubrey's</u> JOB NUMBER _____

PROBLEM: Service

REPAIRED: Serviced

PARTS: Filters 626.00 Power Equipment

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>1405</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>924K</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE: <u>3-13-25</u> DATE COMPLETED <u>3-13-25</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____	JOB NAME/LOCATION <u>Wilson Judicial</u> JOB NUMBER _____	
PROBLEM: <u>blown hoses</u>		
REPAIRED: <u>replaced quick connect hoses</u>		
PARTS: <u>2 hoses</u> <u>186.8X</u> <u>Crook's Auto</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	
EQUIP. #	1404	HOURS	DAYS
MAKE	Komatsu	REASON	
MODEL	WA200	PARTS	LABOR
SERIAL #		OTHER	
HOUR METER	6K MRS		
MILES			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			
SMOKES SHORTED VIBRATE OTHER			
JOB NAME/LOCATION		JOB NUMBER	
Ghail Kan			
MECHANIC		DATE COMPLETED	
Bryan		4-23-25	
COMPONENT CODES		DATE COMPLETED	
BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		5-8-25	
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED			
COMPONENT LOCATION			
FRONT REAR LEFT RIGHT UPPER LOWER			
OTHER			

PROBLEM: Service

REPAIRED: Serviced

PARTS: Filters

605.89

Power Equipment

1 EC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>1404</u> MAKE <u>Komatsu</u> MODEL <u>WA-200</u> SERIAL # _____ HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
---	---	--

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: _____ DATE COMPLETED <u>5-22-25</u> MECHANIC <u>Bryan</u>
JOB NAME/LOCATION: <u>Quail Run</u>	
JOB NUMBER: _____	

PROBLEM: bad batteries, broke park brake switch

REPAIRED: replaced batteries and park brake switch.

PARTS: 4-29H batteries 596.⁰² IBS of Middle TN.
switch 58.⁷⁵ Power Equipment.

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>1404</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Komatsu</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>WA200</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # <u>10101</u>	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
OUR METER <u>6200 HRS</u>		OTHER _____
MILES _____		

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE: _____ DATE COMPLETED <u>12-15-25</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC <u>Ben</u>	
SMOKE SHORTED VIBRATE OTHER _____	JOB NAME/LOCATION <u>High Park</u>	JOB NUMBER _____

PROBLEM: bad sensor

REPAIRED: replaced turbo Knox sensor

PARTS: sensor 1114.93 Power Equipment