

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0116</u>		HOURS _____	DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ford</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>11' F650</u>		PARTS _____	LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES <u>34K mi</u>					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: <u>2-6-23</u>		DATE COMPLETED: <u>2-22-23</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>All</u>			
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Shop</u>		JOB NUMBER _____	
PROBLEM: <u>bought used 90 over & service</u>					
REPAIRED: <u>Fully serviced changed all oils new air comp belt.</u>					
<u>new muffle straps</u>					
PARTS: <u>Filters</u> <u>304.59</u> <u>Tenn Filter sales</u>					
<u>QR valve</u> <u>27.19</u> <u>Truck Pro</u>					
<u>8qt trans. oil</u> <u>166.73</u> <u>Advance Auto Parts</u>					
<u>air comp belt</u> <u>20.05</u> <u>Nash. Rubber & Gasket</u>					
<u>Muffle + DPF straps</u> <u>86.50</u> <u>Mid Tenn Ford</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0116</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ford</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>11' F650</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE: _____ DATE COMPLETED <u>2-23-23</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC <u>Anthony</u>	
SMOKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION <u>Shop</u>	
PROBLEM: <u>Det tank cracked</u>				JOB NUMBER _____	
REPAIRED: <u>replaced tank needs NOX sensors checked out</u>					
PARTS: <u>Tank</u> <u>940.55</u> <u>Mid Term Ford</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0116
MAKE Ford
MODEL 11' F650
SERIAL # _____
HOUR METER _____
MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
REASON _____
PARTS _____ LABOR _____
OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 4-10-23

MECHANIC Anthony

JOB NAME/LOCATION

Shop

JOB NUMBER

PROBLEM: Vibration

REPAIRED: replaced two rear u-joints, New caps.

PARTS: 2-joints & 2-cap kits 222.⁷⁶ Dave's Driveshaft Shop.

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0116
MAKE Ford
MODEL 11' F650
SERIAL # _____
HOUR METER _____
MILES 38K mi

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
REASON _____
PARTS _____ LABOR _____
OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER
OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SMOKES SHORTED VIBRATE OTHER _____

DATE: 6-8-23 DATE COMPLETED 6-19-23

MECHANIC Anthony + Justin

JOB NAME/LOCATION

Shop

JOB NUMBER

PROBLEM: Service

REPAIRED: Serviced

PARTS: Filters

211.00

Teur Filter

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0116

MAKE Ford

MODEL 11' F650

SERIAL # _____

HOUR METER _____

MILES 40K mi.

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS

LABOR

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 9-11-23

MECHANIC Anthony & Justin

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: needs steel tires

REPAIRED: replaced steel tires

PARTS: 2 Teco M177 1300^{cc} Gateway Tire

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0116</u>	HOURS _____ DAYS _____ REASON PARTS LABOR OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>Ford</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>11' F650</u>		COMPONENT LOCATION		
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER		
OUR METER _____		OTHER _____		
MILES <u>43 38 K mi</u>				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE <u>12-7-23</u> DATE COMPLETED <u>12-15-23</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Anthony</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER	
PROBLEM: <u>Service</u>				
REPAIRED: <u>Serviced</u>				
PARTS: <u>Filters</u> <u>186.19</u> <u>Tann Filter</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0116

MAKE Food

MODEL 11' F650

SERIAL # _____

HOUR METER _____

MILES 49,000 mi

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS

LABOR

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 6-13-24

MECHANIC Ben

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: Service

REPAIRED: serviced

PARTS: Filters

252.27

Napa

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0116</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ford</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>11' F650</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE: _____ DATE COMPLETED <u>5-7-25</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC <u>Bryan</u>	
SMOKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION <u>Shop</u>	
PROBLEM: <u>radio blacked out</u>				JOB NUMBER _____	

REPAIRED: _____

PARTS: radio

109.74

O'Reilly Auto Parts

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0116
 MAKE Ford
 MODEL 11' F650
 SERIAL # _____
 HOUR METER _____
 MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
 REASON _____
 PARTS _____ LABOR _____
 OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
 POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER
 OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
 OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
 SMOKES SHORTED VIBRATE OTHER _____

DATE: 5-12-25 DATE COMPLETED 5-14-25

MECHANIC Bryan

JOB NAME/LOCATION

Shop.

JOB NUMBER

PROBLEM: A/C repair

REPAIRED: replaced A/C comp., drier + 4 hoses.
Topped off system.

PARTS: comp

289.²⁷

O'Reilly Auto Parts

Drier + hose

198.⁵⁶

O'Reilly Auto Parts

3 hoses

436.²²

Mid Run Ford

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION

IP. # 0116

MAKE Ford

MODEL 11' F650

SERIAL # _____

HOUR METER _____

MILES 60k mi

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON _____

PARTS _____

LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SHAKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 7-22-25

MECHANIC Bryan

JOB NAME/LOCATION

Shop

JOB NUMBER

PROBLEM: Service

REPAIRED: serviced

PARTS: Filters

217.66

Term Filter

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0116</u>	HOURS _____ DAYS _____ REASON PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____		
MAKE <u>Ford</u>				
MODEL <u>F650 II</u>				
SERIAL # _____				
HOUR METER _____				
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE <u>7-28-25</u> DATE COMPLETED <u>8-29-25</u> MECHANIC <u>Bryan</u> JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____		
PROBLEM: <u>Needs steer tires</u>				

REPAIRED: replaced steer tires.

PARTS 2-11R-22.5 Polson Rmr 51 1715:26 Smile Fleet.
beed bags 28.58 Charlie's Tire

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0116</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ford</u>		REASON		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>11' F650</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE: <u>9-12-25</u> DATE COMPLETED <u>9-15-25</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC <u>Bryan</u>	
SMOKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION <u>Shop</u>	
				JOB NUMBER _____	
PROBLEM: <u>Trailer brake controller bad. Air leak</u>					
REPAIRED: <u>replaced brake controller & air fitting</u>					
PARTS: <u>controller</u> <u>290.⁰⁰</u> <u>Trailer Depot</u>					
<u>fitting</u> <u>44.¹⁷</u> <u>Crook's</u>					

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0116</u>	HOURS _____ DAYS _____ REASON PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____		
MAKE <u>Ford</u>				
MODEL <u>11' F650</u>				
SERIAL # _____				
HOUR METER _____				
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>9-15-25</u> DATE COMPLETED <u>9-24-25</u> MECHANIC <u>Bryan</u> JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____		
PROBLEM: <u>hole in air tank</u> <u>Ordered tank from Mid Tenn Ford.</u>				
REPAIRED: <u>replaced air tank and te fittings</u>				
PARTS: <u>Tank, clamps, and some fittings</u> <u>1048.12</u> <u>Mid Tenn Ford</u> <u>hose</u> <u>26.00</u> <u>O'Reilly</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0116</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ford</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>11' F650</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE: <u>3-16-26</u> DATE COMPLETED <u>3-16-26</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC <u>Bryan</u>	
SMOKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION <u>Shop</u>	
				JOB NUMBER _____	

PROBLEM: needs windshield

REPAIRED: Lawrence glass replaced windshield
right front slide adjuster came off. needed washer
and spring.

PARTS: windshield 404.98 Lawrence Glass