

EQUIPMENT
REPAIRS

DATE 4-16-07

MILEAGE/HOURS _____

EQUIPMENT REPAIRED #311 330C

REPAIRS MADE _____

changed to 30" bucket

HOURS WORKED _____

PARTS USED

8 shims
2 bolts
4 nuts

\$120.77 Thompson Machinery

EQUIPMENT
REPAIRS

DATE 5-11-07

MILEAGE/HOURS _____

EQUIPMENT REPAIRED #311 330C Stacker Bucket

REPAIRS MADE replace Adapter

HOURS WORKED _____

PARTS USED

adapter # 56.45
Pin
Retainer

EQUIPMENT
REPAIRS

DATE 8-22-07

MILEAGE/HOURS 2100

EQUIPMENT REPAIRED #311 330C

REPAIRS MADE welded all cracks on old 3170
bucket replaced all side tips, pins and
retainers

HOURS WORKED _____

PARTS USED

1 Tip 12 pins 12 retainers \$256.50
7 Tips \$611.76

Thompson

EQUIPMENT
REPAIRS

DATE 11-9-07

2434
MILEAGE/HOURS 2500

EQUIPMENT REPAIRED *311 330C

REPAIRS MADE Complete Service
Oil, Air, Hydro Filters

HOURS WORKED _____

PARTS USED

All Filters 447.01
A.C. Filters 125.00

EQUIPMENT
REPAIRS

DATE 3-17-08

MILEAGE/HOURS 2576 HRS

EQUIPMENT REPAIRED #311 330C

REPAIRS MADE Replaced door assembly inside
heat and air unit.

HOURS WORKED _____

PARTS USED

Door Assembly 23.⁰² Thompson

EQUIPMENT
REPAIRS

DATE 5-5-08

MILEAGE/HOURS 2701. HRS

EQUIPMENT REPAIRED #309 330C

REPAIRS MADE master link + 1 link
RT Track warranty

HOURS WORKED _____

PARTS USED

Labor \$100.00 warranty Thompson

EQUIPMENT
REPAIRS

DATE 10-20-08

MILEAGE/HOURS 3,000 HRS

EQUIPMENT REPAIRED #311 330C

REPAIRS MADE Serviced

HOURS WORKED _____

PARTS USED

Filters	413.44	
	26.21	
	<u>\$439.65</u>	Total
		Thompson

EQUIPMENT
REPAIRS

DATE 10-27-08

MILEAGE/HOURS #311

EQUIPMENT REPAIRED 330c 60" bucket

REPAIRS MADE welded a lift hook on back
of bucket

HOURS WORKED _____

PARTS USED

hook used hook in stock



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>311</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>330C</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # <u>HDKV4398</u>		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: _____ DATE COMPLETED <u>2-26-09</u>	
			MECHANIC <u>JAMES</u>	
			JOB NAME/LOCATION <u>Owl Hollow</u>	JOB NUMBER
PROBLEM: <u>blown hose</u>				
REPAIRED: <u>replaced bucket cylinder on right side</u>				
PARTS: <u>hose assembly 310.18 Thompson</u>				



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>311</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON PARTS _____ LABOR _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>330C</u>		COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOURLY METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN <u>WORN</u> ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>2-17-09</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>JAMES</u>	
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Owl Hollow</u>	JOB NUMBER
PROBLEM: <u>horn switch</u>			
REPAIRED: <u>replaced horn switch</u>			
PARTS: _____			
<u>Horn switch & seal</u> <u>\$90.⁵²</u> <u>Thompson</u>			



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>311</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>330C</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>7-20-09</u>	DATE COMPLETED <u>8-27-09</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>JAMES & Daniel</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION	JOB NUMBER
			<u>Shop</u>	
PROBLEM: <u>hood latch broken</u>				
REPAIRED: <u>replaced hood latch, washed machine</u>				
PARTS: <u>latch assembly</u> <u>71.13</u> <u>Thompson</u>				

EQUIPMENT
REPAIRS

DATE 12-1-09

MILEAGE/HOURS 3450 HRS

EQUIPMENT REPAIRED 330C #311

REPAIRS MADE serviced changed all filters

HOURS WORKED _____

PARTS USED

Donaldson Filters



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>309</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>330C</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>5-17-10</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>JAMES</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION	JOB NUMBER
PROBLEM: <u>bolts for swapping buckets</u>				
REPAIRED: _____				
PARTS: <u>3- 5x7 bolts</u> <u>Fastenal</u> <u>\$36.00</u>				
<u>2- 5x9 bolts</u>				



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>311</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>330C</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>6-16-10</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>James</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION	JOB NUMBER
			<u>Wilson Bank MT</u>	<u>Truck</u>
PROBLEM: <u>window loose</u>				
REPAIRED: <u>glued right cab window</u>				
PARTS: _____				
<u>Sealer + Gun</u> <u>\$24.12</u> <u>NAPA</u>				



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>311</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>CAT</u>	REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>330C</u>	PARTS LABOR	COMPONENT LOCATION		
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER		
HOURLY METER _____		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>7-6-10</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>James</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER	
PROBLEM: <u>36" bucket broken right end shank</u>				
REPAIRED: <u>replaced shank</u>				
Warranty				
PARTS: <u>shank 479.03 Thompson</u>				
<u>2 locks</u>				
<u>locks 27.76 EAI</u>				
<u>shank 380.96</u>				



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>311</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>330C</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>7-22-10</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>JAMES</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION	JOB NUMBER
			<u>Wilson Bank</u>	
PROBLEM: <u>hydraulic leak</u>				
REPAIRED: <u>replaced upper main pressure hose</u>				
PARTS: <u>hose</u> <u>514.4E</u> <u>Thompson</u>				



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>311</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>330C</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOOR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>9-19-11</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Jan & Robb</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>ML Juliet</u>	JOB NUMBER
PROBLEM: <u>blown pilot hose</u>				
REPAIRED: <u>replaced hose & fitted with oil</u>				
PARTS: <u>Hose Assembly 6' 7" NAPA</u>				



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>311</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Cat</u>	REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>330C</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOOR METER _____		OTHER _____
MILES _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>10-10-11</u> MECHANIC <u>James</u>
		JOB NAME/LOCATION <u>MT Juliet</u> JOB NUMBER _____
PROBLEM: <u>blown bucket cylinder hose left side.</u>		
REPAIRED: <u>replaced hose</u>		
PARTS: <u>hose assembly</u> <u>345.13</u> <u>Thompson</u>		

EQUIPMENT
REPAIRS

DATE 10-8-11

MILEAGE/HOURS _____

EQUIPMENT REPAIRED #311 Cat 330C

REPAIRS MADE Replaced Fuel Filters on
Job site in MT Juliet

HOURS WORKED _____

PARTS USED

Sep. Filter

29.⁸⁵

Thompson

Fuel Filter

17.⁵⁰

Tenn Filter

EQUIPMENT
REPAIRS

DATE 11-2-11

MILEAGE/HOURS 4,000 HRS

EQUIPMENT REPAIRED #311 330C

REPAIRS MADE served

window repair (glued side window cut plexi-glass for)
Front foot section
washed, welded cracks on bucket.

HOURS WORKED _____

PARTS USED

All Filters	405. ⁵³	Thompson
Window urethane	27. ³⁰	Advance




THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>311</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>330L</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>3-21-12</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>James & Jeff</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>cab window falling out.</u>				
REPAIRED: <u>removed right cab window and sealed.</u>				
PARTS: <u>sealer</u> <u>24, 24</u> <u>NAPA</u>				



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>311</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>330C</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>5-24-12</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>JAMES</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Bel-Air</u>	JOB NUMBER
PROBLEM: <u>swing drive vent missing</u>				
REPAIRED: <u>replaced vent</u>				
PARTS: <u>vent assembly</u> <u>56.50</u> <u>Thompson</u>				



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>311</u>	MAKE <u>Cat</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MODEL <u>330C</u>	SERIAL # _____	REASON PARTS _____ LABOR _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
HOURLY METER _____	MILES _____	OTHER _____	COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>6-13-12</u>	MECHANIC <u>JAMES</u>	
		JOB NAME/LOCATION <u>Bel-Air</u>	JOB NUMBER _____	
PROBLEM: <u>side window fell out</u>				
REPAIRED: <u>re-sealed and made plates to help hold window in place.</u> <u>Fuel cap filter assembly replaced</u>				
PARTS: <u>Silicone</u> <u>13.10</u> <u>NAPA</u> <u>Hardware</u> <u>18.50</u> <u>TSC</u> <u>Fuel cap filter kit</u> <u>35.41</u> <u>Thompson</u>				



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>311</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>330C</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>7-20-12</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>James & Jeff</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION	JOB NUMBER
			<u>Bel-Air</u>	
PROBLEM: <u>Hydraulic leak</u>				
REPAIRED: <u>pilot valve on main control valve leaking</u>				
<u>removed valve replaced mounting o-rings,</u>				
PARTS: <u>2 o-ring seals</u> <u>5.00</u> <u>Thompson Machinery</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>311</u>		HOURS _____ DAYS _____		BASIC MACHINE	HYDRAULIC ENGINE IMPLEMENT
MAKE <u>CAT</u>		REASON		POWER TRAIN	ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>330C</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>9-10-12</u> DATE COMPLETED <u>9-12-12</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>JAMES</u>		
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>BEL-AIR</u> JOB NUMBER _____		
PROBLEM: <u>tree went through pump compartment door</u>					
REPAIRED: <u>removed broken hydraulic return filter base</u> <u>replaced two broken pilot hoses</u> <u>removed damaged door. Repaired door to</u> <u>be used temporary.</u> <u>replaced base filter & orings. Tapped off</u> <u>with hydraulic oil.</u> <u>welded door latch striker</u>					
PARTS: <u>2 pilot lines 9/11 Thompson</u> <u>Filter housing block orings</u> <u>Tedicator 668.00 Thompson</u>					



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>311</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>330C</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>9-28-12</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>JAMES</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION	JOB NUMBER
			<u>Bel-Air</u>	
PROBLEM: <u>left bucket cylinder hose damaged by tree.</u>				
REPAIRED: <u>replaced hose assembly & o-rings.</u>				
PARTS: <u>bucket cylinder hose #372, 3/4" Thompson</u>				



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>311</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>CAT</u>	REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>330C</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOURLY METER _____		OTHER _____
MILES <u>4548</u>		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>1-10-13</u> MECHANIC <u>JAMES</u> JOB NAME/LOCATION <u>Back with to shop</u> JOB NUMBER _____
PROBLEM: <u>won't start. All four batteries blown</u>		
REPAIRED: <u>replaced batteries, to shop to clean up and check over</u> <u>replaced sun roof latch. Repaired armrests.</u> <u>removed broken lights off of boom. Tied up wiring.</u> <u>straightened steel tube on stick cylinder.</u> <u>topped off fluids & greased</u>		
PARTS: <u>4-batteries 458.63 Interstate battery</u> <u>29H-VHD</u> <u>latch for sunroof \$59.80 Thompson</u>		



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>311</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>CAT</u>	REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>330C</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>1-29-13</u> MECHANIC <u>James Hobbs</u> JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____
PROBLEM: <u>Master link pin on left track backed out</u>		
REPAIRED: <u>replaced master link pin on left track.</u>		
PARTS: <u>pin, split pin, bolts nuts 103,50 Thompson</u>		

EQUIPMENT
REPAIRS

DATE 8-17-12

MILEAGE/HOURS 4,500 HRS

EQUIPMENT REPAIRED #311 Cat 330C

REPAIRS MADE Serviced

HOURS WORKED _____

PARTS USED

Filters 332.95 Tenn Filter Sales



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>311</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>	REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>330C</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOOR METER _____		OTHER _____	
MILES <u>4558 HRS</u>			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>2-6-13</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>James</u>	
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION	JOB NUMBER
		<u>Goodwill Miller</u>	
PROBLEM: <u>Monitor warning low engine oil pressure</u>			
REPAIRED: <u>replaced Engine oil pressure switch</u>			
PARTS: <u>switch & O ring 166.02 Thompson</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>311</u> MAKE <u>CAT</u> MODEL <u>330C</u> SERIAL # _____ HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>10-1-13</u> MECHANIC <u>JAMES</u> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 70%;">JOB NAME/LOCATION <u>Shop</u></td> <td style="width: 30%;">JOB NUMBER</td> </tr> </table>	JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER			
PROBLEM: <u>Cab glass + window track</u>				
REPAIRED: <u>replaced upper + lower front glass and frame rollers</u>				
PARTS: <u>Track rollers + lower glass 208.09 Thompson</u> <u>front glass 276.95 Lawrence Glass</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>311</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>330C</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>5K HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>12-3-13</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>JAMES</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Farm Credit</u>	JOB NUMBER _____
PROBLEM: <u>Service</u>				
<u>needs exhaust elbow, fill cap seal</u>				
<u>hose assembly</u>				
REPAIRED: <u>Serviced</u>				
<u>cut a 5" turn out to make fit the 5 1/8" cat</u>				
<u>muffler outlet</u>				
<u>replaced one oil filter housing hose</u>				
<u>replaced oil cap o-ring</u>				
PARTS: <u>Filters \$340.00</u> <u>new filter hoses</u>				
<u>hose + cap seal \$184.89</u> <u>Thompson Machinery</u>				

EQUIPMENT
REPAIRS

DATE 4-3-14

MILEAGE/HOURS _____

EQUIPMENT REPAIRED #311 Cat 330C

REPAIRS MADE replaced fuel filters

Service light was on.

HOURS WORKED _____

PARTS USED

2-fuel filters

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>311</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>330C</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>2-14-14</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>JAMES</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Step</u>	JOB NUMBER _____
PROBLEM: <u>pump noise, hose leaking</u>				
REPAIRED: <u>replaced case drain hose + all hydraulic filters.</u>				
PARTS: <u>Hydraulic Filters</u> <u>134.22</u> <u>Tenn filter sales</u>				
<u>hose assembly</u> <u>82.53</u> <u>NAPA</u>				
<u>Door roller</u> <u>in stock</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>311</u> MAKE <u>CAT</u> MODEL <u>330C</u> SERIAL # _____ HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>5-22-14</u> MECHANIC <u>James</u> JOB NAME/LOCATION _____ JOB NUMBER _____
PROBLEM: <u>Engine oil Pressure sensor sending wrong signal</u> <u>grease line broken at turn table</u>		
REPAIRED: <u>replaced sensor, replaced grease line and fitting, washed and greased.</u> <u>Adjusted front window slide</u>		
PARTS: <u>Sensor + 2 O-rings</u> \$ <u>176.91</u> <u>Thompson Machinery</u> <u>Tube</u> <u>48.21</u> <u>Thompson</u> <u>Elbow</u> <u>2.22</u> <u>Thompson</u>		

EQUIPMENT
REPAIRS

DATE 6-23-11

MILEAGE/HOURS _____

EQUIPMENT REPAIRED #311 Cat 330C

REPAIRS MADE Ordered 6-pins & 12 retainers
for large bucket.

HOURS WORKED _____

PARTS USED

6-pins & 12 retainers \$121.82

White Horse Equipment

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>311</u>	HOURS _____ DAYS _____ REASON PARTS LABOR OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>Cat</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>330C</u>		COMPONENT LOCATION		
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>7-17-14</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>JAMES</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>PEG</u>	JOB NUMBER	
PROBLEM: <u>blown hose</u>				
REPAIRED: <u>replaced bucket cylinder hose on</u>				
<u>right side of boom</u>				
PARTS: <u>hose</u> <u>387.68</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>311</u> MAKE <u>Cat</u> MODEL <u>330C</u> SERIAL # _____ HOUR METER <u>5,500 HRS</u> MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>8-23-14</u> MECHANIC <u>Tanner</u> <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:70%;">JOB NAME/LOCATION <u>Cedarstone Brake</u></td> <td style="width:30%;">JOB NUMBER</td> </tr> </table>	JOB NAME/LOCATION <u>Cedarstone Brake</u>	JOB NUMBER
JOB NAME/LOCATION <u>Cedarstone Brake</u>	JOB NUMBER			
PROBLEM: <u>window latch stoppers broken</u> <u>served</u>				
REPAIRED: <u>served</u>				
PARTS: <u>2-stoppers & 2 screws \$42.46</u> <u>Thompson Machinery</u> <u>All Filters</u> <u>368.87</u> <u>Thompson</u>				

TEC
THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>311</u> MAKE <u>Cat</u> MODEL <u>330C</u> SERIAL # _____ HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____ _____
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>4-22-15</u> MECHANIC <u>James & Steven</u> JOB NAME/LOCATION <u>Lebman Medical</u> JOB NUMBER _____
PROBLEM: <u>blown hose going to left travel motor</u> _____ _____		
REPAIRED: <u>replaced blown hose</u> _____ _____ _____ _____ _____ _____ _____		
PARTS: <u>hose</u> <u>223.74</u> <u>NAPA</u> _____ _____ _____ _____ _____		

EQUIPMENT
REPAIRS

DATE 3-31-15

MILEAGE/HOURS 6K

EQUIPMENT REPAIRED #311 CAT 330C

REPAIRS MADE service + check air conditioner
replaced heat + air control in cab.

HOURS WORKED _____

PARTS USED

All Filters	383. ⁴⁸	Tenn Filter
Heat + Air controller	449. ⁴³	Thompson
Silicon	6. ⁰⁰	Home Depot

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>311</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>330C</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: _____ DATE COMPLETED <u>7-23-15</u> MECHANIC <u>James & Steven</u>	
			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>Air controller not working</u> <u>needs stick bushings at bucket</u>				
REPAIRED: <u>replaced bushings and seals in lower end</u> <u>of stick</u> <u>greased</u>				
PARTS: <u>Controller Gp</u> <u>449.43</u> <u>Thompson</u> <u>Stick Bushings</u> <u>310.46</u> <u>Thompson</u> <u>seals</u> <u>85.74</u> <u>Thompson</u>				

EQUIPMENT
REPAIRS

DATE 9-24-15

MILEAGE/HOURS 6500 HRS

EQUIPMENT REPAIRED #311 330C

REPAIRS MADE serviced

HOURS WORKED _____

PARTS USED

All Filters ~~1000000~~ New Filter

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0504</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		FASON		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>330C</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE <u>5-20-21</u> DATE COMPLETED <u>5-27-21</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC _____	
SMOKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION <u>Eastgate</u> JOB NUMBER _____	
PROBLEM: <u>Master pin backed out</u>					
<u>blown hose</u>					
REPAIRED: <u>replaced hose</u>					
PARTS: <u>Master pin 4 clips 91.31</u>					
<u>hose 436.82</u>					
<u>Thompson</u>					
<u>Thompson</u>					



**WHITE HOUSE
EQUIPMENT & SUPPLY INC.**
HEAVY EQUIPMENT PARTS

Office: (615) 451-3385
171 W. Factory St., Suite C
Gallatin, TN 37066

4C

330C bucket

414100XF20X17

34M20

58"

or 60"

TEC
THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>311</u> MAKE <u>CAT</u> MODEL <u>330C</u> SERIAL # _____ HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____ _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>10-1-15</u> MECHANIC <u>James</u> <table border="1" style="width: 100%; border-collapse: collapse;"><tr><td style="width: 70%;">JOB NAME/LOCATION <u>Smith Travel</u></td><td style="width: 30%;">JOB NUMBER </td></tr></table>	JOB NAME/LOCATION <u>Smith Travel</u>	JOB NUMBER
JOB NAME/LOCATION <u>Smith Travel</u>	JOB NUMBER 			
PROBLEM: <u>blown hose</u> _____ _____				
REPAIRED: <u>replaced hose on back of stick</u> <u>cylinder</u> _____ _____ _____ _____ _____ _____				
PARTS: <u>hose</u> <u>411.78</u> <u>Thompson</u> _____ _____ _____ _____				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>311</u>	MAKE <u>CAT</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MODEL <u>330C</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
SERIAL # _____	HOUR METER <u>6816 HRS</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
MILES _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: _____ DATE COMPLETED <u>1-16-16</u> MECHANIC <u>James & Jeff M.</u>	
			JOB NAME/LOCATION <u>CATO</u>	JOB NUMBER
PROBLEM: <u>Turbo bad hole in muffer</u>				
REPAIRED: <u>replaced Turbo + Muffer</u>				
PARTS: <u>Turbo, Muffer + Hardware 199.⁰⁰ Thompson</u> <u>Pipes/Hardware 445.²⁶</u> <u>Turbo 2500.⁰⁰</u> <u>Muffer 700.⁰⁰</u>				

EQUIPMENT
REPAIRS

DATE 4-2-16

MILEAGE/HOURS 7K HRS

EQUIPMENT REPAIRED #311 CAT 330C

REPAIRS MADE served

HOURS WORKED _____

PARTS USED

All Filters

393.⁷⁹

Tennessie Filter

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>311</u>	HOURS _____ DAYS _____ REASON PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>330C</u>		COMPONENT LOCATION	
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 5-6-16
MECHANIC James
JOB NAME/LOCATION Shop JOB NUMBER _____

PROBLEM: Engine ECM failure, no A/C

REPAIRED: replaced Intake heater solenoid and Throttle position switch.

PARTS Solenoid switch 356.00 Thompson

TEC
THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION SERIAL # <u>311</u> MODEL <u>Cot</u> MODEL <u>330C</u> SERIAL # _____ HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____ _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>6-30-16</u> MECHANIC <u>Steele</u> <table border="1" style="width: 100%; border-collapse: collapse;"><tr><td style="width: 70%;">JOB NAME/LOCATION <u>Lehner</u></td><td style="width: 30%;">JOB NUMBER </td></tr></table>	JOB NAME/LOCATION <u>Lehner</u>	JOB NUMBER
JOB NAME/LOCATION <u>Lehner</u>	JOB NUMBER 			
PROBLEM: <u>pin backing out of teeth</u> _____ _____ _____				
REPAIRED: <u>replaced loose pins</u> _____ _____ _____ _____ _____ _____				

Pins & retainers

143.29

Thompson