

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 1202

MAKE Komatsu

MODEL HM300-1

SERIAL # _____

HOURLY METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: 9-12-22

DATE COMPLETED 9-23-22

MECHANIC All

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: hub leaking, high flow valve leaking

REPAIRED: replaced RT center outer carrier plate.

removed steering amp valve & resealed.

repaired parking brake system

PARTS hub & seals

Power Equipment

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 1202

MAKE Komatsu

MODEL Hn300-1

SERIAL # _____

HOUR METER 11k HRS

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON _____

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE 12-8-22 DATE COMPLETED 12-9-22

MECHANIC Anthony & Ben

JOB NAME/LOCATION

Anthem

JOB NUMBER

PROBLEM: Service

REPAIRED: serviced

PARTS

Filters

742.96

Ten Filter Jakes

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>1202</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>HM300-1</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE: <u>2-10-23</u> DATE COMPLETED <u>4-18-23</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION <u>Arthurs</u> JOB NUMBER _____	

PROBLEM: hoses leaking

REPAIRED: replaced 4 brake & steer hoses 1 fuel hose
bar bearing on front axle arms.
re-sealed left steer cylinder and both lift cylinders
replaced one left lift cylinder hose
replaced left rear tire

PARTS: Hoses & fittings 690.⁰⁰ Nashville Rubber & Gasket
1 steer 2 lift cylinder reseat 2075.⁷⁵ Mid South Tire
677.³⁵
hose 388.⁴⁵ Volunteer hose
Tire 2500.⁰⁰ Gateway Tire

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 1202
 MAKE Komatsu
 MODEL HM300-1
 SERIAL # _____
 HOUR METER 11,500 HRS
 MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
 REASON _____
 PARTS _____ LABOR _____
 OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
 POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER
 OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
 OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
 SMOKES SHORTED VIBRATE OTHER _____

DATE 7-27-23 DATE COMPLETED 7-28-23

MECHANIC Anthony

JOB NAME/LOCATION
41st Ave

JOB NUMBER

PROBLEM: Service

REPAIRED: serviced

PARTS: Filters

619.¹⁷⁴

Teau Filter

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1202</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>Hm300-1</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>9-22-23</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>41st Ave</u>	JOB NUMBER
PROBLEM: <u>leaks</u>				
REPAIRED: <u>changed two hoses</u>				
PARTS: <u>hose</u> 256. ¹³				
<u>hose & Adapters</u> 105. ⁰⁰				
<u>Nashville Rubber & Gasket</u>				
<u>Nashville Rubber & Gasket</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>1202</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Komatsu</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>HM300-1</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SMOKES SHORTED VIBRATE OTHER _____

DATE 10-16-23 DATE COMPLETED 11-27-23
MECHANIC Anthony + Justin
JOB NAME/LOCATION To Shop JOB NUMBER _____

PROBLEM: leaks & codes

REPAIRED: replaced brake valve
replaced coupling at hyd. Tank
replaced km sensor back at tail lights

PARTS: <u>brake valve</u>	<u>\$2,300.00</u>	<u>Power Equipment</u>
<u>hose</u>	<u>\$138.35</u>	<u>Crook's</u>
<u>coupling</u>	<u>\$395.54</u>	<u>Power Equipment</u>
<u>sensor</u>	<u>\$680.00</u>	<u>Pittman Equipment</u>

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>1202</u>		HOURS _____ DAYS _____		BASIC MACHINE	HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Komatsu</u>		REASON _____		POWER TRAIN	ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>HM300L</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>7-17-24</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>All</u>		
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>		JOB NUMBER _____
PROBLEM: <u>RT front brake leak.</u>					
REPAIRED: <u>removed hub & resented</u>					
PARTS: <u>Seals & O-rings</u> <u>3,904.89</u> <u>Power</u>					
<u>Seal</u> <u>90.30</u> <u>Power</u>					
<u>Seal</u> <u>920.83</u> <u>Power</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1202</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>HM300-1</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>12K HRS</u>		OTHER _____	
MILES _____			

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: _____ DATE COMPLETED <u>1-15-25</u> MECHANIC <u>ALL</u> <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:50%;">JOB NAME/LOCATION <u>new shop</u></td> <td style="width:50%;">JOB NUMBER</td> </tr> </table>	JOB NAME/LOCATION <u>new shop</u>	JOB NUMBER
JOB NAME/LOCATION <u>new shop</u>	JOB NUMBER		

PROBLEM: Service

REPAIRED: Serviced

PARTS: Filters 653.76 Tenn Filter.

EQUIPMENT
REPAIRS

DATE 4-24-08

MILEAGE/HOURS _____

EQUIPMENT REPAIRED #1005 NM300

REPAIRS MADE _____

HOURS WORKED _____

PARTS USED

Friction reducer \$45.35 Power Equipment

EQUIPMENT
REPAIRS

DATE 4-30-08

MILEAGE/HOURS 4,000 HRS

EQUIPMENT REPAIRED #1005 HM300-1

REPAIRS MADE full service changed all oil

HOURS WORKED _____

PARTS USED

filters & sample Bottles	793.51	Power Equipment
Element & oil	\$75.00	Power Equipment

EQUIPMENT
REPAIRS

DATE 7-29-08

MILEAGE/HOURS 4,198 HRS

EQUIPMENT REPAIRED #1005 HM300

REPAIRS MADE replaced batteries

HOURS WORKED _____


PARTS USED

2-4D Batteries #268. 65 Interstate

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1005</u>	HOURS _____ DAYS _____	REASON PARTS LABOR OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>			POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>Hm300-1</u>			COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER	
SERIAL # _____			OTHER _____	
HOUR METER _____				
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>3-18-09</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>James, Tech, Clinton, David</u>	
SMOKES SHORTED VIBRATE OTHER <u>blow out</u>			JOB NAME/LOCATION <u>Thompson Station</u>	JOB NUMBER
PROBLEM: <u>Right center tire blow out.</u>				
REPAIRED: <u>replaced tire and spring seal</u>				
PARTS: <u>Tire 23.5k25</u> <u>in stock</u>				



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1005</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>HM300-1</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # <u>1113</u>		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>4,500</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>6-4-09</u> DATE COMPLETED <u>8-5-09</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>JAMES</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>Service</u>				
REPAIRED: <u>Serviced</u>				
PARTS: <u>Filters</u> <u>249.20</u> <u>Term. Filter</u>				
<u>Hyd Filter</u> <u>80.44</u> <u>Power</u>				



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1005</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>HM300-1</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>4-1-10</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>JAMES</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION	JOB NUMBER
			<u>Shop</u>	
PROBLEM: <u>clean up</u>				
REPAIRED:				
PARTS: <u>Paint + Primer \$25.00</u> <u>Advance Auto Parts</u>				
<u>80gr Sandpaper 25¢</u> <u>12.01</u> <u>NAPA</u>				



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1005</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>HM300-1</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>4-7-10</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>JAMES</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>bad battery</u>				
REPAIRED: <u>replaced battery</u>				
PARTS: <u>1- 4D Battery</u> <u>\$152.90</u> <u>Interstate Battery</u>				

EQUIPMENT
REPAIRS

DATE 9-23-10

MILEAGE/HOURS _____

EQUIPMENT REPAIRED #1005 Komatsu HM300-1

REPAIRS MADE Installed load counter

HOURS WORKED _____

PARTS USED

Tally Counter \$17.⁰⁰ White Horse Equipment

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>1005</u>		HOURS _____	DAYS _____	BASIC MACHINE	HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Komatsu</u>		REASON		POWER TRAIN	ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>HM300-1</u>		PARTS	LABOR	COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT	REAR LEFT RIGHT UPPER LOWER
HOUR METER _____				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE: _____ DATE COMPLETED _____	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC <u>Jones</u>	
SMOKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION <u>Water Town</u>	JOB NUMBER _____
PROBLEM: <u>won't start</u> <u>hoist system problem</u> <u>left front suspension leaking oil.</u>					
REPAIRED: <u>replaced fuel filters</u> <u>replaced oil bushing and packing in left</u> <u>suspension cylinder</u> <u>EPC bad needs replaced</u>					
PARTS: <u>Fuel Filters</u> <u>46.58</u> <u>NAPA</u> <u>packing & seals</u> <u>38.00</u> <u>Signal Products</u> <u>bushing</u> <u>90.00</u> <u>White Horse Equipment</u> <u>hose</u> <u>54.00</u> <u>NAPA</u> <u>Hose assembly</u> <u>87.36</u> <u>NAPA</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1005</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>KOMATSU</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>HM300-1</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: _____ DATE COMPLETED <u>8-29-13</u>	
			MECHANIC <u>JAMES</u>	
			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>remove batteries for a scraper</u>				
REPAIRED: <u>Installed two new batteries</u>				
<u>washed</u>				
PARTS: <u>2- 4D batteries 305.00</u> <u>Advance Auto Parts</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>1005</u> MAKE <u>Komatsu</u> MODEL <u>HM300-1</u> SERIAL # _____ HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____ _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>4-2-14</u> MECHANIC <u>James</u> <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:70%;">JOB NAME/LOCATION <u>Shop</u></td> <td style="width:30%;">JOB NUMBER</td> </tr> </table>	JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER			
PROBLEM: <u>RT Front suspension cylinder down</u> _____ _____				
REPAIRED: <u>replaced pressure seal, wiper seal & bushing in cylinder</u> _____ _____ _____ _____ _____				
PARTS: <u>comp wiper seals 67.11</u> <u>Signal Industrial</u> <u>Bushing 80.30</u> <u>White Horse Equipment</u> <u>valve 398.76</u> <u>White Horse Equipment</u> <u>Blumag valve</u> <u>7926 101280 BQ 49 166</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1005</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>Ham 300-1</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>9-19-14</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Truel</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>clump lever broken</u>				
REPAIRED: <u>replaced lever</u>				
PARTS: <u>lever</u> <u>White Horse equipment</u>				

TEC
THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1005</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>Hm 300-1</u>	PARTS LABOR	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: <u>11-8-14</u> DATE COMPLETED <u>11-8-14</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>JAMES</u>	
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION JOB NUMBER	
		<u>Shop</u>	
PROBLEM: <u>needs fan belts</u>			
<u>check over</u>			
REPAIRED: <u>replaced fan belts</u>			
<u>greased, checked air in tires</u>			
PARTS: <u>Fan Belts</u> <u>122.39</u> <u>NAPA</u>			

EQUIPMENT
REPAIRS

DATE 9-23-15

MILEAGE/HOURS 5000 HRS

EQUIPMENT REPAIRED #1005 Komatsu HM300-1

REPAIRS MADE needs serviced

Serviced

HOURS WORKED _____

PARTS USED

All Filters

596.²⁵

Term. Filter Sales

EQUIPMENT
REPAIRS

DATE 4-19-16

MILEAGE/HOURS 5500 HRS

EQUIPMENT REPAIRED #1005 Komatsu HM300-1

REPAIRS MADE serviced, replaced RT mirror

HOURS WORKED _____

PARTS USED

All Filters
Mirror

596 ⁷⁵
239 53

Tenn Filter
White House Equipment

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>1005</u> MAKE <u>Komatsu</u> MODEL <u>HM300-1</u> SERIAL # _____ HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>9-16-16</u> MECHANIC <u>James & Steven B</u>
		JOB NAME/LOCATION JOB NUMBER <u>Legends Drive</u> _____
PROBLEM: _____		
REPAIRED: <u>replaced hood latch</u> <u>put sealer in rear hys</u>		

<u>2- relays</u>	<u>133.04</u>	<u>Power Equipment</u>
<u>Hood latch</u>		
<u>4</u>		
<u>Fuel cap</u>	<u>406.83</u>	<u>Power Equipment</u>

SINCE 1963

Ten. Filla asks
Power Equipment

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1002</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>Hm300-1</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>6520 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE <u>12-20-17</u> DATE COMPLETED <u>2-12-18</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC _____	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION	JOB NUMBER
PROBLEM: <u>decals & service</u>				
REPAIRED: <u>put decals on switches serviced</u>				
PARTS: <u>Switch</u> <u>767²⁵</u> <u>Power Equipment</u>				
<u>lock</u>				
<u>Decal & Handle</u>				
<u>Steer Fitter</u> <u>94⁰⁰</u> <u>Power Equipment</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963


EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1202</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>KOMATSU</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>HM300-1</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>3.9.18</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Charles</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION	JOB NUMBER
PROBLEM: <u>TRANS. sight tube broken</u>				
REPAIRED: <u>replaced tube & Topped of Transmission</u>				
PARTS: <u>Tube & Fittings 104.⁰⁴ Power Equipment</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1202</u>	REASON HOURS _____ DAYS _____ PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>Komatsu</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>HM300-1</u>		COMPONENT LOCATION		
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>5-9-18</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Charles</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Pine wood</u>	JOB NUMBER	
PROBLEM: <u>broken driveshaft</u>				
REPAIRED: <u>left front wheel shaft broken</u>				
PARTS: <u>yoke, spider, seal & hardware 1494.20</u> <u>Power Equipment</u>				



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963


EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1202</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>HM300-1</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>9-17-17</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Charles</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Beckwith west</u> JOB NUMBER _____	
PROBLEM: <u>one bad battery</u>				
REPAIRED: <u>replaced battery</u>				
PARTS: <u>4D-XHD</u> <u>210.00</u> <u>Interstate battery</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1202</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Komatsu</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>HM300-1</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>7K HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: _____ DATE COMPLETED <u>10-19-18</u> MECHANIC <u>Charles</u>	
			JOB NAME/LOCATION <u>Beckwith</u>	JOB NUMBER
PROBLEM: <u>needs serviced</u>				
REPAIRED: _____				
PARTS: <u>All Filters</u> <u>in stock</u>				




THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1202</u>	HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>Komatsu</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>HM300-1</u>		COMPONENT LOCATION		
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____	DATE COMPLETED <u>10-22-18</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Charles</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Beckwith</u>	JOB NUMBER _____	
PROBLEM: <u>bad battery</u>				
REPAIRED: <u>replaced battery</u>				
PARTS: <u>4DXHD battery</u> <u>209.00</u> <u>Interstate battery</u>				

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP # <u>1202</u>	MAKE <u>Komatsu</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MODEL <u>HM300-1</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
SERIAL # _____	HOUR METER _____	PARTS _____ LABOR _____	COMPONENT LOCATION	
MILES _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____	DATE COMPLETED <u>12-13-18</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Charles</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Warden Parcelin</u>	JOB NUMBER _____	
PROBLEM: <u>Flat tires</u>				
REPAIRED: <u>replaced bad tires</u>				
PARTS: <u>2-23.5X25</u> <u>4,450²³</u> <u>Gateway Tire</u>				
<u>6 coming</u>				
<u>MAXAM MS301</u>				



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1202</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>KOMATSU</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>HM300-1</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>1-8-19</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>BRYAN</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>MCH</u>	JOB NUMBER _____
PROBLEM: <u>lost fuel cap</u>				
REPAIRED: <u>replaced cap</u>				
PARTS: <u>CAP</u> <u>8214</u> <u>Power Equipment</u>				