

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 1207
MAKE Volvo
MODEL A40G
SERIAL # _____
HOUR METER 6500 HRS
MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
REASON _____
PARTS _____ LABOR _____
OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER
OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SMOKES SHORTED VIBRATE OTHER _____

DATE: 4-26-23 DATE COMPLETED 4-29-23

MECHANIC Anthony

JOB NAME/LOCATION
Stone Trace

JOB NUMBER

PROBLEM: Service

REPAIRED: serviced

PARTS: Filters 394.01 Scott Equipment

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 1207

MAKE Volvo

MODEL A40G

SERIAL # _____

HR METER 2K HRS

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 7-12-23

MECHANIC Anthony

JOB NAME/LOCATION Stone Trace

JOB NUMBER _____

PROBLEM: Service

REPAIRED: serviced

PARTS: filters \$ 1,067.⁰² Scott Equipment

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1207</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Volvo</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>A40G</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>7500 HRS</u>		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: <u>10-31-23</u> DATE COMPLETED <u>11-2-23</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Anthony</u>	
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION	JOB NUMBER
		<u>Stone Trace</u>	
PROBLEM: <u>Service</u>			
REPAIRED: <u>Service</u>			
PARTS: <u>Filters</u> <u>266.96</u> <u>Scott Equipment</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1207</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Volvo</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>A40G</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE <u>8-30-24</u> DATE COMPLETED <u>9-23-24</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC <u>Anthony & Lawrence Glass</u>		
SMOKES SHORTED VIBRATE OTHER _____	JOB NAME/LOCATION <u>Pucil Run</u>		
	JOB NUMBER _____		
PROBLEM: <u>Service</u>			
REPAIRED: <u>Service</u> <u>new left door glass.</u>			
PARTS: <u>filters</u>	<u>368.62</u>	<u>Scott Equipment</u>	
<u>glass</u>	<u>233.79</u>	<u>Lawrence glass</u>	
<u>Lawrence glass</u>	<u>528.71</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1207</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Volvo</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>A406</u>	PARTS LABOR	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE <u>10-28-24</u> DATE COMPLETED <u>10-30-24</u>	
		MECHANIC <u>Anthony</u>	
		JOB NAME/LOCATION <u>Quail Run</u>	JOB NUMBER
PROBLEM: <u>won't start</u>			
REPAIRED: <u>replaced both batteries, switch and starter.</u>			
PARTS: <u>2 batteries</u> <u>458.⁰⁰</u> <u>Interstate battery</u> <u>starter repair</u> <u>485.¹⁰</u> <u>Cook's</u> <u>switch</u> <u>200.⁰⁰</u> <u>Scott Equipment</u>			

1100

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES			
EQUIP. # <u>1207</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS			
MAKE <u>Volvo</u>		REASON		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED			
MODEL <u>A40G</u>		PARTS _____ LABOR _____		COMPONENT LOCATION			
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER			
HOUR METER _____				OTHER _____			
MILES _____							

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>6-4-25</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION	
		<u>TCAT</u>	
		JOB NUMBER	

PROBLEM: bad det pick up

REPAIRED: replaced assembly

PARTS: pick up 1675.89 Scott Equipment

110

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES			
EQUIP. # <u>12017</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS			
MAKE <u>Volvo</u>		REASON		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED			
MODEL <u>A40G</u>		PARTS _____ LABOR _____		COMPONENT LOCATION			
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER			
HOUR METER _____				OTHER _____			
MILES _____							

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE: <u>6-12-25</u>		DATE COMPLETED: <u>6-17-25</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC <u>Ben</u>			
SMOKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION		JOB NUMBER	
				<u>TCAT</u>			

PROBLEM: SCR failure

REPAIRED: replaced damaged def. injector lines.

PARTS: lines 418.4 Scott Equipment
clean codes & flash 1,231.96 Scott Equipment

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION IP. # <u>1207</u> MAKE <u>Valvo</u> MODEL <u>A40G</u> SERIAL # _____ HOUR METER _____ NOTES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
--------------------------------------------------------------------------------------------------------------------------------------------------	---------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SHAKES SHORTED VIBRATE OTHER _____	DATE: _____ DATE COMPLETED <u>7-3-25</u> MECHANIC <u>Ben</u> JOB NAME/LOCATION <u>TCAT</u> JOB NUMBER _____
-------------------------------------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------------

PROBLEM: blown out steer tire

REPAIRED: replaced tire.

PARTS: 29.5x25 MS301 4071.73 Caterpillar tire