

**DOVE CREEK AUTOMOTIVE**

5177 Stapley Road, Courtenay, BC V9J 1P5 250.532.1365

Date: 7/2/25  
Invoice #: 285

BillTo: [REDACTED]

Vehicle Year/Make/Model/VIN#	Payment Terms
bmw x5 2007 z39766	Due upon receipt

**LABOUR**

Qty	Work Performed	Unit Price	Line Total
1.00	inspection	\$58.50	\$58.50
2.50	rear left taillight diodes replace+bulbs	\$58.50	\$146.25
1.50	pcv membrane replace	\$58.50	\$87.75
2.00	heater valves replace	\$58.50	\$117.00
1.00	seaat calibration&service reset	\$58.50	\$58.50
		\$58.50	\$0.00

**PARTS**

Qty	Parts Description	Unit Price	Line Total
1	misc shop supplies	\$20.00	\$20.00
1	window master switch	\$38.00	\$38.00
1	diodes	\$12.00	\$12.00
0	parts	278.26	\$0.00
0			\$0.00

Subtotal	\$538.00
Tax	
Amount Due	\$538.00

Please e-transfer payment to: DoveCreekAutomotive@gmail.com

**THANK YOU FOR YOUR BUSINESS!**



Trust the Midas touch.

Midas Auto & Tire Service #11  
2275 Cliffe Avenue  
Courtenay, BC BC V9N 2L5  
+1 250-338-7211  
midas.com

Date	2/21/2025	Vehicle	2007 BMW X5
Customer	[REDACTED]	License Plate	BC
		Odometer	227,687 km
Repair Order	250221003	VIN	5UXFE83557LZ39766

## Midas Touch Visual Courtesy Check

### Priority Recommendations

Inspection Point	Finding/Recommendations
Fluids and filters that should be changed due to poor/contaminated condition	
Fluid Leaks	No  Technician's Notes: Oil leak
General repairs: Inspection found the following items	
Notes	Technician's Notes: No sticker but oil looks good also right front grill and Gill are missing plastic pieces and fell out
Steering and Front End	Finding: Front end play Recommendation: See Notes Technician's Notes: Both front lower control arms have play
Monitor Only: At this time we will be monitoring the issue only and do not recommend any further action.	
Wheels Removed and Pictures of Brakes taken	Yes  Technician's Notes: Rear pads are 6 mm front pads are 8 mm all pads wearing evenly
No action required	
Battery/Cables	Finding: Remote Post requiring labor to test Recommendation: Additional labor charge

### Cabin and Under Hood

### Finding/Recommendations

Are All Dash Warning Lights Off?	
Wipers	
Horn Working OK?	Yes
Are All Exterior Lights Working?	Yes

## Engine Air Filter



Belts (Except Timing Belt)

Hood/Hatch supports

Engine Oil Level/Condition

Power Steering Fluid Level / Condition

Coolant Level / Condition

Coolant performs two essential jobs in the engine. It cools the engine and protects against freezing. Coolant also has important additives to prevent corrosion inside the cooling system. A coolant pH of 8 and above will provide protection against corrosion. Coolant with a pH of 7.5 or lower will begin to corrode the inside of the engine causing widespread failures.

Cooling System Hoses

Brake Fluid Level / Condition 1 ppm

### Tires and Brakes

### Finding/Recommendations

Left Front Tire Condition 5 /32nds

Right Front Tire Condition 5 /32nds

Right Rear Tire Condition 4 /32nds

Left Rear Tire Condition 4 /32nds

Tire's Replaced - Gino

Did Midas rotate wheels? Green 103 ft lbs  
yes / Red no

### Under Vehicle

### Finding/Recommendations

Shocks and Struts

CV and U-joints Yes

Exhaust System Yes

Cameron ., A Certified Technician has made this inspection; it reflects the car's condition on this day and does not imply a warranty on the items checked. This inspection should only be used as an aid. This inspection does not mean that there were no other problems, but

only what we noticed or what appeared at the time of inspection. Certain items may need further inspection to determine the extent of damage and cost.