

Vehicle claims history report



ICBC Vehicle Claims History

VIN	Year	Make	Model
2G2FS22K0V2213412	1997	PONTIAC	FIRBD

Your Search Results

Status: **Normal**

If a vehicle does not have a status of rebuilt, salvage, non-repairable, or altered, it is considered to have a normal status. "Normal" is simply a term used for the purposes of vehicle registration.

A normal status does not mean the vehicle has never been damaged or is in good mechanical condition. Vehicle status alone does not fully describe a vehicle's mechanical condition or damage history.

**Vehicle
Imported:
(from
outside B.C.)** **NO**

ICBC Claim History

Claim Date	Type of Claim	Amount	Description	Primary Area of Damage
11-May-2012	GLASS	\$723.36	REPAIRS	

Statements of Limitation

Vehicle Status:

B.C.-registered vehicles may have a status of normal, rebuilt, salvage, altered, or non-repairable.

Please note: Vehicle status alone does not fully describe a vehicle's mechanical condition or damage history.

Vehicle status records are obtained from the B.C. vehicle registry at the date and time of a VIN search. Any changes to a vehicle's status after that date will change the information shown.

The status may not represent the vehicle accurately for a number of reasons, including any of the following:

- A written off vehicle has not been reported to the B.C. vehicle registry.
- A vehicle wrecker or recycler has not reported a vehicle that has been decommissioned.

Miles Automotive Ltd

A 1002 Herring Gull Way
Parksville, BC. V9P 2N1
Phone: 250-248-9679

INVOICE**37695****INVOICE**

Printed Date: 07/29/2025 Work Completed: 07/29/2025

1997 Pontiac - Firebird - 3.8L, V6 (231CI) VIN(K)

Lic # :

Odometer In : 151097

Cellular 250-927-0757

VIN # : 2G2FS22K0 V2213412

Part Description	Qty	Sale	Ext	Labor Description	Ext
DELCO BELT	1.00	112.99	112.99	Replace belt	75.00
DISTRIBUTORLESS COIL	1.00	96.99	96.99	Replace front coil for #3 and #6	75.00
Shop Supplies			15.00	test drive vehicle, scan codes (no codes found) on board diag showed misfires on cylinder 3 and 6 replaced coil that controls both	
				Environmental Charge	5.00
Taxes					
GST					19.00
PST					15.75

[Payments -]

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Labor:	150.00
Parts:	224.98
HazMat:	5.00
Sub:	379.98
Tax:	34.75
Total:	\$414.73
Bal Due:	\$414.73

Vehicle Received: 07/29/2025

Customer Number : 8210

Signature _____ Date _____

Email Address: milesauto24@gmail.com