



Tire Exchange

3745 Trans Canada Highway | Cobble Hill, BC V0R 1L7
Phone: 250-743-6743 Ext 1 | Fax: 250-743-6526
accounting@tireexchange.ca | www.tireexchange.ca

SO# 536361

SERVICE ORDER CUSTOMER COPY



Printed 09/28/2024 10:42:43 AM

User Zar Page 1

Customer No 31878



BC

Home (604) 790-6320 Bus
Cell (250) 389-0889 Today
Email

Term Visa

Advisor Ember Promised 09/28/2024 5:00 PM Tag#
Shop S1 Opened 09/28/2024 10:01 AM Location
Priority Cashiered 09/28/2024 10:42 AM PO #

License	Odom In	Odom Out	In Service Date	Stock No
	249904	249906		
Year	Make	Model	Model Number	Colour
2005	MAZDA	MAZDA3	D4TD55	
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
JM1BK123451347204				
Engine	2.3L DOHC EFI 16-valve I4 engine			

Request	Description						Job	CSR	Status
PMB4	PASSENGER MOUNT & BALANCE 4 TIRES WITH VALVE STEM						1	EMBER	Original
Labour	Description							Type	Amount
PMB4	PASSENGER MOUNT & BALANCE 4 TIRES WITH VALVE STEM							C	120.00
Part	Description	Shp	Bin	Type	Retail	Price			Amount
P STICKY WEIGHTS	PASSENGER STICKY WEIGHTS 2OZ	4		CRO	2.00	2.00			8.00
VALVE250	TR413, TR413CHROME, TR418, TR412, TR412L, 33-070-9,	4		CRO	2.50	2.50			10.00
6959613721861	205-50-17 GREENTRAC SEANSON MASTER	4		CRO	129.00	129.00			516.00
TLEVY	Tire Levy	4		CRO	6.50	6.50			26.00
Fill Rate	0.00			Parts Total					560.00
Technician	MATT -			Labour Total					120.00
				Request Sub-total					680.00

Please make all E-transfer payments to accounting@tireexchange.ca memo INV/SO #
It is the customers' responsibility and our recommendation that the vehicle is brought in to have the wheels retorqued after 100km free of charge. All new tires are subject to the manufacturers standard warranty.
PST#: 1012-3448 GST#: 851048967 Business number: 0762948 BC LTD

KROFFAT BRAKE AND WHEEL**4970 POLKEY RD #4**

Date Finished:

2024-09-25**DUNCAN, B.C. V9L6W3****PHONE: (250) 748-0441 FAX: (250) 748-0474****2024-09-25****5:00:46 PM**

InvoiceNumber:	WorkorderID	Odometer	License Number	Engine Size
34733	36310	249751	LM506M	

Name	[REDACTED]	Phone Number	([REDACTED])	Date Received	2024-09-25
Address				P.O #	
City	B C	2005, MAZDA, 3		Pst Number:	0

Total Labour	\$79.20
Total Parts	\$68.31
TotalSublet	
S/S and Other	\$9.50
Sub Total	\$157.01

Pst Tax:	\$10.99
Gst Tax	\$7.85
Total Fees	\$0.00
Parts TaxIncluded	\$0.00
Total Invoice	\$175.85
Total Payment	\$0.00

Amount Due **\$175.85**

Payment Method	Payment Amount	net 30 days
Charge	\$0.00	

Title of goods shall remain in the name of the vendor until fully paid for

Customer Signature _____

customer must return vehicle to have wheel nuts retorqued with in 100 km after initial repair.

I hereby acknowledge the satisfactory completion of the above service work

September 25, 2024

KROFFAT BRAKE AND WHEEL

KROFFAT BRAKE AND WHEEL**4970 POLKEY RD #4**

Date Finished:

2024-09-25**DUNCAN, B.C. V9L6W3****PHONE: (250) 748-0441 FAX: (250) 748-0474****2024-09-25****5:00:46 PM**

InvoiceNumber: 34733 WorkorderID: 36310 Odometer: 249751 License Number: LM506M Engine Size:

Name: [REDACTED] Phone Number: [REDACTED] Date Received: 2024-09-25
Address: [REDACTED] P.O #:
City: B C 2005, MAZDA, 3 Pst Number: 0

Parts

Qty	PartNumber	Description	List Price	Sell Price	Ext Price
1	31-21	WIPER BLADE		\$11.90	\$11.90
1	31-19	WIPER BLADE		\$11.90	\$11.90
1	CH9641	OIL FILTER		\$11.88	\$11.88
4	5-20	OIL		\$7.22	\$28.88
0.5	WASHER FLUID	WINDSHIELD WASHER FLUID		\$7.50	\$3.75
Total					\$68.31

Labour

Comment	List Labour:	Net Labour
Service: Oil change and check over. SEE NOTES		\$49.50
Check burnt out drivers head light. SEE NOTES		\$29.70

Sublet Labour**SHOP SUPPLIES \$7.50****OIL/ FILTER DISPOSAL CHA \$2.00****BALANCE FORWARD \$0.00****Workorder Notes:**

FRONT AND REAR BRAKES >50%. RECOMMEND AT LEAST 2 NEW TIRES FOR WINTER.
HEADLIGHT CONNECTOR ON ORDER!

Title of goods shall remain in the name of the vendor until
fully paid for

Customer Signature _____

customer must return vehicle to have wheel nuts retorqued with in 100 km
after initial repair.

I hereby acknowledge the satisfactory completion of the above
service work

September 25, 2024

KROFFAT BRAKE AND WHEEL

Page 1 of 2

KROFFAT BRAKE AND WHEEL

4970 POLKEY RD #4

DUNCAN, B.C. V9L6W3

PHONE: (250) 748-0441 FAX: (250) 748-0474

2024-05-14

2:22:30 PM

Confirmed**WorkorderID** **Odometer**
35401 242895**License Number**
LM506M**Engine Size****Name** [REDACTED]
Address
City **B C****Phone Number** [REDACTED]

2005, MAZDA, 3**Date Received** 2024-05-14
P.O #
Pst Number: 0**Total Labour** \$425.70
Total Parts \$443.36
TotalSublet
S/S and Other \$12.00
Sub Total \$881.06**Pst** \$61.67
Gst \$44.05
Total Fees \$0.00
Parts TaxIncluded \$0.00
Total Invoice \$986.78
Total Payment \$0.00**Amount Due** \$986.78**Payment Method** **Payment Amount**
Charge \$0.00**Customer Signature** _____

Kroffatauto@gmail.com

May 14, 2024

KROFFAT BRAKE AND WHEELTitle of goods shall remain in
the name of the vendor until
fully paid for

KROFFAT BRAKE AND WHEEL**4970 POLKEY RD #4****DUNCAN, B.C. V9L6W3****PHONE: (250) 748-0441 FAX: (250) 748-0474****2024-05-14****2:22:30 PM****Confirmed**

WorkorderID	Odometer	License Number	Engine Size
35401	242895	LM506M	

Name	[REDACTED]	Phone Number	[REDACTED]	Date Received	2024-05-14
Address				P.O #	
City	B C	2005, MAZDA, 3		Pst Number:	0

Parts

Qty	PartNumber	Description	List Price	Sell Price	Ext Price
1	K060520	SERPENTINE BELT		\$46.41	\$46.41
1	902-682	THERMOSTAT AND HOUSING		\$67.74	\$67.74
1	265-879	TRANSMISSION PAN		\$95.20	\$95.20
1	K050264SF	AC BELT		\$64.62	\$64.62
1	45996	IDLER PULLEY		\$42.76	\$42.76
1	58617	TRANSMISSION FILTER KIT		\$43.91	\$43.91
4	252-2005	AUTOMATIC TRANSMISSION FLUID: MAZDA SYNTHETIC		\$17.07	\$68.28
2	LORDAFC	ANTIFREEZE		\$7.22	\$14.44
Total					\$443.36

Labour

Comment	List Labour:	Net Labour
Replaced transmission pan and filter. Filled with new trans fluid.		\$148.50
Replace burnt out LF head light bulb. (customer supplied parts)		\$29.70
Replace thermostat housing, both drive belts and main drive belt tensioner pulley. Topped up coolant and bled.		\$247.50

Sublet Labour

SHOP SUPPLIES	\$10.00
OIL/ FILTER DISPOSAL CHA	\$2.00
BALANCE FORWARD	\$0.00

Workorder Notes:**Customer Signature** _____**Kroffatauto@gmail.com**Title of goods shall remain in
the name of the vendor until
fully paid for

May 14, 2024

KROFFAT BRAKE AND WHEEL

Page 1 of 2



Tire Exchange

3745 Trans Canada Highway | Cobble Hill, BC V0R 1L7
Phone: 250-743-6743 Ext 1 | Fax: 250-743-6526
accounting@tireexchange.ca | www.tireexchange.ca

SO# 536361

SERVICE ORDER CUSTOMER COPY



Printed 09/28/2024 10:42:43 AM

User Zar Page 2

Customer No 31878
[Redacted]
BC
Home (604) 790-6320 Bus
Cell (250) 389-0889 Today
Email
Term Visa

Advisor	Ember	Promised	09/28/2024 5:00 PM	Tag#
Shop	S1	Opened	09/28/2024 10:01 AM	Location
Priority		Cashiered	09/28/2024 10:42 AM	PO #

License	Odom In	Odom Out	In Service Date	Stock No
	249904	249906		
Year	Make	Model	Model Number	Colour
2005	MAZDA	MAZDA3	D4TD55	
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
JM1BK123451347204				
Engine	2.3L DOHC EFI 16-valve I4 engine			

EITHER 2 NEW 205 55 16 GREEN TRACS OR 2 USED AS

OLD TIRES TOSS / BAG # BAGS USED _____ LOCK KEY RETURN _____

Patch _____ Valve _____

KMS _____ TRQ _____

PSI _____ TORQUED BY _____ WEIGHTS _____

Labour	120.00
Parts	560.00
Supplies	4.80
Sub-Total	684.80
GST	34.24
PST	47.94
Total Invoice	766.98
Visa	766.98

Please make all E-transfer payments to accounting@tireexchange.ca memo INV/SO #
It is the customers' responsibility and our recommendation that the vehicle is brought in to have the wheels retorqued after 100km free
of charge. All new tires are subject to the manufacturers standard warranty.
PST#: 1012-3448 GST#: 851048967 Business number: 0762948 BC LTD

Confirmed

KROFFAT BRAKE AND WHEEL
4970 POLKEY RD #4
DUNCAN, B.C. V9L6W3
PHONE: (250) 748-0441 FAX: (250) 748-0474

2024-04-18
12:13:14 PM

WorkorderID	Odometer	License Number	Engine Size
35231	241574	LM506M	

Name	[REDACTED]	Phone Number	[REDACTED]	Date Received	2024-04-18
Address	[REDACTED]			P.O #	
City	B C	2005, MAZDA, 3		Pst Number:	0

Total Labour	\$49.50	Pst	\$7.11
Total Parts	\$42.56	Gst	\$5.08
TotalSublet		Total Fees	\$0.00
S/S and Other	\$9.50	Parts TaxIncluded	\$0.00
Sub Total	\$101.56	Total Invoice	\$113.75
		Total Payment	\$0.00

Amount Due \$113.75

Payment Method	Payment Amount
Charge	\$0.00

Customer Signature _____

Kroffatauto@gmail.com

April 18, 2024

KROFFAT BRAKE AND WHEEL

Title of goods shall remain in
the name of the vendor until
fully paid for

KROFFAT BRAKE AND WHEEL
4970 POLKEY RD #4
DUNCAN, B.C. V9L6W3
PHONE: (250) 748-0441 FAX: (250) 748-0474

2024-04-18
12:13:13 PM

Confirmed

WorkorderID 35231 Odometer 241574 License Number LM506M Engine Size

Name [REDACTED] Phone Number [REDACTED] Date Received 2024-04-18
Address [REDACTED] P.O #
City B C 2005, MAZDA, 3 Pst Number: 0

Parts					
Qty	PartNumber	Description	List Price	Sell Price	Ext Price
4.25	5-20	OIL			
1	CH9641	OIL FILTER		\$7.22	\$30.69
				\$11.88	\$11.88
Total					\$42.57

Labour		
Comment	List Labour:	Net Labour
Service: Oil change and check over.		\$49.50
Sublet Labour		

SHOP SUPPLIES \$7.50
OIL/ FILTER DISPOSAL CHA \$2.00
BALANCE FORWARD \$0.00

Workorder Notes:

FRONT AND REAR BRAKES >50%. COOLANT THERMOSTAT HOUSING IS LEAKING
SLIGHTLY, RECOMMEND REPLACING THERMOSTAT HOUSING AND DRIVE BELTS
(COOLANT WILL GET ONTO BELTS AND MAKE BELTS NOISEY). RECOMMEND TRANS PAN
AND TRANS SERVICE. BATTERY IS MARGINAL-OK FOR NOW.
RECOMMEND AIR FILTERS NEXT SERVICE.

Customer Signature _____

Kroffatauto@gmail.com

Title of goods shall remain in
the name of the vendor until
fully paid for

April 18, 2024

KROFFAT BRAKE AND WHEEL

Page 1 of 2

KROFFAT BRAKE AND WHEEL**4970 POLKEY RD #4****DUNCAN, B.C. V9L6W3****PHONE: (250) 748-0441 FAX: (250) 748-0474****2024-02-12****12:37:06 PM****Confirmed**

WorkorderID	Odometer	License Number	Engine Size
34842	237946	LM506M	

Name	Phone Number	Date Received	2024-02-07
Address		P.O #	
City	2005, MAZDA, 3	Pst Number:	0

Total Labour	\$564.30	Pst	\$100.06
Total Parts	\$857.68	Gst	\$71.47
TotalSublet		Total Fees	\$0.00
S/S and Other	\$7.50	Parts TaxIncluded	\$0.00
Sub Total	\$1,429.48	Total Invoice	\$1,601.01
		Total Payment	\$0.00

Amount Due \$1,601.01

Payment Method	Payment Amount
Charge	\$0.00

Customer Signature _____**Kroffatauto@gmail.com****Title of goods shall remain in
the name of the vendor until
fully paid for****February 12, 2024****KROFFAT BRAKE AND WHEEL****Page 2 of 2**

Confirmed

KROFFAT BRAKE AND WHEEL
4970 POLKEY RD #4
DUNCAN, B.C. V9L6W3
PHONE: (250) 748-0441 FAX: (250) 748-0474

2024-02-12
12:37:06 PM

WorkorderID 34842 Odometer 237946 License Number LM506M Engine Size

Name [REDACTED] Phone Number [REDACTED] Date Received 2024-02-07
Address [REDACTED] P.O #
City B C 2005, MAZDA, 3 Pst Number: 0

Parts					
Qty	PartNumber	Description	List Price	Sell Price	Ext Price
1	W1336311L	STRUT ASSEMBLY			
1	W1336311R	STRUT ASSEMBLY		\$230.78	\$230.78
2	K80235	FRONT SWAY BAR LINK		\$230.78	\$230.78
1	81003	REAR COIL SPRING SET		\$93.11	\$186.22
				\$209.90	\$209.90
			Total		\$857.68

Labour		
Comment	List Labour:	Net Labour
Drop In: Cust was walking out to her car to unlock it and heard a bang(like something snapped) and the car shook and set the alarm off- Advise. Front coil spring broke and caused alarm to go off?		
Replace both front strut assemblies and sway bar links.		\$297.00
Replace both rear coil springs.		\$148.50
Wheel alignment.		\$118.80
Sublet Labour		

SHOP SUPPLIES \$7.50

Workorder Notes: BALANCE FORWARD \$0.00

TRANSMISSION PAN IS QUITE RUSTY - RECOMMEND REPLACING PAN WHEN SERVICING
TRANS FLUID. BUDGET 600\$ PLUS TAXES TO REPLACE TRANS PAN, GASKET, FILTER AND
FILL WITH NEW FLUID.

Customer Signature _____

Kroffatauto@gmail.com

Title of goods shall remain in
the name of the vendor until
fully paid for

February 12, 2024

KROFFAT BRAKE AND WHEEL

Page 1 of 2

KROFFAT BRAKE AND WHEEL
4970 POLKEY RD #4
DUNCAN, B.C. V9L6W3
PHONE: (250) 748-0441 FAX: (250) 748-0474

2023-10-23
1:06:55 PM

Confirmed

WorkorderID 34205 Odometer 233652 License Number LM506M Engine Size

Name [REDACTED] Phone Number [REDACTED] Date Received 2023-10-23
Address [REDACTED] P.O #
City B C 2005, MAZDA, 3 Pst Number: 0

Total Labour	\$99.00	Pst	\$11.66
Total Parts	\$50.58	Gst	\$8.33
Total Sublet		Total Fees	\$0.00
S/S and Other	\$17.00	Parts Tax Included	\$0.00
Sub Total	\$166.58	Total Invoice	\$186.57
		Total Payment	\$0.00

Amount Due \$186.57

Payment Method Payment Amount
Charge \$0.00

Customer Signature _____

Kroffatauto@gmail.com

Title of goods shall remain in
the name of the vendor until
fully paid for

October 23, 2023

KROFFAT BRAKE AND WHEEL

Page 2 of 2

KROFFAT BRAKE AND WHEEL

4970 POLKEY RD #4

DUNCAN, B.C. V9L6W3

PHONE: (250) 748-0441 FAX: (250) 748-0474

2023-10-23

1:06:55 PM

Confirmed

WorkorderID Odometer

34205 233652

License Number

LM506M

Engine Size

Name [REDACTED] Phone Number [REDACTED] Date Received 2023-10-23
Address [REDACTED] P.O #
City B C 2005, MAZDA, 3 Pst Number: 0

Parts

Qty	PartNumber	Description	List Price	Sell Price	Ext Price
4.5	5-20	OIL			
1	CH9641	OIL FILTER		\$7.22	\$32.49
0.5	WASHER FLUID	WINDSHIELD WASHER FLUID		\$11.88	\$11.88
1	194 BULB	BULB		\$9.28	\$4.64
				\$1.57	\$1.57
Total					\$50.58

Labour

Comment	Billable Hours:	List Labour:	Net Labour
Service: Oil change and check over. Replaced license plate light bulb. Cleaned beattery terminals. Installed new rear exhaust hanger.	1.00		\$99.00

Sublet Labour

SHOP SUPPLIES \$15.00
OIL/ FILTER DISPOSAL CHA \$2.00
BALANCE FORWARD \$0.00

Workorder Notes:

LF COIL SPRING IS BROKEN, NEEDS FRONT STRUT ASSEMBILES. ONE OF THE REAR COIL SPRINGS IS BROKEN, NEEDS A SET OF REAR COIL SPRINGS. REAR TRAILING ARM BUSHINGS ARE SEPERATING-OK FOR NOW. RECOMMEND TRANS PAN DRAIN AND RE-FILL. FRONT AND REAR BRAKES >50%.

BUDGET UP TO 1,500\$ PLUS TAXES TO REPLACE BOTH FRONT STRUT ASSEMBLIES, SWAY BAR LINKS, AND REAR COIL SPRINGS. (INCLUDES WHEEL ALIGNMENT)

Customer Signature _____

Kroffatauto@gmail.com

Title of goods shall remain in
the name of the vendor until
fully paid for

October 23, 2023

KROFFAT BRAKE AND WHEEL

Page 1 of 2

Kroffat Brake, Wheel and Muffler Shop

4970 Polkey Road
Duncan, BC V9L6W5

Phone Number: 250-748-0441

Customer:

Company:

License No:

Odometer:

Date:

9/26/2022 11:50 AM

VIN

Technician:

Order No.:

VEHICLE ALIGNMENT REPORT

MAZDA, 2005, 3 All Models

Primary Angles

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	3.8°	2.0°	4.0°	3.8°
		Right	2.4°	2.0°	4.0°	2.4°
	Camber	Left	-1.1°	-1.7°	0.3°	-1.1°
		Right	-1.5°	-1.7°	0.3°	-1.5°
	Toe	Left	0.30°	-0.10°	0.30°	0.25°
		Right	0.15°	-0.10°	0.30°	0.15°
Total		0.45°	-0.20°	0.55°	0.40°	
Rear	Camber	Left	-2.2°	-2.3°	-0.3°	-2.2°
		Right	-1.8°	-2.3°	-0.3°	-1.8°
	Toe	Left	0.10°	-0.10°	0.30°	0.10°
		Right	0.05°	-0.10°	0.30°	0.05°
		Total	0.15°	-0.20°	0.55°	0.15°
	Thrust Angle		0.0°	-0.8°	0.8°	0.0°

Secondary Angles

Secondary Angles		Initial	Specifications		Final
			Min.	Max.	
SAI	Left	14.1°	14.1°	14.1°	14.1°
	Right	14.7°	14.1°	14.1°	14.7°
Included Angle	Left	13.0°	----	----	13.0°
	Right	13.2°	----	----	13.2°
Toe Out On Turns	Left	----	----	----	----
	Right	----	----	----	----
Maximum Turns	Left	----	36.8°	42.8°	----
	Right	----	36.8°	42.8°	----
Toe Curve Change	Left	----	----	----	----
	Right	----	----	----	----
Setback	Front	0.2"	----	----	0.2"
	Rear	-0.4"	----	----	-0.3"
Track Width Diff.		0.7"			0.7"
Wheel Base Diff.		0.5"			0.5"
Front Ride Height	Left	----	----	----	----
	Right	----	----	----	----
Rear Ride Height	Left	----	----	----	----
	Right	----	----	----	----
Frame Angle					----

KROFFAT BRAKE AND WHEEL LTD**4970 POLKEY RD #4****DUNCAN, B.C. V9L6W3****PHONE: (250) 748-0441 FAX: (250) 748-0474****9/26/2022****12:12:19 PM****Confirmed**

WorkorderID	Odometer	License Number	Engine Size
31721	218339	LM506M	

Name	[REDACTED]	Phone Number	[REDACTED]	Date Received	9/26/2022
Address				P.O #	
City	B C	2005, MAZDA, 3		Pst Number:	0

Total Labour	\$266.00	Pst	\$31.53
Total Parts	\$179.37	Gst	\$22.52
TotalSublet		Total Fees	\$0.00
S/S and Other	\$5.00	Parts TaxIncluded	\$0.00
Sub Total	\$450.37	Total Invoice	\$504.42
		Total Payment	\$0.00

Amount Due \$504.42

Payment Method	Payment Amount
Charge	\$0.00

Customer Signature _____

Kroffatauto@gmail.com

Title of goods shall remain in
the name of the vendor until
fully paid for

#####

KROFFAT BRAKE AND WHEEL LTD

KROFFAT BRAKE AND WHEEL LTD**4970 POLKEY RD #4****DUNCAN, B.C. V9L6W3****PHONE: (250) 748-0441 FAX: (250) 748-0474****9/26/2022****12:12:19 PM****Confirmed****WorkorderID** **Odometer**
31721 **218339****License Number**
LM506M**Engine Size****Name** **[REDACTED]****Address****Phone Number** **[REDACTED]****Date Received** **9/26/2022****City** **B C****2005, MAZDA, 3****P.O #****Pst Number:** **0****Parts**

Qty	PartNumber	Description	List Price	Sell Price	Ext Price
1	102-5548	LOWER CONTROL ARM		\$179.37	\$179.37
			Total		\$179.37

Labour

Comment	Billable Hours:	List Labour:	Net Labour
Replace RF lower control arm	2.00		\$190.00
Check wheel alignment.	0.80		\$76.00

Sublet Labour**SHOP SUPPLIES** **\$5.00****Workorder Notes:****BALANCE FORWARD** **\$0.00****Customer Signature** _____**Kroffatauto@gmail.com**Title of goods shall remain in
the name of the vendor until
fully paid for

#####

KROFFAT BRAKE AND WHEEL LTD

Confirmed

KROFFAT BRAKE AND WHEEL LTD
4970 POLKEY RD #4
DUNCAN, B.C. V9L6W3
PHONE: (250) 748-0441 FAX: (250) 748-0474

1/10/2023
12:35:27 PM

WorkorderID Odometer
32343 156988

License Number
SJ557H

Engine Size

Name [REDACTED]
Address [REDACTED]
City B C

Phone Number [REDACTED]

2008, HYUNDAI, VERACRUZ

Date Received 1/10/2023
P.O #
Pst Number: 0

Total Labour \$29.70
Total Parts \$32.60
TotalSublet \$5.00
S/S and Other \$67.30
Sub Total

Pst \$4.71
Gst \$3.37
Total Fees \$0.00
Parts TaxIncluded \$0.00
Total Invoice \$75.38
Total Payment \$0.00

Amount Due \$75.38

Payment Method Payment Amount
Charge \$0.00

Customer Signature _____

KROFFAT BRAKE AND WHEEL LTD

Title of goods shall remain in
the name of the vendor until
fully paid for

KROFFAT BRAKE AND WHEEL LTD
4970 POLKEY RD #4
DUNCAN, B.C. V9L6W3
PHONE: (250) 748-0441 FAX: (250) 748-0474

1/10/2023
9:05:13 AM

Confirmed

WorkorderID Odometer License Number Engine Size
32331 222169 LM506M

Name [REDACTED] Phone Number [REDACTED] Date Received 1/9/2023
Address [REDACTED] P.O #
City B C 2005, MAZDA, 3 Pst Number: 0

Parts			
Qty	PartNumber	Description	
4	5141	SPARK PLUGS	
		List Price	Ext Price
		\$7.82	\$31.28
		Total	\$31.28

Labour			
Comment	Billable Hours:	List Labour:	Net Labour
No start, tried to boost it a few times, no luck, tow truck driver came out and started it and had it towed here, but suggested it didn't sound too good when it did start? It started this morning okay. Test battery + check			
Vehicle started normally here. Weather is much warmer than when initial failure happened. Remove lower dash to access OBD connector (SEE NOTES). No codes present. Replace spark plugs and road test. All seems okay	1.20		\$118.80

Sublet Labour

SHOP SUPPLIES \$5.00

Workorder Notes: BALANCE FORWARD \$0.00

OBD II CONNECTOR IS NOW ACCESSIBLE, BUT IS LOOSE IN CHANGE POCKET ON LOWER DASH.

Customer Signature _____

Kroffatauto@gmail.com

Title of goods shall remain in the name of the vendor until fully paid for

KROFFAT BRAKE AND WHEEL LTD

KROFFAT BRAKE AND WHEEL LTD
4970 POLKEY RD #4
DUNCAN, B.C. V9L6W3
PHONE: (250) 748-0441 FAX: (250) 748-0474

6/27/2022
10:55:56 AM

Confirmed

WorkorderID Odometer License Number Engine Size
31140 213388 LM506M

Name [REDACTED] Phone Number [REDACTED] Date Received 6/27/2022
Address [REDACTED] P.O #
City B C 2005, MAZDA, 3 Pst Number: 0

Parts

Labour

Comment	Billable Hours:	List Labour:	Net Labour
Replace customer supplied rear brake pads. Service calipers. SEE NOTES	1.50		\$142.50
Check front brakes for noise? SEE NOTES			

Sublet Labour

SHOP SUPPLIES \$5.00

Workorder Notes: BALANCE FORWARD \$0.00

FRONT BRAKES MAKING NOISE LIKELY DUE TO POOR QUALITY BRAKE PADS. EXPECT NOISE FROM THE REAR, TOO. (SORRY!) MONITOR REAR BRAKES FOR UNEVEN WEAR: IF UNEVEN WEAR IS NOTED, CALIPERS WILL NEED REPLACEMENT.

Total Labour	\$142.50	Pst	\$10.33
Total Parts	\$0.00	Gst	\$7.38
TotalSublet		Total Fees	\$0.00
S/S and Other	\$5.00	Parts TaxIncluded	
Sub Total	\$147.50	Total Invoice	\$165.21
		Total Payment	\$0.00

Amount Due \$165.21

Payment Method Payment Amount
Charge \$0.00

Customer Signature _____

Kroffatauto@gmail.com

Title of goods shall remain in
the name of the vendor until
fully paid for

Monday, June 27, 2022 KROFFAT BRAKE AND WHEEL LTD

Page 1 of 1

KROFFAT BRAKE AND WHEEL LTD

4970 POLKEY RD #4

DUNCAN, B.C. V9L6W3

PHONE: (250) 748-0441 FAX: (250) 748-0474

9/13/2022

1:28:21 PM

Confirmed

WorkorderID 31643
Odometer 217661

License Number LM506M

Engine Size

Name [REDACTED]

Phone Number [REDACTED]

Date Received 9/13/2022

Address

P.O #

City B C

2005, MAZDA, 3

Pst Number: 0

Parts

Qty	PartNumber	Description	List Price	Sell Price	Ext Price
1	CH9641	OIL FILTER			
4.5	5-20	OIL		\$11.88	\$11.88
0.5	WASHER FLUID	WINDSHIELD WASHER FLUID		\$7.22	\$32.49
				\$6.78	\$3.39
Total					\$47.76

Labour

Comment	Billable Hours:	List Labour:	Net Labour
Service: Oil change and check over. Check trans fluid.	0.50		\$47.50
Check for a intermittent clunk, and feeling rough changing into 2nd gear. SEE NOTES			

Sublet Labour

SHOP SUPPLIES \$5.00

OIL/ FILTER DISPOSAL CHA \$2.00

BALANCE FORWARD \$0.00

Workorder Notes:

FRONT AND REAR BRAKES LIKE NEW. A/C BELT IS SHOWING SIGNS OF WEAR, RECOMMEND REPLACING BOTH BELTS. REAR EXHAUST HANGER IS ROTTED OFF. RIGHT FRONT LOWER BALL JOINT IS WORN OUT, CONTROL ARM AND BALL JOINT ASSEMBLY NEED TO BE REPLACED.

BOTH REAR LATERAL ARMS BUSHINGS ARE WORN OUT. LEFT FRONT STRUTS COIL SPRING IS BROKEN, BOTH FRONT STRUTS NEED TO BE REPLACED. (PLUS WHEEL ALIGNMENT)

★ right front lower control arm 500\$ + tax
w/ ball joint

Customer Signature

Kroffatauto@gmail.com

★ front struts, sway bar links 1000 + tax

#####

KROFFAT BRAKE AND WHEEL LTD

Title of goods shall remain in the name of the vendor until fully paid for

Confirmed

KROFFAT BRAKE AND WHEEL LTD
4970 POLKEY RD #4
DUNCAN, B.C. V9L6W3
PHONE: (250) 748-0441 FAX: (250) 748-0474

9/13/2022
1:28:21 PM

WorkorderID	Odometer	License Number	Engine Size
31643	217661	LM506M	

Name	[REDACTED]	Phone Number	[REDACTED]	Date Received	9/13/2022
Address				P.O #	
City	B C	2005, MAZDA, 3		Pst Number:	0

Total Labour	\$47.50
Total Parts	\$47.76
Total Sublet	
S/S and Other	\$7.00
Sub Total	\$102.26

Pst	\$7.16
Gst	\$5.11
Total Fees	\$0.00
Parts Tax Included	\$0.00
Total Invoice	\$114.53
Total Payment	\$0.00

Amount Due \$114.53

Payment Method	Payment Amount
Charge	\$0.00

Customer Signature _____

Kroffatauto@gmail.com

Title of goods shall remain in
the name of the vendor until
fully paid for

#####

KROFFAT BRAKE AND WHEEL LTD