



ISLAND AUTOMOTIVE

250-248-8995

Auto Repair

- Satisfactory
- May Require Further Attention
- Requires Immediate Attention

STOCK #	C-1200	VEHICLE	2003 SAAB
CUSTOMER NAME	FIVE STAR	ODOMETER	199 267

Interior / Exterior			
Headlights (check high and low beam)	■	■	■
Tailights	✓		
Turn signal	✓		
Brake lights	✓		
Hazard warning lights	✓		
Interior lights	✓		
Windshield washer spray, operation, blades	✓		
Parking brake			
Horn operation	✓		

Tire Condition				■ 25 - 4.5mm ■ 4 - 2.5mm ■ 2mm or less		
Left Front				Right Front		
✓		Wear Pattern	Wear Pattern	✓		
✓		Tire thread <u>6</u> /mm	Tire thread <u>7</u> /mm	✓		
Left Rear				Right Rear		
		Wear Pattern	Wear Pattern			
	✓	Tire thread <u>4</u> /mm	Tire thread <u>4</u> /mm		✓	
Front tire inflation set to: _____ psi Rear tire inflation set to: _____ psi						

Battery Performance		
Pass		✓
Fail		

Brake Condition				■ 5mm or more ■ 3 - 4mm ■ 2mm or less		
Left Front				Right Front		
✓		<u>12</u> mm <u>100</u> %	<u>12</u> mm <u>100</u> %	✓		
Left Rear				Right Rear		
✓		<u>12</u> mm <u>100</u> %	<u>12</u> mm <u>100</u> %	✓		

Under Hood			
Engine oil level	✓		
Coolant level & Protection level		<u>-50°C</u>	
Power steering fluid level	✓		
Brake fluid level*	✓		
Windshield washer fluid level			
Transmission fluid level			
External drive belts and radiator hoses			
Air filters			

Comments:

- BELTS POOR CONDITION
- LEFT CV BOOT
- RIGHT SIDE CV BOOT
- SIGNIFICANT OIL LEAK AT FRONT OF ENGINE
- BATTERY TESTS BORDERLINE
- NEEDS COOLANT FLUSH
- RIGHT HEADLIGHT OUT
- PARK BRAKE WEAR (NOT HOLDING)
- AIR FILTER BOX BOLTS RUSTY / STRIPPED
- CLUNK IN FRONT?

Under Vehicle			
Brake lines/Hoses/Parking brake cable	✓		
Shock absorbers/Struts/Suspension			
Exhaust System			
Engine oil and/or fluid leaks			
Drive shaft/Constant velocity boots & bands			

