


TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0017</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ram</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>18' 1500 4x4</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES <u>New</u>				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>6-2-18</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Tony</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Cargill</u>	JOB NUMBER
PROBLEM: _____				
REPAIRED: <u>new tool box + bed mat</u>				
PARTS: <u>box + mat</u> <u>926.44</u> <u>Chuck's Trach All</u>				



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # _____	MAKE <u>Dodge</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MODEL <u>18</u>	SERIAL # _____	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
HOOR METER _____	MILES <u>5439</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
			OTHER _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>7-5-18</u> DATE COMPLETED <u>7-5-18</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Charles</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION _____	JOB NUMBER _____
PROBLEM: <u>Service</u>				
REPAIRED: <u>serviced</u>				
PARTS: <u>oil & filter in stock</u>				

PREMIER DODGE CHRYSLER JEEP OF LEBANON, LLC

600 Pleasant Grove Rd.
Mount Juliet, TN 37122
(615) 288-8525



SERVICE DEPARTMENT HOURS
7:30 a.m. to 6:00 p.m.
Monday - Friday
8:00 a.m. - 4:00 p.m. Saturday

R/O Open Date	R/O Number
11/12/18	6108558/1
R/O Close Date	Status
11/12/18	Pre-Invoice
Mileage In	Mileage Out
25010	25010
Service Advisor / Tag #	
Albee Holt/114*W*	
Vehicle Identification Number	
1C6RR7ST9JS237130	
Delivery Date	In-Service Date
5/30/18	5/30/18
Color	License Number
RED	

THORNES EXCAVATING CO LLC
624 OLD HORN SPRINGS RD
LEBANON, TN 37087-1811

Year	Make	Model
2018	RAM	1500

D10049

DESCRIPTION OF SERVICE AND PARTS	AMOUNT
Cell: 615-289-6006 Email: erict@tec63.com	
#1 - RECALL: RECALL RECALL / CSN 2 U53: CUSTOMER SATISFACTION NOTIFICATION U53 - OCCUPANT RESTRAINT CONTROL MODULE** Caused by COMPLETE Tech: MATT SMITH (627)	Warranty
#2 - RECALL: RECALL RECALL / CSN 1 U61: SAFETY RECALL U61 - REPROGRAM POWERTRAIN CONTROL MODULE** Caused by COMPLETE Tech: MATT SMITH (627)	Warranty
#3 - 9090: EXPRESS LANE INSPECTION MULTI-POINT INSPECTION (ACCORDING TO MAINTENANCE INTERVAL) Sub Total: .00	

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES: Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

LABOR	.00
PARTS	.00
DEDUCTIBLE	.00
SUBLET	.00
SHOP SUPPLIES	.00
HAZARDOUS MATERIALS	.00
SALES TAX OR TAX I.D.	.00
SPECIAL ORDER DEPOSIT	.00
DISCOUNTS	.00
TOTAL DUE	.00

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.

X

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0017</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ram</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>18' 1500 4X4</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # <u>Craig</u>		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES <u>44K mi</u>				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>4-2-19</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Charlie's Tire</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Charlie's Tire</u>	JOB NUMBER
PROBLEM: <u>new Tires</u>				
REPAIRED: <u>replaced tires</u>				
PARTS: <u>4- P265/70-17</u> <u>1770.43</u> <u>Charlie's Tire</u>				
<u>Goodyear Wrangler JIR-A</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>17</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ram</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>18' 1500 4x4</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
OUR METER <u>Craig</u>			OTHER _____	
MILES <u>50K mi</u>				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>5-10-19</u> DATE COMPLETED <u>5-13-19</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>James</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>needs service & brakes</u>				
REPAIRED: <u>replaced Front Pads & rotors, Replaced rear pads</u>				
<u>serviced</u>				
PARTS: <u>Front rotors & Front, rear pads</u> <u>156.38</u> <u>Advance Auto Parts</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0017</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>RAM</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>18'1500 4x4</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES <u>55k mi</u>				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>5-17-19</u> DATE COMPLETED <u>6-4-19</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>All</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>needs Power Inverter</u>				
<u>service</u>				
<u>needs bumper + spoiler</u>				
REPAIRED: <u>serviced</u>				
<u>Installed power inverter</u>				
<u>replaced bumper + brackets + spoiler</u>				
PARTS: <u>1500w Inverter</u> <u>196.65</u> <u>Advance Auto Parts</u>				
<u>bumper + spoiler</u> <u>962.00</u> <u>Premier Ram</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0017</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ram</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>18' 1500</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # <u>Phillip</u>		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>3-24-2020</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>James</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>blown bulb</u>				
REPAIRED: <u>replaced left low beam bulb</u>				
PARTS: <u>H11 bulb</u> <u>NAPA</u> <u>in stock</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0017</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ram</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>18' 1500</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # <u>Phillip</u>		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES <u>85k mi</u>				
REASON FOR FAILURE: ☐ BROKEN ☐ WORN ☐ ABUSE ☐ LOOSE ☐ SEIZED			DATE: <u>1-15-21</u> DATE COMPLETED <u>1-21-21</u>	
OVERHEAT ☐ PLANNED ☐ CONTAM ☐ LEAKING ☐ NOISY ☐ SCRATCH			MECHANIC <u>All</u>	
SMOKES ☐ SHORTED ☐ VIBRATE ☐ OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>won't fill with gas properly</u>				
REPAIRED: <u>new Tank vent, new gas tank serviced</u>				
PARTS: <u>Tank vent filter</u> <u>31.67</u> <u>Premier Ram</u>				
<u>Fuel Tank</u> <u>340.99</u> <u>Premier Ram</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0017</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ram</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>17' 1500</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # <u>Phillip</u>		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>3-10-21</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Phillip</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Eastgate</u>	JOB NUMBER _____
PROBLEM: <u>needs safety light</u>				
REPAIRED: <u>new safety light</u>				
PARTS: <u>light assembly</u>				
<u>wheel</u> <u>300.00</u> <u>Truckers light house</u>				
<u>WHEMCL6MF</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0017</u>	MAKE <u>Ram</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MODEL <u>17' 1500</u>	SERIAL # <u>Phillip</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
HOUR METER _____	MILES _____	PARTS _____ LABOR _____	COMPONENT LOCATION	
		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
			OTHER _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>3-17-21</u> DATE COMPLETED _____	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>James</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>check engine, busted tire fuel cap light</u>				
REPAIRED: <u>Put spare on reg rim, put used tire on spare rim.</u>				
PARTS: <u>Fuel cap</u> <u>29.25</u> <u>Premier Ram</u>				
<u>tire swap</u> <u>54.00</u> <u>Charlies Tire</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0017</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE _____		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL _____		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES <u>90K mi</u>				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: <u>4-27-21</u> DATE COMPLETED <u>4-28-21</u> MECHANIC <u>Al</u>	
			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>needs battery & service</u>				
REPAIRED: <u>replaced battery & serviced</u>				
PARTS: <u>battery & oil</u> <u>246.⁰⁰</u> <u>Advance Auto Parts</u> <u>4 yr warranty</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0017</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ram</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>17' 1500</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # <u>Phillip</u>		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES <u>90,651 mi.</u>				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>5-13-21</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Charlie's Tire</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION	JOB NUMBER
PROBLEM: <u>needs Tires</u>				
REPAIRED: <u>4-Tires</u>				
PARTS: <u>4 LT 265-70-17 \$1,046.¹⁸ Charlie's Tire</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0017</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ram</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>18 American</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # <u>Phillip</u>		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>P264</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Lawrence Glass</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>11</u> JOB NUMBER _____		
PROBLEM: <u>cracked windshield</u>				
REPAIRED: <u>replaced wind shield</u>				
PARTS: <u>glass</u> <u>\$304.81</u> <u>Lawrence Glass</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0017</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ram</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>18' 1500 4x4</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # <u>Phillip</u>		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES <u>105K mi</u>					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE: _____ DATE COMPLETED <u>3-3-22</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC <u>James + Caleb</u>	
SMOKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____	
PROBLEM: <u>Service needs brakes</u>					
REPAIRED: <u>Serviced, replaced front rotors & Pads & wear pads</u>					
PARTS: <u>Front rotors + pads F&R 181.07 Autozone</u>					

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0017</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ram</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>1500</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # <u>Philip</u>		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: _____ DATE COMPLETED <u>9-9-22</u> MECHANIC <u>Anthony</u>	
PROBLEM: <u>won't start</u>			JOB NAME/LOCATION <u>Stone Trace</u> JOB NUMBER _____	
REPAIRED: <u>replaced battery</u>				
PARTS: <u>MTP. 94R</u> <u>1571.40</u> <u>Interstate Battery</u>				