

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0810
MAKE Takachi
MODEL 12V
SERIAL # _____
HOUR METER 250 HRS
MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
REASON _____
PARTS _____ LABOR _____
OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SMOKES SHORTED VIBRATE OTHER _____

DATE 10-16-24 DATE COMPLETED 10-26-24

MECHANIC Anthony

JOB NAME/LOCATION

JOB NUMBER

Abrey's

PROBLEM: service

REPAIRED: serviced

PARTS: Filters to 250HRS 282.61 Power Equipment

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0810
 MAKE Takenchi
 MODEL _____
 SERIAL # _____
 HOUR METER _____
 MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
 REASON _____
 PARTS _____ LABOR _____
 OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
 POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER
 OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
 OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
 SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 4-28-25
 MECHANIC Ben

JOB NAME/LOCATION Christians court JOB NUMBER _____

PROBLEM: Quick connects broken

REPAIRED: replaced connector and elbows that were broken.

PARTS: Fittings 68.00 Nashville Rubber & Gasket
connectors 128.60 IR & G

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0810</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Takeuchi</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>TV120R</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>500 HRS</u>				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE: _____ DATE COMPLETED <u>9-8-25</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION	
				<u>Shop</u>	
				JOB NUMBER	
PROBLEM: <u>service & wash</u>					
REPAIRED: <u>serviced washed</u>					
PARTS: <u>Filters</u> <u>360.24</u> <u>Power Equipment</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0810
 MAKE Takeuchi
 MODEL _____
 SERIAL # _____
 HOUR METER _____
 MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
 REASON _____
 PARTS _____ LABOR _____
 OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
 POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER
 OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
 OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
 SMOKES SHORTED VIBRATE OTHER _____

DATE: 10-8-25 DATE COMPLETED 11-1-25
 MECHANIC Ben

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: A/C clutch not working

REPAIRED: replaced clutch, thermostat & relay

PARTS: <u>Compressor</u>	<u>601.14</u>	<u>Power Equipment</u>
<u>relay</u>	<u>55.99</u>	<u>Napa</u>
<u>A/C Thermostat</u>	<u>170.81</u>	<u>Power Equipment</u>